

IEEE P802.3an Comments

2/25/2005

Cl 01 SC 1.3 P3 L24 # 121
 Booth, Brad Intel
 Comment Type E Comment Status A
 Typo.
 Suggested Remedy
 Change "augemented" to "augmented".
 Response Response Status C
 ACCEPT.

Cl 28 SC P5 L1 # 124
 Booth, Brad Intel
 Comment Type E Comment Status A
 Remove unedited text.
 Suggested Remedy
 Remove 28.1, 28.4 and 28.6.
 Response Response Status C
 ACCEPT.

Cl 01 SC 1.4 P3 L35 # 122
 Booth, Brad Intel
 Comment Type E Comment Status A
 Text not required.
 Suggested Remedy
 Remove "is used in 10GBASE-T".
 Response Response Status C
 ACCEPT.

Cl 28 SC 28.2.1.2 P12 L34 # 126
 Booth, Brad Intel
 Comment Type T Comment Status A
 In Figure 28-7, the Technology Ability Field arrow includes bit D12 (A7). This bit has been modified to be an indication for extended next pages which is less of a technology ability as it is an auto-negotiation ability.
 Suggested Remedy
 Change A7 to be XNP. Shift the arrow to only point to A6. Shift 28.2.1.2.3-5 to be 28.2.1.2.4-6. Add new 28.2.1.2.3 as found in 28B.3. Remove A7 and extended next page information from Annex 28B.
 Response Response Status C
 ACCEPT.

Cl 01 SC 1.5 P3 L56 # 123
 Booth, Brad Intel
 Comment Type E Comment Status A
 Change "CAT6" to be "Cat 6".
 Suggested Remedy
 As per comment.
 Response Response Status C
 ACCEPT.

Cl 28 SC 28.2.3.4.2 P18 L28 # 75
 Lynskey, Eric UNH-IOL
 Comment Type E Comment Status A management
 Two periods at end of sentence.
 Suggested Remedy
 Remove period.
 Response Response Status C
 ACCEPT.

Cl 28 SC P5 L1 # 125
 Booth, Brad Intel
 Comment Type T Comment Status A
 This should be a revision to 802.3REVam.
 Suggested Remedy
 Verify that this is a revision to the existing REVam draft.
 Response Response Status C
 ACCEPT.

Cl 28 SC 28.2.4.1.1 P21 L34 # 12
Thompson, Todd SolarFlare Communica

Comment Type E Comment Status A

The register definition for MII control register 0 is defined in 22.2.4.1.

Suggested Remedy

Change 28.2.4.1 to 22.2.4.1.

Response Response Status C

ACCEPT.

This is an error also existing in the 2002 edition. Will also check to see if this has been caught in 802.3REVam.

Cl 28 SC 28.2.4.1.2 P21 L54 # 13
Thompson, Todd SolarFlare Communica

Comment Type E Comment Status A

The MII status register 1 is defined in 22.2.4.2 not 28.2.4.2.

Suggested Remedy

Change 28.2.4.2 to 22.2.4.2.

Response Response Status C

ACCEPT.

This is an error also existing in the 2002 edition. Will also check to see if this has been caught in 802.3REVam.

Cl 28 SC 28.2.4.1.8 P26 L1 # 127
Booth, Brad Intel

Comment Type E Comment Status A

In Table 28-8, break the MII/MDIO column into two columns.

Suggested Remedy

Create one column for MII (Clause 22), and another column for MDIO (Clause 45).

Response Response Status C

ACCEPT IN PRINCIPLE.

Cl 28 SC 28.3.1 P30 L31 # 128
Booth, Brad Intel

Comment Type E Comment Status A

Remove wasted space.

Suggested Remedy

Fix.

Response Response Status C

ACCEPT.

Cl 28 SC 28.3.2 P36 L # 14
Thompson, Todd SolarFlare Communica

Comment Type T Comment Status A

This is on page 36 lines 57-59 and page 37 lines 1-2 and the table 28-9. Regarding the time out values for nlp_test_min_timer, I don't think it's clear if the time out values is tied to whether a PHY supports extended next pages or is currently in the process of exchanging extended next pages. The spec seems to be saying that a phy that has support of extended next pages should always use the 6.75-7.25 timeout value. The base page is to be exchanged using the standard protocol and as such I would have expected the base page exchange to use all the non-extended next page timeout values and counts. However, this part of the spec seems to be saying that the extended next page value is to be used even during base page exchange.

Suggested Remedy

Clarify when the second timeout value of 6.75-7.25 ms is to be used and when the 5-7 ms timeout value is to be used.

Response Response Status C

ACCEPT IN PRINCIPLE.

Add text to clause 55 that clarifies 10GBASE-T will always use the optimized timers.

Cl 28 SC 28.3.2 P37 L42 # 129
Booth, Brad Intel

Comment Type E Comment Status A

Remove wasted space.

Suggested Remedy

Fix.

Response Response Status C

ACCEPT.

Cl 28 SC 28.5.3 P44 L37 # 130

Booth, Brad Intel

Comment Type T Comment Status A

It should be mandatory that AN support non-extended next page exchanges and non-optimized FLP-to-FLP burst timing. Therefore, the only options/capabilities that should be required to be listed are *ENP and *OPT.

Suggested Remedy

Remove *RNP and *RPT from options table and from other PICS entries.

Response Response Status C

ACCEPT.
If an implementation supports extended next pages and optimized FLP Burst to FLP Burst spacing, it also necessarily supports regular next pages and FLP Burst spacing.

Cl 28 SC 28.6 P57 L54 # 76

Lynskey, Eric UNH-IOL

Comment Type E Comment Status A

Missing text. I don't remember removing this text.

Suggested Remedy

Insert "Annex 28B" in appropriate location.

Response Response Status C

ACCEPT.

Cl 28C SC P64 L18 # 131

Booth, Brad Intel

Comment Type T Comment Status A

The use of M10 to indicate extended next pages seems to be overkill considering that we have exchanged extended next page capabilities in the base page.

Suggested Remedy

Delete text about M10 and its association with extended next pages.

Response Response Status C

ACCEPT.

Cl 28C SC P65 L9 # 132

Booth, Brad Intel

Comment Type E Comment Status A

In Table 28C-1, the 10GBASE-T Technology Message Code also contains information about 1000BASE-T.

Suggested Remedy

Add 1000BASE-T to the message code description.

Response Response Status C

ACCEPT.

Cl 28C SC 28C.11 P66 L51 # 133

Booth, Brad Intel

Comment Type T Comment Status R

Message code #9 should be able to work even if extended next pages are not used.

Suggested Remedy

Remove "extended" from first sentence. Delete last sentence.

Response Response Status C

REJECT.

Cl 28C SC 28C.11 P66 L55 # 134

Booth, Brad Intel

Comment Type T Comment Status A

Replace TBD.

Suggested Remedy

Cross-reference to 55.6.1.

Response Response Status C

ACCEPT.

IEEE P802.3an Comments

2/25/2005

Cl 28D SC 28D.5 P69 L45 # 135
 Booth, Brad Intel
 Comment Type T Comment Status A
 The addition of "extended next pages" in this normative annex would imply that Clause 40 now supports extended next pages. While the Task Force is permitting this ability with message code #9, we don't need to call out "extended".
 Suggested Remedy
 Remove inserted text in item b).
 Response Response Status C
 ACCEPT IN PRINCIPLE.
 Insert word "optionally" with appropriate commas in item b).

Cl 44 SC 44 P89 L20 # 33
 Lynskey, Eric UNH-IOL
 Comment Type E Comment Status A
 The draft includes an Annex 55A that is not listed here.
 Suggested Remedy
 Change text to read "...and Annex 44A through Annex 55A."
 Response Response Status C
 ACCEPT.

Cl 45 SC 45.2.1 P101 L47 # 136
 Booth, Brad Intel
 Comment Type E Comment Status A
 Numbering is not in order.
 Suggested Remedy
 Change 1.132 to 1.131. Change the next row of the table to start at 1.132 instead of 1.133.
 Response Response Status C
 ACCEPT.

Cl 45 SC 45.2.1.59.1 P104 L35 # 142
 Booth, Brad Intel
 Comment Type E Comment Status A
 Sentence does make sense.
 Suggested Remedy
 Change "... during the startup protocol and invalid." to "... during the startup protocol are invalid."
 Response Response Status C
 ACCEPT.

Cl 45 SC 45.2.1.59.1 P104 L36 # 143
 Booth, Brad Intel
 Comment Type T Comment Status A
 Replace TBD.
 Suggested Remedy
 Change TBD to read:
 PMA link_status = FAIL.
 Response Response Status C
 ACCEPT.

Cl 45 SC 45.2.1.61 P106 L41 # 144
 Booth, Brad Intel
 Comment Type E Comment Status A
 Incorrect register reference.
 Suggested Remedy
 Change 1.133 to be 1.131.
 Response Response Status C
 ACCEPT.

Cl 45 SC 45.2.1.7.4 P102 L50 # 137
 Booth, Brad Intel
 Comment Type E Comment Status A
 Replace TBD.
 Suggested Remedy
 Change TBD to 55.4.2.2.
 Response Response Status C
 ACCEPT.

Cl 45 SC 45.2.1.7.5 P103 L8 # 139
 Booth, Brad Intel
 Comment Type T Comment Status A
 Replace TBD with reference.
 Suggested Remedy
 Change TBD to be 55.4.2.3.
 Response Response Status C
 ACCEPT.

Cl 45 SC 45.2.3.11.1 P113 L36 # 145
 Booth, Brad Intel
 Comment Type E Comment Status A
 Need a space.
 Suggested Remedy
 Insert a space between & and 10GBASE-T.
 Response Response Status C
 ACCEPT.

Cl 45 SC 45.2.1.8 P103 L28 # 141
 Booth, Brad Intel
 Comment Type E Comment Status A
 There is only one 10GBASE-CX4 PMD.
 Suggested Remedy
 Insert a "the" before 10GBASE-CX4 and change PMDs to PMD.
 Response Response Status C
 ACCEPT.

Cl 45 SC 45.2.7 P115 L # 15
 Thompson, Todd SolarFlare Communica
 Comment Type E Comment Status A
 Table 45-117 and the entire clause 45.2.7 numbering of registers does not match Table 55-4 in Clause 55.6.
 The bottom line of Table 45-117 on page 115 is missing.
 Suggested Remedy
 Make table 55-4 match Table 45-117 or vise versa.

Cl 45 SC 45.2.3.1.2 P L # 83
 McClellan, Brett Solarflare
 Comment Type T Comment Status R Gpcspma
 The Loopback (3.0.14) bit description needs to be updated to include 10GBASE-T.
 Suggested Remedy
 Add text:
 When bit 3.0.14 is set to a one, the 10GBASE-T PCS shall accept data on the transmit path and return it on the receive path. The specific behavior of the 10GBASE-T PCS during loopback is specified in 55.3.
 Response Response Status C
 REJECT.
 Suggested text was already in the draft.

Fix the bottom outline of Table 45-117 on page 115.
 Response Response Status C
 ACCEPT IN PRINCIPLE.
 Comments 23 and 148 will change and consolidate registers to c45. Once concluded editors will coordinate to ensure c55 will match c45.

Cl 45 SC 45.2.7 P115 L 25 # 23
 Thompson, Todd SolarFlare Communica

Comment Type TR Comment Status A

This comment applies to all of Clause 45.2.7 and also 55.6.

Only when coming upon a reference to bit 6.1 in Table 45-121 and Clause 45.2.7.6.5 did it become clear that it's intended that a mixture of Clause 22/28 registers and Clause 45 registers will be required to manage auto-negotiation for a 10GBASE-T PHY.

All other functions for 10GBASE-T PHYs can be accomplished using only Clause 45 registers.

A single-speed 10GBASE-T PHY should be capable of being managed entirely using Clause 45 registers.

Suggested Remedy

Duplicate the functionality of Clause 22/28 Registers needed for auto-negotiation in Clause 45 so that a 10GBASE-T PHY may be managed entirely with an auto-negotiation MMD.

Make the Clause 22/28 registers optional for 10GBASE-T, so that an implementor who is implementing a multi-speed PHY can manage the auto-negotiation using Clause 22/28 and only needs to turn to Clause 45 registers when needed to support the extended next page functionality offered in Clause 45.

If this approach is not taken, and an approach that splits the functionality between Clause 22/28 and 45 is used, then write a section documenting the bits and their usage for all bits in the Clause 22/28 registers which apply and do not apply to managing the PHY. (For example, there's a reset bit in the clause 22 register 0. Does setting this bit result in resetting all MMD's within the PHY? Just the auto-neg MMD? Etc. There are several other bits in the Clause 22 registers whose usage become vague when these registers get pulled in. (status bits, etc.)

Finally, some of the bits in Clause 22/28 were moved to Clause 45 registers. If the Clause 22/28 registers are left, these should be removed from Clause 45 (for example, 7.0.12 and 7.0.9 are also located in Clause 22 Register 0.

Response Response Status C

ACCEPT IN PRINCIPLE.

See response to comment 148

Cl 45 SC 45.2.7 P116 L 15 # 18
 Thompson, Todd SolarFlare Communica

Comment Type E Comment Status A

Lines 15-17, Table 45-117. This comment also applies to Table 55-4 in Clause 55.6 and throughout Clause 45.2.7 in all other places.

The names in these two tables do not match and the names in Table 45-117 are incorrect (and throughout Clause 45.2.7). They are inconsistent with the names in Clause 28 and Clause 22 even though they share the same functionality.

Suggested Remedy

Both tables should have the same register names and register numbering.

Registers 7.19-7.21 in both tables and throughout 45.2.7 should be changed from "AN LD XNP ability register" to "AN XNP Transmit Register" to match the similar name in Clause 28 and to match it's functionality.

Registers 7.22-7.24 in both tables and throughout 45.2.7 should be changed from "AN LP XNP ability register" to either "AN LP Next Page Ability Register" to match Clause 28 or "AN LP Received Next Page" to match Clause 22. At least it should have the words "next page" in the name so as not to confuse it with register 7.16 in that same table (45-117).

Response Response Status C

ACCEPT IN PRINCIPLE.

Names should match. Ability register will become transmit register only for 7.19 through 7.21

XNP has already been used for "extended next page" thus 7.22-7.24 current name should be ok.

Cl 45 SC 45.2.7.1 P116 L36 # 146
Booth, Brad Intel

Comment Type T Comment Status A

Table 45-118 for register 7.0 should have a reset bit.

Suggested Remedy

Add reset bit (7.0.15) to the table and the following text as 45.2.7.1.1:
Resetting AN is accomplished by setting bit 7.0.15 to a one. This action shall set all AN registers to their default states. As a consequence, this action may change the internal state of AN and the state of the physical link. This action may also initiate a reset in any other MMDs that are instantiated in the same package. This bit is self-clearing, and AN shall return a value of one in bit 7.0.15 when a reset is in progress and a value of zero otherwise. AN is not required to accept a write transaction to any of its registers until the reset process is completed. The reset process shall be completed within 0.5 s from the setting of bit 7.0.15. During a reset, AN shall respond to reads from register bit 7.0.15. All other register bits should be ignored.

NOTE—This operation may interrupt data communication.

Response Response Status C
ACCEPT.

Cl 45 SC 45.2.7.10 P122 L50 # 150
Booth, Brad Intel

Comment Type T Comment Status A

The order in Table 45-124 seems a bit strange. Normal transmission is the message next page, then two unformatted code messages. From reading this table, someone might mistake the order of the data.

Suggested Remedy

List register 19, then 20, followed by 21.

Same applies to Table 45-125.

Response Response Status C
ACCEPT.

Cl 45 SC 45.2.7.2 P117 L20 # 16
Thompson, Todd SolarFlare Communica

Comment Type E Comment Status A

Table 45-122 reference is wrong.

Suggested Remedy

It should be Table 45-119.

Response Response Status C
ACCEPT.

Cl 45 SC 45.2.7.2 P117 L34 # 17
Thompson, Todd SolarFlare Communica

Comment Type E Comment Status A

Remote fault bit should be SC and LH in addition to RO. See the text regarding the behavior of this bit and also see the similar bit definition in Clause 22.

Suggested Remedy

Add SC and LH to the R/W column for this bit.

Response Response Status C
ACCEPT IN PRINCIPLE.
Make sure footnote has SC and LH

Cl 45 SC 45.2.7.2.1 P117 L47 # 19
Thompson, Todd SolarFlare Communica

Comment Type E Comment Status A

Lines 47-53.

The references to 7.16 and 7.19-7.21 are incorrect.

Looking at the similar Clause 28.2.4.1.2, the registers listed are 4,5,6 (in Clause 28) which are the registers "AN Advertisement Register", "LP AN Ability Register", and the "AN Expansion Register".

This confusion seems to have been partially a result of the name being incorrect for Registers 7.19-21 being labelled "ability" when it is in fact a "transmit" register.

Suggested Remedy

7.16 should be listed, but not 7.19-21.

Until the Clause 22/28 issues are resolved, it's not clear which other registers should be listed in addition to 7.16.

If the Clause 22/28 registers are left, then registers 4 and 6 should be added to the list. If the functionality of registers 4 and 6 are moved to equivalent Clause 45 registers, the new registers should be listed.

Response Response Status C
ACCEPT IN PRINCIPLE.

Should be registers 7.16 and 7.22-7.24 for a link partner

Cl 45 SC 45.2.7.2.2 P117 L55 # 147
 Booth, Brad Intel
 Comment Type E Comment Status A
 Remote fault bit references PMA/PMD when this bit is only associated with AN.
 Suggested Remedy
 Change PMA/PMD in the subclause to be AN.
 Response Response Status C
 ACCEPT IN PRINCIPLE.
 Delete remote fault bit

Cl 45 SC 45.2.7.5 P118 L26 # 148
 Booth, Brad Intel
 Comment Type TR Comment Status A
 The setup of the registers here are a little jumbled because there is a mix of Clause 22 functionality. Unlike Clause 22, Clause 45 has the ability to separately manage each part of the PHY. AN should be treated as a separate entity.
 Suggested Remedy
 In Table 45-117, shift registers 7.16 to 7.24 to be 7.19 to 7.27. Add register 7.16 to be AN LD base page ability register. Change register 7.7 to indicate the status of next page transmissions (as in MII register 6), delete all other information. Move registers 7.8 and 7.9 to registers 7.32 and 7.33. Register 7.32 should be renamed "10GBASE-T AN status register". Information for the base pages and next pages should be contained in 55.6.
 Response Response Status C
 ACCEPT. PROPOSED ACCEPT
 Appropriate bits in clause 22 will be mirrored in clause 45

Cl 45 SC 45.2.7.5.1 P119 L4 # 21
 Thompson, Todd SolarFlare Communica
 Comment Type E Comment Status A
 Word is missing on line 4.
 Suggested Remedy
 Add the word "use" between the words "will" and "Auto-negotiation".
 Response Response Status C
 ACCEPT.

Cl 45 SC 45.2.7.5.5 P119 L37 # 22
 Thompson, Todd SolarFlare Communica
 Comment Type E Comment Status A
 211 should be 2 raised to the 11th power.
 Suggested Remedy
 Modify 11 to be an exponent of 2.
 Response Response Status C
 ACCEPT.

Cl 45 SC 45.2.7.6 P120 L1 # 149
 Booth, Brad Intel
 Comment Type E Comment Status A
 Register 7.8 is not about the status of 10GBASE-T, but about the resolution of the local device and link partner.
 Suggested Remedy
 Change heading and supporting text to reference register as "10GBASE-T auto-negotiation resolution status register".
 Response Response Status C
 ACCEPT.

Cl 45 SC 45.2.7.7 P121 L26 # 24
 Thompson, Todd SolarFlare Communica
 Comment Type T Comment Status A
 Test Mode Register 7.9 does not seem to be auto-negotiation related.
 Suggested Remedy
 Place the test mode control register into another MMD (PMA or PCS), or explain the connection to auto-negotiation.
 Response Response Status C
 ACCEPT.
 Coordinate with clause 55.

Cl 45 SC 45.2.7.9 P122 L 123 # 25
Thompson, Todd SolarFlare Communica

Comment Type E Comment Status A

These comments apply to pages 122-123, all sections and tables related to the registers below.

The names are incorrect for registers 7.19-21 and 7.22-24. See previous comment regarding these names.

Suggested Remedy

Change the names as per previous comment.

Response Response Status C

ACCEPT IN PRINCIPLE.

See comment 18.

Cl 55 SC P225 L 1 # 154
Booth, Brad Intel

Comment Type E Comment Status A annex

Annex 55A doesn't follow the correct format.

Suggested Remedy

Update the format to comply with the IEEE style guide.

Response Response Status C

ACCEPT.

Cl 55 SC 55.1 P139 L 12 # 9
Eisler, George Solarflare

Comment Type TR Comment Status A intro-cabling

Recommendation for testing all cabling systems prior to installation of equipment

Suggested Remedy

Add the following text:

"It is highly recommended that any cabling system, newly or previously installed, be measured/tested before the installation of 10GBASE-T equipment by following the guidelines in (proposed) ANSI/TIA/EIA TSB 155."

Response Response Status C

ACCEPT IN PRINCIPLE.

Motion to accept proposed response:

Yes: 25

No: 15

Motion fails

"It is recommended that the guidelines (proposed) in ANSI/TIA TSB 155 and ANSI/TIA 568-B.2-10 be considered before the installation of 10GBASE-T equipment for any cabling system."

Following text is approved by acclamation

"It is recommended that the guidelines (proposed) in ANSI/TIA TSB 155, ANSI/TIA 568-B.2-10 and ISO/IEC 11801 Edition 2.1 be considered before the installation of 10GBASE-T equipment for any cabling system."

Cl 55 SC 55.1 P139 L 35 # 32
Powell, Scott Broadcom

Comment Type TR Comment Status R cablingafext

55m to 100m Class E objective is misleading as to support over the installed base. Alien FEXT measurements indicate that 10Gbps cannot be broadly supported over bundled class E cabling. No data has been presented to indicate what percentage of currently installed bundled class E cabling is capable of supporting 10GBASE-T.

Suggested Remedy

Change "Class E" in objective (f) to "cat 6a" (or the appropriate name for the new cable). Some portion of the installed Class E will meet cat 6a specifications and this portion can carry 10GBASE-T traffic. See presentation for measured AFEXT data.

Response Response Status C

REJECT.

WITHDRAWN.

See response to comment #31

IEEE P802.3an Comments

2/25/2005

Cl 55 SC 55.12 P219 L1 # 51
 Lynskey, Eric UNH-IOL
 Comment Type E Comment Status A pics
 PICS are incomplete, and in different format than other recent clauses.
 Suggested Remedy
 Commenter volunteers to help out with this.
 Response Response Status C
 ACCEPT IN PRINCIPLE.
 PICs will be taken out of current draft and generated from Shalls in other sections

Cl 55 SC 55.2.1.2.1 P146 L31 # 87
 McClellan, Brett Solarflare
 Comment Type T Comment Status A pcspma
 The value link_status = READY is defined but never used.
 Suggested Remedy
 Remove this value.
 Response Response Status C
 ACCEPT IN PRINCIPLE.

Add text to clause 55 saying that for 10GBASE-T, link_status does not take the value "READY"

Cl 55 SC 55.3.10 P164 L58 # 43
 Lynskey, Eric UNH-IOL
 Comment Type E Comment Status A pcspma
 The second figure reference does not contain a figure number.
 Suggested Remedy
 Replace with Figure 55-6.
 Response Response Status C
 ACCEPT.

Cl 55 SC 55.3.10 P164 L59 # 42
 Lynskey, Eric UNH-IOL
 Comment Type E Comment Status A pcspma
 Missing period at end of sentence.
 Suggested Remedy
 Add period.
 Response Response Status C
 ACCEPT.

Cl 55 SC 55.3.11 P165 L6 # 44
 Lynskey, Eric UNH-IOL
 Comment Type E Comment Status A pcspma
 Give full primitive name.
 Suggested Remedy
 Replace UNIDATA.request with PMA_UNITDATA.request.
 Response Response Status C
 ACCEPT.

Cl 55 SC 55.3.12 P165 L8 # 99
 Tellado, Jose Teranetics
 Comment Type T Comment Status A testpattern
 Current Test pattern generator text was copied directly from Clause 49 as a reference, and values were replaced by TBD. The first test should be covered by the PMA electrical tests. The second test is not useful. The third test is intended to measure the link BER, but as described does not include the LDPC error correcting capability
 Suggested Remedy
 Eliminate the placeholder reference test 1 and 2 and update the last test to include the LDPC encoder and LDPC decoder. Moreover, to reduce the number of PRBS generators required, use the 58 bit PCS scrambler PRBS to generate pseudo random binary data.
 Response Response Status C
 ACCEPT.

Cl 55 SC 55.3.12 P165 L8 # 78
 McClellan, Brett Solarflare
 Comment Type T Comment Status D pcpma
 This test pattern section was copied from clause 49, but doesn't add any value for 10GBASE-T. 55.5.3 already specifies Transmitter test modes
 Suggested Remedy
 Remove this section.
 Response Response Status Z
 WITHDRAWN.

Cl 55 SC 55.3.12 P165 L8 # 111
 Seki, Katsutoshi NEC Electronics
 Comment Type T Comment Status A testpattern
 I propose Pseudo random test pattern for BER monitor.
 The proposed pattern is useful to evaluate link including LDPC encoder/decoder, tx and rx AFE and cable.
 Test patterns for transmitter and thier control MDIO register are also defined in 55.5.3.
 Pseudo random test mode should be marged into MDIO register for transmitter test mode.
 Suggested Remedy
 See proposal in seki_1_0205.pdf
 Response Response Status C
 ACCEPT.

Cl 55 SC 55.3.12 P165 L9 # 45
 Lynskey, Eric UNH-IOL
 Comment Type TR Comment Status R testpattern
 Are additional test patterns needed besides the ones defined in 55.5.3? Presently, I am not aware of tests that are being defined that would require these test patterns. Currently, these test patterns are defined to bypass all of the scrambling and coding of the PCS, and connect directly to the PMA. Unless a proposal is brought forward to fully define these patterns, I recommend removing this section.
 Suggested Remedy
 Remove subclause 55.3.12.

Response Response Status C
 REJECT.
 WITHDRAWN.
 Modify subclause 55.3.12 once the test patterns are defined
 defer till test patterns are defined.

Cl 55 SC 55.3.14 P166 L14 # 46
 Lynskey, Eric UNH-IOL
 Comment Type TR Comment Status A pcpma
 The sentence is incomplete. Also, the descrambler being used by the MASTER should be defined.
 Suggested Remedy
 Finish sentence with "...for the SLAVE, and shall produce the same result as the implementation shown in Figure 55-12 for the MASTER." Also, add figure 55-12 to show the MASTER descrambler.
 Response Response Status C
 ACCEPT.

Cl 55 SC 55.3.16 P167 L22 # 47
 Lynskey, Eric UNH-IOL
 Comment Type E Comment Status A pcpma
 Wrong word for Auto-Negotiation. Also occurs on line 30 on this same page and subclause.
 Suggested Remedy
 Replace autoneg with Auto-Negotiation.
 Response Response Status C
 ACCEPT.

Cl 55 SC 55.3.16 P167 L 22 # 100

Tellado, Jose Teranetics

Comment Type T Comment Status A infofield

Repetition period for periodic PMA training sequence mode is TBD. For simplicity it should be a multiple of 256 the repetition period of the pair A sync bit which is aligned with the LDPC codeword boundary

Suggested Remedy

Replace TBDperiodic with $2^{16}=16384$

Response Response Status C

ACCEPT.

Cl 55 SC 55.3.16 P167 L 22 # 50

Lynskey, Eric UNH-IOL

Comment Type TR Comment Status A pcspma

Currently, no bits exist that allow for the resetting of the scrambler state after TBD periods.

Suggested Remedy

Remove this from the Auto-Negotiation process or define these pages.

Response Response Status C

ACCEPT IN PRINCIPLE.

Remove this from the auto-negotiation process; this will be hardcoded

Cl 55 SC 55.3.16 P167 L 29 # 49

Lynskey, Eric UNH-IOL

Comment Type TR Comment Status A pcspma

Currently, there exists no page defined to transmit these 66 bit scrambler state seed values between link partners during Auto-Negotiation.

Suggested Remedy

Remove this from the Auto-Negotiation process or define these pages.

Response Response Status C

ACCEPT IN PRINCIPLE.

Remove this from the auto-negotiation process; the seeds will be hardcoded

Cl 55 SC 55.3.16.2 P169 L 10 # 101

Tellado, Jose Teranetics

Comment Type T Comment Status R infofield

InfoField bits must be defined to indicate current local tx THP/PBO, future local tx THP/PBO desired remote tx THP/PBO, counters, SNR and loc_rcv_status.

Suggested Remedy

'4' bits for each THP index, '3' bits for each PBO index, 12 bits for each counter to indicate multiples of PMA training periods with a max time interval of $2^{14}/800e6*(2^{12}-1) = 335ms$, 5 bits for slicer SNR margin in 0.5dB increments from -5dB to 10.5dB. The number of counters should include remaining periods to Master THP/PBO increase, periods to THP update and periods to transition to data PCS mode

Response Response Status C

REJECT.

WITHDRAWN.

Cl 55 SC 55.3.16.2 P169 L 8 # 80

McClellan, Brett Solarflare

Comment Type T Comment Status A infofield

The description of the info field is incomplete.

Suggested Remedy

Fill in complete description, see proposal.

Response Response Status C

ACCEPT IN PRINCIPLE.

Accept proposal in mclellan_2_205.pdf

Cl 55 SC 55.3.16.3 P169 L 20 # 79

McClellan, Brett Solarflare

Comment Type T Comment Status A pcspma

This section is a remnant from clause 40 and should be eliminated.

Suggested Remedy

Remove the section.

Response Response Status C

ACCEPT.

Cl 55 SC 55.3.16.3 P169 L21 # 102
 Tellado, Jose Teranetics
 Comment Type E Comment Status A pcpma
 This section header was copied from clause 40 and is not needed here. This section is currently empty
 Suggested Remedy
 Remove this header
 Response Response Status C
 ACCEPT.

Cl 55 SC 55.3.18.2 P173 L39 # 103
 Tellado, Jose Teranetics
 Comment Type T Comment Status R Gpcspma
 Error block counter is TBD
 Suggested Remedy
 Replace with 6 bit counter
 Response Response Status C
 REJECT.
 WITHDRAWN.

Cl 55 SC 55.3.18.2 P173 L39 # 81
 McClellan, Brett Solarflare
 Comment Type T Comment Status A pcpma
 Error blocks counter is defined in 45.2.3.12.4 to be 8 bits.
 Suggested Remedy
 Change TBD-bit to 8-bit.
 Response Response Status C
 ACCEPT.

Cl 55 SC 55.3.18.2 P174 L14 # 54
 Lynskey, Eric UNH-IOL
 Comment Type T Comment Status A pcpma
 Relating to Figure 55-13, the 125us_timer is not defined.
 Suggested Remedy
 Need to add subclause prior to the state diagrams.
 55.x.x.x Timers
 State diagram timers follow the conventions of 14.2.3.2.
 125us_timer
 Timer that is triggered every 125us +1%, -25%
 Response Response Status C
 ACCEPT.

Cl 55 SC 55.3.18.2 P174 L3 # 53
 Lynskey, Eric UNH-IOL
 Comment Type T Comment Status A testpattern
 As shown in Figure 55-13, the variable r_test_mode is not defined anyplace.
 Suggested Remedy
 If no PCS test modes are defined, then this variable can be removed from the state diagram. Or, if PCS test modes will be defined, then this variable needs to be defined. Recommend renaming to rx_test_mode and defining as such:
 rx_test_mode: Boolean variable controlling receive channel operating mode. When false, the receive channel operates in normal mode. When true, the receive channel operates in test-pattern mode.
 Response Response Status C
 ACCEPT IN PRINCIPLE.
 remove reference to r_test_mode from the state diagram

Cl 55 SC 55.3.18.2 P174 L4 # 55
 Lynskey, Eric UNH-IOL

Comment Type T Comment Status A pcspma

As shown in Figure 55-13 and Figure 55-15, the device will be stuck in the LFER_MT_INIT or RX_INIT states if !block_lock is true. None of the state diagrams in this clause define how the block_lock variable is set or used. Its definition states that it is set true when the receiver acquires block delineation, but this is never explicitly defined.

Suggested Remedy

Explicitly define the circumstances that set block_lock (and also how it is lost), preferably in a state diagram.

Response Response Status C
 ACCEPT.

Cl 55 SC 55.3.18.2 P176 L2 # 56
 Lynskey, Eric UNH-IOL

Comment Type T Comment Status A pcspma

In Figure 55-15, there is a reset variable that brings you back to the RX_INIT state. It seems that there is no need to have both a pcs_reset (used in Figures 55-14 and 55-13) and the reset (used in Figure 55-15).

Suggested Remedy

Collapse into a single variable and make consistent throughout diagrams.

Response Response Status C
 ACCEPT.

Cl 55 SC 55.3.18.3 P174 L52 # 82
 McClellan, Brett Solarflare

Comment Type T Comment Status A pcspma

The Loopback mode register bit is located in 3.0.14.

Suggested Remedy

Change TBD to 3.0.14.
 Also update 45.2.3.1.2 (see other comment).

Response Response Status C
 ACCEPT IN PRINCIPLE.

Change TBD to 3.0.14.

Cl 55 SC 55.3.2.1 P154 L16 # 108
 Seki, Katsutoshi NEC Electronics

Comment Type T Comment Status A pcspma

PMA_SIGNAL.indicates(SIGNAL_OK)" and "sync_status" are not defined and doesn't match the rest of Clause55

Suggested Remedy

Change "PMA_SIGNAL.indicates(SIGNAL_OK)" to "PMA_RXSTATUS.indicates(OK)"
 Change "sync_status" to "block_lock"

Response Response Status C
 ACCEPT.

Cl 55 SC 55.3.2.2 P154 L16 # 34
 Lynskey, Eric UNH-IOL

Comment Type T Comment Status A pcspma

The PMA_SIGNAL.indicate primitive used here is not defined anyplace.

Suggested Remedy

Change text to "...PMA_RXSTATUS.indicate(loc_rcvr_status). When loc_rcvr_status indicates OK..."

Response Response Status C
 ACCEPT.

Cl 55 SC 55.3.2.2 P154 L17 # 35
 Lynskey, Eric UNH-IOL

Comment Type E Comment Status A pcspma

The PMA_UNITDATA primitive name is chopped off.

Suggested Remedy

Change to "PMA_UNITDATA.indicate primitive".

Response Response Status C
 ACCEPT.

Cl 55 SC 55.3.2.2 P154 L20 # 36
 Lynskey, Eric UNH-IOL

Comment Type T Comment Status A pcspma

The sync_status flag is not defined anywhere.

Suggested Remedy

Define.

Response Response Status C
 ACCEPT.

Cl 55 SC 55.3.4.1 P155 L51 # 109
 Seki, Katsutoshi NEC Electronics

Comment Type T Comment Status A pcspma
 correspondence between DSQ symbols and air A/B/C/D should be defined

Suggested Remedy

Define correspondence as follow
 Pair A : DSQ<4*n>
 Pair B : DSQ<4*n+1>
 Pair C : DSQ<4*n+2>
 Pair D : DSQ<4*n+3>

Response Response Status C
 ACCEPT.

Cl 55 SC 55.3.4.6 P160 L11 # 110
 Seki, Katsutoshi NEC Electronics

Comment Type T Comment Status A pcspma
 The payload of invalid PHY frame and first 65B block of next PHY frame should be forced to error block in order to prevent undetected packet error.

Suggested Remedy

Add the following conditions for invalid block.
 e) The payload of invalid PHY frame and the first block of next PHY frame

Response Response Status C
 ACCEPT.

Cl 55 SC 55.3.6 P162 L53 # 37
 Lynskey, Eric UNH-IOL

Comment Type T Comment Status A pcspma
 No diagram currently exists for SLAVE scrambler.

Suggested Remedy

Add diagram for SLAVE scrambler.

Response Response Status C
 ACCEPT.

Cl 55 SC 55.3.6 P163 L1 # 39
 Lynskey, Eric UNH-IOL

Comment Type T Comment Status A scrambler
 Since this is a self synchronizing scrambler, is it necessary to define initial values?

Suggested Remedy

Replace the first two sentences on this page with "There is no requirement on the initial value of the scrambler."

Response Response Status C
 ACCEPT.

Cl 55 SC 55.3.6 P163 L1 # 98
 Tellado, Jose Teranetics

Comment Type T Comment Status A scrambler
 Master and Slave have different 58bit self sync scramblers. There is no need make sure the initial condition is different

Suggested Remedy

Make initial seeds implementer's choice

Response Response Status C
 ACCEPT.

Cl 55 SC 55.3.6 P163 L1 # 77
 McClellan, Brett Solarflare

Comment Type T Comment Status D scrambler
 The scrambler initial states are TBD.

Suggested Remedy

Replace with:
 "The master and slave scrambler initial values shall be set to ensure sufficient randomness between the remote and local device as well as adjacent devices."

Response Response Status Z
 WITHDRAWN.

Cl 55 SC 55.3.7 P163 L27 # 38
 Lynskey, Eric UNH-IOL

Comment Type T Comment Status A pcspma
 No diagram currently exists for CRC8.

Suggested Remedy

Add diagram.

Response Response Status C
 ACCEPT.

Cl 55 SC 55.3.8 P163 L32 # 41
 Lynskey, Eric UNH-IOL
 Comment Type T Comment Status A scrambler
 It is not clear, from my reading of the text, which bits are to be coded and which are to be uncoded. Figure 55-8 seems to show that 3 bits are uncoded, skip 4, then the next 3... However, this diagram appears to be informational, and not supporting mandatory text describes how this works. Since I am not exactly clear how the bits are split up, I cannot offer a detailed suggested remedy.
 Suggested Remedy
 Define how the scrambled bits enter the LDPC encoder.
 Response Response Status C
 ACCEPT.

Cl 55 SC 55.3.8 P163 L42 # 40
 Lynskey, Eric UNH-IOL
 Comment Type E Comment Status A pcspma
 Wrong word
 Suggested Remedy
 Change Appendix to Annex.
 Response Response Status C
 ACCEPT.

Cl 55 SC 55.3.8.2 P173 L39 # 52
 Lynskey, Eric UNH-IOL
 Comment Type E Comment Status A pcspma
 Since 8 bits are defined for this counter, maybe it should be an 8-bit counter.
 Suggested Remedy
 Change TBD to 8.
 Response Response Status C
 ACCEPT.

Cl 55 SC 55.4.2.2 P178 L48 # 138
 Booth, Brad Intel
 Comment Type T Comment Status A pcspma
 Insert text for transmit fault.
 Suggested Remedy
 Insert the following paragraph:
 The PMA transmit fault function is optional. The faults detected by this function are implementation specific. If the MDIO interface is implemented, then this function shall be mapped to the transmit fault bit as specified in 45.2.1.7.4.
 Response Response Status C
 ACCEPT.

Cl 55 SC 55.4.2.3 P179 L9 # 140
 Booth, Brad Intel
 Comment Type T Comment Status A pcspma
 Interest text for receive fault function.
 Suggested Remedy
 Insert the following paragraph:
 The PMA receive fault function is optional. The PMA receive fault function is the logical OR of link_status = FAIL and any implementation specific fault. If the MDIO interface is implemented, then this function shall contribute to the receive fault bit specified in 45.2.1.7.5.
 Response Response Status C
 ACCEPT.

Cl 55 SC 55.4.2.4 P179 L14 # 105
 Tellado, Jose Teranetics
 Comment Type T Comment Status R startup
 PHY control defines the start-up sequence. Draft 1.3 has a baseline start-up that requires more details from THP and Power Backoff settings and timers for each state.
 Suggested Remedy
 Update PHY control diagram based on tellado_1_0205.pdf
 Response Response Status C
 REJECT.
 WITHDRAWN.
 See response to comment #84

Cl 55 SC 55.4.2.4 P179 L27 # 8
Zimmerman, George Solarflare Communicat

Comment Type TR Comment Status A powerbackoff

Power backoff levels require definition to work with AFEXT and AFEXT scaling.

Suggested Remedy

Define 2 dB steps as in zimmerman_1_0205.pdf, as follows:
Power Backoff Schedule

Length (m)	IL 250 MHz (dB)	Backoff (dB)
0-25	<9.0	14
25-45	9.0-16.2	12
45-55	16.2-19.8	10
55-65	19.8-23.4	8
65-75	23.4-26.9	6
75-85	26.9-30.5	4
85-95	30.5-34.1	2
>95	>34.1	0

Response Response Status C

ACCEPT IN PRINCIPLE.

Motion to accept in principle
Yes: 26
No: 6
Abstain: 9

Change the table in the suggested remedy by adding an extra column as the first column titled "received signal power (dBm) on worst pair"

The Received signal power at MDI is computed assuming nominal TX power.

The length and IL columns are for reference.

An Editorial note will be added that says that the length and IL columns have not been voted into the draft and are only for informational purposes to help people in understanding the table, and will be deleted when the column for received signal power is filled in.

Cl 55 SC 55.4.3.1 P180 L34 # 106
Tellado, Jose Teranetics

Comment Type T Comment Status A thp

THP details are missing. Specifically FIR and IIR coefficients and number of sets

Suggested Remedy

Update THP details with updated THP proposal in tellado_1_0205.pdf

Response Response Status C

ACCEPT IN PRINCIPLE.
Moved by: Jose Tellado
seconded by : Albert Vareljian

Yes: 35
No: 6
Abstain: 13
Motion passes

With the changes listed below to tellado_1_0205.pdf:
item #1 - change 15 to 16
item #4 - Add extra zero (1+betaD) {beta not equal to 1}

Cl 55 SC 55.4.3.1 P180 L40 # 48
Lynskey, Eric UNH-IOL

Comment Type E Comment Status A pcspma

Wrong word for Auto-Negotiation.

Suggested Remedy

Replace with Auto-Negotiation.

Response Response Status C

ACCEPT.

Cl 55 SC 55.4.4.1 P181 L15 # 59
Lynskey, Eric UNH-IOL

Comment Type T Comment Status D pcspma

No state diagram is defined for 10GBASE-T Automatic MDI/MDI-X operation.

Suggested Remedy

Define a new state diagram in Clause 55 or reference the diagram from Clause 40.

Response Response Status Z

WITHDRAWN.

Refer to appropriate diagram in clause 40

Cl 55 SC 55.4.4.1 P181 L 16 # 112
 Seki, Katsutoshi NEC Electronics
 Comment Type T Comment Status A mdi
 Figure of Automatic MDI/MDI-X state machine are missing
 Suggested Remedy
 Refer to Figure 40-17 "1000BASE-T Auto Crossover state diagram", or copy it.
 Response Response Status C
 ACCEPT IN PRINCIPLE.
 Refer to the appropriate section in clause 40 and make appropriate changes to clause 40 to make it applicable to 10GBASE-T

Cl 55 SC 55.4.5.1 P182 L 16 # 104
 Tellado, Jose Teranetics
 Comment Type T Comment Status X Gpowerbackoff
 Power backoff levels have been specified, but the required algorithm to select the appropriate PBO setting as a function a channel characteristics is missing
 Suggested Remedy
 Adopt PBO values from joint Power Back Presentation zimmerman_1_0205.pdf
 Response Response Status Z
 WITHDRAWN.
 See response to comment #8
 Task force to discuss & decide

Cl 55 SC 55.4.5.2 P182 L 35 # 86
 McClellan, Brett Solarflare
 Comment Type T Comment Status D pcspma
 The "A_timer" defines a timer for a state diagram not included in the draft.
 Either the Clause 40 Auto Crossover state diagram (Fig 40-17) needs to be added to clause 55 or this timer should be removed.
 I propose that this text be removed and have 55.4.4 refer to 40.4.4 rather than repeat the same text in clause 55.
 Suggested Remedy
 Delete A_timer text.
 Remove text in 55.4.4, 55.4.4.1 and 55.4.4.2 and instead place a reference that the PHY shall comply with 40.4.4.

Response Response Status Z
 WITHDRAWN.
 Cl 55 SC 55.4.5.2 P182 L 42 # 57
 Lynskey, Eric UNH-IOL
 Comment Type T Comment Status D pcspma
 In case vendors want to support both 1000BASE-T and 10GBASE-T, there is no need to have different values for A_TIMER.
 Suggested Remedy
 This timer shall have a period of 1.3s +/- 25%.
 Response Response Status Z
 WITHDRAWN.
 Will reference the state diagram in clause 40

Cl 55 SC 55.4.5.2 P183 L 7 # 58
 Lynskey, Eric UNH-IOL
 Comment Type T Comment Status D pcspma
 In case vendors want to support both 1000BASE-T and 10GBASE-T, there is no need to have different values for sample_timer.
 Suggested Remedy
 This timer shall have a period of 62 +/- 2ms.
 Response Response Status Z
 WITHDRAWN.
 Replace by reference to appropriate section of clause 40

Cl 55 SC 55.4.6 P185 L # 11
 Thompson, Todd SolarFlare Communica
 Comment Type T Comment Status A mdi
 The auto-crossover state diagram (figure 40-17 in 802.3-2002) should be duplicated here just after the link monitor state diagram, figure 55-19.
 Suggested Remedy
 Include the diagram.
 Response Response Status C
 ACCEPT IN PRINCIPLE.
 Changed comment to apply to 55.4.6 and not clause 40
 See response to comment # 112

Cl 55 SC 55.4.6 P185 L1 # 85
 McClellan, Brett Solarflare
 Comment Type T Comment Status A startup
 The Link Monitor state diagram does not match the text on page 182 In 52 (loc_rcvr_status vs. PCS_status)
 Furthermore, this state diagram allows only 558 ms for startup (see page 36: link_fail_inhibit_timer).
 I propose a new state diagram that corrects these issues.
 See presentation.
 Suggested Remedy
 Update state diagram per the presentation.
 Response Response Status C
 ACCEPT IN PRINCIPLE.
 Change the text for the link_fail_inhibit_timer definition in clause 28 to make the link timer choose a different value for 10GBASE-T
 Adopt the diagram in mcclellan_2_0205.pdf (proposal for fig 55-19) page 8 to be consistent with this change.
 Change link_status=fail

Cl 55 SC 55.4.6.1 P184 L1 # 84
 McClellan, Brett Solarflare
 Comment Type T Comment Status A startup
 The PHY Control state diagram has missing transitions, unused timers, missing timer start and endless loops.
 Additionally, the maxwait and minwait timers on page 182 are TBD.
 See presentation for proposed state diagram and timers.
 Suggested Remedy
 Update section with proposed state diagram and timers.
 Response Response Status C
 ACCEPT IN PRINCIPLE.
 Update section with proposed state diagrams and timers in mcclellan_2_0205.pdf

Cl 55 SC 55.4.6.2 P185 L31 # 107
 Tellado, Jose Teranetics
 Comment Type E Comment Status A pcspma
 Figure reference to autoneg ref is not confirmed
 Suggested Remedy
 Eric L. should confirm
 Response Response Status C
 ACCEPT IN PRINCIPLE.

Cl 55 SC 55.5.1 P187 L10 # 88
 Tellado, Jose Teranetics
 Comment Type TR Comment Status A pmaisolation
 Review and approve text relating to isolation requirement. This text is similar to clause 40 text with references updated
 Suggested Remedy
 Review and approve text relating to isolation requirement. This text is similar to clause 40 text with references updated
 Response Response Status C
 ACCEPT.

Cl 55 SC 55.5.10 P195 L34 # 97
 Tellado, Jose Teranetics
 Comment Type T Comment Status A pmacommon
 Complete and approve 55.5.10
 Suggested Remedy
 On line 35, replace TBD with '2' and f1 with 80MHz
 Response Response Status C
 ACCEPT.

Cl 55 SC 55.5.2 P187 L # 117
 Chris, Pagnanelli Solarflare Communicat
 Comment Type TR Comment Status A pmajitter
 The test channel specified in paragraph 55.5.2 (see Figure 55-20 and Table 55-2) is not required for measuring Master/Slave timing jitter and distortion. Master and Slave timing jitter and distortion can be measured using the simplified procedures given in recent contributions addressing the subject of timing jitter and distortion. These simplified procedures only require that connections be made to resistive terminations or Master/Slave terminals using short lengths of UTP cabling.
 Suggested Remedy
 Delete paragraph 55.5.2.
 Response Response Status C
 ACCEPT.

Cl 55 SC 55.5.2 P188 L10 # 93
 Tellado, Jose Teranetics
 Comment Type T Comment Status A pmajitter
 Test channel for transmitter jitter test is not approved
 Suggested Remedy
 Remove table
 Response Response Status C
 ACCEPT.

Cl 55 SC 55.5.3 P188 L35 # 64
 Lynskey, Eric UNH-IOL
 Comment Type E Comment Status A management
 In Table 55-3, the test mode bits can be defined. This also applies to the TBD in line 28 on this same page.
 Suggested Remedy
 For line 28: "...shall be enabled by setting bits 7.9.15:13...)
 For Table, replace bit 3 with 7.9.13; bit 2 with 7.9.14; and bit one with 7.9.15.
 Response Response Status C
 ACCEPT.

Cl 55 SC 55.5.3 P189 L # 114
 Chris, Pagnanelli Solarflare Communicat
 Comment Type TR Comment Status A pmalinearity
 Need to specify frequencies for single-tone and two-tone tests. Frequencies are currently TBD.
 Suggested Remedy
 Replace TBDs with test frequencies proposed in contribution titled "Proposal for Transmitter Linearity Specification". Test frequencies below 40 MHz are not required to ensure linearity requirements are met.
 Response Response Status C
 ACCEPT.
 Task force to decide & discuss;
 single tone: 800/1024*{53, 101 & 167}
 to be reviewed together with comment # 90
 Proposal for two tone frequencies:
 800/1024*{ [179,181], [277,281], [397,401]}
 matches proposal in comment #91

Cl 55 SC 55.5.3 P189 L1 # 89
 Tellado, Jose Teranetics
 Comment Type T Comment Status R pmavoltage
 TBDnumbsym is unspecified. Setting this to 10 corresponds to an output frequency of 40MHz
 Suggested Remedy
 Replace TBDnumbsym by 10
 Response Response Status Z
 WITHDRAWN.

Cl 55 SC 55.5.3 P189 L19 # 90
 Tellado, Jose Teranetics
 Comment Type T Comment Status R pmalinearity
 Specify frequencies for single tone nonlinearity test
 Suggested Remedy
 Frequencies shall be 800/1024*[13 23 53 101 167]
 Response Response Status C
 REJECT.
 Motion to accept the proposed response:
 This would add two additional frequencies 800/1024[13, 23] to the set listed below
 Motion to accept:
 Yes:15
 No: 11
 Abstains: ~30
 Motion fails
 Task force to discuss & decide; see comment #114 Which recommends [53, 101, 167]

Cl 55 SC 55.5.3 P189 L21 # 91
 Tellado, Jose Teranetics
 Comment Type T Comment Status A pmalinearity
 Frequency pairs for two tone tests are not specified
 Suggested Remedy
 The following pairs shall be used for the two tone test:
 800/1024*{ [179,181], [277,281], [397,401]}
 Response Response Status C
 ACCEPT.
 Motion to accept the resolution:
 Yes: 29
 No: 1
 Abstaining: ~30
 Motion passes
 final decision should be input to comment #64

Cl 55 SC 55.5.3 P192 L # 116
 Chris, Pagnanelli Solarflare Communicat
 Comment Type TR Comment Status X pmajitter
 Test set up (Figure 55-24) for transmitter timing jitter measurement is not suitable and lacks sufficient detail. Figure does not show connection between Master and Slave necessary for loop timing and does not show means of isolating Master and Slave output signals.
 Suggested Remedy
 Replace Figure 55-24 with figure provided in contribution titled "Proposal for Transmitter Timing Jitter Specification."
 Response Response Status Z
 WITHDRAWN.
 Task force to review & decide
 Review together with comment #92

Cl 55 SC 55.5.3 P192 L10 # 92
 Tellado, Jose Teranetics
 Comment Type T Comment Status X pmajitter
 Test setup for tx jitter measurements is not approved
 Suggested Remedy
 Replace figure 55-24 with figure in presentation tellado_1_0205.pdf
 Response Response Status Z
 WITHDRAWN.
 Task force to discuss & decide. Review together with comment #116

Cl 55 SC 55.5.4 P192 L42 # 6
 Zimmerman, George Solarflare Communicat

Comment Type T Comment Status A pmavoltage

Peak to peak voltage spec is redundant and unnecessary now that transmit power and PSD mask defined. Keeping this redundant spec also comes with the cost of an additional test mode.

Suggested Remedy

Delete peak-to-peak voltage specification.

Response Response Status C

ACCEPT.

Motion to accept the suggested remedy:

Yes: 31

No: 9

Abstain:

Motion passes

Task force to discuss & decide

Review with comment # 94

Cl 55 SC 55.5.4 P192 L42 # 94
 Tellado, Jose Teranetics

Comment Type T Comment Status X pmavoltage

Transmit voltage is provided as a range (2V,2.5V); recommend a specific voltage

Suggested Remedy

2V +- 15%

Response Response Status Z

WITHDRAWN.

Cl 55 SC 55.5.5 P103 L18 # 119
 Halder, Bijit Plato Networks

Comment Type T Comment Status A pmalinearity

The distortion specifications should be calculated so that there is no significant loss of receiver SNR, say no more than a small fraction of a dB.

Suggested Remedy

Given the reduction in average PSANEXT and new PSAFEXT model, we recommend the following values for the 4 TBDs in equation 55-7:

1. X_nonlin =52
2. X_nslope =20
3. f1= 50 MHz
4. f0 = 1MHz

This setting is to be applied for full power operation, that is with 0dB power back off. The specified values results in 0.4dB loss in SNR for 100m Class E cable.

Response Response Status C

ACCEPT.

Motion to reconsider

Yes: 32

No: 4

Motion to accept the suggested remedy;

Yes: 29

No: 4

Abstain:

Motion passes

Task force to discuss & decide; review together with comment # 113

Straw poll on accepting 52dB SFDR

Yes: 20

Straw poll on 48dB SNDR

Yes: 11

Motion to accept the suggested remedy:

Yes: 20

No: 11

Abstain:

Motion fails

Cl 55 SC 55.5.5 P192 L17 # 7
 Zimmerman, George Solarflare Communicat

Comment Type E Comment Status A pmalinearity

TX nonlinearity specification is overly complex. Specification requires synchronous maintenance of frequency breakpoints, slope and floor. Simplify.

Suggested Remedy

Replace equation 55-7 with form as in pagnanelli_4_0105.pdf, slide 1.

Response Response Status C

ACCEPT IN PRINCIPLE.

Motion to accept the proposed response:

Yes: 23

No: 4

abstain:

Replace equation with equation on slide 4 of pagnanelli_1_0205.pdf with the left side changed to

"SNDR or SFDR"

Cl 55 SC 55.5.5 P193 L # 113
 Chris, Pagnanelli Solarflare Communicat

Comment Type TR Comment Status R pmalinearity

Transmitter linearity specification based on SFDR and IMD does not properly address distortion due to jitter and noise, and TBDs make specification incomplete: lower end of range (fo) and breakpoint for frequency roll off (f1) are not specified; distortion upper limit (Xnonlin) and distortion slope (NLslope) are not specified.

Suggested Remedy

Specify transmitter linearity in terms of frequency-dependent signal-to-noise-plus distortion ratio over 5 MHz to 400 MHz band, using single equation with appropriate lower limit and slope. Tabulate specifications for clarity. Replace existing transmitter linearity specification text with new text as proposed in contribution titled "Proposal for Transmitter Linearity Specification."

Response Response Status C

REJECT.

See response to comment # 119

Motion to accept the suggested remedy

Yes: 20

No: 11

Abstain:

Motion fails:

Task force to discuss & decide; review with comment #119

Cl 55 SC 55.5.5 P193 L18 # 95
 Tellado, Jose Teranetics

Comment Type T Comment Status X pmalinearity

Lower end of frequency range for nonlinearity measurement, Fo is not specified.

Suggested Remedy

Replace Fo with 5 MHz

Response Response Status Z

WITHDRAWN.

Task force to discuss & decide. Review together with comment #113 &119

CI 55 SC 55.5.5 P193 L37 # 96
 Tellado, Jose Teranetics
 Comment Type T Comment Status A pmalinearity
 The draft calls out recommended nonlinearity specs, which are unspecified
 Suggested Remedy
 Set recommended values as Xnonlin=60, Xnlslope=0 or eliminate reference to recommended values.
 Response Response Status C
 ACCEPT IN PRINCIPLE.
 Eliminate reference to recommended values
 See response to comment #5

CI 55 SC 55.5.5 P193 L37 # 5
 Zimmerman, George Solarflare Communicat
 Comment Type T Comment Status A pmalinearity
 "Recommended" linearity specification is TBD. Values are internal to vendors' designs and are not required for interoperability by definition. Debate on simply the required (normative) specifications has highlighted significant differences in vendors' linearity requirements. Hence a general "recommendation" is unlikely to represent common design assumptions.
 Suggested Remedy
 Delete reference to "recommended" linearity specification. Provide only normative specification required for interoperability.
 Response Response Status C
 ACCEPT.
 Task force to discuss & decide; review with comment # 96 converted from "E" to "T"

CI 55 SC 55.5.6 P193 L # 115
 Chris, Pagnanelli Solarflare Communicat
 Comment Type TR Comment Status A pmajitter
 Transmitter timing jitter specification is incomplete. Text is needed. Specification is needed for maximum jitter introduced by Slave loop timing function.
 Suggested Remedy
 Adopt specification proposed in contribution titled "Proposal for Transmitter Timing Jitter Specification"
 Response Response Status C
 ACCEPT IN PRINCIPLE.
 Motion to accept the proposed response
 Passes by acclamation
 Task force to discuss & decide.

Text as per slide 8 of pagnanelli_2_0205.pdf
 figure as per slide 9 of pagnanelli_2_0205.pdf
 Jitter specification must apply to master as well as to slave in loop timed mode

CI 55 SC 55.5.7 P194 L17 # 118
 Halder, Bijit Plato Networks
 Comment Type T Comment Status D
 The definition of lower PSD mask starts from 5MHz. This allows transformer 3dB high pass cut off to be at least 5 MHz. Transformer with such high 3dB cutoff will produce excessive droop. The range of transformer allowed by the current specifications is too loose and pose significant problem for interoperability.
 Suggested Remedy
 Reduce the start frequency for lower mask to no larger than 500KHz.
 Response Response Status Z
 WITHDRAWN.

No change is necessary in the PSD mask because the specific problem highlighted, which is droop at the transformer output, is covered by the droop test in "55.5.4.2 Maximum output droop" of draft 1.3

Cl 55 SC 55.6 P197 L35 # 151
 Booth, Brad Intel
 Comment Type T Comment Status A management
 Table 55-4 references Clause 22 register set.
 Suggested Remedy
 Delete Clause 22 register references from the table.
 Response Response Status C
 ACCEPT IN PRINCIPLE.
 Appropriate additional references will be added based on resolution of other comments.

Cl 55 SC 55.6 P198 L # 20
 Thompson, Todd SolarFlare Communica
 Comment Type E Comment Status A management
 Table 55-4 is missing several registers defined in 45.2.7.
 Suggested Remedy
 Add the missing registers into Table 55-4.
 For example, 7.2, 7.3, 7.5, 7.6.
 Response Response Status C
 ACCEPT IN PRINCIPLE.
 Necessary register references will be added. See also comment 27.

Cl 55 SC 55.6.1 P197 L21 # 60
 Lynskey, Eric UNH-IOL
 Comment Type E Comment Status A management
 Another purpose of Auto-Negotiation for 10GBASE-T is to negotiate loop timing.
 Suggested Remedy
 Add item mentioning loop timing to list.
 Response Response Status C
 ACCEPT.

Cl 55 SC 55.6.1 P197 L24 # 61
 Lynskey, Eric UNH-IOL
 Comment Type T Comment Status A Gmanagement
 With the addition of loop timing negotiation, this statement is not correct.
 Suggested Remedy
 Recommend removing these 3 sentences.
 Response Response Status C
 ACCEPT.
 Would like some discussion on this.

Cl 55 SC 55.6.1.1 P197 L36 # 26
 Thompson, Todd SolarFlare Communica
 Comment Type E Comment Status A management
 Table 55-4 Register 0, Type should be R/W.
 Suggested Remedy
 Control register 0 is a writeable register. Change it to R/W.
 Response Response Status C
 ACCEPT IN PRINCIPLE.
 The correction will be made, or this row may be removed pending resolution of comment 151.

Cl 55 SC 55.6.1.1 P198 L1 # 27
 Thompson, Todd SolarFlare Communica
 Comment Type E Comment Status A management
 Table 55-4 is inconsistent with Clause 45.2.7.
 Suggested Remedy
 Make the register numbering, Names, and descriptions match 45.2.7. There are mistakes in the Description/paragraph numbers, numbering, some AN registers are missing that are defined in 45.2.7, and the name of AN LP XNP NP TX register should be AN LP XNP NP ability register.
 Response Response Status C
 ACCEPT IN PRINCIPLE.
 See also comment 20.

Cl 55 SC 55.6.1.2 P198 L45 # 152
Booth, Brad Intel

Comment Type T Comment Status A management

Table 55-5 is a bit confusing.

Suggested Remedy

Change table headings to be Bit, Name and Description.

Under base page: D15 is next page as per 28.2.1.2.5, D14 is acknowledge as per 28.2.1.2.4, D13 is remote fault as per 28.2.1.2.3, D12 is extended next page as per a new reference based on a Clause 28 comment, D11:D5 is the technology ability field as per 28.2.1.2.2, and D4:D0 is the selector field as per 28.2.1.2.1.

Under extended next page: M10:M0 is the message code as per Annex 28C, T is toggle as per 28.2.3.4.7, Ack2 is acknowledge 2 as per 28.2.3.4.6, MP is message page as per 28.2.3.4.5, Ack is acknowledge as per 28.2.3.4.4 and NP is next page as per 28.2.3.4.3.

The unformatted portion looks okay other than specifying the register, give the subclause reference.

Response Response Status C

ACCEPT.

Cl 55 SC 55.6.1.3 P199 L55 # 62
Lynskey, Eric UNH-IOL

Comment Type T Comment Status A management

Referring readers to Annex 40C may not be the best thing to do. This is an informative Annex written to talk about sending normal next pages following a 1000BASE-T page negotiation. Going back to this Annex could lead to reader confusion. I think there are two ways to proceed with this.

Suggested Remedy

Option A: We could write a new informative Annex that shows several examples of auto-negotiation (extended next page negotiating with regular next page; sending extra extended next pages; ...)

Option B: We can simply remove most of this text, as Clause 28 does define how to send additional pages.

Response Response Status C

ACCEPT IN PRINCIPLE.

Remove most of this text, as Clause 28 does define how to send additional pages.

Consider writing an informative Annex later.

Cl 55 SC 55.6.2 P200 L1 # 28
Thompson, Todd SolarFlare Communica

Comment Type E Comment Status A management

Comment applies to 55.6.2 in its entirety.

There are a number of TBD's that should now be resolved.

Suggested Remedy

Remove TBD's and replace with appropriate register/bit definitions.

Response Response Status C

ACCEPT IN PRINCIPLE.

TBDs that can be replaced, will be replaced.

Cl 55 SC 55.6.2 P200 L20 # 63
Lynskey, Eric UNH-IOL

Comment Type E Comment Status A management

Since only a single page is being sent, it is not correct to refer to "unformatted page 1".

Suggested Remedy

Replace with "10GBASE-T Technology Message Code".

Response Response Status C

ACCEPT.

IEEE P802.3an Comments

2/25/2005

Cl 55 SC 55.6.2 P200 L5 # 29
 Thompson, Todd SolarFlare Communica

Comment Type E Comment Status A management

There are several TBDs in this section.

On page 201 line 42 there is a reference to 10.15 which should be changed to refer to the new fault bit.

Suggested Remedy

Replace the TBD's below with the text indicated:

Page	Line	New Value
200	5	Table 55-6
200	6	Table 55-5
200	28	Table 55-6
201	42	Is 10.15 should be 7.8.15
201	46	7.7.15
201	47	7.7.14
201	51	7.8.15
201	57	55.4.2.4
202	1	7.7.15
202	9	First occurence 7.8.15 second 7.8.14
202	13	55.2.4
202	16	7.8.15

Response Response Status C

ACCEPT IN PRINCIPLE.
 Also see comments 65-73.

Cl 55 SC 55.6.2 P201 L42 # 65
 Lynskey, Eric UNH-IOL

Comment Type E Comment Status A management

Wrong bit reference.

Suggested Remedy

Change 10.15 to 7.8.15.

Response Response Status C

ACCEPT.

Cl 55 SC 55.6.2 P201 L46 # 66
 Lynskey, Eric UNH-IOL

Comment Type E Comment Status A management

Replace TBD.

Suggested Remedy

Replace TBD with 7.7.15.

Response Response Status C

ACCEPT.

Cl 55 SC 55.6.2 P201 L47 # 67
 Lynskey, Eric UNH-IOL

Comment Type E Comment Status A management

Replace TBD.

Suggested Remedy

Replace TBD with 55.4.2.4.

Response Response Status C

ACCEPT.

Cl 55 SC 55.6.2 P201 L51 # 68
 Lynskey, Eric UNH-IOL

Comment Type E Comment Status A management

Replace TBD.

Suggested Remedy

Replace TBD with 7.8.15.

Response Response Status C

ACCEPT.

Cl 55 SC 55.6.2 P201 L57 # 69
 Lynskey, Eric UNH-IOL

Comment Type E Comment Status A management

Replace TBD.

Suggested Remedy

Replace TBD with 7.8.14.

Response Response Status C

ACCEPT.

IEEE P802.3an Comments

2/25/2005

Cl 55 SC 55.6.2 P202 L1 # 70
 Lynskey, Eric UNH-IOL
 Comment Type E Comment Status A management
 Replace TBD.
 Suggested Remedy
 Replace TBD with 7.7.15.
 Response Response Status C
 ACCEPT.

Cl 55 SC 55.6.2 P202 L10 # 71
 Lynskey, Eric UNH-IOL
 Comment Type E Comment Status A management
 Replace TBDs.
 Suggested Remedy
 Replace first TBD on this line with 7.8.15, and replace second TBD with 7.8.14.
 Response Response Status C
 ACCEPT.

Cl 55 SC 55.6.2 P202 L13 # 72
 Lynskey, Eric UNH-IOL
 Comment Type E Comment Status A management
 Replace TBD.
 Suggested Remedy
 Replace TBD with 55.2.4.
 Response Response Status C
 ACCEPT.

Cl 55 SC 55.6.2 P202 L17 # 73
 Lynskey, Eric UNH-IOL
 Comment Type E Comment Status A management
 Replace TBD.
 Suggested Remedy
 Replace TBD with 7.8.15.
 Response Response Status C
 ACCEPT.

Cl 55 SC 55.6.2 P202 L23 # 74
 Lynskey, Eric UNH-IOL
 Comment Type E Comment Status A management
 Change note to include 1000BASE-T.
 Suggested Remedy
 Modify to "...if 10GBASE-T or 1000BASE-T is selected..."
 Response Response Status C
 ACCEPT.

Cl 55 SC 55.7 P203 L9 # 10
 Eisler, George Solarflare
 Comment Type TR Comment Status A intro-cabling
 Recommendation for testing all cable installations
 Suggested Remedy
 Add the following paragraph:
 "It is highly recommended that any cabling system, newly or previously installed, be measured/tested before the installation of 10GBASE-T equipment by following the guidelines in (proposed) ANSI/TIA/EIA TSB 155."
 Response Response Status C
 ACCEPT IN PRINCIPLE.
 See response to comment #9

Cl 55 SC 55.7.2 P203 L37 # 1
 Alan Flatman LAN Technologies
 Comment Type TR Comment Status A cabling
 We need to reference the ISO/IEC specification for installed cabling.
 Suggested Remedy
 Insert the following editor's note at the end of this subclause:
 "Editor's Note: ISO/IEC TR-24750: Assessment of installed Class E and Class F cabling beyond their maximum specified frequencies, should be available before 802.3an is approved. In which case, it will replace the above reference to TIA/EIA TSB-155."
 Response Response Status C
 ACCEPT.
 to add applicable ISO references when available. Agree to add proposed editors note with following modification to replace the words "will replace" with "may replace".
 "Proposed Editor's Note: ISO/IEC TR-24750: Assessment of installed Class E and Class F cabling beyond their maximum specified frequencies, should be available before 802.3an is approved. In which case, 802.3an will reference both and may replace the above reference to TIA/EIA TSB-155."

Cl 55 SC 55.7.3.1.2 P208 L56 # 153
 Booth, Brad Intel
 Comment Type T Comment Status A cabling
 Note c is not applicable as Class F IL does not need to be extrapolated to 500 MHz.
 Suggested Remedy
 Remove note c.
 Response Response Status C
 ACCEPT IN PRINCIPLE.
 Provide reference to Class F in note c.
 "The PS ANEXT for a Class F channel assumes the maximum insertion loss of a Class F channel specified in ISO/IEC 11801."

Cl 55 SC 55.7.3.1.2 P209 L4 # 2
 Alan Flatman LAN Technologies
 Comment Type TR Comment Status A cabling
 We need to reference the ISO/IEC specification for installed cabling.
 Suggested Remedy
 Insert the following editor's note at the end of this subclause:
 "Editor's Note: ISO/IEC TR-24750: Assessment of installed Class E and Class F cabling beyond their maximum specified frequencies, should be available before 802.3an is approved. In which case, it will replace the above reference to TIA/EIA TSB-155."
 Response Response Status C
 ACCEPT IN PRINCIPLE.
 to add applicable ISO references when available. A single instance of the editor's note (resolution to comment #1 Alan Flatman) is sufficient
 See response to comment #1 on wording

Cl 55 SC 55.7.3.2.2 P210 L45 # 31
 Powell, Scott Broadcom
 Comment Type TR Comment Status A cablingafext
 The PS AELFEXT constant for 55m Category 6 cabling is substantially better than measured data previously reported to the task force (vanderlaan_1_0303.pdf).
 Suggested Remedy
 See presentation for independent confirmation of measured data. Suggest operation over Cat 6 be optional, rather than required, for 10GBASE-T compliance. Cat 6 specifications could be included as informative.
 Response Response Status C
 ACCEPT IN PRINCIPLE.
 Modify bullet f in objectives section of Draft 1.3 to read:
 Define a single 10Gb/s PHY that would support links of at least 55 m to 100 m on four pair balanced copper cabling as specified in 55.7

Cl 55 SC 55.7.3.2.2 P210 L53 # 3
 Alan Flatman LAN Technologies
 Comment Type TR Comment Status A cabling
 We need to reference the ISO/IEC specification for installed cabling.
 Suggested Remedy
 Insert the following editor's note at the end of this subclause:
 "Editor's Note: ISO/IEC TR-24750: Assessment of installed Class E and Class F cabling beyond their maximum specified frequencies, should be available before 802.3an is approved. In which case, it will replace the above reference to TIA/EIA TSB-155."
 Response Response Status C
 ACCEPT IN PRINCIPLE.
 to add applicable ISO references when available. A single instance of the editor's note (resolution to comment#1 Alan Flatman) is sufficient.
 See response to comment #1

Cl 55 SC 55.7.3.2.2 P211 L1 # 30
 Powell, Scott Broadcom
 Comment Type TR Comment Status A cablingafext
 Comment implies (to me, anyway) that the currently envisioned system with identical AFEXT on each wire pair will perform the same as the same system with unequal AFEXT on each wire pair - as long as the "identical" AFEXT is equal to the average of the "unequal" AFEXT. No presentation has been made to support the accuracy of this implied claim.
 Suggested Remedy
 Remove this claim. A more accurate statement is that simulations should assume one worst case wire pair with AFEXT that is 4dB higher than the average AFEXT over all 4 pairs. See presentation with simulations comparing performance under unequal SNR/pair situation to equal SNR/pair situation.
 Response Response Status C
 ACCEPT IN PRINCIPLE.
 based on response to comment #120
 Remove the note based on the averages being added to the column in table 55-8

CI 55 SC 55.7.3.2.2 P211 L2 # 120

Halder, Bijit Plato Networks

Comment Type T Comment Status A cablingafext

The Note states for calculating the system margin we must use an average improvement of 4dB over the limit line for PSAFEXT. Since the cable are certified based on the limit line and system are designed with the 4dB margin, it is not clear how the standard guarantees the 4dB average improvement. In other words, in the event the 4dB gain due to averaging is not seen in practice, how does the standard guarantees operation of 10G system given the slim system margin even with the 4dB improvement.

Similar comment applies to 3.5 dB improvement for PSANEXT number in Section 55.7.3.1.2, page 209, line 11.

Suggested Remedy

Either change the limit line to match the improvement, or require the cable to qualify a test for average PSAFEXT lines in addition to the worst case limit line.

Response Response Status C

ACCEPT IN PRINCIPLE.

In table 55-8, add a column for the average value which will be 4 dB higher (based on averaging over pairs)

In table 55-7, add a column for the average value which will be 1dB higher based on averaging over pairs.

In regard to cabling specifications, we need to broaden the investigation of the alien crosstalk assumptions by requesting the assistance of the TR42 and ISO cabling groups and on the basis of their response determine the best course of action for the level of detail we need for 10GBASE-T.

CI 55 SC 55.8.3.1 P214 L37 # 4

Cobb, Terry Systimax

Comment Type T Comment Status A mdi

Return loss requirements and measurements do not use a reference that has a tolerance.

Suggested Remedy

Remove the +/- TBD % and replace "an impedance" with "a nominal differential characteristic impedance"

Response Response Status C

ACCEPT.