

Comments received

IEEE P802.3az D3.0 Energy Efficient Ethernet comments

Cl 00 SC 0 P L # 327
 Dambrosia, John Force10 Networks
 Comment Type ER Comment Status X
 Bookmark for 40.5.1 is under 40.4
 SuggestedRemedy
 Correct bookmark for 40.5.1 so it is not under 40.4
 Proposed Response Response Status O

Cl 00 SC 0 P262 L20 # 341
 Dambrosia, John Force10 Networks
 Comment Type TR Comment Status X
 there are no PIC statements for all corresponding SHALL statements in Clause 78
 SuggestedRemedy
 create PICs section and add pics for all appropriate SHALLs
 Proposed Response Response Status O

Cl 00 SC 0 P L # 328
 Dambrosia, John Force10 Networks
 Comment Type ER Comment Status X
 Bookmark for 40.6.1.x.x is under 40.5.1.2
 SuggestedRemedy
 Correct bookmarks
 Proposed Response Response Status O

Cl 00 SC 0 P4 L22 # 66
 Mclendon, Jonathon Spirent Communicatio
 Comment Type E Comment Status X
 TLV is misspelled
 SuggestedRemedy
 Proposed Response Response Status O

Cl 00 SC 0 P15 L # 22
 Byrd, William PRIVACOM VENTUR
 Comment Type G Comment Status X
 The page numbers do not agree with the Table of Contents. For example: Scope is shown in the table of contents as Page 16. It is actually shown on page 15 of the document. The authors are looking at the computer programs page numbering instead of the actual page numbers they have on the bottom of each page.
 SuggestedRemedy
 Re-page number document to match the table of contents.
 Proposed Response Response Status O

Cl 00 SC 0 P4 L30 # 104
 Law, David 3Com
 Comment Type E Comment Status X
 'IEEE Std 802.3-2008(TM)/Cor 1-200X' should read 'IEEE Std 802.3-2008(TM)/Cor 1-2009' now that the corrigendum has been published.
 SuggestedRemedy
 See comment.
 Proposed Response Response Status O

Comments received

IEEE P802.3az D3.0 Energy Efficient Ethernet comments

CI 00 SC 00 P12 L42 # 304
 Dambrosia, John Force10 Networks
 Comment Type ER Comment Status X TOC
 ToC is incorrect. 55.2.2.3.1, 55.2.2.9, 55.2.2.10, 55.2.2.11, 55.3.2.2, and 55.3.2.3 are put under 55.1.4
 SuggestedRemedy
 Correct headings so that ToC is correct
 Proposed Response Response Status O

CI 14 SC 14.10.4.7.1 P22 L7 # 311
 Dambrosia, John Force10 Networks
 Comment Type TR Comment Status X
 Stated parameter for LS4 is for a type 10BASE-T MAU but this does not agree with the text in 14.4.2.1 which states for a 10BASE-T MAU that is not a 10BASE-Te MAU.
 SuggestedRemedy
 Change parameter for LS4 to agree with text in 14.4.2.1
 Proposed Response Response Status O

CI 00 SC 00 P12 L43 # 306
 Dambrosia, John Force10 Networks
 Comment Type ER Comment Status X TOC
 ToC for Clause 55 is totally wrong, and needs to be completely reviewed. Subclauses are not under appropriate subclauses
 SuggestedRemedy
 do total review of all headings and relations of subclause headings, so that it is correct.
 Proposed Response Response Status O

CI 22 SC 22.2.1 P23 L10 # 67
 Mclendon, Jonathon Spirent Communicatio
 Comment Type G Comment Status X
 The document has many phrases of the form "If the EEE capability is supported, ..."
 Although I do not see a way to administratively disable EEE, I suspect that network designers will demand such a capability. If so, then nearly all of the clauses of the above form will need to be changed to ...
 SuggestedRemedy
 "If the EEE capability is supported and administratively enabled, ..." or "If the EEE capability is enabled, ..."
 Proposed Response Response Status O

CI 00 SC 00 P12 L44 # 305
 Dambrosia, John Force10 Networks
 Comment Type ER Comment Status X TOC
 ToC is incorrect for Clause 55. 55.3.5.2.3, 55.3.5.2.4, 55.3.5.2.5 are shown under 55.3.4a.3. 55.10, and 55.12 is not in the ToC
 SuggestedRemedy
 Correct headings so that ToC is correct
 Proposed Response Response Status O

CI 22 SC 22.6a.2.2 P29 L31 # 24
 Turner, Edward J Gnodal Ltd
 Comment Type ER Comment Status X
 The phrase 'time expired since' is confusing.
 SuggestedRemedy
 Change to 'time since'
 Proposed Response Response Status O

Comments received

IEEE P802.3az D3.0 Energy Efficient Ethernet comments

Cl 22 SC 22.6a.3.1 P30 L 8 # 122
 Healey, Adam LSI Corporation
 Comment Type E Comment Status X
 Extraneous period in the transition from LPI_DEASSERTED to LPI_ASSERTED.
 SuggestedRemedy
 Change to "LPI_REQUEST = ASSERT"
 Proposed Response Response Status O

Cl 24 SC 24.2.2 P35 L 13 # 26
 Turner, Edward J Gnodal Ltd
 Comment Type E Comment Status X
 Missing something between 'period' and 'upon'.
 SuggestedRemedy
 Add 'begun'
 Proposed Response Response Status O

Cl 22 SC 22.7.3.2a P31 L 24 # 312
 Dambrosia, John Force10 Networks
 Comment Type TR Comment Status X
 Feature for L2 reads - RX_CLK max high/low time transitioning to START_RX_SLEEP state, but there is no mention of START_RX_SLEEP state in identified subclause 22.2.2.2.
 SuggestedRemedy
 Change parameter for L2 to agree with text in 22.2.2.2
 Proposed Response Response Status O

Cl 24 SC 24.2.2 P35 L 13 # 25
 Turner, Edward J Gnodal Ltd
 Comment Type E Comment Status X
 Missing determiner before 'PCS'
 SuggestedRemedy
 Add 'the' before 'PCS'.
 Proposed Response Response Status O

Cl 22 SC 22.7.3.2a P31 L 30 # 313
 Dambrosia, John Force10 Networks
 Comment Type TR Comment Status X
 no SHALLS for L4 and L6
 SuggestedRemedy
 add appropriate SHALL statements
 Proposed Response Response Status O

Cl 24 SC 24.2.2 P35 L 14 # 27
 Turner, Edward J Gnodal Ltd
 Comment Type E Comment Status X
 Confusing wording in 'and generate proper commands sending through MII as described in 22.2.2.7'
 SuggestedRemedy
 Change to 'and generate commands through the MII as described in 22.2.2.7'
 Proposed Response Response Status O

Cl 22 SC 22.7.3.2a P31 L 33 # 314
 Dambrosia, John Force10 Networks
 Comment Type TR Comment Status X
 L5 parameter should refer to RX-CLK restarting which is what the shall statement refers to
 SuggestedRemedy
 change I5 parameter text to Restat of RX_CLK before LPI deasserted
 Proposed Response Response Status O

Cl 24 SC 24.2.2 P35 L 15 # 28
 Turner, Edward J Gnodal Ltd
 Comment Type E Comment Status X
 Missing determiners.
 SuggestedRemedy
 Add 'the' before 'Link Monitor' and PMA.
 Proposed Response Response Status O

Comments received

IEEE P802.3az D3.0 Energy Efficient Ethernet comments

CI 24 SC 24.2.3.4 P37 L 38 # 37
 Turner, Edward J Gnodal Ltd
 Comment Type E Comment Status X
 Definition of timer period.
 SuggestedRemedy
 Change 'to' to 'and'.
 Proposed Response Response Status O

CI 24 SC 24.2.3.4 P37 L 50 # 41
 Turner, Edward J Gnodal Ltd
 Comment Type E Comment Status X
 Missing determiners.
 SuggestedRemedy
 Add 'the' before 'PHY' and 'the' before 'Quiet'.
 Proposed Response Response Status O

CI 24 SC 24.2.3.4 P37 L 41 # 38
 Turner, Edward J Gnodal Ltd
 Comment Type E Comment Status X
 Missing determiner.
 SuggestedRemedy
 Add 'the' before 'Idle state'
 Proposed Response Response Status O

CI 24 SC 24.2.3.4 P37 L 53 # 42
 Turner, Edward J Gnodal Ltd
 Comment Type E Comment Status X
 Definition of timer period.
 SuggestedRemedy
 Change 'to' to 'and'.
 Proposed Response Response Status O

CI 24 SC 24.2.3.4 P37 L 43 # 39
 Turner, Edward J Gnodal Ltd
 Comment Type E Comment Status X
 Missing determiners.
 SuggestedRemedy
 Add 'the' before 'Sleep state' and 'the' before 'Quiet state'
 Proposed Response Response Status O

CI 24 SC 24.2.3.4 P38 L 15 # 48
 Turner, Edward J Gnodal Ltd
 Comment Type E Comment Status X
 Missing determiner.
 SuggestedRemedy
 Add 'the' before 'PHY'.
 Proposed Response Response Status O

CI 24 SC 24.2.3.4 P37 L 45 # 40
 Turner, Edward J Gnodal Ltd
 Comment Type E Comment Status X
 Definition of timer period.
 SuggestedRemedy
 Change 'to' to 'and'.
 Proposed Response Response Status O

CI 24 SC 24.2.3.4 P38 L 16 # 49
 Turner, Edward J Gnodal Ltd
 Comment Type TR Comment Status X
 The statement '.. before it must wake for refresh signal.' is not a clear description of how the state machine uses the timer.
 SuggestedRemedy
 Change to '.. before it must wake to signal refresh'
 Proposed Response Response Status O

Comments received

IEEE P802.3az D3.0 Energy Efficient Ethernet comments

CI 24 SC 24.2.3.4 P38 L17 # 50
 Turner, Edward J Gnodal Ltd
 Comment Type E Comment Status X
 Definition of timer period.
 SuggestedRemedy
 Change 'to' to 'and'.
 Proposed Response Response Status O

CI 24 SC 24.2.3.4 P38 L4 # 44
 Turner, Edward J Gnodal Ltd
 Comment Type E Comment Status X
 Definition of timer period.
 SuggestedRemedy
 Change 'to' to 'and'.
 Proposed Response Response Status O

CI 24 SC 24.2.3.4 P38 L20 # 51
 Turner, Edward J Gnodal Ltd
 Comment Type E Comment Status X
 Missing determiners.
 SuggestedRemedy
 Add 'the' before 'PHY', add 'the' before 'Sleep state', and add 'the' before 'Quiet state'.
 Proposed Response Response Status O

CI 24 SC 24.2.3.4 P38 L7 # 45
 Turner, Edward J Gnodal Ltd
 Comment Type E Comment Status X
 Missing determiner.
 SuggestedRemedy
 Add 'the' before 'Quiet'.
 Proposed Response Response Status O

CI 24 SC 24.2.3.4 P38 L21 # 52
 Turner, Edward J Gnodal Ltd
 Comment Type E Comment Status X
 Definition of timer period.
 SuggestedRemedy
 Change 'to' to 'and'.
 Proposed Response Response Status O

CI 24 SC 24.2.3.4 P38 L8 # 46
 Turner, Edward J Gnodal Ltd
 Comment Type E Comment Status X
 Missing determiners.
 SuggestedRemedy
 Add 'the' before 'PHY' and 'the' before 'Refresh'.
 Proposed Response Response Status O

CI 24 SC 24.2.3.4 P38 L3 # 43
 Turner, Edward J Gnodal Ltd
 Comment Type E Comment Status X
 Missing determiners.
 SuggestedRemedy
 Add 'the' before 'PHY' and 'the' before 'Sleep'.
 Proposed Response Response Status O

CI 24 SC 24.2.3.4 P38 L9 # 47
 Turner, Edward J Gnodal Ltd
 Comment Type E Comment Status X
 Missing determiner.
 SuggestedRemedy
 Add 'the' before 'Wake'.
 Proposed Response Response Status O

Comments received

IEEE P802.3az D3.0 Energy Efficient Ethernet comments

Cl 24 SC 24.3.2.3 P43 L22 # 53
 Turner, Edward J Gnodal Ltd
 Comment Type E Comment Status X
 Missing determiners throughout this paragraph.
 SuggestedRemedy
 Add 'the' before the following: 'PMA_RXLPI.request' (line 22), 'PMA' (line 22), 'Far-End' (line 23), 'PMA_LPILINKFAIL.request' (line 24), 'PMA' (line 25).
 Proposed Response Response Status O

Cl 24 SC 24.4.1.4 P46 L32 # 57
 Turner, Edward J Gnodal Ltd
 Comment Type E Comment Status X
 Missing determiner.
 SuggestedRemedy
 Add 'the' before 'Quiet'.
 Proposed Response Response Status O

Cl 24 SC 24.3.3.2 P43 L37 # 54
 Turner, Edward J Gnodal Ltd
 Comment Type E Comment Status X
 Missing determiner.
 SuggestedRemedy
 Add 'the' before 'PCS'.
 Proposed Response Response Status O

Cl 24 SC 24.4.1.5.1 P47 L6 # 58
 Turner, Edward J Gnodal Ltd
 Comment Type E Comment Status X
 Missing determiner.
 SuggestedRemedy
 Add 'the' before 'Quiet'.
 Proposed Response Response Status O

Cl 24 SC 24.3.3.2 P43 L45 # 55
 Turner, Edward J Gnodal Ltd
 Comment Type E Comment Status X
 Missing determiner.
 SuggestedRemedy
 Add 'the' before 'PCS'.
 Proposed Response Response Status O

Cl 25 SC 25.4a.1.1.2 P52 L11 # 59
 Turner, Edward J Gnodal Ltd
 Comment Type E Comment Status X
 Lower case NRZ.
 SuggestedRemedy
 Change to capitals.
 Proposed Response Response Status O

Cl 24 SC 24.4.1.4 P46 L31 # 56
 Turner, Edward J Gnodal Ltd
 Comment Type E Comment Status X
 Misplaced 'the'.
 SuggestedRemedy
 Change 'Process of PCS only if the EEE' to 'Process of the PCS only if EEE'
 Proposed Response Response Status O

Cl 25 SC 25.4a.2.1.2 P53 L37 # 60
 Turner, Edward J Gnodal Ltd
 Comment Type E Comment Status X
 Lower case NRZ.
 SuggestedRemedy
 Change to capitals.
 Proposed Response Response Status O

Comments received

IEEE P802.3az D3.0 Energy Efficient Ethernet comments

Cl 35 **SC 35.3a.2.2** **P71** **L 34** # **64**
 Turner, Edward J Gnodal Ltd
Comment Type **E** **Comment Status** **X**
 Unnecessary word.
SuggestedRemedy
 Delete 'expired'.
Proposed Response **Response Status** **O**

Cl 35 **SC 35.5.3.3a** **P73** **L 7** # **318**
 Dambrosia, John Force10 Networks
Comment Type **TR** **Comment Status** **X**
 Referenced subclause is incorrect, and there is no corresponding SHALL statement
SuggestedRemedy
 change subclause to 35.2.2.6. change feature to assertion of LPI in RX direction. Change value to as defined in Table 35-2. Add corresponding SHALL statement
Proposed Response **Response Status** **O**

Cl 35 **SC 35.5.3.3a** **P73** **L 10** # **320**
 Dambrosia, John Force10 Networks
Comment Type **TR** **Comment Status** **X**
 no shall statements for L3.
SuggestedRemedy
 add appropriate SHALL statement
Proposed Response **Response Status** **O**

Cl 40 **SC 40.12.5** **P113** **L 35** # **72**
 Turner, Edward J Gnodal Ltd
Comment Type **E** **Comment Status** **X**
 Missing space after 'exceed'.
SuggestedRemedy
 Insert space after 'exceed'.
Proposed Response **Response Status** **O**

Cl 35 **SC 35.5.3.3a** **P73** **L 5** # **319**
 Dambrosia, John Force10 Networks
Comment Type **ER** **Comment Status** **X**
 Feature includes value statement
SuggestedRemedy
 Change feature to assertion of LPI in TX Direction change value to "as defined in Table 35-1.
Proposed Response **Response Status** **O**

Cl 40 **SC 40.12.6** **P113** **L 18** # **322**
 Dambrosia, John Force10 Networks
Comment Type **TR** **Comment Status** **X**
 There is no variable defined for PMF28
SuggestedRemedy
 add a variable definition. In value field Pperate should be changed to Operate
Proposed Response **Response Status** **O**

Cl 40 **SC 40.12.6** **P114** **L 20** # **324**
 Dambrosia, John Force10 Networks
Comment Type **E** **Comment Status** **X**
 Text discusses state diagram Fig. 40-15b
SuggestedRemedy
 Add reference in Value column to Fig 40-15b
Proposed Response **Response Status** **O**

Comments received

IEEE P802.3az D3.0 Energy Efficient Ethernet comments

CI 40 SC 40.3.3.1 P98 L48 # 321
 Dambrosia, John Force10 Networks
 Comment Type TR Comment Status X
 no shall or PIC for lpi_mode
 SuggestedRemedy
 add shall statement and appropriate PIC
 Proposed Response Response Status O

CI 40 SC 40.4.2.4 P102 L35 # 70
 Turner, Edward J Gnodal Ltd
 Comment Type E Comment Status X
 Missing words before 'transmitter circuits'.
 SuggestedRemedy
 Insert 'that the' before 'transmitter circuits'.
 Proposed Response Response Status O

CI 40 SC 40.4.2.4 P102 L11 # 65
 Turner, Edward J Gnodal Ltd
 Comment Type E Comment Status X
 Missing an 'a'.
 SuggestedRemedy
 Add 'a' before 'period'.
 Proposed Response Response Status O

CI 40 SC 40.4.2.4 P102 L45 # 71
 Turner, Edward J Gnodal Ltd
 Comment Type E Comment Status X
 Missing 'a' before 'time'.
 SuggestedRemedy
 Insert 'a' before 'time'.
 Proposed Response Response Status O

CI 40 SC 40.4.2.4 P102 L15 # 68
 Turner, Edward J Gnodal Ltd
 Comment Type ER Comment Status X
 Missing underscore within 'lpi_posupdate timer'
 SuggestedRemedy
 Insert underscore before 'timer'.
 Proposed Response Response Status O

CI 40 SC 40.4.5.1 P103 L42 # 323
 Dambrosia, John Force10 Networks
 Comment Type TR Comment Status X
 shouldn't there be a SHALL and associated PIC
 SuggestedRemedy
 add appropriate SHALL and PIC
 Proposed Response Response Status O

CI 40 SC 40.4.2.4 P102 L27 # 69
 Turner, Edward J Gnodal Ltd
 Comment Type E Comment Status X
 Missing 'the' before 'period'.
 SuggestedRemedy
 Insert 'the' before 'period'.
 Proposed Response Response Status O

CI 40 SC 40.5.1 P108 L35 # 325
 Dambrosia, John Force10 Networks
 Comment Type TR Comment Status X
 Add SHALL statement and PIC
 SuggestedRemedy
 Add "SHALL" statement and PIC
 Proposed Response Response Status O

Comments received

IEEE P802.3az D3.0 Energy Efficient Ethernet comments

Cl 40 SC 40.6.1.2.7 P110 L42 # 326
 Dambrosia, John Force10 Networks
 Comment Type **TR** Comment Status **X**
 The following statement is made - When the PHY supports the optional EEE capability, it is required to transmit Idle symbols while in the WAKE state (see the PHY Control state diagram, Figure 40--15b). If it is required there should be a corresponding SHALL statement
 SuggestedRemedy
 add corresponding shall statement
 Proposed Response Response Status **O**

Cl 45 SC 45 P115 L48 # 367
 Bennett, Michael Lawrence Berkeley Na
 Comment Type **T** Comment Status **X**
 Submitted on behalf of Michael Grimwood. The fast retrain status and control register (1.147) is in the PMA and should be reset by PMA reset, not PCS reset.
 SuggestedRemedy
 Change: "These bits shall be reset to all zeros when read or upon execution of the PCS reset." To: "These bits shall be reset to all zeros when read or upon execution of the PMA reset."
 Proposed Response Response Status **O**

Cl 45 SC 45 P116 L4 # 368
 Bennett, Michael Lawrence Berkeley Na
 Comment Type **T** Comment Status **X**
 Submitted on behalf of Michael Grimwood. The fast retrain status and control register (1.147) is in the PMA and should be reset by PMA reset, not PCS reset.
 SuggestedRemedy
 Change: "These bits shall be reset to all zeros when read or upon execution of the PCS reset." To: "These bits shall be reset to all zeros when read or upon execution of the PMA reset."
 Proposed Response Response Status **O**

Cl 45 SC 45 P189 L45 # 207
 Brown, Matthew Applied Micro (AMCC)
 Comment Type **GR** Comment Status **X**
 EEE terminology.
 SuggestedRemedy
 Change "LPI-capable PHYs" to "EEE-capable PHYs".
 Proposed Response Response Status **O**

Cl 45 SC 45.2.1.76a P115 L39 # 149
 Parnaby, Gavin Solarflare Communicat
 Comment Type **E** Comment Status **X**
 Further to my earlier comment on 45.2.1.65a.1 and 45.2.1.76a.2, 45.2.1.67a.3 is also out of order.
 The three subclauses should be listed in the following order:
 LP fast retrain count (1.147.15:11)
 LD fast retrain count (1.147.10:6)
 Fast retrain enable (1.147.0)
 SuggestedRemedy
 As comment
 Proposed Response Response Status **O**

Cl 45 SC 45.2.1.76a P115 L46 # 147
 Parnaby, Gavin Solarflare Communicat
 Comment Type **E** Comment Status **X**
 The description for bits 10 to 6 should come before the description for bit 0.
 SuggestedRemedy
 Move LD fast retrain count (1.147.10:6) description before the Fast retrain enable (1.147.0) description
 Proposed Response Response Status **O**

Comments received

IEEE P802.3az D3.0 Energy Efficient Ethernet comments

CI 45 SC 45.2.1.76a.1 P115 L42 # 148
 Parnaby, Gavin Solarflare Communicat

Comment Type **TR** Comment Status **X**
 Add text stating
 'This bit shall be set high by the PHY upon successful negotiation of fast retrain ability with the link partner. See 45.2.7.10.5a'

SuggestedRemedy
 As comment

Proposed Response Response Status **O**

CI 45 SC 45.2.3.1.3a P117 L25 # 155
 Brown, Matthew Applied Micro (AMCC)

Comment Type **GR** Comment Status **X**
 Several references in Clause 45 to 46.3.2.4a, which should be 46.3.2.4.

SuggestedRemedy
 Change all instances of 46.3.2.4a to 46.3.2.4.

Proposed Response Response Status **O**

CI 45 SC 45.2.3.2.2a P118 L29 # 156
 Brown, Matthew Applied Micro (AMCC)

Comment Type **GR** Comment Status **X**
 3.1.6 the xMII is driven by the RS layer not the MAC.

SuggestedRemedy
 Change definition as follows... Change "the MAC may stop" to "the RS may stop". Change "the MAC does not support" to "the PHY does not support".

Proposed Response Response Status **O**

CI 45 SC 45.2.4.1.3a P121 L26 # 157
 Brown, Matthew Applied Micro (AMCC)

Comment Type **GR** Comment Status **X**
 I assume that this is the PHY XS transmit clock (TX_CLK) which attaches to the PCS receive clock (RX_CLK). Make this clear.

SuggestedRemedy
 Change "the PHY XS may stop the transmit xMII clock" to "the PHY XS may stop the PHY_XS transmit (or PCS receive) xMII clock from the attached PCS". Change "stop the receive clock" to "stop the PHY_XS transmit clock". Need statement in Clause 48.

Proposed Response Response Status **O**

CI 45 SC 45.2.4.1.3a P121 L26 # 106
 Horner, Rita Avago Technologies

Comment Type **TR** Comment Status **X**
 The text is a bit confusing. "If bit 4.0.10 is set to 1 then the PHY XS may stop the transmit xMII clock while it is signaling LPI otherwise it shall keep the clock "active. If the PHY XS does not support EEE capability or is not able to stop the receive clock then this bit has no effect". Is this to stop TX_CLK or RX_CLK @ XGMII interface?

SuggestedRemedy
 Change the text for better clarity.

Proposed Response Response Status **O**

CI 45 SC 45.2.4.1.3a P121 L28 # 73
 Turner, Edward J Gnodal Ltd

Comment Type **T** Comment Status **X**
 Incorrect reference to 'receive clock'. The PHY XS only has the capability to stop the transmit clock (as discussed in the previous sentence of this sub clause).

SuggestedRemedy
 Change 'receive' to 'transmit'.

Proposed Response Response Status **O**

Comments received

IEEE P802.3az D3.0 Energy Efficient Ethernet comments

Cl 45 SC 45.2.4.1.3b P121 L32 # 107
 Horner, Rita Avago Technologies

Comment Type TR Comment Status X

In the statement: "If bit 4.0.9 is set to 1 then the PHY XS may stop signaling on the XAUI in the receive direction during LPI . . . ", is the bit 4.0.9 to stop XAUI signaling going out from the PHY? How would this correlates to XAMII clock? Disabling the interface clock does not gurantee that the low power mode is entered for all applications.

SuggestedRemedy

Suggest to remove the correlation between clock disable and data disable during LPI mode.

Proposed Response Response Status O

Cl 45 SC 45.2.4.1.3b P121 L34 # 74
 Turner, Edward J Gnodal Ltd

Comment Type T Comment Status X

Incorrect reference to 'receive clock'. This register bit controls stopping XAUI signalling, rather than clocks.

SuggestedRemedy

Change 'receive clock' to 'receive path XAUI signals'.

Proposed Response Response Status O

Cl 45 SC 45.2.4.2.2a P122 L39 # 158
 Brown, Matthew Applied Micro (AMCC)

Comment Type GR Comment Status X

I assume that this is the PHY XS transmit clock (TX_CLK) which attaches to the PCS transmit clock (TX_CLK). Make this clear.

SuggestedRemedy

Change "the PHY XS is capable to allow the attached PHY to stop the recive xMII clock" to "the PHY XS is capable of stopping the PHY_XS transmit (or PCS receive) xMII clock".
 Change "stop the receive clock" to "stop the PHY_XS transmit clock". Need statement in Clause 48.

Proposed Response Response Status O

Cl 45 SC 45.2.4.2.2a P122 L39 # 108
 Horner, Rita Avago Technologies

Comment Type TR Comment Status X

If bit 4.1.6 is set to 0, bit 4.0.10 and 4.0.9 have no effect?

SuggestedRemedy

This needs to be clearly stated if that is what is inteneded to be.

Proposed Response Response Status O

Cl 45 SC 45.2.4.2.2a P122 L39 # 75
 Turner, Edward J Gnodal Ltd

Comment Type TR Comment Status X

The first sentence is unclear, and the second sentence related to PHY behavior which is not controlled through the MMD.

SuggestedRemedy

Delete second sentence completely and change first sentence to : 'If bit 4.1.6 is set to a one then the PHY XS is indicating that the attached PHY is permitted to stop the receive xMII clock whilst it is signalling LPI. If the bit is set to a zero then the PHY XS is indicating that the attached PHY is not permitted to stop the receive xMII clock whilst it is signalling LPI.' You may wish to consider an additional sentence: 'It is the responsibility of the management entity to ensure that an attached PHY device does not have it's stop clock enable bit (3.0.10) set if this bit is cleared'.

Proposed Response Response Status O

Cl 45 SC 45.2.4.2.2a P126 L39 # 160
 Brown, Matthew Applied Micro (AMCC)

Comment Type GR Comment Status X

The DTE XS transmit xMII clock is driven by the RS not the MAC.

SuggestedRemedy

Change "the DTE XS is capable to allow the MAC to stop the transmit xMII clock" to "the DTE XS is capable of stopping the RS transmit xMII clock". Change "stop the transmit clock" to "stop the DTE XS transmit clock". Need statement in Clause 48.

Proposed Response Response Status O

Comments received

IEEE P802.3az D3.0 Energy Efficient Ethernet comments

Cl 45 SC 45.2.4.8a.2 P123 L 28 # 76
 Turner, Edward J Gnodal Ltd

Comment Type TR Comment Status X

The first sentence is unclear, and the second sentence discusses a receive clock.

SuggestedRemedy

Delete second sentence completely and change first sentence to : 'If bit 4.20.0 is set to a one then the PHY XS is indicating that the attached DTE XS is permitted to stop transmitting XAUI signals during LPI. If the bit is set to a zero then the PHY XS is indicating that the attached DTE XS is not permitted to stop transmitting XAUI signals during LPI.' You may wish to consider an additional sentence: 'It is the responsibility of the management entity to ensure that an attached DTE XS device does not have it's XAUI stop enable bit (5.0.9) set if this bit is cleared'

Proposed Response Response Status O

Cl 45 SC 45.2.5.1.3a P125 L 26 # 159
 Brown, Matthew Applied Micro (AMCC)

Comment Type GR Comment Status X

I assume that this is the DTE XS transmit clock (TX_CLK) which attaches to the RS transmit clock (RX_CLK). Make this clear.

SuggestedRemedy

Change "the DTE XS may stop the transmit xMII clock" to "the DTE XS may stop the DTE transmit (or RS transmit) xMII clock". Change "stop the receive clock" to "stop the DTE XS transmit clock". Need statement in Clause 48.

Proposed Response Response Status O

Cl 45 SC 45.2.5.1.3b P125 L 34 # 77
 Turner, Edward J Gnodal Ltd

Comment Type T Comment Status X

Incorrect reference to 'receive clock'.

SuggestedRemedy

Change 'receive clock' to transmit path XAUI signals'.

Proposed Response Response Status O

Cl 45 SC 45.2.5.2 P126 L 43 # 161
 Brown, Matthew Applied Micro (AMCC)

Comment Type GR Comment Status X

Table 45-125 refers to incorrect MDIO register 4.1; should be 5.1.

SuggestedRemedy

Change 4.1 to 5.1.

Proposed Response Response Status O

Cl 45 SC 45.2.5.2 P126 L 5 # 78
 Turner, Edward J Gnodal Ltd

Comment Type TR Comment Status X

Incorrect table name and register numbers.

SuggestedRemedy

Change title to 'DTE XS status 1 register bit definitions' and change all register bit numbers from 4.1 to 5.1.

Proposed Response Response Status O

Cl 45 SC 45.2.5.2 P126 L 5 # 139
 Parnaby, Gavin Solarflare Communicat

Comment Type T Comment Status X

I think the bits referred to in the first column of 45-125 are incorrect. 4.X should be 5.X

SuggestedRemedy

Change the first column of the table to refer to 5.X

Proposed Response Response Status O

Comments received

IEEE P802.3az D3.0 Energy Efficient Ethernet comments

CI 45 SC 45.2.5.2.2a P126 L39 # 79
 Turner, Edward J Gnodal Ltd

Comment Type TR Comment Status X

The first sentence is unclear, and the second sentence discusses MAC functionality.

SuggestedRemedy

Delete the second sentence and change the first sentence to : 'If bit 5.1.6 is set to a one then the DTE XS is indicating that the attached MAC is permitted to stop the transmit xMII clock whilst it is signalling LPI. If the bit is set to a zero then the DTE XS is indicating that the attached MAC is not permitted to stop the transmit xMII clock whilst it is signalling LPI.'. You may wish to consider an additional sentence: 'It is the responsibility of the management entity to ensure that the attached RS does not stop the transmit xMII clock if this bit is cleared'.

Proposed Response Response Status O

CI 45 SC 45.2.5.8a.2 P127 L28 # 80
 Turner, Edward J Gnodal Ltd

Comment Type TR Comment Status X

The first sentence is unclear, and the second sentence discusses a receive clock.

SuggestedRemedy

Delete second sentence completely, and change the first sentence to : 'If bit 5.20.0 is set to a one then the DTE XS is indicating that the attached PHY XS is permitted to stop the XAUI signalling in the receive direction during LPI. If the bit is set to a zero then the DTE XS is indicating that the attached PHY XS is not permitted to stop the XAUI signalling on the receive direction during LPI.' You may wish to consider an additional sentence: 'It is the responsibility of the management entity to ensure that an attached PHY XS device does not have it's XAUI stop enable bit (4.0.9) set if this bit is cleared.'

Proposed Response Response Status O

CI 45 SC 45.2.7.14 P132 L23 # 162
 Brown, Matthew Applied Micro (AMCC)

Comment Type GR Comment Status X

Sub-clauses for each of the link partner ability bits are missing.

SuggestedRemedy

Add sub-clauses for each of the link partner ability bits listed in table 44-157b. Suggest copying entire contents of 45.2.7.13 and restating as link partner abilities, etc.

Proposed Response Response Status O

CI 46 SC 46.1.7 P135 L24 # 163
 Brown, Matthew Applied Micro (AMCC)

Comment Type GR Comment Status X

Receipt of local fault also causes override of transmitted signal. Receipt of local or remote fault should also result in asserting carrier_sense.

SuggestedRemedy

Append to last sentence of paragraph "or link is in a fault state."

Proposed Response Response Status O

CI 46 SC 46.1.7.3 P136 L49 # 164
 Brown, Matthew Applied Micro (AMCC)

Comment Type TR Comment Status X

Sub-clause 46.1.7.3 (from 802.3-2008) says that PLS_CARRIER is not used. 46.1.7.3 must be modified to reflect the usage of PLS_CARRIER.indication in LPI mode and link fault states on EEE capable PHYs.

SuggestedRemedy

Insert instruction to add the following text to 46.1.7.3. "On PHYs that support EEE, CARRIER_STATUS will be set to defer MAC data when transmit LPI is active or if the link is in a fault state. CARRIER_STATUS is set in response to LPI_INDICATION as shown in Figure 46-10a. Also, if LOCAL FAULT or REMOTE FAULT is detected on RXD/RXC CARRIER_STATUS is set to CARRIER_ON."

Proposed Response Response Status O

CI 46 SC 46.3.1.5 P136 L25 # 81
 Turner, Edward J Gnodal Ltd

Comment Type TR Comment Status X

The part of the sentence '..only if the stop clock capable bit is asserted (see 45.2.3.2.2a) only reference a PCS MMD. The device attached to the RS could be a DTE XS.

SuggestedRemedy

Change the end of the sentence to '.. only if the clock stop capable bit of the attached sublayer is asserted (see 45.2.3.2.2a and 45.2.5.2.2a).

Proposed Response Response Status O

Comments received

IEEE P802.3az D3.0 Energy Efficient Ethernet comments

Cl 46 SC 46.3.1.5 P136 L25 # 105
 Turner, Edward J Gnodal Ltd
 Comment Type **TR** Comment Status **X**
 Additional qualification required regarding the halting of the TX_CLK (this is an extension of the comment regarding an additional reference to the DTE XS stop clock capable bit being required in this sub clause).
 SuggestedRemedy
 Add the sentence: 'It is the responsibility of the management entity to ensure that the RS does not halt the TX_CLK if the attached device does not have its stop clock capable bit set'.
 Proposed Response Response Status **O**

Cl 46 SC 46.3.1.5 P136 L25 # 166
 Brown, Matthew Applied Micro (AMCC)
 Comment Type **ER** Comment Status **X**
 One if is enough.
 SuggestedRemedy
 Change "if and only if" to "if".
 Proposed Response Response Status **O**

Cl 46 SC 46.3.1.5 P136 L26 # 165
 Brown, Matthew Applied Micro (AMCC)
 Comment Type **GR** Comment Status **X**
 Need to specify when the clock must be turned back on.
 SuggestedRemedy
 Add sentence: "If TX_CLK is halted during LPI mode, TX_CLK must be restarted when LPI mode ends."
 Proposed Response Response Status **O**

Cl 46 SC 46.3.1.6 P137 L25 # 169
 Brown, Matthew Applied Micro (AMCC)
 Comment Type **ER** Comment Status **X**
 One if is enough.
 SuggestedRemedy
 Change "if and only if" to "if".
 Proposed Response Response Status **O**

Cl 46 SC 46.3.1.6 P137 L26 # 168
 Brown, Matthew Applied Micro (AMCC)
 Comment Type **GR** Comment Status **X**
 Need to specify when the clock must be turned back on.
 SuggestedRemedy
 Add sentence: "If RX_CLK is halted during LPI mode, RX_CLK must be restarted when LPI mode ends."
 Proposed Response Response Status **O**

Cl 46 SC 46.3.2.4 P136 L21 # 167
 Brown, Matthew Applied Micro (AMCC)
 Comment Type **ER** Comment Status **X**
 Change IDLE to match value in table.
 SuggestedRemedy
 Change "IDLE" to "Idle".
 Proposed Response Response Status **O**

Comments received

IEEE P802.3az D3.0 Energy Efficient Ethernet comments

Cl 46 SC 46.3.2.4 P137 L 23 # 82
 Turner, Edward J Gnodal Ltd
 Comment Type T Comment Status X
 This sentence only discusses a PHY, but it could be a DTE XS that is stopping the RX_CLK.
 SuggestedRemedy
 Change start of sentence to 'The PHY or DTE XS may halt RX_CLK ..' and change the end to '(see 45.2.3.1.3a and 45.2.5.1.3a).
 Proposed Response Response Status O

Cl 46 SC 46.3a P138 L 42 # 170
 Brown, Matthew Applied Micro (AMCC)
 Comment Type TR Comment Status X
 CRS is not a XGMII signal. Instead map LP_IDLE.request, local fault, and remote fault to PLS_CARRIER.indication.
 SuggestedRemedy
 Replace sentence with "PLS_CARRIER.indication(CARRIER_STATUS) will be set to CARRIER_ON when the link is in LPI mode or if the link is in a fault state. See sub-clause 47.1.7.3."
 Proposed Response Response Status O

Cl 46 SC 46.3.4 P137 L 52 # 150
 Parnaby, Gavin Solarflare Communicat
 Comment Type TR Comment Status X
 We made a modification on line 50, but the same modification needs to be made on line 52.
 SuggestedRemedy
 Change 'the RS stops sending MAC data' to 'the RS stops sending MAC data or LPI'
 Proposed Response Response Status O

Cl 46 SC 46.3a.2.1 P139 L 36 # 83
 Turner, Edward J Gnodal Ltd
 Comment Type E Comment Status X
 Unnecessary 'expired'.
 SuggestedRemedy
 Delete 'expired'.
 Proposed Response Response Status O

Cl 46 SC 46.3a P138 L 13 # 171
 Brown, Matthew Applied Micro (AMCC)
 Comment Type GR Comment Status X
 XGMII not MII
 SuggestedRemedy
 Change "MII" to "XGMII"
 Proposed Response Response Status O

Cl 46 SC 46.3a.2.1 P139 L 43 # 84
 Turner, Edward J Gnodal Ltd
 Comment Type T Comment Status X
 Unclear when tw_timer_done is asserted.
 SuggestedRemedy
 Change to 'The signal tw_timer_done is asserted when tw_timer reaches its terminal count.'
 Proposed Response Response Status O

Comments received

IEEE P802.3az D3.0 Energy Efficient Ethernet comments

Cl 46 SC 46.3a.3.1 P140 L 29 # 172
 Brown, Matthew Applied Micro (AMCC)
 Comment Type GR Comment Status X
 XGMII not MII
 SuggestedRemedy
 Change "MII" to "XGMII". Two instances.
 Proposed Response Response Status O

Cl 46 SC 46.5.3.3a P141 L 25 # 329
 Dambrosia, John Force10 Networks
 Comment Type TR Comment Status X
 No corresponding SHALL statements for L1, L2, L3
 SuggestedRemedy
 add corresponding shall statement
 Proposed Response Response Status O

Cl 46 SC 46.5.3.3a P141 L 25 # 330
 Dambrosia, John Force10 Networks
 Comment Type ER Comment Status X
 redundant item numbers
 SuggestedRemedy
 renumber item number's accordingly
 Proposed Response Response Status O

Cl 47 SC 47.1 P142 L 13 # 173
 Brown, Matthew Applied Micro (AMCC)
 Comment Type GR Comment Status X
 Clarification of the direction of receive/send would be helpful especially to separate sending from/to XGMII.
 SuggestedRemedy
 Change "When LPI is received" to "When LPI is received on the transmit XGMII ". Also, on line 19, change "asserted at the XGMII" to "asserted at the transmit XGMII".
 Proposed Response Response Status O

Cl 47 SC 47.6.4.4 P144 L 30 # 331
 Dambrosia, John Force10 Networks
 Comment Type TR Comment Status X
 no corresponding SHALL statements for LP-04
 SuggestedRemedy
 add corresponding shall statement
 Proposed Response Response Status O

Cl 48 SC 48.1.5 P145 L 13 # 174
 Brown, Matthew Applied Micro (AMCC)
 Comment Type GR Comment Status X
 A statement is required to to make it clear what is meant by EEE is supported. As I understand it, EEE is supported only if both local device and link partner advertise the EEE capability. This means that it is implemented on both devices and both devices have been programmed via ability bits to support EEE.
 SuggestedRemedy
 Add the following sentence... "EEE is supported only if during auto-negotiation both the local device and link partner advertise the EEE capability. If EEE is not supported all EEE functionality, if implemented, will be disabled. For instance, LPI control characters will not be sent and LPI control characters received will be treated as errors."
 Proposed Response Response Status O

Comments received

IEEE P802.3az D3.0 Energy Efficient Ethernet comments

CI 48 SC 48.2.4.2 P148 L19 # 175
Brown, Matthew Applied Micro (AMCC)

Comment Type TR Comment Status X

||LPIDLE|| and ||I|| are mutually exclusive, ||LPIDLE|| is not a special case of ||I||.

SuggestedRemedy

Change the first sentence as follows: ||LPIDLE|| is coded in the same manner as ||I|| except that the /20.5/ code group replaces one code group in each ||K|| and ||R|| (not ||A||) column with a random uniform distribution across the lanes.

Proposed Response Response Status O

CI 48 SC 48.2.6.1.5a P150 L46 # 176
Brown, Matthew Applied Micro (AMCC)

Comment Type GR Comment Status X

The terminal count description wording makes it unclear of the intent and is written differently than for other timers.

SuggestedRemedy

Change "shall not exceed the maximum value of TWR" with "shall be set to a value no larger than the maximum value given for TWR".

Proposed Response Response Status O

CI 48 SC 48.2.6.1.5a P150 L52 # 177
Brown, Matthew Applied Micro (AMCC)

Comment Type GR Comment Status X

A quiescent state is not defined.

SuggestedRemedy

Change "quiescent" to "QUIET".

Proposed Response Response Status O

CI 48 SC 48.2.6.2.5 P157 L18 # 179
Brown, Matthew Applied Micro (AMCC)

Comment Type TR Comment Status X

Table 48-10. Tolerance on TWTF has same value for minimum and maximum. Minimum is not required.

SuggestedRemedy

Delete minimum value.

Proposed Response Response Status O

CI 48 SC 48.2.6.2.5 P157 L5 # 178
Brown, Matthew Applied Micro (AMCC)

Comment Type TR Comment Status X

Table 48-9. Tolerance on TSL and TUL are too tight (100 ns) and will preclude implementations that control EEE through firmware.

SuggestedRemedy

Change tolerance to +/- 1 us.

Proposed Response Response Status O

CI 48 SC 48.7.4.8 P159 L24 # 332
Dambrosia, John Force10 Networks

Comment Type TR Comment Status X

no corresponding SHALL statements for LP-01

SuggestedRemedy

add corresponding shall statement

Proposed Response Response Status O

CI 49 SC 49.1.5 P161 L31 # 180
Brown, Matthew Applied Micro (AMCC)

Comment Type GR Comment Status X

A statement is required to to make it clear what is meant by EEE is supported. As I understand it, EEE is supported only if both local device and link partner advertise the EEE capability. This means that it is implemented on both devices and both devices have been programmed via ability bits to support EEE.

SuggestedRemedy

Add the following sentence... "EEE is supported only if during auto-negotiation both the local device and link partner advertise the EEE capability. If EEE is not supported all EEE functionality, if implemented, will be disabled. For instance, LPI control characters will not be sent and LPI control characters received will be treated as errors."

Proposed Response Response Status O

CI 49 SC 49.1.5 P182 L47 # 203
Brown, Matthew Applied Micro (AMCC)

Comment Type GR Comment Status X

A statement is required to to make it clear what is meant by EEE is supported. As I understand it, EEE is supported only if both local device and link partner advertise the EEE capability. This means that it is implemented on both devices and both devices have been programmed via ability bits to support EEE.

SuggestedRemedy

Add the following sentence... "EEE is supported only if during auto-negotiation both the local device and link partner advertise the EEE capability. If EEE is not supported all EEE functionality, if implemented, will be disabled. For instance, LPI control characters will not be sent and LPI control characters received will be treated as errors."

Proposed Response Response Status O

CI 49 SC 49.2.13.1 P173 L44 # 123
Healey, Adam LSI Corporation

Comment Type TR Comment Status X

In Figure 49-17, there is a problem with the mechanism described to recover from a wake time fault. The variable energy_detect is used to determine if the transmitter has returned to the quiet state. This requires capabilities beyond what is otherwise assumed for 10GBASE-KR energy_detect. Per 72.6.4 (page 236, line 26), the value of PMD signal_detect is determined by the 10GBASE-KR training state diagram (in other words, it is set to TRUE) when rx_mode is DATA. Since rx_mode is set to DATA in the RX_WAKE state, and not changed upon a transition to the RX_WTF state, the branch to the RX_QUIET state can never be taken. Also note energy_detect has been defined as a mechanism to detect the transmitter's transition from TX_QUIET to TX_ALERT (it is only enabled during rx_mode = QUIET) and a special alert signal has been defined to facilitate this. The energy_detect variable should not be assumed to be a general indication of signal presence (or absence). If there is no robust means to distinguish between a quiet and an active line, then this transition has little value. It may be more reasonable to extend the refresh time to give the receiver a reasonable chance to recover before the line goes quiet again. If the receiver is unable to recover, then it is likely the link needs to fully retrained and therefore be taken down.

SuggestedRemedy

Remove the transition from RX_WTF to RX_QUIET. Consider extending the refresh time to give the receiver a longer opportunity to recover from a wake time fault during refresh.

Proposed Response Response Status O

CI 49 SC 49.2.13.2.2 P166 L9 # 120
Healey, Adam LSI Corporation

Comment Type E Comment Status X

This content of this note is already stated in 49.2.9 (page 163, line 16). It seems like this observation only needs to be stated once. In addition, this editorial instruction pertains to a subclause preceding 49.2.13.3 and should be placed there.

SuggestedRemedy

Remove redundant text. If the text pertaining to the new note is kept, relocate it so the change instructions are listed in clause order.

Proposed Response Response Status O

Comments received

IEEE P802.3az D3.0 Energy Efficient Ethernet comments

Cl 49 SC 49.2.13.2.3 P163 L24 # 333
 Dambrosia, John Force10 Networks
 Comment Type ER Comment Status X
 subclauses are out of order with 49.2.13.2.2 on Page 166
 SuggestedRemedy
 reorder subclauses
 Proposed Response Response Status O

Cl 49 SC 49.2.13.2.3 P163 L33 # 114
 Gustlin, Mark Cisco Systems, Inc.
 Comment Type T Comment Status X
 Change:
 one of the five or six types
 To:one of six types
 Doesn't make sense to say both...there are 6 types
 SuggestedRemedy
 Proposed Response Response Status O

Cl 49 SC 49.2.13.2.3 P163 L54 # 183
 Brown, Matthew Applied Micro (AMCC)
 Comment Type GR Comment Status X
 For PHYs that do not support EEE, LI characters are always treated as errors. Make this clear.
 SuggestedRemedy
 Add sentence, "A PCS that does not support EEE, will classify vectors containing one or more /LI/ control characters as type E."
 Proposed Response Response Status O

Cl 49 SC 49.2.13.2.3 P164 L50 # 115
 Gustlin, Mark Cisco Systems, Inc.
 Comment Type T Comment Status X
 Change:one of the five types
 To:one of the six types
 There are six types now.
 SuggestedRemedy
 Proposed Response Response Status O

Cl 49 SC 49.2.13.2.3 P165 L1 # 119
 Healey, Adam LSI Corporation
 Comment Type E Comment Status X
 Figure 49-13 appear right in the middle of the definition of TX_BLOCK_TYPE.
 SuggestedRemedy
 More Figure 49-13 to a more logical location.
 Proposed Response Response Status O

Cl 49 SC 49.2.13.2.3 P166 L3 # 185
 Brown, Matthew Applied Micro (AMCC)
 Comment Type GR Comment Status X
 For PHYs that do not support EEE, LI characters are always treated as errors. Make this clear.
 SuggestedRemedy
 Add sentence, "A PCS that does not support EEE, will classify vectors containing one or more /LI/ control characters as type E."
 Proposed Response Response Status O

Comments received

IEEE P802.3az D3.0 Energy Efficient Ethernet comments

CI 49 SC 49.2.13.2.5 P167 L14 # 111
 Horner, Rita Avago Technologies
 Comment Type TR Comment Status X
 one_us_timer is approximately 4.9 FEC frames long.
 SuggestedRemedy
 Change the one_us_timer value to be 32 * 5 66-bit blocks. This ensures reception of 4 FEC frames containing unscrambled data.
 Proposed Response Response Status O

CI 49 SC 49.2.13.2.5 P167 L15 # 121
 Healey, Adam LSI Corporation
 Comment Type T Comment Status X
 The value of one_us_timer should have a tolerance.
 SuggestedRemedy
 Define minimum and maximum values for the terminal count.
 Proposed Response Response Status O

CI 49 SC 49.2.13.2.5 P167 L23 # 186
 Brown, Matthew Applied Micro (AMCC)
 Comment Type GR Comment Status X
 The terminal count description wording makes intent unclear and is written differently than for other timers.
 SuggestedRemedy
 Change "shall not exceed the maximum value of TWR" with "shall be set to a value no larger than the maximum value given for TWR".
 Proposed Response Response Status O

CI 49 SC 49.2.13.2.5 P167 L29 # 187
 Brown, Matthew Applied Micro (AMCC)
 Comment Type GR Comment Status X
 A "quiescent" state is not defined.
 SuggestedRemedy
 Change "quiescent" to "QUIET".
 Proposed Response Response Status O

CI 49 SC 49.2.13.3.1 P171 L7 # 188
 Brown, Matthew Applied Micro (AMCC)
 Comment Type GR Comment Status X
 What does "synchronizes the receive state diagram with the end of LPI" mean?
 SuggestedRemedy
 Clarify.
 Proposed Response Response Status O

CI 49 SC 49.2.13.3.1 P173 L # 110
 Horner, Rita Avago Technologies
 Comment Type TR Comment Status X
 In Figure 49-17, Transition from RX_WTF is ambiguous
 SuggestedRemedy
 The transition from RX_WTF to either RX_LINK_FAIL or RX_SLEEP or RX_ACTIVE should also be based on energy_detect to give energy_detect highest priority.
 The transition from RX_WTF to RX_SLEEP should be based on energy_detect. i.e. :
 !rx_wf_timer_done * rx_block_lock * R_TYPE(rx_coded) = LI * energy_detect
 The transition from RX_WTF to RX_ACTIVE should be based on energy_detect. i.e. :
 !rx_wf_timer_done * rx_block_lock * R_TYPE(rx_coded) not equal LI * energy_detect
 The transition from RX_WTF to RX_LINK_FAIL should be based on energy_detect. i.e. :
 rx_wf_timer_done * energy_detect
 Proposed Response Response Status O

Comments received

IEEE P802.3az D3.0 Energy Efficient Ethernet comments

CI 49 SC 49.2.13.3.1 P173 L # 109
 Horner, Rita Avago Technologies

Comment Type TR Comment Status X

In Figure 49-17, Transition priority from RX_SLEEP state is ambiguous

SuggestedRemedy

The transition from RX_SLEEP to RX_SLEEP should be qualified with signal_ok. i.e. :
 ~rx_tq_timer_done * R_TYPE(rx_coded)=LI * signal_ok.
 The transition from RX_SLEEP to RX_ACTIVE should also be based on signal_ok : i.e.
 rx_block_lock * ~rx_tq_timer_done * R_TYPE(rx_coded)=IDLE * signal_ok.

Proposed Response Response Status O

CI 49 SC 49.2.13.3.1 P173 L40 # 152
 Parnaby, Gavin Solarflare Communicat

Comment Type T Comment Status X

The transitions from RX_WTF to RX_QUIET and RX_LINK_FAIL are not exclusive.

SuggestedRemedy

Add logic to make the transitions exclusive.
 e.g. change the transition to RX_QUIET to
 !energy_detect * !rx_wf_timer_done

Proposed Response Response Status O

CI 49 SC 49.2.13.3.1 P173 L45 # 190
 Brown, Matthew Applied Micro (AMCC)

Comment Type GR Comment Status X

In RX_LINK_FAIL, assignment to block lock is somewhat ambiguous since the se states
 are timeless and block_lock takes on the value of rx_block_lock in the following state.

SuggestedRemedy

A clarification of the intended behavior is requested.

Proposed Response Response Status O

CI 49 SC 49.2.13.3.1 P173 L45 # 189
 Brown, Matthew Applied Micro (AMCC)

Comment Type GR Comment Status X

In RX_LINK_FAIL, assignment of rx_mode is redundant since it always gets set in the next
 state.

SuggestedRemedy

In RX_LINK_FAIL, delete "rx_mode = DATA".

Proposed Response Response Status O

CI 49 SC 49.2.13.3.1 P174 L18 # 191
 Brown, Matthew Applied Micro (AMCC)

Comment Type TR Comment Status X

Table 49-2. 1% tolerance on TSL, TUL, and TWL precludes firmware implementation.

SuggestedRemedy

Change tolerance to +/- 1us.

Proposed Response Response Status O

CI 49 SC 49.2.13.3.1 P174 L37 # 125
 Healey, Adam LSI Corporation

Comment Type TR Comment Status X

For the case where signal_ok is generated by the PMA sublayer (i.e. no FEC sublayer in
 the stack), it seems that more is being read into the meaning of this variable than what is
 actually defined. In the RX_SLEEP state, rx_mode is set to DATA which means that, per
 72.6.4, signal_detect is determined by the 10GBASE-KR training state diagram (e.g. it is
 TRUE). Per 51.4.1, the PMA qualifies this signal with the optional PMA loopback signal
 (irrelevant) or the optional Sync_Err function. Even when implemented, the Sync_Err
 function is defined to report TRUE when there is a synchronization error but it is also stated
 that a value of FALSE does not guarantee synchronization. Therefore, the PMA signal_ok
 signal does not appear to be a sufficiently robust indicator of the absence of an input signal.

SuggestedRemedy

Change the condition for the transition from RX_SLEEP to RX_QUIET to be
 !rx_tq_timer_done * !rx_block_lock. Since !signal_ok also forces rx_block_lock to be
 FALSE, the intended behavior is preserved if signal_ok behaves as assumed by the
 current state diagram. If signal_ok is not a robust indicator of the absence of the signal,
 then loss of block lock provides a fail-safe to ensure the receiver enters the RX_QUIET
 state. This works equally well when the FEC sublayer is included.

Proposed Response Response Status O

Cl 49 SC 49.2.13.3.1 P174 L37 # 124
Healey, Adam LSI Corporation

Comment Type TR Comment Status X

The values for TWR (for both scr_bypass_enable = FALSE are TRUE) are too large. The values significantly exceed minimum MAC transmit deferral time Tw_sys_tx defined in Table 78-4. This implies that the packet (or packets) transmitted immediately follow the minimum deferral time will disappear and no error will be recorded to account for their absence. Note that rx_lpi_active remains TRUE until the wake is successful (i.e. a transition to the RX_ACTIVE state). As long as rx_lpi_active is TRUE, the PCS receive state diagram cannot leave the RX_LI state which means any data received while the PHY is in the process of waking will be swallowed by the PHY and only LPI will be presented at the receive XGMII. Because of this, it is critical that the PHY count wake errors to account for any disappearance of packets. The times were initially extended to provide for the case of a WAKE directly from refresh. This is a non-issue when the FEC sublayer is not included in the PHY stack (the receiver will either transition to RX_ACTIVE directly or via RX_SLEEP and there will be no wake time fault) . When FEC is included, it may be an issue since entry into x_SCR_BYPASS may be delayed which will in turn delay rx_block_lock. This issue is readily addressed by a simplification of the Transmit LPI state diagram where a refresh is rendered as the sequence TX_ALERT -> TX_WAKE -> [TX_SCR_BYPASS] -> TX_SLEEP. The existing transition from TX_SLEEP to TX_ACTIVE addresses "wake from refresh" events. Such a change greatly simplifies the state diagram, allows the definition of T_WR values that enable the correct counting of wake errors, and ensures that entry into TX_SCR_BYPASS occurs on a consistent schedule for any series of refresh, wake, or wake from refresh events.

SuggestedRemedy

A presentation will be submitted that proposed a new Transmit LPI state machine that addresses the core issue and revises the TWR values.

Proposed Response Response Status O

Cl 49 SC 49.2.4.4 P161 L22 # 117
Healey, Adam LSI Corporation

Comment Type T Comment Status X

In Figure 49-4, the block diagram explicitly provides for a PMA, FEC, or WIS sublayer below the PCS. It also provides for the rx_lpi_active signal to be sent to that sublayer when it is a FEC sublayer. Therefore, it should also be stated FEC_SIGNAL.indication primitive is passed to the PCS when the sublayer below it is the FEC sublayer.

SuggestedRemedy

Update the block diagram accordingly.

Proposed Response Response Status O

Cl 49 SC 49.2.4.4 P161 L40 # 181
Brown, Matthew Applied Micro (AMCC)

Comment Type GR Comment Status X

EEE is an option not LPI. If a PHY supports EEE it must support LPI. Note: There is a general problem that it is unclear in this section what is always required if implemented (whether or not resolved by AN) vs what is required if supported (AN resolves EEE). Language needs to be precise.

SuggestedRemedy

Change sentence to "The ability to transmit or receive Low Power Idle is required for PHYs that support EEE."

Proposed Response Response Status O

Cl 49 SC 49.2.4.4 P161 L41 # 182
Brown, Matthew Applied Micro (AMCC)

Comment Type GR Comment Status X

Let's be clear as to what is or is not supported. In this case, the intent is to say that if EEE is not supported (whether because its not implemented or because it was not resolved during AN) that LPI shall not be transmitted. In other words, PHY without EEE support treat LPI control characters are errors.

SuggestedRemedy

Change "If this option is not supported..." to "If EEE is not supported..."

Proposed Response Response Status O

Cl 49 SC 49.2.6 P162 L33 # 118
Healey, Adam LSI Corporation

Comment Type E Comment Status X

Equation (49-1) appears to be cropped in the PDF.

SuggestedRemedy

Correct the issue.

Proposed Response Response Status O

Comments received

IEEE P802.3az D3.0 Energy Efficient Ethernet comments

Cl 49 SC 49.2.6 P162 L33 # 151
 Parnaby, Gavin Solarflare Communicat
 Comment Type E Comment Status X
 The scrambler polynomial is unreadable.
 SuggestedRemedy
 Fix the text.
 [this is unchanged text from the base clause]
 Proposed Response Response Status O

Cl 49 SC 49.2.9 P163 L16 # 184
 Brown, Matthew Applied Micro (AMCC)
 Comment Type GR Comment Status X
 Refer to "EEE support" rather than "LPI implementation".
 SuggestedRemedy
 Change "optional LPI function is implemented" to "EEE is supported".
 Proposed Response Response Status O

Cl 49 SC 49.2.6 P162 L33 # 112
 Gustlin, Mark Cisco Systems, Inc.
 Comment Type E Comment Status X
 The scrambler equation does not show clearly in the pdf.
 SuggestedRemedy
 Fix it.
 Proposed Response Response Status O

Cl 49 SC 49.3.6.6 P176 L32 # 334
 Dambrosia, John Force10 Networks
 Comment Type TR Comment Status X
 no corresponding shall statements for LP-04, LP-05, and LP-06
 SuggestedRemedy
 add corresponding shall statements
 Proposed Response Response Status O

Cl 49 SC 49.2.8 P163 L3 # 113
 Gustlin, Mark Cisco Systems, Inc.
 Comment Type T Comment Status X
 Saying "The scrambler shall continue to advance normally." seems strange, it is really just advancing normally, though operating in bypass mode.
 SuggestedRemedy
 Change:The scrambler shall continue to operate normally.
 To:The scrambler state shall continue to advance normally.
 Proposed Response Response Status O

Cl 51 SC 51.10.4.5 P181 L22 # 335
 Dambrosia, John Force10 Networks
 Comment Type TR Comment Status X
 no corresponding shall statements for LP-01
 SuggestedRemedy
 add corresponding shall statement
 Proposed Response Response Status O

Cl 51 SC 51.2.4.3 P178 L26 # 192
 Brown, Matthew Applied Micro (AMCC)
 Comment Type GR Comment Status X
 Only the receiver is affected.
 SuggestedRemedy
 Chage the "PMA is" to "the PMA receive is".
 Proposed Response Response Status O

Comments received

IEEE P802.3az D3.0 Energy Efficient Ethernet comments

Cl 51 SC 51.2.5 P178 L32 # 193
 Brown, Matthew Applied Micro (AMCC)
 Comment Type GR Comment Status X
 Generated by PCS transmit.
 SuggestedRemedy
 Change "PCS receive process" to "PCS transmit process".
 Proposed Response Response Status O

Cl 51 SC 51.2.5.3 P178 L49 # 196
 Brown, Matthew Applied Micro (AMCC)
 Comment Type ER Comment Status X
 spelling
 SuggestedRemedy
 Change "nomally" to "normally".
 Proposed Response Response Status O

Cl 51 SC 51.2.5 P178 L33 # 194
 Brown, Matthew Applied Micro (AMCC)
 Comment Type GR Comment Status X
 If talking about the PMD must also talk about ALERT signalling. Suggest leaving details to
 to subsequent sub-clauses.
 SuggestedRemedy
 Change "to indicate ... see 49.3.6.6" to "to invoke the appropriate PMA and PMD transmit
 EEE states".
 Proposed Response Response Status O

Cl 51 SC 51.2.6.1 P179 L11 # 197
 Brown, Matthew Applied Micro (AMCC)
 Comment Type GR Comment Status X
 Use full name name.
 SuggestedRemedy
 Change SIGNAL_OK to PMD_SIGNAL.indication(SIGNAL_OK)
 Proposed Response Response Status O

Cl 51 SC 51.2.5.3 P178 L48 # 195
 Brown, Matthew Applied Micro (AMCC)
 Comment Type GR Comment Status X
 Only the transmitter is affected.
 SuggestedRemedy
 Change "the PMA is" to "the PMA transmit is".
 Proposed Response Response Status O

Cl 51 SC 51.2.6.1 P179 L15 # 198
 Brown, Matthew Applied Micro (AMCC)
 Comment Type GR Comment Status X
 energy_detect reflects changes in SIGNAL_OK
 SuggestedRemedy
 Change "of the energy detect parameter" to "of the SIGNAL_OK parameter".
 Proposed Response Response Status O

Cl 51 SC 51.8a P179 L41 # 199
 Brown, Matthew Applied Micro (AMCC)
 Comment Type GR Comment Status X
 Sub-clause 51.8a is redundant and obsolete.
 SuggestedRemedy
 Delete 51.8a.
 Proposed Response Response Status O

Comments received

IEEE P802.3az D3.0 Energy Efficient Ethernet comments

Cl 55 SC 55 P182 L0 # 201
Brown, Matthew Applied Micro (AMCC)

Comment Type GR Comment Status X

Use consistent terminology for EEE capability support through clause. Phrases currently include: "EEE capability", "LPI-capable", "EEE function", "LPI function", etc. My assumption is that all of these are the same, but I can't be sure.

SuggestedRemedy

A comprehensive list of proposed amendments will be provided.

Proposed Response Response Status O

Cl 55 SC 55 P182 L1 # 200
Brown, Matthew Applied Micro (AMCC)

Comment Type ER Comment Status X

Consistent terminology throughout Clause 55 for LPI control characters. Use either "/LI/" or "LPI control characters".

SuggestedRemedy

As a minimum change the following (Page 184 / line 36) replace "LP_IDLE characters" with "LPI control characters"; (191/8) replace title with "LPI (/LI/)"; (191/10) replace "Low power idle control" with "Low power idle (LPI) control"; (191/11) replace "LPI characters" with "LPI control characters"; (191/41) replace "LP_IDLE characters" with "LPI control characters"; (192/12) replace "LP_IDLE codewords" with "LPI control characters"; (192/19) replace "LP_IDLE" with "LPI"; (193/15) replace "LP_IDLE" with "LPI control". Consider generally replacing "LPI control characters" globally and above with "/LI/" or "/LI/ characters".

Proposed Response Response Status O

Cl 55 SC 55 P183 L22 # 361
Bennett, Michael Lawrence Berkeley Na

Comment Type T Comment Status X

Submitted on behalf of Michael Grimwood. loc_lpi_en is used to signal from the PMA to the PCS that the PHY Control state diagram is in PCS_Test. This can be generalized to communicate when the PHY Control is in PCS_Data in order to hold the PCS state diagrams in INIT when not in PCS_Data. Replace loc_lpi_en with the variable, pcs_data_mode, and the primitive PMA_LOCLPIEN with PMA_PCSDATAMODE.

SuggestedRemedy

A presentation will be submitted showing the required detailed changes to the text and state diagrams 55-15 and 55-24.

Proposed Response Response Status O

Cl 55 SC 55 P194 L9 # 364
Bennett, Michael Lawrence Berkeley Na

Comment Type T Comment Status X

Submitted on behalf of Michael Grimwood. Clarify that the transition to PCS_Test serves as the fixed timing reference for LPI refresh signaling in fast retraining (as well as initial training and normal retraining).

SuggestedRemedy

In Section 55.3.4a.1, page 194 line 9 Change: "As in training without the EEE capability, the master and slave signal when they will transition to PCS_Test using the transition counter following the procedure described in 55.4.2.5.14." To: " In initial training, normal retraining, and fast retraining, with or without the EEE capability being supported, the master and slave signal when they will transition to PCS_Test using the transition counter following the procedure described in 55.4.2.5.14."

Proposed Response Response Status O

Cl 55 SC 55 P201 L2 # 363
Bennett, Michael Lawrence Berkeley Na

Comment Type T Comment Status X

Submitted on behalf of Michael Grimwood. 55.3.5.4 The expected behavior of the PCS 64/65B Transmit state diagram during fast retraining is not clear. Propose to hold the diagram in TX_INIT when a fast retrain is occurring.

SuggestedRemedy

In Figure 55-15, change the condition to enter state TX_INIT from pcs_reset to (pcs_reset + !pcs_data_mode). Note that this has a common resolution with an issue in which the transmit and receive PCS state diagrams can get out of sync.

Proposed Response Response Status O

CI 55 SC 55 P201 L2 # 360
Bennett, Michael Lawrence Berkeley Na

Comment Type T Comment Status X

Submitted on behalf of Michael Grimwood. It is possible for the PCS 64B/65B transmit state diagram to encode LP_IDLE but not transition into TX_L, resulting in the transmitter and receiver being out-of-sync. This can occur during PCS_Test when loc_lpi_en is false and the transmitter encodes tx_raw of type LI resulting in the receiver decoding rx_raw of type LI.

SuggestedRemedy

In Figure 55-15, add a transition into TX_INIT conditioned on the PHY Control state diagram not being in state PCS_Data. Eliminate all dependence on the variable loc_lpi_en. In Figure 55-16, add a transition into RX_INIT conditioned on the PHY Control state diagram not being in state PCS_Data. A presentation will be submitted showing the required changes to Figures 55-15 and 55-16.

Proposed Response Response Status O

CI 55 SC 55 P205 L3 # 362
Bennett, Michael Lawrence Berkeley Na

Comment Type T Comment Status X

55.3.5.4 The EEE transmit state diagram conflicts with the fast retrain state diagram. The fast retrain state diagram should take precedence. This can be resolved by holding the EEE transmit state diagram in state TX_NORMAL when a fast retrain is occurring.

SuggestedRemedy

Change the condition to enter state TX_NORMAL from pcs_reset to (pcs_reset + !pcs_data_mode).

Proposed Response Response Status O

CI 55 SC 55 P209 L # 369
Bennett, Michael Lawrence Berkeley Na

Comment Type T Comment Status X

Submitted on behalf of Paul Langner Paul.Langner@aquantia.com Currently the IEEE fast-retrain mechanism being proposed does not implement a mechanism to inform the MAC that the link is temporarily unavailable. As a result, the MAC will continue to send data during a fast-retrain (for up to 30 ms). This data will all be lost. In order to prevent this from occurring, a mechanism is needed to inform the MAC that the link is temporarily unavailable, so that the data will not be lost, and can be buffered until the link is available.

SuggestedRemedy

Create a control code (similar to Local Fault) that indicates that the link is temporarily unavailable, and this control code would be sent continuously to the MAC until the retrain is completed.

Proposed Response Response Status O

CI 55 SC 55 P209 L46 # 365
Bennett, Michael Lawrence Berkeley Na

Comment Type T Comment Status X

Submitted on behalf of Michael Grimwood. In initial training the THP is turned off at the beginning of state PMA_Coeff_Exch. During PCS_Data, the THP is on. During a fast retrain in PMA_Coeff_Exch, is the THP on or off?

SuggestedRemedy

Change: "After completing the link failure signal the PHY shall transition to the PMA_Coeff_Exch state and send PAM2 signaling within a time period equivalent to 9 LDPC frame periods ." To: "After completing the link failure signal the PHY shall transition to the PMA_Coeff_Exch state, keep its THP turned on with its previously-exchanged coefficients, and send PAM2 signaling within a time period equivalent to 9 LDPC frame periods."

Proposed Response Response Status O

Cl 55 SC 55 P209 L 52 # 366
 Bennett, Michael Lawrence Berkeley Na

Comment Type T Comment Status X

Submitted on behalf of Michael Grimwood. LPI uses a training sequence based on scramblers that are free running from PCS Reset or if scrambler re-initialization is used for initial training, from PCS_Test. In order to ensure that fast retraining is compatible with LPI, the scrambler should not be re-initialized by fast retraining events. To accomplish this, constrain fast retraining to use a training sequence without periodic re-initialization and establish that it be free running from PCS reset or from the first entry to PCS_Test if scrambler re-initialization is used for initial training. (similar to the specifications for LPI).

SuggestedRemedy

Add this paragraph after line 52: The PAM2 symbols are generated using the PMA side-stream scrambler polynomials shown in Figure 55-13. The training sequence without periodic re-initialization described in 55.3.4 shall be used during fast retraining, with the scramblers free-running from PCS Reset. If scrambler re-initialization is used for initial training, it shall be disabled and the scramblers shall begin free-running when the PHY Control state diagram enters the PCS_Test state and the variable fr_active is FALSE.

Proposed Response Response Status O

Cl 55 SC 55.1 P182 L 11 # 202
 Brown, Matthew Applied Micro (AMCC)

Comment Type TR Comment Status X

Last sentence of paragraph implies that fast retrain is available only if EEE capability is supported, whereas subsequent sub-clauses implies that support for fast retrain is independent. I believe that the intent that EEE and fast retrain support are independent. In other words, either or both may be implemented and if both are implemented then neither, either, or both may be resolved through AN.

SuggestedRemedy

Clarify which is the case: (a) fast retrain may be supported only if EEE is supported or (b) fast retrain may be supported independent of EEE.

Proposed Response Response Status O

Cl 55 SC 55.1 P182 L 11 # 353
 Ganga, Ilango Intel Corporation

Comment Type ER Comment Status X

Fast retrain capability is optional, so change the sentence as suggested.

SuggestedRemedy

10GBASE-T PHYs with EEE capability may optionally support a fast retrain mechanism

Proposed Response Response Status O

Cl 55 SC 55.1.1 P182 L 15 # 352
 Ganga, Ilango Intel Corporation

Comment Type ER Comment Status X

There is no need to repeat the 10GBASE-T objectives in this amendment. Change editing instructions to insert the new objectives for EEE.

SuggestedRemedy

Change editing instruction as follows: "Insert the following objective to the end of the list as follows:" " I) Support a EEE capability as part of Energy Efficient Ethernet (Clause 78)"

Proposed Response Response Status O

Cl 55 SC 55.1.3 P182 L 48 # 356
 Ganga, Ilango Intel Corporation

Comment Type E Comment Status X

Only 10GBASE-T PHYs with EEE capability may optionally support Fast Retrain mechanism, so change sentence as suggested

SuggestedRemedy

10GBASE-T PHYs with EEE capability may optionally support a fast retrain mechanism.

Proposed Response Response Status O

Comments received

IEEE P802.3az D3.0 Energy Efficient Ethernet comments

Cl 55 SC 55.1.3 P183 L24 # 204
 Brown, Matthew Applied Micro (AMCC)
 Comment Type GR Comment Status X
 Line for loc_lpi_en should be dashed to indicate that it is intend for EEE only.
 SuggestedRemedy
 Change loc_lpi_en line to dashed.
 Proposed Response Response Status O

Cl 55 SC 55.1.4 P185 L33 # 206
 Brown, Matthew Applied Micro (AMCC)
 Comment Type G Comment Status X
 Some primitive names use underscore to separate joined words while others are not. For readability modify all new (EEE) primitives names to include underscores.
 SuggestedRemedy
 Change PMA_ALERTDETECT to PMA_ALERT_DETECT. Change "PMA_LOCLPIEN" to "PMA_LOC_LPI_EN". Make changes through Clause 55.
 Proposed Response Response Status O

Cl 55 SC 55.1.3 P183 L3 # 357
 Ganga, Ilango Intel Corporation
 Comment Type ER Comment Status X
 As per style manual 16.3, a note to a figure is informative and a footnote to a figure is normative. So change this not to a footnote as applicable
 SuggestedRemedy
 Check notes to figures and tables and change to guidelines in style manual if applicable
 Proposed Response Response Status O

Cl 55 SC 55.12 P220 L9 # 355
 Ganga, Ilango Intel Corporation
 Comment Type ER Comment Status X
 The "Value/Comment" column should be after the subclause column to match the PICS tables in the base standard.
 SuggestedRemedy
 Move the "Value/Comment" column to match the base standard. Make this change in this clause and and in other clauses as applicable
 Proposed Response Response Status O

Cl 55 SC 55.1.3.3 P184 L10 # 358
 Ganga, Ilango Intel Corporation
 Comment Type E Comment Status X
 Change sentence as follows "A 10GBASE-T PHY may optionally support EEE capability"
 SuggestedRemedy
 As per comment
 Proposed Response Response Status O

Cl 55 SC 55.12.2 P220 L13 # 354
 Ganga, Ilango Intel Corporation
 Comment Type ER Comment Status X
 Provide reference to subclause where the fast retrain option is specified.
 SuggestedRemedy
 Add subclause reference to PICS items FR and EEE
 Proposed Response Response Status O

Cl 55 SC 55.1.3.3 P184 L54 # 205
 Brown, Matthew Applied Micro (AMCC)
 Comment Type GR Comment Status X
 Incorrect figure #.
 SuggestedRemedy
 Change Figure 55-16 to Figure 55-16b.
 Proposed Response Response Status O

Comments received

IEEE P802.3az D3.0 Energy Efficient Ethernet comments

Cl 55 SC 55.12.3 P220 L27 # 343
 Dambrosia, John Force10 Networks
 Comment Type TR Comment Status X
 PCT1a value comment field refers to Fig 55-16, but there is no reference in 55.3.2.2 to Fig 55-16
 SuggestedRemedy
 delete reference to Fig 55-16
 Proposed Response Response Status O

Cl 55 SC 55.12.3 P221 L10 # 346
 Dambrosia, John Force10 Networks
 Comment Type TR Comment Status X
 PCT15C, PCT15d, PCT15j-PCT15p, and PCT17 subclause references do not exist in this amendment, therefore there are no corresponding SHALL statements for these pics.
 SuggestedRemedy
 Add appropriate proper subclauses with appropriate SHALL statements
 Proposed Response Response Status O

Cl 55 SC 55.12.3 P220 L29 # 344
 Dambrosia, John Force10 Networks
 Comment Type TR Comment Status X
 PCT2 subclause reference 55.3.2.2.4 does not exist. PCT3 subclause reference 55.3.2.2.6 does not exist in this amendment. PCT4a subclause reference 55.3.2.2.10 does not exist in this amendment. Subclause references for PCT5 - PCT10 do not exist in this amendment. Therefore there are no appropriate SHALL statements for these PICs.
 SuggestedRemedy
 Add appropriate proper subclauses with appropriate SHALL statements
 Proposed Response Response Status O

Cl 55 SC 55.12.3 P221 L24 # 347
 Dambrosia, John Force10 Networks
 Comment Type TR Comment Status X
 LPI tx wake timer does not exist in this draft other than in the PIC
 SuggestedRemedy
 add appropriate text and SHALL statement
 Proposed Response Response Status O

Cl 55 SC 55.12.3 P220 L53 # 345
 Dambrosia, John Force10 Networks
 Comment Type TR Comment Status X
 subclauses references for PCT11 - PCT15 are incorrect.
 SuggestedRemedy
 change 55.3.3 for PCT11 to 55.3.3a.1. Change 55.3.4 for PCT12 PCT15 to 55.3.4a.1
 Proposed Response Response Status O

Cl 55 SC 55.12.3 P222 L18 # 348
 Dambrosia, John Force10 Networks
 Comment Type TR Comment Status X
 PMF16a comment to Table 55-6A is incorrect, as this is for Recommended fast retrain sequence timing
 SuggestedRemedy
 Move reference in comment field to PMF16B
 Proposed Response Response Status O

Comments received

IEEE P802.3az D3.0 Energy Efficient Ethernet comments

Cl 55 SC 55.12.3 P222 L 18 # 349
 Dambrosia, John Force10 Networks
 Comment Type **TR** Comment Status **X**
 There is no corresponding SHALL statement related to a start up sequence
 SuggestedRemedy
 add shall statement for appropriate text related to start up sequence.
 Proposed Response Response Status **O**

Cl 55 SC 55.12.3 P222 L 23 # 350
 Dambrosia, John Force10 Networks
 Comment Type **ER** Comment Status **X**
 The definitions of the feature for PMF16c and PMF16d include text that is appropriate for Value comment field.
 SuggestedRemedy
 correct text in Feature and Value / Comment fields accordingly
 Proposed Response Response Status **O**

Cl 55 SC 55.12.3 P222 L 31 # 351
 Dambrosia, John Force10 Networks
 Comment Type **TR** Comment Status **X**
 There is no corresponding SHALL statement related to seeing Table 55-6A. In the text following the timing in this table is defined as should
 SuggestedRemedy
 Replace text on Line 5 Page 210 from "To ensure interoperability the training times in Table 55--6a should be observed during the fast retrain." to "To ensure interoperability the training times in Table 55--6a shall be observed during the fast retrain."
 Proposed Response Response Status **O**

Cl 55 SC 55.2.2.11 P188 L 10 # 140
 Parnaby, Gavin Solarflare Communicat
 Comment Type **GR** Comment Status **X**
 loc_lpi_en does not control the PHY as intended.
 loc_lpi_en was intended to inhibit transitions to the transmit low power mode if the PHY had not reached the PCS data mode (i.e. during PCS Test).
 In the PCS 64B/65B state machine, Figure 55-15, the loc_lpi_en variable is used to inhibit transitions to TX_LI. However, when lpi_loc_en is asserted the tx state machine will stay in the TX_C state, which still encodes the XGMII data into the transmit signal. Therefore LPI codewords will be sent to the link partner, which will interpret them as a SLEEP command, and begin the transition into low power signaling. Since the transmit side is prevented from entering the TX_L state until PCS_data, the low power signaling will not be sent and the link will likely fail.
 SuggestedRemedy
 Use a different mechanism to prevent transitions to LPI during PCS_Test e.g. hold the transmitter in TX_INIT until the PCS_Data state.
 Proposed Response Response Status **O**

Cl 55 SC 55.2.2.3.1 P187 L 5 # 141
 Parnaby, Gavin Solarflare Communicat
 Comment Type **E** Comment Status **X**
 ALERT) should be ALERT
 SuggestedRemedy
 As comment
 Proposed Response Response Status **O**

Cl 55 SC 55.3.2.2.21 P191 L 36 # 208
 Brown, Matthew Applied Micro (AMCC)
 Comment Type **GR** Comment Status **X**
 proper term
 SuggestedRemedy
 Change "65B" to "64B/65B".
 Proposed Response Response Status **O**

Comments received

IEEE P802.3az D3.0 Energy Efficient Ethernet comments

Cl 55 SC 55.3.2.2.21 P191 L49 # 209
 Brown, Matthew Applied Micro (AMCC)
 Comment Type ER Comment Status X
 spelling
 SuggestedRemedy
 Change "lpi_tx_mode" variables" to "lpi_tx_mode variable".
 Proposed Response Response Status O

Cl 55 SC 55.3.2.2.21 P192 L13 # 213
 Brown, Matthew Applied Micro (AMCC)
 Comment Type GR Comment Status X
 Which characters is referred to by "These characters".
 SuggestedRemedy
 Change "LP_IDLE codewords are no longer detected" to "codewords other than LP_IDLE are detect". Change "These characters" to "These codewords".
 Proposed Response Response Status O

Cl 55 SC 55.3.2.2.21 P192 L24 # 214
 Brown, Matthew Applied Micro (AMCC)
 Comment Type GR Comment Status X
 This paragraph is really clumsy. Please modify last to sentences to state the point more clearly.
 SuggestedRemedy
 Suggestion: "The maximum PHY wake time when wake is requested before sleep has been transmitted is 7.36 us (lpi_wake_timer=Tw_phy as defined by Clause 78). The maximum PHY wake time when wake is requested after sleep has been transmitted is 4.48 us."
 Proposed Response Response Status O

Cl 55 SC 55.3.2.2.21 P192 L32 # 215
 Brown, Matthew Applied Micro (AMCC)
 Comment Type GR Comment Status X
 Refer to reference in Clause 78. It seems redundant to have the wake times specified in three locations. Consider consolidating.
 SuggestedRemedy
 To title of columns 3 and 4 add "10GBASE-T Case-1 in Table 78.4". To title in columns 4 and 5 add "10GBASE-T Case-2 in Table 78-4".
 Proposed Response Response Status O

Cl 55 SC 55.3.2.2.21 P192 L9 # 212
 Brown, Matthew Applied Micro (AMCC)
 Comment Type ER Comment Status X
 spelling
 SuggestedRemedy
 Change "lpi_tx_mode" variables" to "lpi_tx_mode variable".
 Proposed Response Response Status O

Cl 55 SC 55.3.2.2.9 P191 L1 # 210
 Brown, Matthew Applied Micro (AMCC)
 Comment Type ER Comment Status X
 consistent (with clause 48) terminology
 SuggestedRemedy
 Replace "idle and lp_idle ordered sets" with either "||| and ||LPIDLE||" or "idle and LPI ordered sets."
 Proposed Response Response Status O

Comments received

IEEE P802.3az D3.0 Energy Efficient Ethernet comments

Cl 55 SC 55.3.2.2.9a P191 L10 # 211
 Brown, Matthew Applied Micro (AMCC)
 Comment Type GR Comment Status X
 LPI is requested by the LPI client not the MAC.
 SuggestedRemedy
 Replace "MAC" with "LPI client"
 Proposed Response Response Status O

Cl 55 SC 55.3.4a.1 P194 L12 # 143
 Parnaby, Gavin Solarflare Communicat
 Comment Type T Comment Status X
 Add clarifying text to state that this synchronization also takes place during fast retrain.
 SuggestedRemedy
 'This synchronization shall also be performed at the transition to PCS_Test during a fast retrain '
 Proposed Response Response Status O

Cl 55 SC 55.3.4a.1 P194 L14 # 217
 Brown, Matthew Applied Micro (AMCC)
 Comment Type GR Comment Status X
 By definition, in order for a PHY to support EEE the other must as well. No need for new terminology here.
 SuggestedRemedy
 Change "When both PHYs support the EEE capability, the slave" to "A EEE-capable PHY in slave mode" or "A SLAVE PHY with EEE capability".
 Proposed Response Response Status O

Cl 55 SC 55.3.4a.1 P194 L21 # 216
 Brown, Matthew Applied Micro (AMCC)
 Comment Type GR Comment Status X
 "Low power mode" specifically refers to "low power idle mode" or "LPI mode". Note that a "low power" mode is defined for all 802.3 PHYs and is invoked by setting MDIO bit 1.0.11 to 1.
 SuggestedRemedy
 Replace "low power mode" with "LPI mode".
 Proposed Response Response Status O

Cl 55 SC 55.3.4a.1 P194 L37 # 218
 Brown, Matthew Applied Micro (AMCC)
 Comment Type GR Comment Status X
 Table 55-1b and 55-1c. When are tx_refresh_active and rx_refresh_active set FALSE?
 SuggestedRemedy
 Add sentence on page 194 line 30 stating "rx_refresh_active and tx_refresh_active are set FALSE except where set true in the tables."
 Proposed Response Response Status O

Cl 55 SC 55.3.4a.3 P195 L35 # 142
 Parnaby, Gavin Solarflare Communicat
 Comment Type T Comment Status X
 The text should clarify whether scrambler reinitialization can be used for fast retrain.
 SuggestedRemedy
 State that scrambler reinitialization is not used for fast retrain.
 Proposed Response Response Status O

Comments received

IEEE P802.3az D3.0 Energy Efficient Ethernet comments

Cl 55 SC 55.3.4a.3 P195 L46 # 219
 Brown, Matthew Applied Micro (AMCC)
 Comment Type GR Comment Status X
 Need to specify ALERT precedence for SLAVE PHY as well.
 SuggestedRemedy
 Change "If lpi_tx_mode=REFRESH_A" to "If lpi_tx_mode=REFRESH_A on a MASTER PHY or lpi_tx_mode=REFRESH_C on a SLAVE PHY",
 Proposed Response Response Status O

Cl 55 SC 55.3.5.2.4 P198 L16 # 223
 Brown, Matthew Applied Micro (AMCC)
 Comment Type GR Comment Status X
 EEE terminology.
 SuggestedRemedy
 For I, LI, and LII, change "the optional LPI function is supported" and "the optional EEE function is supported" to "the EEE capability is supported".
 Proposed Response Response Status O

Cl 55 SC 55.3.4a.3 P196 L49 # 220
 Brown, Matthew Applied Micro (AMCC)
 Comment Type TR Comment Status X
 !tx_lpi_active should be !tx_lpi_qr_active.
 SuggestedRemedy
 Change !tx_lpi_active to !tx_lpi_qr_active.
 Proposed Response Response Status O

Cl 55 SC 55.3.5.2.4 P198 L35 # 224
 Brown, Matthew Applied Micro (AMCC)
 Comment Type GR Comment Status X
 EEE terminology.
 SuggestedRemedy
 Change the "EEE function" to "EEE capability". Two instances.
 Proposed Response Response Status O

Cl 55 SC 55.3.4a.3 P197 L10 # 221
 Brown, Matthew Applied Micro (AMCC)
 Comment Type TR Comment Status X
 Indicate that tx_refresh_active is to FALSE outside of period indicated in tables.
 SuggestedRemedy
 Append the sentence with "and is set FALSE otherwise"
 Proposed Response Response Status O

Cl 55 SC 55.3.5.2.4 P198 L52 # 225
 Brown, Matthew Applied Micro (AMCC)
 Comment Type GR Comment Status X
 EEE terminology.
 SuggestedRemedy
 For I, LI, and LII, change "the optional LPI function is supported" and "the optional EEE function is supported" to "the EEE capability is supported".
 Proposed Response Response Status O

Cl 55 SC 55.3.5.2.4 P197 L50 # 222
 Brown, Matthew Applied Micro (AMCC)
 Comment Type GR Comment Status X
 EEE terminology.
 SuggestedRemedy
 Change the "EEE function" to "EEE capability". Two instances.
 Proposed Response Response Status O

Comments received

IEEE P802.3az D3.0 Energy Efficient Ethernet comments

CI 55 SC 55.3.5.2.5 P199 L22 # 226
 Brown, Matthew Applied Micro (AMCC)
 Comment Type **TR** Comment Status **X**
 The tx_ldpc_frame_cnt counter must be reset after every training event, normal or fast retrain, not just the first one.
 SuggestedRemedy
 Change "initial training" to "normal training or fast retraining".
 Proposed Response Response Status **O**

CI 55 SC 55.3.5.2.5 P199 L28 # 227
 Brown, Matthew Applied Micro (AMCC)
 Comment Type **GR** Comment Status **X**
 The rx_ldpc_frame_cnt counter must be reset after every training event, normal or fast retrain, not just the first one.
 SuggestedRemedy
 Change "initial training" to "normal training or fast retraining".
 Proposed Response Response Status **O**

CI 55 SC 55.3.5.4 P199 L46 # 228
 Brown, Matthew Applied Micro (AMCC)
 Comment Type **G** Comment Status **X**
 It would be more definitive to use variables to delineate the period during which LFER may not be updated.
 SuggestedRemedy
 Change end of sentence to "during LPI receive operation while (!rx_lpi_active * !rx_lpi_wake)."
 Proposed Response Response Status **O**

CI 55 SC 55.3.5.4 P200 L3 # 146
 Parnaby, Gavin Solarflare Communicat
 Comment Type **G** Comment Status **X**
 Add a note to this state diagram (or elsewhere) stating that rx_lpi_active and rx_lpi_wake are both set to FALSE if the EEE capability is not supported.
 SuggestedRemedy
 As comment
 Proposed Response Response Status **O**

CI 55 SC 55.3.5.4 P201 L12 # 145
 Parnaby, Gavin Solarflare Communicat
 Comment Type **E** Comment Status **X**
 The note states 'Signals and functions shown with dashed lines are only required for the EEE capability'.
 However, on this diagram (and on some others), there is a single transition inside the dashed lines, and I don't believe this is classified as a signal or a function.
 Should the text be changed to say
 'Signals, functions and transitions shown with dashed lines are only required for the EEE capability'
 SuggestedRemedy
 As comment
 Proposed Response Response Status **O**

CI 55 SC 55.3.5.4 P201 L14 # 144
 Parnaby, Gavin Solarflare Communicat
 Comment Type **E** Comment Status **X**
 Arrow head is badly placed on transition from TX_INIT to TX_C
 SuggestedRemedy
 Fix arrow head
 Proposed Response Response Status **O**

Comments received

IEEE P802.3az D3.0 Energy Efficient Ethernet comments

Cl 55 SC 55.3.6.1 P199 L 54 # 229
 Brown, Matthew Applied Micro (AMCC)
 Comment Type GR Comment Status X
 Status definitions for MDIO 3.1.8 and 3.1.9 not defined.
 SuggestedRemedy
 Add section 55.3.6.1 along with instructions to include the following text. Use the text from Clause 49.2.14.1.
 Proposed Response Response Status O

Cl 55 SC 55.4.1 P206 L 23 # 233
 Brown, Matthew Applied Micro (AMCC)
 Comment Type ER Comment Status X
 Figure 55-17. missing connection of scr_status/pcs_status signal to LINK MONITOR block. This is an error in the base specification that 802.3az already corrected in Figure 55.3.
 SuggestedRemedy
 Add line from scr_status/pcs_status line to LINK MONITOR block.
 Proposed Response Response Status O

Cl 55 SC 55.4.2.2.1 P207 L 35 # 234
 Brown, Matthew Applied Micro (AMCC)
 Comment Type ER Comment Status X
 xPR_Master and xPR_Master used with mixed case and lower case (55.4.2.4) only in Clause 55. No need for fancy-dancy mixed case. :)
 SuggestedRemedy
 Change all to lower case.
 Proposed Response Response Status O

Cl 55 SC 55.4.2.5.14 P209 L 32 # 235
 Brown, Matthew Applied Micro (AMCC)
 Comment Type GR Comment Status X
 spelling
 SuggestedRemedy
 change "start" to "starts"
 Proposed Response Response Status O

Cl 55 SC 55.4.2.5.15 P209 L 42 # 359
 Ganga, Ilango Intel Corporation
 Comment Type TR Comment Status X
 The effect Clause 55 Fast Retrain on the Reconciliation Sublayer & MAC is unclear. Fast Retrain mechanism should be specified in a such a way that it does not indicate link down/link failure to the higher layers and also does not cause any data loss (that may cause packet drops). When the PHY Control State Diagram exits the PCS Data state to enter PMA_INIT_FR, it is unclear what action the PHY will take with respect to the XGMII path to the MAC. If PHY sends Local Fault up to the XGMII (i.e., if block_lock is lost, forcing the Local Fault ordered set) then the MAC will see this as a loss of link and this will be very disruptive to the System. The Fast Retrain mechanism is 'fast' enough to allow for recovery without sending alarms to higher functions. However, if the fast retrain is not signaled to the MAC, then the MAC may continue to send data that will be lost. It is also undesirable to drop 30msec of data without notification.
 SuggestedRemedy
 Fast Retrain mechanism should be specified in such a way that it does not cause a Local Fault (or signal link down to higher layers). The mechanism should also prevent the MAC from transmitting data during the retrain period to avoid any data loss or packet drops.
 Proposed Response Response Status O

Cl 55 SC 55.4.2.6a P210 L 20 # 237
 Brown, Matthew Applied Micro (AMCC)
 Comment Type ER Comment Status X
 Editorial instruction for 55.4.2.6a is in wrong place.
 SuggestedRemedy
 Move editorial instruction to above sub-clause 55.4.2.6a title.
 Proposed Response Response Status O

Comments received

IEEE P802.3az D3.0 Energy Efficient Ethernet comments

CI 55 SC 55.4.25.14 P209 L37 # 236
 Brown, Matthew Applied Micro (AMCC)
 Comment Type GR Comment Status X
 The receive is under control of link partner and transmit is under control of local LPI client.
 SuggestedRemedy
 Change sentence to "After reaching the PCS_Data state, PHYs with the EEE capability can transition the receiver to LPI mode under control of the link partner and can transition the transmitter to LPI mode under control of the local LPI client."
 Proposed Response Response Status O

CI 55 SC 55.4.5.1 P211 L15 # 153
 Parnaby, Gavin Solarflare Communicat
 Comment Type E Comment Status X
 The sentence says there are four variables.
 There are 6 variables listed.
 SuggestedRemedy
 Change the text to say 'The following six variables...'.
 Proposed Response Response Status O

CI 55 SC 55.4.5.1 P211 L22 # 238
 Brown, Matthew Applied Micro (AMCC)
 Comment Type GR Comment Status X
 Since fast retrain is initiated both locally and remotely, keep local and remote entities clear.
 SuggestedRemedy
 Change "the receiver" to "the local receiver".
 Proposed Response Response Status O

CI 55 SC 55.4.5.1 P211 L26 # 239
 Brown, Matthew Applied Micro (AMCC)
 Comment Type GR Comment Status X
 Since fast retrain is initiated both locally and remotely, keep local and remote entities clear.
 SuggestedRemedy
 Change "the receiver" to "the local receiver".
 Proposed Response Response Status O

CI 55 SC 55.4.5.1 P211 L38 # 240
 Brown, Matthew Applied Micro (AMCC)
 Comment Type GR Comment Status X
 Clarify that flag is set after not during sending/receiving of signal. Also, signal is elsewhere referred to as link failure signal not fast_retrain signal.
 SuggestedRemedy
 Change definition of fast_retrain_flag to "Set TRUE after the PHY generates or detects a link failure signal and set FALSE otherwise."
 Proposed Response Response Status O

CI 55 SC 55.4.5.4 P201 L14 # 230
 Brown, Matthew Applied Micro (AMCC)
 Comment Type TR Comment Status X
 Figure 55-15.
 SuggestedRemedy
 Three arrow ends need to be fixed.
 Proposed Response Response Status O

Comments received

IEEE P802.3az D3.0 Energy Efficient Ethernet comments

Cl 55 SC 55.4.5.4 P205 L18 # 231
 Brown, Matthew Applied Micro (AMCC)
 Comment Type GR Comment Status X
 Figure 55-16b. Initialization of tx_lpi_initial_quiet is not required in SEND_SLEEP since this variable is only effective when tx_lpi_qr_active is TRUE.
 SuggestedRemedy
 Delete "tx_lpi_initial_quiet=TRUE" in SEND_SLEEP state.
 Proposed Response Response Status O

Cl 55 SC 55.4.5.4 P212 L21 # 242
 Brown, Matthew Applied Micro (AMCC)
 Comment Type GR Comment Status X
 Indicate that counter is reflected in register...
 SuggestedRemedy
 Add "This counter is reflected in MDIO register 1.147.15:11 specified in sub-clause 45.2.76a.3."
 Proposed Response Response Status O

Cl 55 SC 55.4.5.4 P205 L47 # 232
 Brown, Matthew Applied Micro (AMCC)
 Comment Type ER Comment Status X
 missing underscore
 SuggestedRemedy
 change "lpi_wake_timer done" to "lpi_wake_timer_done".
 Proposed Response Response Status O

Cl 55 SC 55.4.6 P213 L46 # 154
 Parnaby, Gavin Solarflare Communicat
 Comment Type T Comment Status X
 The transition from PCS_Data due to a fast retrain should be qualified with minwait_timer_done, in the same manner as a normal retrain.
 SuggestedRemedy
 Change the transition from PCS_Data to PMA_INIT_FR to fast_retrain_flag * minwait_timer_done
 Also note that in several places in Figure 55-24 minwait_timer_done is shown as minwait timer_done; this should be corrected.
 Proposed Response Response Status O

Cl 55 SC 55.4.5.4 P212 L16 # 241
 Brown, Matthew Applied Micro (AMCC)
 Comment Type GR Comment Status X
 Indicate that counter is reflected in register...
 SuggestedRemedy
 Add "This counter is reflected in MDIO register 1.147.10:6 specified in sub-clause 45.2.76a.2."
 Proposed Response Response Status O

Cl 55 SC 55.4.6.1 P213 L36 # 244
 Brown, Matthew Applied Micro (AMCC)
 Comment Type GR Comment Status X
 State of THP coefficients is for a fast re-train. Coincidentally, they are not specified for normal retrain in the 802.3-2008, either. The generally accepted THP coefficient state for normal re-train is zeros. For fast retrain specify that initialization to zeros is required for robust adaptation. A separate comment is submitted to request THP initial state for normal training.
 SuggestedRemedy
 Specify that THP coefficients, THP_tx are set to zero at the beginning of fast. In PMA_INIT_FR states add "THP_tx = zeros". Add the following in 55.4.2.5.14. During fast retrain, prior to entering the PMA_Coeff_Exch state, the THP coefficients will be set to zero." or similar text.
 Proposed Response Response Status O

Cl 55 SC 55.4.6.1 P213 L36 # 245
Brown, Matthew Applied Micro (AMCC)

Comment Type GR Comment Status X

State of THP coefficients is not specified for normal retrain in the 802.3-2008. The generally accepted THP coefficient state for normal re-train is zeros. For normal training initialization to zeros is required for consistent adaptation.

SuggestedRemedy

Specify that THP coefficients, THP_tx are set to zero at the beginning of normal training. In SILENT states add "THP_tx = zeros". Add the following in 55.4.2.5.14. During normal training, prior to enabling the transmitter, the THP coefficients will be set to zero." or similar text.

Proposed Response Response Status O

Cl 55 SC 55.4.6.1 P213 L37 # 243
Brown, Matthew Applied Micro (AMCC)

Comment Type TR Comment Status X

During a fast retrain, a new PBO is not exchange so PBO_next is not explicitly defined. Statement is required to indicate the intended value for PBO_next for fast retrain.

SuggestedRemedy

In sub-clause 55.4.5.1 modify the definition for PBO_next by adding the following statement. "When fast retrain is invoked PBO_next will have the same value as resolved during normal training."

Proposed Response Response Status O

Cl 55 SC 55.4.6.2 P215 L15 # 247
Brown, Matthew Applied Micro (AMCC)

Comment Type TR Comment Status X

Figure 55-26. Target value for transition count should be better defined. For normal retrain a value of 2^6 should always be used and for fast retrain a value of 2^4 should always be used. The note at the bottom says that if fast retrain is enable the value should be 2^4, however a normal train can occur with fast retrain enabled. The intent is that the counter should be set to 2^4 if fast retrain is occurring.

SuggestedRemedy

Change "master_transition_count > 2^6" to "master_transition_count > stc" in two state transitions. In section 55.4.5.1 specify a new variable stc defined as: "stc is the target transition count for a SLAVE PHY during normal training and fast retraining. stc shall be equal to 2^6 for normal training and 2^4 for fast retrain."

Proposed Response Response Status O

Cl 55 SC 55.4.6.2 P215 L15 # 246
Brown, Matthew Applied Micro (AMCC)

Comment Type TR Comment Status X

Figure 55-25. Value for transition count initialization should be better defined. For normal retrain a value of 2^9 should always be used and for fast retrain a value of 2^5 should always be used. The note at the bottom says that if fast retrain is enable the value should be 2^5, however a normal train can occur with fast retrain enabled. The intent is that the counter should be set to 2^5 if fast retrain is occurring.

SuggestedRemedy

Change "transition_count <= 2^9" to "transition_count<=mtc" in three states. In section 55.4.5.1 specify a new variable mtc defined as: "mtc is the transition count for a MASTER PHY during normal training and fast retraining. mtc shall be equal to 2^9 for normal training and 2^5 for fast retrain."

Proposed Response Response Status O

Comments received

IEEE P802.3az D3.0 Energy Efficient Ethernet comments

Cl 55 **SC 55.4.6.5** **P217** **L 34** # **1**
 Anslow, Peter Ciena Corporation
Comment Type **E** **Comment Status** **X**
 Comment 9 against D 2.3 was not fully implemented
SuggestedRemedy
 In the editing instruction "Insert a new subclause 55.4.6.5, containing Figure 55-27b, after subclause 55.3.6.4, , as shown below" there is a double comma and the last subclause number is wrong.
 Change "subclause 55.3.6.4, , as" to "subclause 55.4.6.4, as"
Proposed Response **Response Status** **O**

Cl 55 **SC 55.4.6.5** **P218** **L 22** # **248**
 Brown, Matthew Applied Micro (AMCC)
Comment Type **GR** **Comment Status** **X**
 Figure 55-27b and Figure 55-24, For consistency all timers should be in figure 55-24. Starting of the fr_maxwait_timer should be placed in the PHY control state machine Figure 55-24.
SuggestedRemedy
 In figure 55-27b delete "start fr_maxwait_timer" in FR_START_TIMER state. Rename FR_START_TIMER state to FR_START. In figure 55-24, add "start fr_maxwait_timer" to PMA_INIT_FR state.
Proposed Response **Response Status** **O**

Cl 55 **SC 55.6.1** **P219** **L 28** # **250**
 Brown, Matthew Applied Micro (AMCC)
Comment Type **GR** **Comment Status** **X**
 Consistent terminology.
SuggestedRemedy
 change "advertise phy as supporting fast retrain" to "Advertise fast retrain capability."
 change "advertise phy as not supporting fast retrain" to "Not advertise fast retrain."
Proposed Response **Response Status** **O**

Cl 55 **SC 55.6.1** **P219** **L 9** # **249**
 Brown, Matthew Applied Micro (AMCC)
Comment Type **GR** **Comment Status** **X**
 Definition of next page attributes is WRT local PHY.
SuggestedRemedy
 Change "link partner is advertising" to "Advertising". change "link partner is not advertising" to "Not advertising."
Proposed Response **Response Status** **O**

Cl 69 **SC 69.2.3** **P223** **L 31** # **251**
 Brown, Matthew Applied Micro (AMCC)
Comment Type **GR** **Comment Status** **X**
 Table 69-1. Clause 78 not listed.
SuggestedRemedy
 Add clause 78 to Table 69-1.
Proposed Response **Response Status** **O**

Cl 69 **SC 69.2.3** **P223** **L 42** # **308**
 Dambrosia, John Force10 Networks
Comment Type **TR** **Comment Status** **X**
 Clause 81 has nothing to do with 1000BASE-KX, 10GBASE-KX4, and 10GBASE-KR
SuggestedRemedy
 Delete optional entry for Clause 81 RS to 1000BASE-KX, 10GBASE-KX4, and 10GBASE-KR.
Proposed Response **Response Status** **O**

Comments received

IEEE P802.3az D3.0 Energy Efficient Ethernet comments

Cl 69 SC 69.2.3 P223 L46 # 307
 Dambrosia, John Force10 Networks
 Comment Type **TR** Comment Status **X**
 Clause 82 is mandatory - not optional for 40GBASE-KR4
 SuggestedRemedy
 Change optional entry to mandatory entry for Clause 82 (40GBASE-R PCS) for 40GBASE-KR4
 Proposed Response Response Status **O**

Cl 69 SC 69.2.3 P223 L46 # 309
 Dambrosia, John Force10 Networks
 Comment Type **TR** Comment Status **X**
 Clause 81 XLGMII is not mandatory for 40GBASE-KR4. It is an optional physical interface.
 SuggestedRemedy
 Change mandatory entry to optional entry for Clause 81 (XLGMII) for 40GBASE-KR4
 Proposed Response Response Status **O**

Cl 69 SC 69.2.6 P224 L3 # 310
 Dambrosia, John Force10 Networks
 Comment Type **TR** Comment Status **X**
 The statement -"With the optional EEE feature, described in Clause 78, the Backplane Ethernet PHYs can achieve lower is not accurate for EEE, as EEE only applies to Backplane Ethernet PHYs for 10Gb/s or lower power consumption
 SuggestedRemedy
 Modify statement to read -With the optional EEE feature, described in Clause 78, Backplane Ethernet PHYs for 10Gb/s or lower can achieve lower power consumption.
 Proposed Response Response Status **O**

Cl 70 SC 70.10.4.1 P229 L31 # 337
 Dambrosia, John Force10 Networks
 Comment Type **TR** Comment Status **X**
 no SHALL statement for FS10
 SuggestedRemedy
 add corresponding shall statement
 Proposed Response Response Status **O**

Cl 70 SC 70.10.4.1 P229 L35 # 260
 Brown, Matthew Applied Micro (AMCC)
 Comment Type **GR** Comment Status **X**
 PICS for tranmit enable/disable times/amplitudes from 70.7.1.5 is missing.
 SuggestedRemedy
 Add PICS for transmit enable/disable times.
 Proposed Response Response Status **O**

Cl 70 SC 70.10.4.1 P229 L35 # 259
 Brown, Matthew Applied Micro (AMCC)
 Comment Type **GR** Comment Status **X**
 PICS for receive signal detect assert and de-assert times from 70.7.2 and 70.6.4 is missing.
 SuggestedRemedy
 Add PICS for signal detect assert and de-assert times.
 Proposed Response Response Status **O**

Cl 70 SC 70.2 P225 L40 # 252
 Brown, Matthew Applied Micro (AMCC)
 Comment Type **ER** Comment Status **X**
 "PMD receive" used elsewhere
 SuggestedRemedy
 change PMD's to PMD.
 Proposed Response Response Status **O**

Comments received

IEEE P802.3az D3.0 Energy Efficient Ethernet comments

Cl 70 SC 70.6.5 P226 L21 # 336
 Dambrosia, John Force10 Networks
 Comment Type **TR** Comment Status **X**
 no PICS for SHALL statements for bullets a and D
 SuggestedRemedy
 add corresponding PIC statements
 Proposed Response Response Status **O**

Cl 70 SC 70.7.1.5 P227 L53 # 86
 Turner, Edward J Gnodal Ltd
 Comment Type **E** Comment Status **X**
 Missing space before units.
 SuggestedRemedy
 Add space before 'mV' and 'ns'.
 Proposed Response Response Status **O**

Cl 70 SC 70.7.1.5 P227 L49 # 300
 Healey, Adam LSI Corporation
 Comment Type **TR** Comment Status **X**
 The requirements of 70.7.1.5 ensure that the transmitter will provide a signal with sufficient amplitude to trigger the receiver signal detect function. It offers the receiver designer no guidance as to when the transmitter output will be fully compliant (amplitude, jitter, etc.).
 SuggestedRemedy
 Define the maximum time the transmitter is allowed, following the assertion of tx_quiet = FALSE, to obtain full compliance. This value is proposed to be 5 microseconds. The values in Table 78-4 must be updated to align with this allowance as this considered to be part of the transmitter's wake time shrinkage. Include a row in Table 70-4 for this value.
 Proposed Response Response Status **O**

Cl 71 SC 71.1 P230 L13 # 87
 Turner, Edward J Gnodal Ltd
 Comment Type **T** Comment Status **X**
 Unclear what is being deactivated in the expression : ' .. ceases transmission and deactivates transmit to conserve energy'.
 SuggestedRemedy
 Insert 'functions' after 'deactivates transmit'
 Proposed Response Response Status **O**

Cl 70 SC 70.7.1.5 P227 L51 # 301
 Healey, Adam LSI Corporation
 Comment Type **TR** Comment Status **X**
 The transmitter is required to transmit a differential peak-to-peak output greater than 800 mV within 500 ns following a tx_quiet being set to false. However, the output voltage during normal operation is allowed to be as low as 800 mV (per Table 70-6). It makes no sense to force the voltage at the start of wake to be greater than the minimum.
 SuggestedRemedy
 Moreover, the output amplitude should only be as large as needed to trigger the receiver signal detect function. In other clauses, this is less than the minimum value during normal operation. Suggest that the value be 700 mV peak-to-peak differential.
 Proposed Response Response Status **O**

Cl 71 SC 71.10.4.2 P234 L31 # 338
 Dambrosia, John Force10 Networks
 Comment Type **TR** Comment Status **X**
 no SHALL statement for FS18
 SuggestedRemedy
 add corresponding shall statement
 Proposed Response Response Status **O**

Cl 71 SC 71.10.4.2 P234 L35 # 264
 Brown, Matthew Applied Micro (AMCC)
 Comment Type **GR** Comment Status **X**
 PICS for transmit enable/disable times/amplitudes from 71.7.2 is missing.
 SuggestedRemedy
 Add PICS for transmit enabled/disabled times.
 Proposed Response Response Status **O**

Comments received

IEEE P802.3az D3.0 Energy Efficient Ethernet comments

Cl 71 SC 71.10.4.2 P234 L35 # 263
 Brown, Matthew Applied Micro (AMCC)
 Comment Type GR Comment Status X
 PICS for receive signal detect assert and de-assert times from 71.7.1.4 is missing.
 SuggestedRemedy
 Add PICS for signal detect assert and de-assert times.
 Proposed Response Response Status O

Cl 71 SC 71.6.12.1.3 P232 L7 # 91
 Turner, Edward J Gnodal Ltd
 Comment Type E Comment Status X
 Missing determiners.
 SuggestedRemedy
 Insert 'the' before 'PCS' and 'the' before 'local receiver'.
 Proposed Response Response Status O

Cl 71 SC 71.6.12 P231 L29 # 89
 Turner, Edward J Gnodal Ltd
 Comment Type ER Comment Status X
 Incorrect reference to backplane auto-neg.
 SuggestedRemedy
 Change 'Clause 45' to 'Clause 73'
 Proposed Response Response Status O

Cl 71 SC 71.6.6 P231 L17 # 88
 Turner, Edward J Gnodal Ltd
 Comment Type E Comment Status X
 Two occurrences of 'specified in' one after another.
 SuggestedRemedy
 Delete one occurrence.
 Proposed Response Response Status O

Cl 71 SC 71.6.12 P231 L31 # 90
 Turner, Edward J Gnodal Ltd
 Comment Type E Comment Status X
 Missing apostrophe before 's' of 'link partners'.
 SuggestedRemedy
 Insert apostrophe.
 Proposed Response Response Status O

Cl 71 SC 71.7.1.4 P232 L40 # 302
 Healey, Adam LSI Corporation
 Comment Type TR Comment Status X
 The requirements of 71.7.1.4 ensure that the transmitter will provide a signal with sufficient amplitude to trigger the receiver signal detect function. It offers the receiver designer no guidance as to when the transmitter output will be fully compliant (amplitude, jitter, etc.).
 SuggestedRemedy
 Define the maximum time the transmitter is allowed, following the assertion of tx_quiet = FALSE, to obtain full compliance. This value is proposed to be 5 microseconds. The values in Table 78-4 must be updated to align with this allowance as this considered to be part of the transmitter's wake time shrinkage. Include a row in Table 71-4 for this value.
 Proposed Response Response Status O

Cl 71 SC 71.6.12 P231 L37 # 262
 Brown, Matthew Applied Micro (AMCC)
 Comment Type ER Comment Status X
 service primitives are listed in the wrong section. move to 71.2.
 SuggestedRemedy
 Move primitives (page 231 line 37 to page 232 line 31) to the end of section 71.2.
 Proposed Response Response Status O

Comments received

IEEE P802.3az D3.0 Energy Efficient Ethernet comments

Cl 71 SC 71.7.1.4 P232 L41 # 92
 Turner, Edward J Gnodal Ltd
 Comment Type E Comment Status X
 Missing spaces before units.
 SuggestedRemedy
 Insert spaces before 'mV' (two instances) and 'ns' (two instances).
 Proposed Response Response Status O

Cl 71 SC 71.7.1.4 P232 L43 # 303
 Healey, Adam LSI Corporation
 Comment Type TR Comment Status X
 The transmitter is required to transmit a differential peak-to-peak output greater than 800 mV within 500 ns following a tx_quiet being set to false. However, the output voltage during normal operation is allowed to be as low as 800 mV (per Table 71-4). It makes no sense to force the voltage at the start of wake to be greater than the minimum.
 SuggestedRemedy
 Moreover, the output amplitude should only be as large as needed to trigger the receiver signal detect function. In other clauses, this is less than the minimum value during normal operation. Suggest that the value be 700 mV peak-to-peak differential.
 Proposed Response Response Status O

Cl 72 SC 72 P235 L1 # 265
 Brown, Matthew Applied Micro (AMCC)
 Comment Type GR Comment Status X
 Throughout Clause 72 "low power mode" is used to refer to what is more technically "low power idle mode" or "LPI mode". Note that a "low power" mode is defined for all 802.3 PHYs and is invoked by setting MDIO bit 1.0.11 to 1.
 SuggestedRemedy
 Change all references to "low power mode" to "LPI mode".
 Proposed Response Response Status O

Cl 72 SC 72.1 P235 L19 # 129
 Healey, Adam LSI Corporation
 Comment Type E Comment Status X
 It was decided that the "low power state" should be referred to as "low power idle (LPI) mode." The GMII signal is labeled "Assert LPI" and not "Assert Low Power Idle" or "Assert PMD_LPI". There is no clear definition of what "sleep symbols" are.
 SuggestedRemedy
 Change paragraph as follows. "A 10GBASE-KR PHY with the optional Energy Efficient Ethernet (EEE) capability may optionally enter the Low Power Idle (LPI) mode to conserve energy during periods of low link utilization. The "Assert LPI" request at the XGMII is encoded in the transmitted symbols. Detection of LPI signaling in the received symbols is indicated as "Assert LPI" at the XGMII. Upon the detection of "Assert LPI" at the XGMII, an Energy Efficient 10GBASE-KR PHY continues transmitting for a pre-defined period, then ceases transmission and deactivates transmit functions to conserve energy. The PHY periodically transmits during this quiet period to allow the remote PHY to refresh its receiver state (e.g. timing recovery, adaptive filter coefficients) and thereby track long term variation in the timing of the link or the underlying channel characteristics. If, during the quiet or refresh periods, normal inter-frame is asserted at the XGMII, the PHY re-activates transmit functions and initiates transmission. This transmission will be detected by the remote PHY, causing it to also exit the LPI mode." In addition, scrub the rest of the clause for instances of "low power mode" and replace them with "LPI mode".
 Proposed Response Response Status O

Cl 72 SC 72.10.4.2 P240 L35 # 339
 Dambrosia, John Force10 Networks
 Comment Type TR Comment Status X
 no SHALL statement for FS12
 SuggestedRemedy
 add corresponding shall statement
 Proposed Response Response Status O

Comments received

IEEE P802.3az D3.0 Energy Efficient Ethernet comments

CI 72 SC 72.6 P236 L11 # 132
 Healey, Adam LSI Corporation
 Comment Type T Comment Status X
 For the "PRESET" state, "preset" is not capitalized. In addition, a cross-reference to 72.6.10.2.3.1 would directly lead the reader to a better definition of the preset state than the currently referenced 72.6.10.3.4.
 SuggestedRemedy
 Per comment.
 Proposed Response Response Status O

CI 72 SC 72.6.10.1 P237 L29 # 94
 Turner, Edward J Gnodal Ltd
 Comment Type E Comment Status X
 Missing apostrophe before 's' of 'link partners'.
 SuggestedRemedy
 Insert apostrophe.
 Proposed Response Response Status O

CI 72 SC 72.6.11 P237 L28 # 272
 Brown, Matthew Applied Micro (AMCC)
 Comment Type GR Comment Status X
 link partner is by definition remote
 SuggestedRemedy
 change "remote link partner's" to "link partner's"
 Proposed Response Response Status O

CI 72 SC 72.6.11 P237 L32 # 136
 Healey, Adam LSI Corporation
 Comment Type T Comment Status X
 The primitives should be defined as part of the PMD service interface (72.2).
 SuggestedRemedy
 Strike lines 32 through 36. Move 72.6.11.2 and 72.6.11.2 to 72.2.
 Proposed Response Response Status O

CI 72 SC 72.6.11 P237 L32 # 273
 Brown, Matthew Applied Micro (AMCC)
 Comment Type GR Comment Status X
 PMD service interface parameters belong in 72.2
 SuggestedRemedy
 On page 235, delete lines 50 to 54. Move definitions from 72.6.11 (page 237 line 32 to page 238 line 28) to section 7.2.
 Proposed Response Response Status O

CI 72 SC 72.6.11.1.2 P237 L51 # 275
 Brown, Matthew Applied Micro (AMCC)
 Comment Type GR Comment Status X
 definition isn't clear, also is a request
 SuggestedRemedy
 Change definition to "The PCS generates this primitive to request the appropriate PMD receive LPI state."
 Proposed Response Response Status O

Comments received

IEEE P802.3az D3.0 Energy Efficient Ethernet comments

Cl 72 **SC 72.6.11.1.2** **P237** **L 52** # **274**
 Brown, Matthew Applied Micro (AMCC)
Comment Type **GR** **Comment Status** **X**
 Sentence does not make sense.
SuggestedRemedy
 Replace with: "The PCS generates this primitive to indicate the current receive LPI state"
Proposed Response **Response Status** **O**

Cl 72 **SC 72.6.11.2.2** **P238** **L 21** # **276**
 Brown, Matthew Applied Micro (AMCC)
Comment Type **GR** **Comment Status** **X**
 definition isn't clear, also is a request
SuggestedRemedy
 Change definition to "The PCS generates this primitive to request the appropriate PMD transmit LPI state."
Proposed Response **Response Status** **O**

Cl 72 **SC 72.6.2** **P236** **L 10** # **93**
 Turner, Edward J Gnodal Ltd
Comment Type **E** **Comment Status** **X**
 Missing determiner.
SuggestedRemedy
 Insert 'the' before 'PMD'.
Proposed Response **Response Status** **O**

Cl 72 **SC 72.6.4** **P236** **L 20** # **135**
 Healey, Adam LSI Corporation
Comment Type **E** **Comment Status** **X**
 This sentence would read better if broken into two separate sentences.
SuggestedRemedy
 Change as follows. "PMD_SIGNAL.indication is used by 10GBASE-KR to indicate the successful completion of the start-up protocol. When the PHY supports the optional EEE capability, PMD_SIGNAL.indication is also used to indicate when the ALERT signal is detected which corresponds to the beginning of a refresh or a wake."
Proposed Response **Response Status** **O**

Cl 72 **SC 72.6.4** **P236** **L 23** # **269**
 Brown, Matthew Applied Micro (AMCC)
Comment Type **GR** **Comment Status** **X**
 EEE terminology.
SuggestedRemedy
 change "EEE is implemented" to "EEE is supported".
Proposed Response **Response Status** **O**

CI 72 SC 72.6.4 P236 L27 # 137
Healey, Adam LSI Corporation

Comment Type TR Comment Status X

The behavior of the PMD signal detect function for the optional EEE capability is not completely defined. While the alert pattern and transmitter state are defined in 72.6.2, the electrical properties of the signal are not defined. The transmitter output properties of 72.7.1.4 should be combined with some notion of a channel in order to completely define the requirements. In addition, the signal detect activation and deactivation times are sequestered in Table 72-9. The cross-reference from Table 72-9 incorrectly points to 72.6.5 which pertains the PMD transmit disable function. There is no reference in 72.6.4 to Table 72-9. This information should be more closely associated with the definition of signal detect.

SuggestedRemedy

Change the paragraph as follows. "The value of the SIGNAL_DETECT is defined by the training state diagram shown in Figure 72--5. When the PHY supports the optional EEE capability, SIGNAL_DETECT is set to FAIL following a transition from rx_mode = DATA to rx_mode = QUIET. When rx_mode = QUIET, signal_detect shall be set to OK within 500 ns following the application of a square wave pattern with a period of 16 unit intervals and peak-to-peak differential output amplitude of TBD mV to the receiver input." A presentation will be provided with the proposed value for the square wave amplitude "TBD". Update Table 72-9 with the defined square wave amplitude and signal detect activation time, correcting the cross-reference to be 72.6.4. Remove the requirement for signal detect de-assertion time from Table 72-9 since as it is irrelevant.

Proposed Response Response Status O

CI 72 SC 72.6.4 P236 L35 # 270
Brown, Matthew Applied Micro (AMCC)

Comment Type GR Comment Status X

EEE terminology.

SuggestedRemedy

change "EEE is not implemented" to "EEE is not supported".

Proposed Response Response Status O

CI 72 SC 72.6.5 P236 L45 # 271
Brown, Matthew Applied Micro (AMCC)

Comment Type TR Comment Status X

Transmitter output is not specified during LPI QUIET period.

SuggestedRemedy

Modify item a) with new text delimited by <> as follows: "variable is set to ONE <or tx_mode is QUIET>, this function..."

Proposed Response Response Status O

CI 72 SC 72.7.1.4 P238 L39 # 134
Healey, Adam LSI Corporation

Comment Type TR Comment Status X

The requirements of 72.7.1.4 ensure that the transmitter will provide a signal with sufficient amplitude to alert the receiver signal detect function. It offers the receiver designer no guidance as to when the transmitter output will be fully compliant (amplitude, jitter, etc.).

SuggestedRemedy

Define the maximum time the transmitter is allowed, following the assertion of tx_mode = ALERT, to obtain full compliance. This value is proposed to be 5 microseconds. The values in Table 78-4 must be updated to align with this allowance as this considered to be part of the transmitter's wake time shrinkage. Include a row in Table 72-6 for this value.

Proposed Response Response Status O

CI 72 SC 72.7.1.4 P238 L 39 # 133
 Healey, Adam LSI Corporation

Comment Type TR Comment Status X

The definition of the transmitter wake signal is flawed. It specifies that the transmitter's differential peak-to-peak amplitude shall be greater than 90% of trained peak-to-peak value within 500 ns of tx_mode being set to ALERT. However, 72.6.2 specifies that the transmitter will be placed in the preset state (c(0) is maximum, c(-1) and c(+1) are zero) when tx_mode = ALERT. Referencing the amplitude of the preset waveform to the amplitude of the post-training waveform adds a degree of uncertainty with respect to what amplitude will actually be delivered to the receiver. Furthermore, a receiver will be required to accomodate the worst-case (lowest) amplitude that a link partner will deliver. In light of this, it makes sense to simply define an absolute minimum output voltage that must be achieved within 500 ns. Per Table 72-8, we know that the amplitude v2 must be within 400 to 600 mV ((zero-to-peak differential) for the preset condition. In this case 90% of the minimum value would be 360 mV. This is an equivalent yet unambiguous threshold.

SuggestedRemedy

Change the requirement as follows. "Furthermore, the transmitter's differential peak-to-peak output voltage shall be greater than 700 mV within 500 ns of tx_mode being set to ALERT." [Rounded down from 720 mV.] Include a row in Table 72-6 for this value and the transmitter partial activation time.

Proposed Response Response Status O

CI 72 SC 72.7.1.4 P238 L 39 # 95
 Turner, Edward J Gnodal Ltd

Comment Type E Comment Status X

Missing space before units.

SuggestedRemedy

Insert space before 'mV' and 'ns' (two instances).

Proposed Response Response Status O

CI 72 SC 72.7.1.4 P238 L 43 # 277
 Brown, Matthew Applied Micro (AMCC)

Comment Type GR Comment Status X

maximum voltage level during QUIET mode is not specified

SuggestedRemedy

add sentence "While in LPI QUIET mode, the PMD output voltage shall be no larger than the maximum specified for TX disabled in Table 72-6." Add PICs statement in 72.10.

Proposed Response Response Status O

CI 74 SC 74.4.1 P241 L 23 # 280
 Brown, Matthew Applied Micro (AMCC)

Comment Type GR Comment Status X

Figure 74-2. LPI blocks appears to be part of receiver but includes transmit and receiver functions.

SuggestedRemedy

Move LPI block outside of the receive block.

Proposed Response Response Status O

CI 74 SC 74.4.1 P241 L 29 # 283
 Brown, Matthew Applied Micro (AMCC)

Comment Type GR Comment Status X

Figure 74-2. Primitives between FEC and PMA should be prefixed with PMA not FEC

SuggestedRemedy

On LPI primitives between FEC and PMA replace "FEC_" with "PMA_".

Proposed Response Response Status O

Comments received

IEEE P802.3az D3.0 Energy Efficient Ethernet comments

CI 74 SC 74.4.1 P241 L29 # 282
 Brown, Matthew Applied Micro (AMCC)
 Comment Type GR Comment Status X
 Figure 74-2. Primitives between FEC and PCS should be prefixed with FEC not PCS.
 SuggestedRemedy
 On LPI primitives between FEC and PCS, replace "PCS_" with "FEC_".
 Proposed Response Response Status O

CI 74 SC 74.4.1 P241 L39 # 281
 Brown, Matthew Applied Micro (AMCC)
 Comment Type GR Comment Status X
 Figure 74-2. FEC_LPI_ACTIVE is not required between PMA and FEC.
 SuggestedRemedy
 Delete FEC_LPI_ACTIVE signal between PMA and FEC.
 Proposed Response Response Status O

CI 74 SC 74.4.1 P241 L46 # 127
 Healey, Adam LSI Corporation
 Comment Type TR Comment Status X
 The are multiple problems with this figure. Service interface primitives between the PCS and FEC sublayers should be labeled FEC_TX_MODE, FEC_RX_MODE, FEC_LPI_ACTIVE, and FEC_ENERGY respectively. Service interface primitives between the FEC and PMA sublayers should be labeled PMA_TX_MODE, PMA_RX_MODE, and PMA_ENERGY respectively. There is no FEC[PMA]_LPI_ACTIVE.request between the FEC and PMA sublayers.
 SuggestedRemedy
 Correct the figure per the comment.
 Proposed Response Response Status O

CI 74 SC 74.5.1 P242 L11 # 126
 Healey, Adam LSI Corporation
 Comment Type T Comment Status X
 The editor's note indicates that Draft 2.3 of IEEE P802.3ba was used as the base document for the proposed changes. Update the changes to be consistent with the most recent draft of IEEE P802.3ba or the approved standard when available. Update the editor's note accordingly.
 SuggestedRemedy
 Per comment.
 Proposed Response Response Status O

CI 74 SC 74.5.1 P242 L21 # 284
 Brown, Matthew Applied Micro (AMCC)
 Comment Type ER Comment Status X
 new text
 SuggestedRemedy
 underline "FEC_ENERGY.indication(energy_detect)"
 Proposed Response Response Status O

CI 74 SC 74.5.1 P242 L22 # 128
 Healey, Adam LSI Corporation
 Comment Type ER Comment Status X
 Editorial instructions are sparse and there appears to be numerous sections of changed (actually inserted) text that are not underlined. Erroneously marked items include page 242, line 22, (item f should be underlined), page 22, line 24, ("Items d, e, . . ." should be underlined), page 242, line 31 (entire paragraph should be underlined or preceded by an insert instruction), page 242 line 38 (the instruction is insert 74.5.1.4 so the inserted content should not be underlined), and page 244, line 27 (the whole sentence should be underlined as it is all changed text).
 SuggestedRemedy
 Scrub the clause to ensure that the guidelines for editing instructions have been satisfied.
 Proposed Response Response Status O

Comments received

IEEE P802.3az D3.0 Energy Efficient Ethernet comments

Cl 74 SC 74.5.1.4 P242 L43 # 285
 Brown, Matthew Applied Micro (AMCC)
 Comment Type GR Comment Status X
 Remove details of signal detection as this not properly defined here and is already specified in the PMD.
 SuggestedRemedy
 Delete end of sentence " is set to ... otherwise".
 Proposed Response Response Status O

Cl 74 SC 74.5.1.8 P244 L10 # 289
 Brown, Matthew Applied Micro (AMCC)
 Comment Type GR Comment Status X
 preclude is the wrong word
 SuggestedRemedy
 change to "The FEC sub-layer will hold off asserting SIGNAL_OK..."
 Proposed Response Response Status O

Cl 74 SC 74.5.1.8 P243 L54 # 287
 Brown, Matthew Applied Micro (AMCC)
 Comment Type ER Comment Status X
 spelling
 SuggestedRemedy
 change "block" to "blocks"
 Proposed Response Response Status O

Cl 74 SC 74.5.1.8 P244 L10 # 288
 Brown, Matthew Applied Micro (AMCC)
 Comment Type ER Comment Status X
 space
 SuggestedRemedy
 add space in "standard.FEC"
 Proposed Response Response Status O

Cl 74 SC 74.5.1.8 P243 L54 # 286
 Brown, Matthew Applied Micro (AMCC)
 Comment Type GR Comment Status X
 spelling
 SuggestedRemedy
 change "FEC_UNIDATA" to "FEC_UNITDATA"
 Proposed Response Response Status O

Cl 74 SC 74.5.1.8 P244 L4 # 96
 Turner, Edward J Gnodal Ltd
 Comment Type E Comment Status X
 Use of 'usec' rather than 'microseconds' or 'us'.
 SuggestedRemedy
 Change to 'us'. Also on line 17.
 Proposed Response Response Status O

Cl 74 SC 74.5.1.8 P244 L10 # 97
 Turner, Edward J Gnodal Ltd
 Comment Type T Comment Status X
 The phrase 'FEC sub layer will precluded from asserting ..' is unclear.
 SuggestedRemedy
 Change to 'The FEC sublayer is prevented from asserting ..'
 Proposed Response Response Status O

Comments received

IEEE P802.3az D3.0 Energy Efficient Ethernet comments

Cl 74 SC 74.5.1.8 P244 L4 # 299
 Healey, Adam LSI Corporation

Comment Type TR Comment Status X

A hold-off of 30 microseconds seems too long. For a normal wake (not a wake from refresh) the FEC rapid block lock mechanism will receive the deterministic frames approximately 12 microseconds following the start of wake. If the rapid block lock mechanism fails to achieve lock during the 1 microsecond transmission of deterministic frames, it will be inhibited from setting signal_ok = TRUE for an additional 17 microseconds even if it has an alternate mechanism to obtain lock during that period. During this period, received frames are simply consumed by the PHY. The purpose of the hold-off is to prohibit the FEC sublayer from setting signal_ok prior to the deterministic frames being received so that those frames are never passed to the PCS for further processing. A hold-off of 13 microseconds would appear to be sufficient. With respect to the variable arrival of deterministic frames for the wake from refresh scenario, a separate comment has been submitted to alter to the transmitter behavior to make schedule for deterministic frame transmission to be deterministic. This proposal should be considered in conjunction with the proposed changes to the LPI state diagram.

SuggestedRemedy
 Per comment.

Proposed Response Response Status O

Cl 74 SC 74.8.4 P244 L27 # 340
 Dambrosia, John Force10 Networks

Comment Type TR Comment Status X

SHALL statement doesn't have appropriate PIC

SuggestedRemedy
 add appropriate PIC

Proposed Response Response Status O

Cl 78 SC 78 P262 L # 20
 Diab, Wael Broadcom

Comment Type TR Comment Status X

Clause 78 is missing PICS

SuggestedRemedy
 Please add PICS

Proposed Response Response Status O

Cl 78 SC 78.1 P246 L15 # 290
 Brown, Matthew Applied Micro (AMCC)

Comment Type E Comment Status X

unnecessary word

SuggestedRemedy
 Replace "the 10GBASE-T" with "10GBASE-T"

Proposed Response Response Status O

Cl 78 SC 78.1 P246 L22 # 291
 Brown, Matthew Applied Micro (AMCC)

Comment Type E Comment Status X

missing word

SuggestedRemedy
 Replace "also met" with "also be met"

Proposed Response Response Status O

Cl 78 SC 78.1 P256 L15 # 2
 Hajduczenia, Marek ZTE Corp.

Comment Type T Comment Status X

It should be stated clearly that EEE does not support optical PHYs.

SuggestedRemedy
 Add a sentence after second paragraph with the following text: 'EEE does not support operation over multimode or signlemode optical cabling'.

Proposed Response Response Status O

Comments received

IEEE P802.3az D3.0 Energy Efficient Ethernet comments

Cl 78 SC 78.1.1 P246 L33 # 3
 Hajduczenia, Marek ZTE Corp.

Comment Type T Comment Status X

'LPI signaling also informs the LPI Client that the link partner' > 'LPI signaling also informs the LPI Client when the link partner' - it is better to focus on the time aspect of the signalling rather than the fact that signalling was sent. In this way, you emphasize the timelyexchange of such information. This additionally goes well with the statements in 78.1.1.2

SuggestedRemedy
 per comment

Proposed Response Response Status O

Cl 78 SC 78.1.2.1.2 P246 L15 # 292
 Brown, Matthew Applied Micro (AMCC)

Comment Type TR Comment Status X

LPI_REQUEST is also ineffective when receiving REMOTE_FAULT. Note that sending REMOTE_FAULT is equivalent to receiving LOCAL_FAULT.

SuggestedRemedy
 Add "e) The PHY is receiving REMOTE_FAULT."

Proposed Response Response Status O

Cl 78 SC 78.1.2.1.3 P248 L18 # 4
 Hajduczenia, Marek ZTE Corp.

Comment Type T Comment Status X

'When this primitive should be generated by the LPI client is unspecified.' > 'Specification of the time, when this primitive is generated by the LPI client, is out of scope of the standard.'

SuggestedRemedy
 Better language offered per comment

Proposed Response Response Status O

Cl 78 SC 78.1.2.2.1 P248 L28 # 5
 Hajduczenia, Marek ZTE Corp.

Comment Type E Comment Status X

Strike 'has' from this sentence. Other sentences are written in past simple tense.

SuggestedRemedy
 Per comment

Proposed Response Response Status O

Cl 78 SC 78.1.3 P249 L30 # 6
 Hajduczenia, Marek ZTE Corp.

Comment Type TR Comment Status X

xMII is used as 'any of the family of medium independent interfaces' yet Figure 78-2 makes assumptions on the number of transmit/receive lanes. Suggest to indicate that the number of lanes might be different.

SuggestedRemedy
 Per comment

Proposed Response Response Status O

Cl 78 SC 78.1.3.3.1 P250 L23 # 293
 Brown, Matthew Applied Micro (AMCC)

Comment Type GR Comment Status X

Sending LPI indicates the tranmit process, not the system, is entering LPI mode.

SuggestedRemedy
 Change "the local system is entering" to "the local transmitter is entering".

Proposed Response Response Status O

Comments received

IEEE P802.3az D3.0 Energy Efficient Ethernet comments

Cl 78 SC 78.1.3.3.2 P251 L5 # 296
Brown, Matthew Applied Micro (AMCC)

Comment Type GR Comment Status X

The PHY indicates LPI when receiving the the SLEEP signal, much before ceasing transmission.

SuggestedRemedy

Change "When the Link partner has ceased transmission," to "When the receiver detects the SLEEP signal,".

Proposed Response Response Status O

Cl 78 SC 78.1.4 P251 L21 # 7
Hajduczenia, Marek ZTE Corp.

Comment Type T Comment Status X

Table 78-1 caption should be changed to read '802.3 PHY optionally supporting EEE'.
Table does not specify anything

SuggestedRemedy

per comment

Proposed Response Response Status O

Cl 78 SC 78.2 P251 L41 # 98
Turner, Edward J Gnodal Ltd

Comment Type TR Comment Status X

The definition of Ts is ambiguous.

SuggestedRemedy

Change to 'The period of time that the PHY transmits sleep before turning all transmitters off.'

Proposed Response Response Status O

Cl 78 SC 78.2 P251 L41 # 8
Hajduczenia, Marek ZTE Corp.

Comment Type E Comment Status X

'Duration PHY ...' > 'Period during which PHY ...'<CR>'Transmitter shrinkage time. Defined as the absolute time difference between the following two timing parameters:' >

'Transmitter shrinkage time is defined as the absolute time difference between the following two timing parameters:'<CR>'Receiver shrinkage time. Defined as the absolute time difference between the following two timing parameters:' > 'Receiver shrinkage time is defined as the absolute time difference between the following two timing parameters:'

SuggestedRemedy

Language improvements offered per comment

Proposed Response Response Status O

Cl 78 SC 78.2 P251 L42 # 99
Turner, Edward J Gnodal Ltd

Comment Type T Comment Status X

The definition of Tq is unclear.

SuggestedRemedy

Change to 'The period of time that the PHY remains quiet before sending the refresh signal.'

Proposed Response Response Status O

Cl 78 SC 78.2 P251 L44 # 294
Brown, Matthew Applied Micro (AMCC)

Comment Type GR Comment Status X

What is a "start of shell delimiter"? SSD is defined in 1.4.334 as "start of stream delimiter".

SuggestedRemedy

Replace "start of shell" with "start of stream". Two instances.

Proposed Response Response Status O

Comments received

IEEE P802.3az D3.0 Energy Efficient Ethernet comments

CI 78 SC 78.2 P251 L44 # 295
 Brown, Matthew Applied Micro (AMCC)
 Comment Type **TR** Comment Status **X**
 SSD is not defined for 10G PHYs. What should be used in its place?
 SuggestedRemedy
 I'm not sure what the right answer is.
 Proposed Response Response Status **O**

CI 78 SC 78.3 P252 L37 # 10
 Hajduczenia, Marek ZTE Corp.
 Comment Type **E** Comment Status **X**
 remove the word 'visually' - the following 'illustrates' says it all
 SuggestedRemedy
 Per comment
 Proposed Response Response Status **O**

CI 78 SC 78.2 P252 L27 # 138
 Healey, Adam LSI Corporation
 Comment Type **TR** Comment Status **X**
 The sleep (Ts), quiet (Tq), and refresh times (Tr) do not appear to be consistent with timers defined in Clause 49. For example, the sleep time is based on TSL (Table 49-2) is assigned a value 5 microseconds +/- 1%. Somehow this appears in Table 78-2 at 4.5 to 5.5 microseconds whereas it should be 4.95 to 5.05 microseconds.
 SuggestedRemedy
 Update the timers. A presentation will be provided that proposes the correct values.
 Proposed Response Response Status **O**

CI 78 SC 78.3 P252 L42 # 21
 Diab, Wael Broadcom
 Comment Type **ER** Comment Status **X**
 The requirement for EEE capability to be exchanged during Auto Neg always points back to 78.3 (e.g. 28C.12 and 28D.7). The language in 78.3 can be improved to include a shall.
 SuggestedRemedy
 Rewrite "The EEE capability is advertised during the Auto-Negotiation stage" to "The EEE capability shall be advertised during the Auto-Negotiation stage"
 Proposed Response Response Status **O**

CI 78 SC 78.2 P252 L4 # 9
 Hajduczenia, Marek ZTE Corp.
 Comment Type **T** Comment Status **X**
 'Parameter employed by the system which corresponds to the behavior of the PHY. It is suggest to remove these words. The following words are sufficient to describe what the parameter is and what does <CR><CR>Likewise, remove 'Parameter employed by the system which corresponds to its requirements. It is' in lines 8 and 11.
 SuggestedRemedy
 Per comment
 Proposed Response Response Status **O**

CI 78 SC 78.3 P252 L47 # 297
 Brown, Matthew Applied Micro (AMCC)
 Comment Type **GR** Comment Status **X**
 What is "link establishment process"? I assume this is auto-negotiation.
 SuggestedRemedy
 Replace "link establishment process" with "auto-negotiation".
 Proposed Response Response Status **O**

Comments received

IEEE P802.3az D3.0 Energy Efficient Ethernet comments

CI 78 SC 78.3 P252 L49 # 298
 Brown, Matthew Applied Micro (AMCC)
 Comment Type **TR** Comment Status **X**
 Some PHYs do not permit asymmetric LPI nor is it necessary to state this here.
 SuggestedRemedy
 Delete "independently in either direction".
 Proposed Response Response Status **O**

CI 78 SC 78.4.2.2 P255 L6 # 11
 Hajduczenia, Marek ZTE Corp.
 Comment Type **TR** Comment Status **X**
 'Integer (2 octets wide)' - other integers in 78.4.2.3 Variables do not have identifier whether they are 1 or 2 bytes wide. Either specifically mark each Integer type variable in terms of length or it is assumed that all of them have the same length. At this time, it is not clear how many bits you assume an Integer to have (16, 8, or 32 or more)
 SuggestedRemedy
 Per comment
 Proposed Response Response Status **O**

CI 78 SC 78.4.2.3 P252 L50 # 12
 Hajduczenia, Marek ZTE Corp.
 Comment Type **TR** Comment Status **X**
 What is a 'Temporary integer' ? Can't you just say 'Integer used to temporarily store the value of ...' or is it something altogether different?
 SuggestedRemedy
 Per comment
 Proposed Response Response Status **O**

CI 78 SC 78.4.2.3 P255 L10 # 13
 Hajduczenia, Marek ZTE Corp.
 Comment Type **ER** Comment Status **X**
 For readability reasons, each variable should have one line separation from the previous / next definitions. Otherwise it becomes hard to read. Please fix it
 SuggestedRemedy
 Per comment
 Proposed Response Response Status **O**

CI 78 SC 78.4.2.3 P256 L15 # 14
 Hajduczenia, Marek ZTE Corp.
 Comment Type **T** Comment Status **X**
 In Table 78-3, the column 'mapping' is not described and there are different options for mapping indicated i.e. left to right or right to left. What is their meaning?
 SuggestedRemedy
 Per comment
 Proposed Response Response Status **O**

CI 78 SC 78.4.2.4 P256 L54 # 15
 Hajduczenia, Marek ZTE Corp.
 Comment Type **TR** Comment Status **X**
 'NEW_RX_VALUE' is located at the very bottom of the page and defined as 'Integer that indicates the value of Tw_sys_tx that the local system wants the remote system to support. ' - seems like a variable rather than function. Why is it part of the Functions subclause then ?
 SuggestedRemedy
 Either change the definition to what the 'NEW_RX_VALUE' needs to represent or move to the proper location in the draft. The current location does not seem to be correct.
 Proposed Response Response Status **O**

Comments received

IEEE P802.3az D3.0 Energy Efficient Ethernet comments

Cl 78 SC 78.4.2.5 P257 L35 # 116
 Gustlin, Mark Cisco Systems, Inc.
 Comment Type E Comment Status X
 New_TX_VALUE should be: NEW_TX_VALUE
 SuggestedRemedy
 Proposed Response Response Status O

Cl 78 SC 78.4.2.5 P257 L6 # 16
 Hajduczenia, Marek ZTE Corp.
 Comment Type T Comment Status X
 'Control for placing data on the medium rests with the transmitting side, hence Tw_sys_tx is enforced by the transmitter.'
 read:<CR>'Transmitter is responsible for controlling placement of data on the medium, hence, Tw_sys_tx is enforced by the transmitter.'
 SuggestedRemedy Per comment
 Proposed Response Response Status O

Cl 78 SC 78.4.3.1 P260 L3 # 100
 Turner, Edward J Gnodal Ltd
 Comment Type E Comment Status X
 Missing words.
 SuggestedRemedy Add 'the' before 'MIRROR UPDATE', add 'the' before 'SYSTEM', add 'state' after 'REALLOCATION', add 'the' before 'TX UPDATE', add 'the' before 'UPDATE MIRROR'
 Proposed Response Response Status O

Cl 78 SC 78.4.3.2 P260 L16 # 101
 Turner, Edward J Gnodal Ltd
 Comment Type E Comment Status X
 Need to change 'lesser than' to 'less than either'.
 SuggestedRemedy Apply change.
 Proposed Response Response Status O

Cl 78 SC 78.4.3.2 P260 L17 # 102
 Turner, Edward J Gnodal Ltd
 Comment Type E Comment Status X
 Missing determiners.
 SuggestedRemedy Add 'the' before 'SYSTEM', add 'the' before 'RX UPDATE', add 'the' before 'SYSTEM REALLOCATION', add 'the' before 'CHANGE'.
 Proposed Response Response Status O

Cl 78 SC 78.5 P261 L3 # 17
 Hajduczenia, Marek ZTE Corp.
 Comment Type T Comment Status X
 line 3: 'In full duplex mode, predictable operation of the MAC ControlPAUSE operation' > 'In the full duplex mode, predictable operation of the MAC Control PAUSE operation'
 line 11: 'Following IDLE code reception on the MAC interface' > 'Following the reception of an IDLE code on the MAC interface'
 SuggestedRemedy per comment
 Proposed Response Response Status O

Comments received

IEEE P802.3az D3.0 Energy Efficient Ethernet comments

Cl 78 **SC 78.5.1** **P262** **L 54** # **18**
 Hajduczenia, Marek ZTE Corp.
Comment Type **TR** **Comment Status** **X**
 Where are PICS for Clause 78? There is a number of shall statements which do not have associated PICS.
SuggestedRemedy
 Either add PICS or provide a clear statement why these are not available.
Proposed Response **Response Status** **O**

Cl 79 **SC 79.5.a** **P266** **L 27** # **342**
 Dambrosia, John Force10 Networks
Comment Type **TR** **Comment Status** **X**
 There are no corresponding SHALL statements for EET1 - EET5
SuggestedRemedy
 add corresponding SHALL statements
Proposed Response **Response Status** **O**

Cl 79 **SC 79.3.a** **P263** **L 33** # **23**
 Diab, Wael Broadcom
Comment Type **ER** **Comment Status** **X**
 Please change the TBA in Figure 79-1a--EEE TLV format to the value in the Table 79-1
SuggestedRemedy
 Change TBA to 5
Proposed Response **Response Status** **O**

Cl 79 **SC 79.3.a.2** **P264** **L 16** # **103**
 Turner, Edward J Gnodal Ltd
Comment Type **E** **Comment Status** **X**
 Missing 'a'.
SuggestedRemedy
 Add 'a' before 'longer'.
Proposed Response **Response Status** **O**

Cl 79 **SC 79.3.a.3** **P264** **L 20** # **19**
 Hajduczenia, Marek ZTE Corp.
Comment Type **E** **Comment Status** **X**
 Font becomes much smaller after the first line of the paragraph. Please fix it.
SuggestedRemedy
 Per comment
Proposed Response **Response Status** **O**