## Revised Receive State Diagram Figure 24-11a

IEEE 802.3az Task Force Chicago, Sep 2009

Joseph Chou

Realtek Semiconductor Corp.





## **Objectives**

- ☐ Modify Receive state diagram (Fig 24-11a) of Clause24 to respond to the following comments:
  - ➤ Comment 147 : Legacy PHY will not take these optional EEE branches.
  - ➤ Comment 148: There is a typo in the original diagram. "not belongs to" should be changed to "belongs to".
  - Comment 149: Why is "rx\_bits[9:0] {equal to} /I/J/ " changed to "rx\_bits[9:0] {equal to} 11111111000 "?
  - ➤ Comment 151 : A single bit error in a /K/ in the SSD /J/K/ can synthesize the sequence rx\_bits[9:0] = /I/P/. In the "classic" 100BASE-X receive state machine, this would be counted as a BAD SSD,











Figure 24–11a—Receive state diagram, part a







link\_status≠OK \*



IEEE 802.3az Sep 2009 Plenary Meeting



## **Summary of Changes**

- □ Introduce a new state WAIT\_SLEEP between IDENTIFY JK and branch point "B" which goes to START RX\_SLEEP
  - ➤ The receiver moves to WAIT\_SLEEP from the state IDENTIFY JK when a bit pattern 1111100000 is received.
  - ➤ It then moves to START RX\_SLEEP when receiving two consecutive SLEEP symbols, /P/P/.
  - Any symbol received other than /P/ following a /P/ symbol will lead to the state of BAD SSD
- □ Rewrite the transition condition between CARRIER DETECT and IDENTIFY JK
  - Change "rx\_bits[9:0] {equal to} 11111111000" back to "rx\_bits[9:0] {equal to} /I/J/"
- □ Enclose all branches and states which are only needed for EEE with dashed box and put a note saying Mandatory to LPI mode
- □ Correct the typo in the branch condition between RECEIVE and DATA
  - Change "rx\_bits[9:5] {not belongs to} DATA" to "rx\_bits[9:5] {belongs to} DATA"





## Thank you!



