

P802.3bv D1.0 Gigabit Ethernet Over Plastic Optical Fiber 1st Task Force review comments

Cl 0 SC P L # 113  
 Grow, Robert RMG Consulting

Comment Type E Comment Status X

Editor can make a number of text, style manual and FrameMaker related improvements.

SuggestedRemedy

1. Add table of contents
2. Subclause reference format differs from base document. Change subclause references to Section format.
3. Search for "Section" and "Figure" update to proper cross reference.
4. Number equations.
5. Some large numbers are missing a non-breaking space as 1000s separator.
6. Review and remove obsolete Editor's Notes.
7. Re-enter some equations as large rather than medium (e.g., 114.2.3.4) to improve readability.
8. Search for .. and replace with : where possible (.. is not an 802.3 convention)

Proposed Response Response Status O

Cl 0 SC P L # 112  
 Grow, Robert RMG Consulting

Comment Type E Comment Status X

There are a few places in PICS where "clause title" has not been replaced

SuggestedRemedy

Search and replace with appropriate title

Proposed Response Response Status O

Cl 00 SC P L # 89  
 Grow, Robert RMG Consulting

Comment Type E Comment Status X

Subclause reference format differs from base document.

SuggestedRemedy

The word Clause only appears in front of complete clauses, any subclause shouldn't have the word Clause. Use correct Cross reference format.

Proposed Response Response Status O

Cl 01 SC 1.4 P13 L12 # 26  
 Pérez-Aranda, Rubén KDPOF

Comment Type E Comment Status X

Some definitions related to the technologies adopted may be included in this subclause.

SuggestedRemedy

See attached gepof\_definitions\_v1.1.docx

Proposed Response Response Status O

Cl 114 SC P L # 102  
 Pérez-Aranda, Rubén KDPOF

Comment Type T Comment Status X

Proposed text for additional subclause explaining the signals in interface between PCS and PMD

SuggestedRemedy

Proposed text is attached in gepof\_interfacePMD\_v1.0.docx

Proposed Response Response Status O

Cl 114 SC P L # 104  
 Pérez-Aranda, Rubén KDPOF

Comment Type TR Comment Status X

Proposed text for additional subclause for Delay Constraints

SuggestedRemedy

Proposed text is attached in gepof\_delay\_constraints\_v1.0

Proposed Response Response Status O

P802.3bv D1.0 Gigabit Ethernet Over Plastic Optical Fiber 1st Task Force review comments

CI 114 SC 114 P29 L28 # 63  
 Pérez-Aranda, Rubén KDPOF  
 Comment Type **ER** Comment Status **X**  
 Baseband medium is not defined in Clause 114, therefore the title of the clause is not correct.  
 SuggestedRemedy  
 Eliminate: "and baseband medium"  
 The title should be:  
 "Physical Coding Sublayer (PCS), Physical Medium Attachment (PMA) sublayer, type 1000BASE-H"  
 Proposed Response Response Status **O**

CI 114 SC 114.1 P29 L34 # 27  
 Pérez-Aranda, Rubén KDPOF  
 Comment Type **E** Comment Status **X**  
 Because the PCS and PMA is defined in Clause 114 independently of PMD, it seems that several PMD Clauses could be defined able to be attached to Clause 114.  
 SuggestedRemedy  
 A modification is suggested to clarify this topic:  
 "This PHY uses a Physical Coding Sublayer (PCS) and a Physical Medium Attachment (PMA) sublayer specified in this clause, which are common to a family of 1000 Mb/s PHY implementations with different Physical Medium Dependent (PMD) sublayers. In particular, Clause 115 defines a PMD sublayer attachable to the PCS and PMA sublayers defined in this clause."  
 Proposed Response Response Status **O**

CI 114 SC 114.1 P31 L7 # 64  
 Pérez-Aranda, Rubén KDPOF  
 Comment Type **ER** Comment Status **X**  
 A functional block diagram should be inserted to aid to understand the relationship among the different parts composing the 1000BASE-H PHY: PCS, PMA, EEE, OAM, PMD, etc.  
 SuggestedRemedy  
 Insert new sub-clause:  
 114.1.5 Functional block diagram  
 Figure 114-3 provides a functional block diagram of the 1000BASE-H PHY.  
 < insert the figure included in the attached file gepof\_functional\_block\_diagram\_v1.0.pdf >  
 Proposed Response Response Status **O**

CI 114 SC 114.1.2 P30 L7 # 28  
 Pérez-Aranda, Rubén KDPOF  
 Comment Type **E** Comment Status **X**  
 It may be indicated in Figure 114-1 which are the sublayers defined in Clause 114 (PCS and PMA), for example, with gray background.  
 SuggestedRemedy  
 See comment  
 Proposed Response Response Status **O**

CI 114 SC 114.1.4 P30 L44 # 1  
 Pérez-Aranda, Rubén KDPOF  
 Comment Type **E** Comment Status **X**  
 Figure 114-2 uses term driver for the transmitter side. Driver is a term more related to the implementation, and in fact it is part of the optical transmitter, composed by the driver and the light emitter photonics device (e.g. LED, laser, etc).  
 SuggestedRemedy  
 To replace driver by Optical Transmitter, and receiver by Optical Receiver in Figure 114-2  
 Proposed Response Response Status **O**

P802.3bv D1.0 Gigabit Ethernet Over Plastic Optical Fiber 1st Task Force review comments

Cl 114 SC 114.2 P31 L11 # 65  
 Pérez-Aranda, Rubén KDPOF

Comment Type ER Comment Status X

The sentence: "The 1000BASE-H PCS couples a Gigabit Media Independent Interface (GMII), see Clause 35, to the Physical Medium Attachment (PMA) sublayer"

is not consistent with the rest of the Clause 114, because a PMA service interface is not defined and PMA does not perform any transformation of the symbols generated by PCS.

According to the suggested functional block diagram, the PCS is directly attached to the PMD.

SuggestedRemedy

Replace sentence by:  
 "The 1000BASE-H PCS couples a Gigabit Media Independent Interface (GMII), see Clause 35, to the Physical Medium Dependent (PMD) sublayer"

Proposed Response Response Status O

Cl 114 SC 114.2.1 P31 L28 # 32  
 Pérez-Aranda, Rubén KDPOF

Comment Type ER Comment Status X

The temporal order of each part composing the Transmit Block should be described in text, since the figure 114-3 is useful to help to understand, but it does not represent a formal definition of that.

SuggestedRemedy

The parts composing the Transmit Block are temporally ordered as:

- S1, D\_0, PHS\_0, D\_1,
- S2\_0, D\_2, PHS\_1, D\_3,
- S2\_1, D\_4, PHS\_2, D\_5,
- S2\_2, D\_6, PHS\_3, D\_7,
- S2\_3, D\_8, PHS\_4, D\_9,
- S2\_4, D\_10, PHS\_5, D\_11,
- S2\_5, D\_12, PHS\_6, D\_13,
- S2\_6, D\_14, PHS\_7, D\_15,
- S2\_7, D\_16, PHS\_8, D\_17,
- S2\_8, D\_18, PHS\_9, D\_19,
- S2\_9, D\_20, PHS\_10, D\_21,
- S2\_10, D\_22, PHS\_11, D\_23,
- S2\_11, D\_24, PHS\_12, D\_25,
- S2\_12, D\_26, PHS\_13, D\_27

Proposed Response Response Status O

Cl 114 SC 114.2.1 P31 L30 # 29  
 Pérez-Aranda, Rubén KDPOF

Comment Type ER Comment Status X

PHS\_12 in Figure 114-3 is used indistinctly to refer to the sub-block composed by the real content that is part of the complete PHS and the preamble and postamble zeroes sequences, and to refer only to the content. The same for S2\_12 and S1 that are indicated in the figure as example.

The term "content" should be used to indicate the content of sub-blocks not including the preamble and postamble to be consistent with the rest of text.

Repeated S2\_1 in the left side of upper row of Fig 114-3. It should be S2\_0.

SuggestedRemedy

To modify the figure following as example the figure attached in p802\_3bv\_D1.0\_figures.pdf

Proposed Response Response Status O

Cl 114 SC 114.2.1 P31 L46 # 107  
 Grow, Robert RMG Consulting

Comment Type TR Comment Status X

Figure 114-3  
 Zero being prepended to content of control subblocks is ambiguous. Data zeroes are not the same as an analog zero.

SuggestedRemedy

Describe better what the 16 symbols of zero actually are (e.g., 16 symbol times of 0 volts. If zero volts, it would be better if illustration in the Transmit Block figure was changed from a box to a line to highlight this.

Proposed Response Response Status O

P802.3bv D1.0 Gigabit Ethernet Over Plastic Optical Fiber 1st Task Force review comments

Cl 114 SC 114.2.1 P45 L15 # 105  
 Grow, Robert RMG Consulting

Comment Type **TR** Comment Status **X**

Figure 114-20  
 The switch in the feedback path makes some unstated assumptions about an open circuit.

*SuggestedRemedy*

Modify figure to replace switch with a mux and make clear what is the feedback data when generation is completed and result is shifted out.

Similar changes to Figure 114-9.

Update supporting text accordingly.

Proposed Response Response Status **O**

Cl 114 SC 114.2.2 P32 L37 # 2  
 Pérez-Aranda, Rubén KDPOF

Comment Type **E** Comment Status **X**

Pilots S1 and S2 are signals a priori known by the receiver. This property allows to receiver to implement symbol synchronization, timing recovery and equalizer adaptation.

*SuggestedRemedy*

Modify text as:  
 Pilots S1 and S2 are predefined signals transmitted in fixed allocated time slots of the Transmit Block and intended to be used by the receiver for initialization and continuous tracking purposes based on data-aided signal processing.

Proposed Response Response Status **O**

Cl 114 SC 114.2.2 P32 L39 # 3  
 Pérez-Aranda, Rubén KDPOF

Comment Type **E** Comment Status **X**

Pilot S1 signal is intended to be used by the receiver for both fast symbol synchronization and for timing recovery

*SuggestedRemedy*

To add timing recovery to the purpose of S1

Proposed Response Response Status **O**

Cl 114 SC 114.2.2.1 P33 L38 # 4  
 Pérez-Aranda, Rubén KDPOF

Comment Type **E** Comment Status **X**

Names of variables that are explained in the text and that are used in the C-code provided below for the LFSR formal definition should be in italic style or other font, to improve understanding of the text.

*SuggestedRemedy*

See comment

Proposed Response Response Status **O**

Cl 114 SC 114.2.2.1 P34 L1 # 5  
 Pérez-Aranda, Rubén KDPOF

Comment Type **E** Comment Status **X**

Distinguish between pilot S1 signal and pilot S1 sub-block by adding "content" where corresponds

*SuggestedRemedy*

See comment

Proposed Response Response Status **O**

Cl 114 SC 114.2.2.2 P34 L10 # 31  
 Pérez-Aranda, Rubén KDPOF

Comment Type **ER** Comment Status **X**

Each S2 pilot sub-block is prepended and postpended ....  
 This is not really correct.

*SuggestedRemedy*

Each S2 pilot chunk is prepended and postpended by zero valued sequences of 16 symbols, thus obtaining the 160 symbols length S2 pilot sub-blocks.

Proposed Response Response Status **O**

P802.3bv D1.0 Gigabit Ethernet Over Plastic Optical Fiber 1st Task Force review comments

Cl 114 SC 114.2.2.2 P34 L8 # 30  
 Pérez-Aranda, Rubén KDPOF

Comment Type ER Comment Status X

The pilot sub-block S2 consists of a pseudo-random sequence of 1664 256 PAM symbols  
 ....  
 This sensence is not correct.  
 The pilot S2 consists of ....  
 The term sub-block is used to indicate each of the 13 chuncks including the preamble and  
 postamble zero valued sequences.

SuggestedRemedy

See comment, and modify text to be consistent.  
 S2 pilot: 1664 symbols length sequence  
 S2 chunks: 128 symbols length  
 S2 pilot sub-block: the S2 chunk including pre and postamble.

Proposed Response Response Status O

Cl 114 SC 114.2.3 P35 L2 # 34  
 Pérez-Aranda, Rubén KDPOF

Comment Type ER Comment Status X

Each PHS sub-block is prepended and postpended ....  
 This is not really correct.

SuggestedRemedy

Each PHS chunk is prepended and postpended by zero valued sequences of 16 symbols,  
 thus obtaining the 160 ...

Proposed Response Response Status O

Cl 114 SC 114.2.3.1 P35 L16 # 74  
 Pérez-Aranda, Rubén KDPOF

Comment Type TR Comment Status X

Figure 114-9 is not complete. The control signal to mux that enable disable the feedback of  
 LFSR is not indicated. The text description from line 12 to 15 does not agree with figure.

SuggestedRemedy

The 704 PHD bits are then used to compute the CRC-16 with the mux configured to  
 CRCgen setting. After the 704 bits have been serially processed, the mux is configured to  
 CRCout setting and the 16 stored values are the CRC-16. CRC-16 is transmitted in order  
 from S15 to S0.  
 Improved figure is attached in p802\_3bv\_D1.0\_figures.pdf

Proposed Response Response Status O

Cl 114 SC 114.2.3.3 P36 L1 # 33  
 Pérez-Aranda, Rubén KDPOF

Comment Type ER Comment Status X

The number of parity bits is p = 176 bits.  
 Indicate variable p, because it is used in G(x) equation.  
 In Equation G(x), eliminate last parathesis.

SuggestedRemedy

See comment

Proposed Response Response Status O

Cl 114 SC 114.2.3.3 P36 L6 # 6  
 Pérez-Aranda, Rubén KDPOF

Comment Type E Comment Status X

The G(x) coefficients are by:

SuggestedRemedy

The G(x) coefficients are by hexadecimal number:

Proposed Response Response Status O

P802.3bv D1.0 Gigabit Ethernet Over Plastic Optical Fiber 1st Task Force review comments

Cl 114 SC 114.2.3.4 P36 L45 # 35  
 Pérez-Aranda, Rubén KDPOF  
 Comment Type **ER** Comment Status **X**  
 Figure 114-11. Incorrect sequence of symbols provided as example at the output BPSK 2-PAM modulator.  
 SuggestedRemedy  
 To correct figure with the correct sequence:  
 -x0,x0,-x1,x1,-x2,x2,-x3,x3,-x4,x4  
 Proposed Response Response Status **O**

Cl 114 SC 114.2.3.4 P36 L51 # 7  
 Pérez-Aranda, Rubén KDPOF  
 Comment Type **E** Comment Status **X**  
 PHS is the Physical Header Sub-frame composed by the symbols stream generated after encoding process of the PHD (Physical Header Data) and which is split in 14 PHS sub-blocks (PHS\_x in text and figures).  
 I think it is clear in text.  
 SuggestedRemedy  
 Clear editor's note.  
 Proposed Response Response Status **O**

Cl 114 SC 114.2.4 P37 L10 # 36  
 Pérez-Aranda, Rubén KDPOF  
 Comment Type **ER** Comment Status **X**  
 Parenthesis for see Clause 114.2.4.1 are missed.  
 Line 11: the bits from PCS encoding are not really mapped to 16-PAM; after scrambling, the bits are encoded by a Multilevel Coset Code that generates symbols mapped onto a 16-PAM constellation. There are FEC and mapping combined in the same process that cannot be separated.  
 Line 15: cross reference is needed to 114.2.1, where it explained that the Transmit Block consists of 28 payload sub-blocks  
 SuggestedRemedy  
 Line 11: ... are encoded by a Multilevel Coset Code that generates symbols mapped onto a 16-PAM constellation (see Clause 114.2.4.3)  
 Line 15: add reference.  
 Proposed Response Response Status **O**

Cl 114 SC 114.2.4 P37 L11 # 38  
 Pérez-Aranda, Rubén KDPOF  
 Comment Type **ER** Comment Status **X**  
 The term "PCS encoding" is used, but it has not been introduced and is not consistent with the Figure 114-12 and the title of Clause 114.2.4.1.  
 SuggestedRemedy  
 Replace all "PCS encoding" by "GMII data stream encapsulation"  
 Replace all "64B/65B PCS encoding" by "64B/65B encoding"  
 Proposed Response Response Status **O**

Cl 114 SC 114.2.4 P37 L19 # 37  
 Pérez-Aranda, Rubén KDPOF  
 Comment Type **ER** Comment Status **X**  
 The text from line 19 to 25 is already repeated in 114.2.4.2.  
 114.2.4.2 is the right section to describe scrambler details.  
 SuggestedRemedy  
 Eliminate text from of lines 19 to 25 related to scrambler details  
 Proposed Response Response Status **O**

P802.3bv D1.0 Gigabit Ethernet Over Plastic Optical Fiber 1st Task Force review comments

CI 114 SC 114.2.4.1 P37 L39 # 69  
 Pérez-Aranda, Rubén KDPOF

Comment Type T Comment Status X

It is not indicated how is the interface with the next data processing block (binary scrambler). It is important to indicate that the interface between Encapsulation and Scrambler is a binary serial stream, because the scrambler is not aware about 65-bit units, operating bit by bit.

SuggestedRemedy

Proposed text:  
 "This encapsulation uses a 64B/65B encoding, with the output result being a stream of 65-bit data units, called Physical Data Blocks (PDB), which are serially transmitted to the binary scrambler at bit-rate of  $65/64 \cdot 1000 = 1015.625$  Mbits/s"

Proposed Response Response Status O

CI 114 SC 114.2.4.1 P37 L40 # 75  
 Pérez-Aranda, Rubén KDPOF

Comment Type TR Comment Status X

The GMII data stream encapsulation described in 114.2.4.1 does not replace any part of the Ethernet preamble or SFD, and it is GMII to GMII transparent for Ethernet packets (from the first byte of the preamble to the last byte of FCS). Therefore, using the term "Ethernet packet" is more correct than using "Ethernet frame", since in reality, the 64B/65B encoding performs encapsulation of the whole Ethernet packet, but not only of the Ethernet frame.

SuggestedRemedy

Replace "frame" by "packet". Also in line 41.

Proposed Response Response Status O

CI 114 SC 114.2.4.1.1 P37 L48 # 8  
 Pérez-Aranda, Rubén KDPOF

Comment Type E Comment Status X

"to indicate to delimit"

SuggestedRemedy

Eliminate "to indicate"

Proposed Response Response Status O

CI 114 SC 114.2.4.1.1 P37 L53 # 9  
 Pérez-Aranda, Rubén KDPOF

Comment Type E Comment Status X

TXD <7:0>, TX\_EN and TX\_ER, compose each GMII word. Size of the word is not indicated.

SuggestedRemedy

TXD <7:0>, TX\_EN and TX\_ER, compose each GMII 10-bit word.

Proposed Response Response Status O

CI 114 SC 114.2.4.1.1 P38 L11 # 11  
 Pérez-Aranda, Rubén KDPOF

Comment Type E Comment Status X

Type and TYPE are used indistinctly. Several parts of the text.

SuggestedRemedy

To use "Type" always.

Proposed Response Response Status O

CI 114 SC 114.2.4.1.1 P38 L3 # 10  
 Pérez-Aranda, Rubén KDPOF

Comment Type E Comment Status X

I miss a reference to Figure 114-14.

SuggestedRemedy

Reference to Figure 114-14 after "... Type bit is set to 1 and PDB.CTRL is generated".

Proposed Response Response Status O

P802.3bv D1.0 Gigabit Ethernet Over Plastic Optical Fiber 1st Task Force review comments

Cl 114 SC 114.2.4.1.1 P38 L41 # 39  
 Pérez-Aranda, Rubén KDPOF

Comment Type ER Comment Status X

Although bit ordering for each field of CB is formally indicated in C/114.2.4.1.2, the text should be improved.

SuggestedRemedy

At the beginning of line 41, replace by: "CTRL<1:0> (CB<7:6>)"  
 Line 44, replace by: "OFS<2:0> (CB<5:3>)"  
 Line 47, replace by: "LEN<2:0> (CB<2:0>)"

Proposed Response Response Status O

Cl 114 SC 114.2.4.1.1 P40 L4 # 12  
 Pérez-Aranda, Rubén KDPOF

Comment Type E Comment Status X

OFS in the right side of Figure 114-15 does not make sense.

SuggestedRemedy

Eliminate OFS of the right side.

Proposed Response Response Status O

Cl 114 SC 114.2.4.1.1 P40 L46 # 76  
 Pérez-Aranda, Rubén KDPOF

Comment Type TR Comment Status X

Equation is not correct

SuggestedRemedy

Replace equation by that in the attached file p802\_3bv\_D1.0\_equations.pdf

Proposed Response Response Status O

Cl 114 SC 114.2.4.1.2 P41 L4 # 114  
 Grow, Robert RMG Consulting

Comment Type E Comment Status X

PCS 64B/65B encoding formal definition might be better as an annex

SuggestedRemedy

Create normative Annex and move content

Proposed Response Response Status O

Cl 114 SC 114.2.4.2 P42 L27 # 13  
 Pérez-Aranda, Rubén KDPOF

Comment Type E Comment Status X

typo: "format definition"

SuggestedRemedy

Replace by "formal definition"

Proposed Response Response Status O

Cl 114 SC 114.2.4.3 P42 L44 # 14  
 Pérez-Aranda, Rubén KDPOF

Comment Type E Comment Status X

"After encapsulation of the GMII data stream and scrambling it is mapped into 16-PAM symbols"

It is important to note that the process is not only consisting of mapping, but parity addition and coset partitioning is also included. The MLCC that is used is a "coded modulation". Channel coding and modulation are unseparable parts of the same thing. The term "mapping" is something that typically does not include any information addition like parity and only translates bits at input to symbols at output without generating extra information.

SuggestedRemedy

Replace the term "mapped" by "encoded"

Proposed Response Response Status O

P802.3bv D1.0 Gigabit Ethernet Over Plastic Optical Fiber 1st Task Force review comments

Cl 114 SC 114.2.4.3 P42 L50 # 40  
 Pérez-Aranda, Rubén KDPOF  
 Comment Type ER Comment Status X  
 The term MLCC is used but it was not previously introduced and is not related to the terms used in the previous paragraph.  
 SuggestedRemedy  
 Modify line 45 to relate MLCC with two-level coser coding, that are concepts not related before:  
 "In particular, a Multilevel Coset Coding (MLCC) of two levels based on ..."  
 Proposed Response Response Status O

Cl 114 SC 114.2.4.3 P43 L10 # 41  
 Pérez-Aranda, Rubén KDPOF  
 Comment Type ER Comment Status X  
 Figure 114-18: the superscript tau of upper case lambda (used to indicate lattice transformations) should be "t" to be in coherence with text and equations later described.  
 SuggestedRemedy  
 Replace in figure "tau" by "t"  
 Proposed Response Response Status O

Cl 114 SC 114.2.4.3 P43 L39 # 77  
 Pérez-Aranda, Rubén KDPOF  
 Comment Type TR Comment Status X  
 Equations for number of bits per 1D symbol and spectral efficiency are not correct.  
 Line 39: equation uses nb that is not defined. It has to use n\_b (subscript)  
 Line 43: equation is a copy of previous one.  
 General, limits of summation should be nearer to upper case sigma symbol.  
 SuggestedRemedy  
 Replace equation by that in the attached file p802\_3bv\_D1.0\_equations.pdf  
 The summation limits could be in line with sumation symbol (upper case sigma) as it indicated in attached document, to avoid overlapping with text.  
 Proposed Response Response Status O

Cl 114 SC 114.2.4.3.1 P43 L53 # 15  
 Pérez-Aranda, Rubén KDPOF  
 Comment Type E Comment Status X  
 Reference to Figure 114-19 not included  
 SuggestedRemedy  
 Add reference to Figure 114-19  
 Proposed Response Response Status O

Cl 114 SC 114.2.4.3.1 P44 L14 # 42  
 Pérez-Aranda, Rubén KDPOF  
 Comment Type ER Comment Status X  
 Reference to a figure 3 that does not exist.  
 SuggestedRemedy  
 Replace by a reference to Figure 114-19.  
 Proposed Response Response Status O

Cl 114 SC 114.2.4.3.1 P44 L19 # 16  
 Pérez-Aranda, Rubén KDPOF  
 Comment Type E Comment Status X  
 Figure 114-19: nb,demux(2)=3 bits is indicated, but not nb,demux(1)=4. I think both or none.  
 SuggestedRemedy  
 To eliminate nb,demux(2)=3 of the figure.  
 Proposed Response Response Status O

Cl 114 SC 114.2.4.3.2 P44 L42 # 43  
 Pérez-Aranda, Rubén KDPOF  
 Comment Type ER Comment Status X  
 Number 9 inserted without meaning.  
 g(i) can only take values 0 or 1.  
 SuggestedRemedy  
 To eliminate 9.  
 Proposed Response Response Status O

P802.3bv D1.0 Gigabit Ethernet Over Plastic Optical Fiber 1st Task Force review comments

Cl 114 SC 114.2.4.3.2 P44 L45 # 17  
 Pérez-Aranda, Rubén KDPOF  
 Comment Type E Comment Status X  
 Typo error in polynomial: "COC4 484A..."  
 SuggestedRemedy  
 Replace by C0C4.  
 The second hexa digit should be ZERO, no upper case letter "O".  
 Proposed Response Response Status O

Cl 114 SC 114.2.4.3.2 P44 L48 # 78  
 Pérez-Aranda, Rubén KDPOF  
 Comment Type TR Comment Status X  
 The equation is not correct; parenthesis order.  
 In addition, the equation should be inserted after line 41, where G(x) is introduced, instead of line 48.  
 SuggestedRemedy  
 Replace equation by that in the attached file p802\_3bv\_D1.0\_equations.pdf.  
 Move upwards the equation. Inline or separated line  
 Proposed Response Response Status O

Cl 114 SC 114.2.4.3.2 P44 L52 # 79  
 Pérez-Aranda, Rubén KDPOF  
 Comment Type TR Comment Status X  
 - k, n and p have not been introduced before. k\_c, n\_c and p\_c were introduced, and they should be used in equations. "\_" indicates subscript.  
 - Equations for M(x), S(x) and C(x) should add an ellipsis between the quadratic term of the polynomial and the highest order term, since in general terms in between will exist.  
 Also affects to pg. 52, where M(x), S(x) and C(x) are involved.  
 SuggestedRemedy  
 Replace k with k\_c, n with n\_c and p with p\_c.  
 Add ellipsis to polynomials M(x), S(x) and C(x).  
 E.g.  $M(x) = m_0 + m_1*x + m_2*x^2 + \dots + m_{(k-1)}*x^{(k-1)}$   
 Proposed Response Response Status O

Cl 114 SC 114.2.4.3.2 P45 L8 # 80  
 Pérez-Aranda, Rubén KDPOF  
 Comment Type TR Comment Status X  
 Text and Figure 114-20 describing the BCH encoder should be improved.  
 In Figure 114-20, the feedback values  $g(i) \cdot x^i$  are undefined when switch is connected to position BCHout.  
 SuggestedRemedy  
 Suggested text:  
 "The delay elements s\_0, s\_1, ..., s\_p-1 shall be initialized to zero before encoding. All the k bits composing the information message are used to calculate the parity and enter the BCH encoder in the same order provided by the MLCC demultiplexer with the muxes indicated in Figure 114-20 connected with BCHgen setting. After all the k bits have been serially processed, the muxes are configured to BCHout setting and the p stored values s\_0, s\_1, ..., s\_p-1 are the parity bits. The parity bits are then transmitted in the order from s\_p-1 to s\_0"  
 Improved figure is attached in p802\_3bv\_D1.0\_figures.pdf  
 Proposed Response Response Status O

Cl 114 SC 114.2.4.3.3 P46 L53 # 81  
 Pérez-Aranda, Rubén KDPOF  
 Comment Type TR Comment Status X  
 Equations for Gray to Bin converter are not correct.  
 SuggestedRemedy  
 Replace equations by those in the attached file p802\_3bv\_D1.0\_equations.pdf.  
 Proposed Response Response Status O

Cl 114 SC 114.2.4.3.3 P47 L6 # 18  
 Pérez-Aranda, Rubén KDPOF  
 Comment Type E Comment Status X  
 "... more significant bit (MSB) ..."  
 SuggestedRemedy  
 Replace by "most significant bit (MSB)"  
 Proposed Response Response Status O

P802.3bv D1.0 Gigabit Ethernet Over Plastic Optical Fiber 1st Task Force review comments

CI 114 SC 114.2.4.3.4 P48 L26 # 44  
 Pérez-Aranda, Rubén KDPOF

Comment Type ER Comment Status X

Lattice transformation indicated in Figure 114-18 is  $\lambda_1(l)$ , but not  $\lambda_{1,1}(l)$ . Please, note that  $\lambda_{1,1}(l)$  is composed by the concatenation of two operations,  $\lambda_{1,1}(l)$  and  $\lambda_{1,2}(l)$ . In Figure 114-18 the complete operation  $\lambda_1(l)$  is indicated.

SuggestedRemedy

Replace  $\lambda_{1,1}(l)$  with  $\lambda_1(l)$ .  
 At the end of line 26, eliminate "."

Proposed Response Response Status O

CI 114 SC 114.2.4.3.4 P48 L39 # 47  
 Pérez-Aranda, Rubén KDPOF

Comment Type ER Comment Status X

C is used to indicate the field of complex numbers. It should be indicated that x is a complex number and C indicates the field of complex numbers just after the equation.

SuggestedRemedy

See comments.

Proposed Response Response Status O

CI 114 SC 114.2.4.3.4 P48 L48 # 82  
 Pérez-Aranda, Rubén KDPOF

Comment Type TR Comment Status X

Equation of lattice transformation is not correct.  
 The summation is superscript of 2 and parenthesis of last superscript are not correct.

SuggestedRemedy

Replace equation by that in the attached file p802\_3bv\_D1.0\_equations.pdf.

Proposed Response Response Status O

CI 114 SC 114.2.4.3.4 P49 L11 # 45  
 Pérez-Aranda, Rubén KDPOF

Comment Type ER Comment Status X

Bad reference to Figure 8

SuggestedRemedy

Replace by reference to Figure 114-24

Proposed Response Response Status O

CI 114 SC 114.2.4.3.4 P49 L4 # 106  
 Grow, Robert RMG Consulting

Comment Type ER Comment Status X

Unreadable inline equation.

SuggestedRemedy

Enter in FrameMaker

Proposed Response Response Status O

CI 114 SC 114.2.4.3.4 P49 L7 # 83  
 Pérez-Aranda, Rubén KDPOF

Comment Type TR Comment Status X

Equation is not correct.

SuggestedRemedy

Replace equation by that in the attached file p802\_3bv\_D1.0\_equations.pdf.

Proposed Response Response Status O

P802.3bv D1.0 Gigabit Ethernet Over Plastic Optical Fiber 1st Task Force review comments

CI 114 SC 114.2.4.4 P50 L1 # 46  
 Pérez-Aranda, Rubén KDPOF

Comment Type ER Comment Status X

114.2.4.4 should be 114.2.4.3.5, because Lattice addition belongs to Coded 16-PAM  
 Because the same reason:  
 114.2.4.5 should be 114.2.4.3.6  
 114.2.4.6 should be 114.2.4.3.7  
 and  
 114.2.4.7 should be 114.2.4.4

SuggestedRemedy

See comment and change labeling of sections.

Proposed Response Response Status O

CI 114 SC 114.2.4.5 P50 L45 # 84  
 Pérez-Aranda, Rubén KDPOF

Comment Type TR Comment Status X

Equation is not correct.

SuggestedRemedy

Replace equation by that in the attached file p802\_3bv\_D1.0\_equations.pdf.

Proposed Response Response Status O

CI 114 SC 114.2.4.5 P51 L21 # 85  
 Pérez-Aranda, Rubén KDPOF

Comment Type TR Comment Status X

Reference to Figure 114-24 is not valid, it should be Figure 114-28.  
 Also equation  $Y = \text{mod}(X, 2^{\text{ceil}(\psi)} - 1)$  is not correct.

SuggestedRemedy

Replace reference to figure as indicated in comment.  
 Replace equation by  $Y = \text{mod}(X, 2^{\text{ceil}(\psi)})$  (eliminate the term -1).

Proposed Response Response Status O

CI 114 SC 114.2.4.7 P53 L18 # 86  
 Pérez-Aranda, Rubén KDPOF

Comment Type TR Comment Status X

Figure 114-31 is not correct.  
 $u(m)$  is the signal in the input of modulo operation.  
 $v$  signal has to add to output of multiplier, but not subtract.

SuggestedRemedy

Improved figure is attached in p802\_3bv\_D1.0\_figures.pdf.

Proposed Response Response Status O

CI 114 SC 114.2.4.8 P53 L33 # 48  
 Pérez-Aranda, Rubén KDPOF

Comment Type ER Comment Status X

"The coefficients of the finite-impulse response (FIR) feedback filter  $b(i)$  are dynamically adapted using the PMD"

SuggestedRemedy

Replace PMD by PHD.

Proposed Response Response Status O

CI 114 SC 114.2.4.8 P53 L45 # 87  
 Pérez-Aranda, Rubén KDPOF

Comment Type TR Comment Status X

Equation is not correct. Replace  $v(m)$  by  $y(m)$ .  
 It should be indicated that  $M$  takes the value of 16 in the text.  
 This is because the symbols that are precoded belongs to a constellation 16-PAM, taking values  $\{-15, -13, \dots, +13, +15\}$ .

SuggestedRemedy

See comment.

Proposed Response Response Status O

P802.3bv D1.0 Gigabit Ethernet Over Plastic Optical Fiber 1st Task Force review comments

CI 114 SC 114.3 P L # 101  
 Pérez-Aranda, Rubén KDPOF  
 Comment Type ER Comment Status X  
 The term "state machine" is used instead of "state diagram"  
 SuggestedRemedy  
 Replace "state machine" with "state diagram" in all the text.  
 Proposed Response Response Status O

CI 114 SC 114.3 P54 L23 # 49  
 Pérez-Aranda, Rubén KDPOF  
 Comment Type ER Comment Status X  
 Organization of the clause 114.3 may be improved to be more clear.  
 Also some modifications for titles of the sub-clauses are suggested.  
 SuggestedRemedy  
 114.3 - Physical Medium Attachment (PMA)  
 114.3.1 - Physical Header Data (PHD)  
 114.3.2 - PMA control state diagrams description  
 114.3.2.1 - PHY RX control state diagram  
 114.3.2.2 - PHY TX control state diagram  
 114.3.2.3 - Link monitor state diagram  
 114.3.2.4 - PHD monitor state diagrams  
 114.3.2.5 - Adaptive THP protocol  
 114.3.2.5.1 - Adaptive THP TX state diagram  
 114.3.2.5.2 - Adaptive THP REQ state diagram  
 114.3.2.6 - PHY quality monitor state diagram  
 114.3.2.7 - PMA control state variables  
 (This sub-clause should include the definition of all the state variables, so only one sub-clause is devoted to that.)  
 114.3.3 - Fixed-point format formal definition  
 114.4 - Test modes  
 (all test modes under the same sub-clause)  
 114.5 - Operations, Administration, and Maintenance (OAM) channel  
 114.6 - Energy Efficient Ethernet (EEE)  
 Proposed Response Response Status O

CI 114 SC 114.3 P54 L27 # 19  
 Pérez-Aranda, Rubén KDPOF  
 Comment Type E Comment Status X  
 The sentence "The PHD sub-blocks support reliable exchange of information to optimize link operation" is redundant with the next sentence about PHS and may produce confusion.  
 Moreover, PHS sub-blocks are defined in 114.2.3 but not PHD sub-blocks.  
 SuggestedRemedy  
 Replace by:  
 "PHD information is encoded into the Physical Header Subframe (PHS) as defined in 114.2.3. The PHS is transmitted periodically once per Transmit Block split in 14 PHS sub-blocks and the modulation and ...."  
 Proposed Response Response Status O

CI 114 SC 114.3 P55 L52 # 57  
 Pérez-Aranda, Rubén KDPOF  
 Comment Type ER Comment Status X  
 The titles of figures do not agree with the text.  
 SuggestedRemedy  
 Figure 114-33 - PHY RX control state diagram  
 Figure 114-34 - PHY TX control state diagram  
 Figure 114-35 - Link monitor state diagram  
 Figure 114-36 - Local PHD reception monitor state diagram  
 Figure 114-37 - Remote PHD reception monitor state diagram  
 Figure 114-38 - PHD monitor state diagram  
 Figure 114-39 - Adaptive THP TX state diagram  
 Figure 114-40 - Adaptive THP REQ state diagram  
 Figure 114-41 - PHY quality monitor state diagram  
 Proposed Response Response Status O

P802.3bv D1.0 Gigabit Ethernet Over Plastic Optical Fiber 1st Task Force review comments

Cl 114 SC 114.3.1 P56 L13 # 50  
 Pérez-Aranda, Rubén KDPOF  
 Comment Type **ER** Comment Status **X**  
 Bad references in table 114-2.  
 - pg 56, line 13: replace 114.3.2 by 114.3.2.2  
 - pg 56, line 18: replace 114.3.1 by 114.2.4.1.1  
 - pg 56, line 21: replace 114.3.1 by 114.3.2.2  
 SuggestedRemedy  
 See comment  
 Proposed Response Response Status **O**

Cl 114 SC 114.3.1 P56 L29 # 51  
 Pérez-Aranda, Rubén KDPOF  
 Comment Type **ER** Comment Status **X**  
 The description of some fiels of Table 114-2 is not coherent with PMA structure  
 PMA receive function is not defined in 114.3. The funcionality is actually performed by the  
 PCS.  
 SuggestedRemedy  
 Pg 56, line 29, replace by: "Indicates whether local PHY is able to ..."  
 Pg 56, line 35, replace by: "The local PHY shall use this field of received PHD to determine  
 ..."  
 Pg 56, line 40, replace by: "Indicates whether local PHY is able to ..."  
 Pg 56, line 45, replace by: "The local PHY shall use this field of received PHD to determine  
 ..."  
 Pg 57, line 10, replace by: The local PHY shall use this field of received PHD to determine  
 ..."  
 Proposed Response Response Status **O**

Cl 114 SC 114.3.2.1.1 P58 L24 # 52  
 Pérez-Aranda, Rubén KDPOF  
 Comment Type **ER** Comment Status **X**  
 PMA receive function is not defined at all.  
 SuggestedRemedy  
 Pg 58, line 24, replace "PMA Receive function" by "PHY receiver operation"  
 Pg 58, line 25, replace "PMA Receive function" by "PHY receiver"  
 Pg 58, line 35, replace "PMA Receive function" by "PHY receiver"  
 Pg 58, line 39, replace "PMA Receive function" by "PHY receiver"  
 Pg 58, line 45, replace "PMA Receive function" by "PHY receiver"  
 Proposed Response Response Status **O**

Cl 114 SC 114.3.2.1.2 P59 L11 # 54  
 Pérez-Aranda, Rubén KDPOF  
 Comment Type **ER** Comment Status **X**  
 PMA transmit function is not defined at all.  
 SuggestedRemedy  
 Pg 59, line 11, replace "PMA Transmit function" by "PHY transmitter operation"  
 Proposed Response Response Status **O**

Cl 114 SC 114.3.2.1.2 P59 L13 # 55  
 Pérez-Aranda, Rubén KDPOF  
 Comment Type **ER** Comment Status **X**  
 Line 13, bad reference to [1]  
 Line 17, bad reference to 114.3.1  
 Line 22, bad reference to Section 3.1.5  
 SuggestedRemedy  
 Line 13, replace by 114.2.1.  
 Line 17, replace by 114.2.4.1.1  
 Line 22, replace by 114.3.2.1.5  
 Proposed Response Response Status **O**

P802.3bv D1.0 Gigabit Ethernet Over Plastic Optical Fiber 1st Task Force review comments

Cl 114 SC 114.3.2.1.2 P59 L5 # 53  
 Pérez-Aranda, Rubén KDPOF  
 Comment Type **ER** Comment Status **X**  
 Bad reference to section 3.1.5.  
 SuggestedRemedy  
 Replace by 114.3.2.1.5.  
 Proposed Response Response Status **O**

Cl 114 SC 114.3.2.1.3 P59 L31 # 56  
 Pérez-Aranda, Rubén KDPOF  
 Comment Type **ER** Comment Status **X**  
 Bad reference to section 3.3  
 SuggestedRemedy  
 Replace by Clause 114.3.2.3  
 Proposed Response Response Status **O**

Cl 114 SC 114.3.2.1.5 P64 L30 # 58  
 Pérez-Aranda, Rubén KDPOF  
 Comment Type **ER** Comment Status **X**  
 Several PMA functions are indicated in state variables description, but these functions, although described as functionalities before, they are not defined as concrete functions. Text should be improved.  
 SuggestedRemedy  
 Pg 64, line 31, eliminate "It is set by the PMA reset"  
 Pg 64, line 46, replace "PMA Clock Recovery function" by "PHY clock recovery function"  
 Pg 64, line 53, replace "PMA Clock Recovery function" by "PHY clock recovery function"  
 Pg 65, line 6, replace "PMA Receive function" by "PHY quality monitor state machine"  
 Pg 65, line 13, replace "the PCS Receive function" by "the reception of PHD"  
 Pg 65, line 14, replace bad reference to Section 2 by Clause 114.3.1  
 Pg 65, line 20, replace "PMA Link Monitor function ..." by "link monitor state machine and used by PMA TX and RX state machines to enable the 64B/65B PCS encoder and decoder, respectively" (eliminate "passed to PCS via the ...", because this primitive is not defined at all)  
 Pg 65, line 28, replace "PMA Receive function" by "local PHD reception monitor state machine"  
 Pg 65, line 35, replace "PCS Receive function" by "remote PHD reception monitor state machine"  
 Pg 65, line 36, replace bad reference to Section 2 by Clause 114.3.1  
 Pg 65, line 42, replace "PMA Receive function" by "PHD monitor state machine"  
 Pg 65, line 49, replace "PCS Receive function" by "PHY receiver"  
 Pg 66, line 2, replace "PMA PHY Control function" by "adaptive THP REQ state machine"  
 Pg 66, line 3, replace "PMA Receive function" by "PHY"  
 Pg 66, line 4, replace "PMA PHY Control function" by "adaptive THP REQ state machine"  
 Pg 66, line 10, replace "PMA PHY Control function" by "PHY RX state machine"  
 Pg 66, line 17, replace "PMA PHY Control function" by "PHY TX state machine"  
 Pg 66, line 26, replace "PMA and PCS" by "PHY", same for line 28  
  
 In general, indentation of variables description and values that can take would help to follow the text.  
 Proposed Response Response Status **O**

Cl 114 SC 114.3.2.2 P66 L49 # 59  
 Pérez-Aranda, Rubén KDPOF  
 Comment Type **ER** Comment Status **X**  
 PMA receive function is not defined.  
 SuggestedRemedy  
 Pg 66, line 49, replace "PMA receive function" by "PHY", the same for line 50.  
 Proposed Response Response Status **O**

P802.3bv D1.0 Gigabit Ethernet Over Plastic Optical Fiber 1st Task Force review comments

Cl 114 SC 114.3.2.2 P67 L1 # 70  
 Pérez-Aranda, Rubén KDPOF  
 Comment Type T Comment Status X  
 FFF also compensate the cursor of inter-symbol interference produced by the channel.  
 SuggestedRemedy  
 Replace by: "FFF compensates the cursor and pre-cursor ISI and whitens the noise ..."  
 Proposed Response Response Status O

Cl 114 SC 114.3.2.2 P67 L24 # 20  
 Pérez-Aranda, Rubén KDPOF  
 Comment Type E Comment Status X  
 Replace sections by clauses  
 SuggestedRemedy  
 See comment  
 Proposed Response Response Status O

Cl 114 SC 114.3.2.2.2 P68 L35 # 21  
 Pérez-Aranda, Rubén KDPOF  
 Comment Type E Comment Status X  
 Condition for transition is not complete  
 SuggestedRemedy  
 Replace by:  
 "new\_rxphd\_event = TRUE \* hdr\_crc16\_status = OK \* REMPHD.TX.NEXT.THP.SETID =  
 thp\_setid"  
 Proposed Response Response Status O

Cl 114 SC 114.3.2.2.2 P68 L38 # 71  
 Pérez-Aranda, Rubén KDPOF  
 Comment Type T Comment Status X  
 Actually the PHY receiver is not receiving payload data sub-blocks TH precoded, but it shall receive them starting in the next received Transmit Block, since the REMPHD carries information announcing the mode of the next Transmit Block

SuggestedRemedy  
 Proposed text (change tense):  
 "The local PHY receiver shall receive payload data sub-blocks TH precoded with the requested coefficients starting from the next Transmit Block received from link partner"  
 Proposed Response Response Status O

Cl 114 SC 114.3.2.2.3 P70 L31 # 60  
 Pérez-Aranda, Rubén KDPOF  
 Comment Type ER Comment Status X  
 Several PMA/PCS functions are indicated in state variables description, but these functions, although described as functionalities before, they are not defined as concrete functions.  
 Text should be improved.

SuggestedRemedy  
 Pg 70, line 31, replace "PCS Transmit function" by "PHY transmitter"  
 Pg 70, line 36, replace "transmitter block" by "Transmit Block"  
 Pg 70, line 41, replace "PMA PHY Control function" by "adaptive THP TX state machine"  
 Pg 70, line 41, replace "PMA Transmit function" by "PHY transmitter"  
 Pg 70, line 47, replace "PCS Receive function" by "reception of PHD"  
 Pg 70, line 50, replace bad reference 2 by Clause 114.3.1 or eliminate it.  
 Pg 71, line 1, replace "PCS Receive function" by "reception of PHD"  
 Pg 71, line 3, replace bad reference 2 by Clause 114.3.1 or eliminate it.  
 Pg 71, line 9, replace "PMA PHY Control" by "Adaptive THP REQ state machine"  
 Pg 71, line 15, replace "PMA PHY Control" by "Adaptive THP REQ state machine"  
 Pg 71, line 29, replace "PMA Receive function" by "PHY receiver"  
 Pg 71, line 36, replace "PMA Receive function" by "PHY receiver"

In general, indentation of variables description and values that can take would help to follow the text.  
 Proposed Response Response Status O

P802.3bv D1.0 Gigabit Ethernet Over Plastic Optical Fiber 1st Task Force review comments

Cl 114 SC 114.3.2.3 P71 L48 # 22  
 Pérez-Aranda, Rubén KDPOF  
 Comment Type **E** Comment Status **X**  
 It is the first time the term "detector" is used and may be no clear.  
 SuggestedRemedy  
 I suggest to replace by "MLCC decoder"  
 Also for Pg 72, lines 1, 7.  
 Proposed Response Response Status **O**

Cl 114 SC 114.3.2.3.1 P73 L39 # 61  
 Pérez-Aranda, Rubén KDPOF  
 Comment Type **ER** Comment Status **X**  
 PMA Receive function is indicated in state variables description, but this function, although described as functionality before, it is not defined as concrete function.  
 Text should be improved.  
 SuggestedRemedy  
 Replace "PMA Receive function" by "PHY receiver"  
 Proposed Response Response Status **O**

Cl 114 SC 114.3.2.3 P72 L10 # 88  
 Pérez-Aranda, Rubén KDPOF  
 Comment Type **TR** Comment Status **X**  
 Equation for link margin (LM) definition is not correct  
 SuggestedRemedy  
 Eliminate parenthesis around (LM = )  
 Proposed Response Response Status **O**

Cl 114 SC 114.3.4 P74 L27 # 67  
 Pérez-Aranda, Rubén KDPOF  
 Comment Type **ER** Comment Status **X**  
 Propose text for Test modes  
 SuggestedRemedy  
 Proposed text is attached in gepof\_test\_modes\_v1.0.docx  
 Proposed Response Response Status **O**

Cl 114 SC 114.3.2.3 P72 L26 # 23  
 Pérez-Aranda, Rubén KDPOF  
 Comment Type **E** Comment Status **X**  
 Threshold value S is not defined. This is a typo  
 SuggestedRemedy  
 Replace by upper case sigma.  
 Proposed Response Response Status **O**

Cl 114 SC 114.4 P74 L32 # 66  
 Pérez-Aranda, Rubén KDPOF  
 Comment Type **ER** Comment Status **X**  
 Propose text for OAM sub-clause  
 SuggestedRemedy  
 Proposed text is attached in gepof\_oam\_channel\_v1.2.docx  
 Proposed Response Response Status **O**

P802.3bv D1.0 Gigabit Ethernet Over Plastic Optical Fiber 1st Task Force review comments

Cl 114 SC 114.5 P74 L37 # 103  
 Pérez-Aranda, Rubén KDPOF  
 Comment Type **TR** Comment Status **X**  
 Improved proposed text for EEE.  
 SuggestedRemedy  
 Proposed text is attached in gepof\_energy\_efficient\_ethernet\_v1.2.docx  
 Proposed Response Response Status **O**

Cl 114 SC 114.5 P74 L39 # 72  
 Pérez-Aranda, Rubén KDPOF  
 Comment Type **T** Comment Status **X**  
 Actually auto-negotiation functionality is not defined, therefore this term should not be used.  
 SuggestedRemedy  
 Eliminate "through auto-negotiation".  
 In line 41, after first point, add: "It is required that the two link partners indicate PHD.CAP.LPI = 1 to enable bidirectional EEE functionality. PHD.CAP.LPI = 1 advertising indicates to link partner that the local PHY can generate Transmit Blocks according to LPI operation and it is able to accept Transmit Blocks from link partner conformed according to LPI operation."  
 Proposed Response Response Status **O**

Cl 114 SC 114.5 P75 L28 # 73  
 Pérez-Aranda, Rubén KDPOF  
 Comment Type **T** Comment Status **X**  
 The PMD service interface should defined in Clause 115 (PMD). Actually, the service interface primitives here defined are a requirement for any PMD attached to a 1000BASE-H PMA.  
 Line 46. The term "timing" is too generic and can produce confusion.  
 SuggestedRemedy  
 Modify wording:  
 "Since special control signaling is required to implement LPI mode, any PMD attached to a 1000BASE-H PMA shall provide the following service interface primitives:"  
 Eliminate reference to Figure 114-43 in pg 75, line 29, and the figure itself in pg 76. This figure should be included in any PMD clause suitable to be attached to 1000BASE-H.  
 Pg 75, line 46. Eliminate the sentence.  
 Proposed Response Response Status **O**

Cl 114 SC 114.5 P75 L34 # 62  
 Pérez-Aranda, Rubén KDPOF  
 Comment Type **ER** Comment Status **X**  
 PMA Transmit and Receive functions are not defined, however they are referenced.  
 SuggestedRemedy  
 Line 34, replace "PMA" by "PCS"  
 Line 38, replace "PMA" by "PCS"  
 Line 40, replace "PMA" by "PCS"  
 Proposed Response Response Status **O**

Cl 114 SC 114.5.1 P76 L18 # 24  
 Pérez-Aranda, Rubén KDPOF  
 Comment Type **E** Comment Status **X**  
 Reference to Table 114-1 does not provide enough information.  
 SuggestedRemedy  
 To replace reference to Table 114-1 by Clause 114.2.4.1  
 Proposed Response Response Status **O**

P802.3bv D1.0 Gigabit Ethernet Over Plastic Optical Fiber 1st Task Force review comments

Cl 114 SC 114.5.3 P77 L25 # 90  
 Grow, Robert RMG Consulting

Comment Type ER Comment Status X

The two tables belong in Clause 78 changes as inserts to existing tables. The paragraph also needs to be edited. Additionally, we need to list 1000BASE-RH in Table 78-1.

SuggestedRemedy

Change the paragraph at line 25 to read: Additional LPI timing parameters for 1000BASE-RH are defined in Clause 78. Note that the 24.82 usec in Table 78-4 is the time needed to transmit a pilot or physical header sub-block and a payload data sub-block.

In clause 78:

Insert new row below into Table 78-1 after 1000BASE-KX:

<Table 78-1 title>  
 PHY or interface type Clause  
 1000BASE-RH 114, 115

Insert new 1000BASE-RH row below into Table 78-2 after 1000BASE-KX:

<what is now Table 114-3>, with table title of Table 78-2>

Insert new 1000BASE-RH row below into Table 78-4 below 1000BASE-KX:

<what is now Table 114-4, with table title of Table 78-4>

Proposed Response Response Status O

Cl 114 SC 114.5.3 P77 L7 # 25  
 Pérez-Aranda, Rubén KDPOF

Comment Type E Comment Status X

Tables 114-3 and 114-4 are rows to be included within the corresponding tables of clause 78 and they should not be included in this clause.

SuggestedRemedy

Move tables to the corresponding rows of tables of Clause 78.

Proposed Response Response Status O

Cl 114 SC 114.6 P78 L1 # 91  
 Grow, Robert RMG Consulting

Comment Type TR Comment Status X

Editor needs to generate a PICs based on occurrence of shalls contained in the clause text.

SuggestedRemedy

See comment.

Proposed Response Response Status O

Cl 115 SC 115 P81 L1 # 68  
 Pérez-Aranda, Rubén KDPOF

Comment Type ER Comment Status X

Propose text for PMD type 1000BASE-RH

SuggestedRemedy

Proposed text is attached in gepof\_pmd\_sublayer\_v1.6.docx

Proposed Response Response Status O

Cl 115 SC 115.12 P86 L19 # 92  
 Grow, Robert RMG Consulting

Comment Type TR Comment Status X

Editor needs to generate a PICs based on occurrence of shalls contained in the clause text after new text is added.

SuggestedRemedy

See comment.

Proposed Response Response Status O

Cl 115 SC 115.2.2 P82 L15 # 96  
 Satoshi Takahashi POF promotion

Comment Type T Comment Status X

Micro-pigtail or lens shall be optional, not mandatory.

SuggestedRemedy

Delete "Micro-pigtail / lens"

Proposed Response Response Status O

P802.3bv D1.0 Gigabit Ethernet Over Plastic Optical Fiber 1st Task Force review comments

Cl 115 SC 115.2.2 P82 L33 # 98  
 Satoshi Takahashi POF promotion  
 Comment Type E Comment Status X  
 (Table 115-1, 3rd line, 2nd row).  
 SuggestedRemedy  
 Change "85C" to "85 C"  
 Proposed Response Response Status O

Cl 115 SC 115.2.2 P82 L33 # 97  
 Satoshi Takahashi POF promotion  
 Comment Type T Comment Status X  
 Lowest ambient temperature for Type B shall be -40 C.(Table 115-1, 2nd line, 2nd row)  
 SuggestedRemedy  
 Change "-45" to "-40"  
 Proposed Response Response Status O

Cl 115 SC 115.2.2 P82 L34 # 99  
 Satoshi Takahashi POF promotion  
 Comment Type E Comment Status X  
 (Table 115-1, 3rd line, 3rd row)  
 SuggestedRemedy  
 Change "4inline" to "4 inline", "0inline" to "0 inline".  
 Proposed Response Response Status O

Cl 30 SC P L # 93  
 Grow, Robert RMG Consulting  
 Comment Type T Comment Status X  
 aSymbolError during Carrier.  
 Make sure assertion of RX\_ER for other than TX\_ER conveyed across the interface is counted. If that can't be done, the 1000 Mb/s BEHAVIOUR needs to be modified.  
 SuggestedRemedy  
 Proposed Response Response Status O

Cl 30 SC P L # 111  
 Grow, Robert RMG Consulting  
 Comment Type T Comment Status X  
 Clause 30 may need updates based on content adopted for Clause 45 management.  
 SuggestedRemedy  
 Authorize the editor to produce changes to Clause 30 as appropriate for adopted Clause 45 content.  
 Proposed Response Response Status O

Cl 35 SC 35.1.1 P L # 94  
 Grow, Robert RMG Consulting  
 Comment Type ER Comment Status X  
 Does item g) need to be modified for us?  
 SuggestedRemedy  
 Proposed Response Response Status O

P802.3bv D1.0 Gigabit Ethernet Over Plastic Optical Fiber 1st Task Force review comments

Cl 45 SC P L # 110  
 Grow, Robert RMG Consulting

Comment Type E Comment Status X

A number of registers need to be defined for 1000BASE-RH. We can follow 1000BASE-KX and define control and status registers for the PHY, or use the generic capabilities of 1.0 and 1.1 which seem to fulfill all PMA/PMD needs.

SuggestedRemedy

If separate registers are desired, change Table 45-3 for PMA/PMD GEPOF register(s), recommend 1.158 for control, 1.159 for status.

If generic registers are used, then in 45.2.1.2.3, Register/bit 1.1.7 define what GEPOF detailed faults this bit is based on.

Proposed Response Response Status O

Cl 45 SC P23 L1 # 100  
 Pérez-Aranda, Rubén KDPOF

Comment Type ER Comment Status X

Propose text for Clause 45

SuggestedRemedy

Proposed text is attached in gepof\_management\_mdio\_v1.4

Proposed Response Response Status O

Cl 45 SC 45.2.1.1.4 P L # 108  
 Grow, Robert RMG Consulting

Comment Type T Comment Status X

Local and remote loopback are not described in Clause 114. Should PMA/PMD loopback be supported and if so should it be mandatory? Recommend mandatory local and remote loopback.

SuggestedRemedy

If remote loopback is supported, a reference to the definition should be added to 45.2.1.1.4. And it should be defined in Clause 114.

If local loopback is mandatory, Clause 45 bit 1.0.0 controls the function and 1000BASE-H should be added to the port type list in 45.2.1.1.5, if optional, no change to 45.2.1.1.5 is necessary. If either mandatory or optional, local loopback should be defined in Clause 114.

If not supported, 1000BASE-H non-support should be added to both of the above sub-clauses.

Proposed Response Response Status O

Cl 45 SC 45.5 P L # 109  
 Grow, Robert RMG Consulting

Comment Type ER Comment Status X

Editor needs to generate PICs changes based on occurrence of shalls contained in the clause text after new text is added.

SuggestedRemedy

See comment.

Proposed Response Response Status O

Cl 78 SC P L # 95  
 Grow, Robert RMG Consulting

Comment Type ER Comment Status X

Need to list 1000BASE-RH in this table

SuggestedRemedy

Insert new row into Table 78-1 below 1000BASE-T (below 1000BASE-T1 if it is approved currently or before this project):

1000BASE-RH 114, 115

Proposed Response Response Status O