

IEEE 802.3by 25 Gb/s Ethernet 1st Task Force review comments

CI 030 SC 30.3.2.1.5 P 29 L 52 # 1 [REDACTED]
 Booth, Brad Microsoft
 Comment Type E Comment Status X
 Media Independent Interface is in the definitions as referencing Clause 22.
 SuggestedRemedy
 When generically referencing XGMII, XLGMII, etc. use "media independent interface" as in 69.2.1.
 Proposed Response Response Status O

CI 106 SC 106.4 P 96 L 13 # 4 [REDACTED]
 Booth, Brad Microsoft
 Comment Type E Comment Status D
 Inconsistent use of 25 Gb/s and 25Gb/s.
 SuggestedRemedy
 Search draft and replace 25Gb/s with 25 Gb/s.
 Proposed Response Response Status O

CI 069 SC 69.1.2 P 50 L 25 # 2 [REDACTED]
 Booth, Brad Microsoft
 Comment Type E Comment Status D
 Definition of 25G-MII not consistent.
 SuggestedRemedy
 25G-MII is defined as 25 Gigabit, not 25 Gb/s. Use 25 Gigabit.
 Replicated in all the layer diagrams throughout the draft.
 Proposed Response Response Status O

CI 000 SC 0 P 1 L 1 # 5 [REDACTED]
 Booth, Brad Microsoft
 Comment Type E Comment Status D
 There are multiple instances throughout the draft where the term "25 Gigabit Media Independent Interface (25G-MII)" is used over and over; whereas, the draft uses "25G-AUI" throughout without the extra verbiage.
 SuggestedRemedy
 After the first use of "25 Gigabit Media Independent Interface (25G-MII)" use the acronym "25G-MII" only.
 Proposed Response Response Status O

CI 106 SC 106 P 93 L 1 # 3 [REDACTED]
 Booth, Brad Microsoft
 Comment Type T Comment Status D
 I've noticed that we've become very inconsistent with our titles, definitions and acronyms. Clause 106 appears to follow the conventions used in 802.3ba, which is inconsistent with the definitions. Technical because it relates to definitions.
 SuggestedRemedy
 Change title of clause to read:
 Reconciliation Sublayer (RS) and 25 Gigabit Media Independent Interface (25G-MII)
 Proposed Response Response Status O

CI 108 SC 108.3 P 109 L 4 # 6 [REDACTED]
 Booth, Brad Microsoft
 Comment Type E Comment Status X
 Clause 83 is for 40G and 100G. Statement of incompatibility is not required and could create confusion.
 SuggestedRemedy
 Delete sentence:
 "The PMA defined in Clause 83 is incompatible with the 25GBASE-R RS-FEC."
 Proposed Response Response Status O

IEEE 802.3by 25 Gb/s Ethernet 1st Task Force review comments

Cl 000 SC 0 P 1 L 1 # 7

Booth, Brad Microsoft

Comment Type E Comment Status D

Inconsistent use of 25 Gigabit Attachment Unit Interface.

SuggestedRemedy

Search and replace 25 Gb/s or 25Gb/s Attachment Unit Interface with 25 Gigabit Attachment Unit Interface

Proposed Response Response Status O

Cl 110 SC 110.10 P 153 L 29 # 8

Booth, Brad Microsoft

Comment Type T Comment Status X

Proposed text for cable assembly with no FEC.

SuggestedRemedy

Add:
c) Cable assembly that supports links between two PHYs that do not include either the 25GBASE-R RS-FEC or the BASE-R FEC sublayers are considered an engineered links. While beyond the scope of this standard, it is recommended implementers consider the COM requirements.

Proposed Response Response Status O

Cl 045 SC 45.2.1.95 P 42 L 40 # 9

Ran, Adeo Intel

Comment Type E Comment Status X

Some of the RS-FEC MDIO registers that are re-used in clause 108 include references to clause 91. References to clause 108 should be added.

The following subclauses need to be brought in after 45.2.1.95:

45.2.1.101.1 and 45.2.1.101.2 (add references to 108.5.3.2)

45.2.1.102.1 and 45.2.1.102.2 (add references to clause 108). Note that the text suggested below is valid for both the 108 meaning of "locked the single lane" and the 91 meaning of "locked and aligned all lanes".

45.2.1.102.7, 45.2.1.102.8, 45.2.1.102.9 (add references to 108.5.3.2)

45.2.1.103 (add reference to 108.6.6)

45.2.1.104 (add reference to 108.6.7)

SuggestedRemedy

Bring in the referenced subclauses from the base document.

Change "(see 91.5.3.3)" to "(see 91.5.3.3 and 108.5.3.2)", whenever it appears in these subclauses.

In 45.2.1.102.1 (PCS align status), change from
"When read as a one, bit 1.201.15 indicates that the RS-FEC described in Clause 91 has locked and aligned all transmit PCS lanes. When read as a zero, bit 1.201.15 indicates that the RS-FEC has not locked and aligned all transmit PCS lanes."

to
"This bit indicates the PCS alignment status of the RS-FEC. For the RS-FEC described in Clause 91, PCS alignment is defined as block lock, alignment markers lock and deskew of all 20 transmit PCS lanes. For the RS-FEC described in Clause 108, PCS alignment is defined as block lock of the transmit PCS signal. When read as a zero, this bit indicates that the RS-FEC has not obtained PCS alignment. When read as one, this bit indicates that the RS-FEC has obtained PCS alignment."

In 45.2.1.102.2 (RS-FEC align status), change from
"When read as a one, bit 1.201.14 indicates that the RS-FEC described in Clause 91 has locked and aligned all receive RS-FEC lanes. When read as a zero, bit 1.201.14 indicates that the RS-FEC has not locked and aligned all receive RS-FEC lanes."

To
"This bit indicates the PMA alignment status of the RS-FEC. For the RS-FEC described in Clause 91, PMA alignment is defined as alignment marker lock and deskew of all four lanes on the PMA service interface. For the RS-FEC described in Clause 108, PMA

IEEE 802.3by 25 Gb/s Ethernet 1st Task Force review comments

alignment is defined as codeword marker lock on the PMA service interface. When read as a zero, this bit indicates that the RS-FEC has not obtained PMA alignment. When read as one, this bit indicates that the RS-FEC has obtained PMA alignment."

Proposed Response Response Status

Cl 108 SC 108.6 P 121 L 20 # 10

Ran, Adee Intel

Comment Type **E** Comment Status **X**

MDIO control variable names should match the variable names in clause 45. In some cases they do not.

In these cases, names in clause 45 text do not match names in clause 45 tables; It seems that the text names are more generic and suitable for a single-lane RS-FEC too. If possible, clause 45 tables should be corrected to match the text, but this may need to be done through maintenance.

SuggestedRemedy

Use the following variable names from clause 45 instead of the names in clause 108 tables 108-2 and 108-3 (based on clause 45 text):

- 45.2.1.102.2 RS-FEC align status (row 4 of table 108-2)
- 45.2.1.103 RS-FEC corrected codewords counter (row 5 of table 108-2)
- 45.2.1.104 RS-FEC uncorrected codewords counter (row 6 of table 108-2)
- 45.2.1.106 RS-FEC symbol error counter lane 0 (row 7 of table 108-2)
- 45.2.1.102.1 PCS align status (row 1 of table 108-3)

Consider changing the tables in clause 45 toom or taking this part to maintenance.

Proposed Response Response Status

Cl 109 SC 109.4.6.1 P 133 L 34 # 11

Ran, Adee Intel

Comment Type **E** Comment Status **X**

Variable to MDIO register mapping paragraph in 109.4.6.1 (Transmit PRBS31 generation) refers to the _receive_ process and to variables that seem irrelevant for this subclause (marked in *), and one relevant variable is missing:

- PRBS31_Tx_checker_ability *
- PRBS31_Rx_checker_ability *
- PRBS31_enable
- PRBS_Tx_gen_enable
- (PRBS31_Tx_generator_ability is missing)

Other subclauses have similar mapping paragraphs, some of which refer to other irrelevant variables, and some other variables are missing.

- 109.4.6.2 (receive PRBS31 generation):
- PRBS31_Rx_checker_ability *
- PRBS31_enable
- PRBS_Rx_gen_enable
- (PRBS31_Rx_generator_ability is missing)

- 109.4.6.3 (transmit PRBS31 checking):
- PRBS31_enable
- PRBS_Tx_check_enable
- (PRBS31_Tx_checker_ability is missing)

- 109.4.6.4 (receive PRBS31 checking):
- PRBS31_enable
- PRBS_Rx_check_enable
- (PRBS31_Rx_checker_ability is missing)

- 109.4.6.5 (transmit PRBS9 generation):
- PRBS9_enable
- PRBS_Tx_gen_enable
- (PRBS9_Tx_generator_ability is missing)

- 109.4.6.6 (receive PRBS9 generation):
- PRBS9_enable
- PRBS_Rx_gen_enable
- (PRBS9_Rx_generator_ability is missing)

SuggestedRemedy

Remove irrelevant variables and add missing ones in each subclause, as listed above.

IEEE 802.3by 25 Gb/s Ethernet 1st Task Force review comments

Proposed Response Response Status

CI 110 SC 110.1 P 141 L 48 # 12

Ran, Adee Intel

Comment Type **T** Comment Status **X**

PMD BER (or DER) requirement when the BASE-R (clause 74) FEC is used is currently TBD. As presented in ran_020415_25GE_adhoc, it is proposed to set the limit to 1e-8, and use the presented limits for bmax (in COM parameters) and codeword error rate (in receiver tolerance test).

(See http://www.ieee802.org/3/by/public/adhoc/architecture/ran_020415_25GE_adhoc.pdf)

SuggestedRemedy

Change TBD to 1e-8 in 110.1, in 110.8.4.1, and in table 110-8 (DER_0 for CA-S).
 Change TBD to 4.7e-10 in table 110-5, test 3 values.
 Change TBD to 0.5 in table 110-8, b_max(n) for CA_S.

Proposed Response Response Status

CI 107 SC 107.1.2 P 99 L 22 # 13

Ran, Adee Intel

Comment Type **T** Comment Status **X**

An additional exception is required to differentiate between clause 49 PCS and clause 107 PCS: Operation with RS-FEC requires a higher threshold in the BER monitor, to prevent being triggered by only two uncorrectable codewords.

Further details to be presented.

SuggestedRemedy

BER monitor for clause 107 should assert hi_ber when ber_cnt>=97 with an observation window of 2 milliseconds.

Editorial license provided to implement in the most readable way.

Proposed Response Response Status

CI 110 SC 110.6 P 144 L 42 # 14

Ran, Adee Intel

Comment Type **T** Comment Status **X**

Although the baseline proposal did not mention operation with no FEC, several presentations showed the desire to enable this mode of operation, and all auto-negotiation proposals seem to address this mode as part of the possible resolutions.

BER without any FEC is already specified in 110.1. The channel requirements to achieve this BER are yet to be defined, and may be beyond the scope of the standard. Auto-negotiation rules should also be defined.

Regardless of the electrical specification and the AN rules, there should be a functional description of this mode.

SuggestedRemedy

Add a third "no-FEC" mode to the list in 110.6.

Change the guidelines in 110.1, the requirements in 110.8.4.1, and the cable assembly description text in 110.10, to use "mode" instead of sublayers in use.

Add the following text to the first paragraph of 110.8.4.2:
 "When no-FEC mode is used, the receiver shall comply with test 4."

Add a new cable assembly type in 110.10:
 c) Cable assembly that supports links between two PHYs that operate in no-FEC mode. This cable assembly type is designated as "cable assembly no-FEC" (CA-N).

Add text in 110.10.2 and a new column in table 110-7 for no-FEC. Maximum insertion loss to be defined/discussed.

Add a new column in table 110-8 for CA-N, with DER_0=1e-12, b_max=0.5.

Proposed Response Response Status

CI 108 SC 108.5.3.7 P 116 L 25 # 15

Frroth, Ingvar Marvell

Comment Type **T** Comment Status **X**

Figure 108-4 (Receive bit ordering): message block shows message symbol m511 as received before m512. This does not seem correct, the expected first symbol would be m513 (since k-1 = 513).

SuggestedRemedy

Edit Figure 108-4 so as to replace m511 with m513.

Proposed Response Response Status

IEEE 802.3by 25 Gb/s Ethernet 1st Task Force review comments

CI 030 SC 30.6.1.1.5 P 34 L 5 # 16
 Anslow, Pete Ciena
 Comment Type E Comment Status X
 The other entries in this list appear in speed and then distance order.
 SuggestedRemedy
 Unless there is a good reason not to, insert the 25G entries between the 10G and 40G entries.
 Proposed Response Response Status O

CI 030 SC 30.3.2.1.5 P 29 L 38 # 19
 Anslow, Pete Ciena
 Comment Type E Comment Status X
 The BEHAVIOUR DEFINED AS: section should be indented as per the APPROPRIATE SYNTAX: section.
 SuggestedRemedy
 Fix the indenting
 Proposed Response Response Status O

CI 045 SC 45.2.1.95 P 42 L 24 # 17
 Anslow, Pete Ciena
 Comment Type E Comment Status X
 The editing instruction contains: "... to "Single lane PHY FEC uncorrected blocks counter"". However, this should be "... to "Single lane PHY BASE-R FEC uncorrected blocks counter""
 SuggestedRemedy
 Change:
 "... to "Single lane PHY FEC uncorrected blocks counter"" to:
 "... to "Single lane PHY BASE-R FEC uncorrected blocks counter""
 Proposed Response Response Status O

CI 045 SC 45.2.1 P 35 L 20 # 20
 Anslow, Pete Ciena
 Comment Type T Comment Status X
 This draft is allocating Register 1.17 to the "25G PMA/PMD extended ability register", but the P802.3bn draft D1.3 has allocated 1.17 to "EPoC PMA/PMD ability register"
 Also, the last word "register" should not appear in the Register name column (even though it does in a few)
 SuggestedRemedy
 Change the row to:
 1.19, 25G PMA/PMD extended ability, 45.2.1.14c
 with consequent changes to what is currently 45.2.1.14a and changing the table there to Table 45-17c
 Proposed Response Response Status O

CI 045 SC 45.2.1.95 P 42 L 42 # 18
 Anslow, Pete Ciena
 Comment Type E Comment Status X
 Spurious "\"
 SuggestedRemedy
 Delete the spurious "\"
 Proposed Response Response Status O

CI 069 SC 69.1.2 P 50 L 32 # 21
 Baden, Eric Broadcom
 Comment Type E Comment Status X
 Should the lettered list after 69-2 include 4-octet wide interface for 25G MII (CL69, 69.1.2)
 SuggestedRemedy
 Proposed Response Response Status O

IEEE 802.3by 25 Gb/s Ethernet 1st Task Force review comments

Cl 074 SC 74.6 P 83 L 30 # 22
 Baden, Eric Broadcom
 Comment Type E Comment Status X
 change B0T to BT
 SuggestedRemedy
 Replace the letters ' B0T ' with ' BT '
 Proposed Response Response Status O

Cl 107 SC 107.1.2 P 99 L 20 # 26
 Baden, Eric Broadcom
 Comment Type E Comment Status X
 Why is the PMA interface one bit wide instead of 16 bits wide like in CL49?
 SuggestedRemedy
 Perhaps add more information as to why this interface is different?
 Proposed Response Response Status O

Cl 105 SC 105.4.1 P 83 L 30 # 23
 Baden, Eric Broadcom
 Comment Type E Comment Status X
 'so' should be 'some' ?
 SuggestedRemedy
 replace the text ' so ' with ' some '
 Proposed Response Response Status O

Cl 107 SC 107.2.1 P 101 L 22 # 27
 Baden, Eric Broadcom
 Comment Type TR Comment Status X
 Only scrambled IDLE generation required
 SuggestedRemedy
 Remove the requirement for a scrambled IDLE checker. That function would not aid in the receiver tests with the FEC enabled.
 Proposed Response Response Status O

Cl 105 SC 105.7 P 92 L 1 # 24
 Baden, Eric Broadcom
 Comment Type E Comment Status X
 Page is blank.
 SuggestedRemedy
 Delete page 92
 Proposed Response Response Status O

Cl 108 SC 108.5.2.2 P 109 L 49 # 28
 Baden, Eric Broadcom
 Comment Type T Comment Status X
 This comment about invalid block types is unnecessary. The letter #a information on line 41 indicates the RX FSM is executed. That FSM validates the block types.
 SuggestedRemedy
 remove these lines entirely as they are superfluous.
 Proposed Response Response Status O

Cl 107 SC 107.1.2 P 99 L 22 # 25
 Baden, Eric Broadcom
 Comment Type TR Comment Status X
 Is detection of scrambled IDLE required, or only generation?
 SuggestedRemedy
 Only scrambled IDLE generation is required. Remove the requirement for a scrambled IDLE checker
 Proposed Response Response Status O

IEEE 802.3by 25 Gb/s Ethernet 1st Task Force review comments

Cl 108 SC 108.5.4.2 P 111 L 9 # 29
 Baden, Eric Broadcom
 Comment Type **TR** Comment Status **X**
 The spacing between the CWs is 81920 and not 81960
 SuggestedRemedy
 replace 81960 with 81920 for the correct spacing of CW markers
 Proposed Response Response Status **O**

Cl 108 SC 108.5.3.6 P 115 L 43 # 30
 Baden, Eric Broadcom
 Comment Type **T** Comment Status **X**
 This comment about invalid block types is unnecessary. The letter #a information on line 41 indicates the RX FSM is executed. That FSM validates the block types.
 SuggestedRemedy
 Remove lines 43 thru 46.
 Proposed Response Response Status **O**

Cl 108 SC 108.5.3.7 P 116 L 25 # 31
 Baden, Eric Broadcom
 Comment Type **TR** Comment Status **X**
 For the message block, the message symbols range from 513 to 0, and not from 511 to 0.
 SuggestedRemedy
 Change m511 to m513 in the figure.
 Proposed Response Response Status **O**

Cl 108 SC 108.5.4.5 P 119 L 9 # 32
 Baden, Eric Broadcom
 Comment Type **TR** Comment Status **X**
 In figure 108-5. The variable test_cwm does not get set to true in this diagram. Is that correct, or where does it need to be set? Is test_cwm an input to the FSM, or a variable of the FSM?
 SuggestedRemedy
 Define the source and usage of test_cwm variable
 Proposed Response Response Status **O**

Cl 108 SC 108.5.4.5 P 120 L 1 # 33
 Baden, Eric Broadcom
 Comment Type **TR** Comment Status **X**
 In figure 108-6. The variable test_cw does not get set to true in this diagram. Is that correct, or where does it need to be set? Is test_cw an input to the FSM, or a variable of the FSM?
 SuggestedRemedy
 Define the source and usage of the test_cw variable.
 Proposed Response Response Status **O**

Cl 108 SC 108.5.4.2 P 117 L 23 # 34
 Baden, Eric Broadcom
 Comment Type **TR** Comment Status **X**
 Cwm_valid checks all 4 sets of AMs at the same time and allows 12 nibbles of error over all 48 nibbles in the CW. That is not consistent with the intention, or with how 802.3bj functions. Cwm_valid should only check the first 'AM' of the CW marker, and whether 9 or more nibbles are correct in that AM.
 SuggestedRemedy
 Cwm_valid should only check the validity of the first 12 nibbles of the CW marker, and whether 9 or more nibbles are correct in that space.
 Proposed Response Response Status **O**

IEEE 802.3by 25 Gb/s Ethernet 1st Task Force review comments

Cl 108 SC 108.5.3.3 P 115 L 5 # 35
Baden, Eric Broadcom

Comment Type TR Comment Status X

When codeword marker lock is FALSE, the output of the FEC is undefined, and the input to the PMA is unknown ('X'). We need to guarantee block_lock is lost by the PCS. We cannot guarantee hi_ber will be triggered with unknown data. We should drive the input to the PMA with zeros (effectively a tx_disable) to ensure block lock is lost by the ensuing PCS.

SuggestedRemedy

When CW marker lock is not achieved by the FEC, the FEC should drive zeros to the PMA, guaranteeing that the receive PCS loses block lock.

Proposed Response Response Status O

Cl 108 SC 108.5.3.6 P 115 L 41 # 36
Baden, Eric Broadcom

Comment Type TR Comment Status X

The function within the FEC to insert IDLEs or Ordered sets to account for CWM deletion shall not re-encode. It shall only insert IDLEs or Ordered sets, and shall not insert any other block types. Only re-scrambling is required and specified.

SuggestedRemedy

The PCS does not re-encode, but should insert the required block types and re-scramble.

Proposed Response Response Status O

Cl 045 SC 45.2.1.4 P 36 L 46 # 37
Marris, Arthur Cadence

Comment Type E Comment Status X

RO should not be underlined because the editorial instruction is insert rather than change.

SuggestedRemedy

Remove underlining of RO.

Proposed Response Response Status O

Cl 045 SC 45.2.1 P 35 L 21 # 38
Marris, Arthur Cadence

Comment Type T Comment Status X

Use of register 1.17 clashes with EPOC. There are other clashes with 802.3bn, 802.3bq and 802.3bw.

SuggestedRemedy

Implement fixes outlined in http://www.ieee802.org/3/by/public/adhoc/architecture/anslow_021815_25GE_adhoc.pdf with editorial license

Proposed Response Response Status O

Cl 074 SC 74.5.1a P 63 L 5 # 39
Nowell, Mark Cisco

Comment Type E Comment Status X

Typo in using the word "encoder" instead of "decoder" on lines 5 & 6.

SuggestedRemedy

Modify two sentences:

From:

When rx_mode is QUIET, the FEC encoder logic may deactivate functional blocks to conserve energy. When rx_mode is DATA, the FEC encoder logic operates normally.

To:

When rx_mode is QUIET, the FEC decoder logic may deactivate functional blocks to conserve energy. When rx_mode is DATA, the FEC decoder logic operates normally.

Proposed Response Response Status O

Cl 074 SC 74.6 P 63 L 30 # 40
Nowell, Mark Cisco

Comment Type E Comment Status X

Typo. Change B0T to BT in text "...shall be no more than 6144 B0T..."

SuggestedRemedy

Change:

...shall be no more than 6144 B0T...

To:

...shall be no more than 6144 BT...

Proposed Response Response Status O

IEEE 802.3by 25 Gb/s Ethernet 1st Task Force review comments

Cl 105 SC 105.4.2 P 85 L 1 # 41
 Nowell, Mark Cisco

Comment Type E Comment Status X

Fig 105-2 and 105-3 on pages 85 &86 are inconsistent in teh labeling of the FEC sublayer.

Fig 105-2 labels it FEC
 Fig 105-3 labels it FEC or RS-FEC (with a note 1)

Since we are calling these seperate sublayers I suggest being consistent with Fig 105-3

SuggestedRemedy

Reconcile to be consistent. Suggest using Fig 105-3 format for both and also adding note 1 in Fig 105-2

Proposed Response Response Status O

Cl 073 SC 73.6.4 P 54 L 31 # 42
 Marris, Arthur Cadence

Comment Type T Comment Status X

Editor's note states at the time draft 0.1 was created there was no baseline proposal for 25GBASE-CR technology abilities. If a base-line proposal is adopted in the March meeting Clause 73 will need to be updated accordingly.

SuggestedRemedy

Update Clause 73 to describe FEC negotiation for 25GBASE-CR if a baseline for this is adopted at this meeting.

Proposed Response Response Status O

Cl 107 SC 107.1.2 P 99 L 24 # 43
 Dudek, Mike QLogic

Comment Type T Comment Status X

The scrambled idle is a useful pattern that should be retained and generating it in the PCS is the easiest place.

SuggestedRemedy

Delete the editor's note.

Proposed Response Response Status O

Cl 107 SC 107.1.3 P 100 L 18 # 44
 Dudek, Mike QLogic

Comment Type E Comment Status X

Footnotes should be superscript both on FEC and AN

SuggestedRemedy

Make them superscript.

Proposed Response Response Status O

Cl 108 SC 108.5.3.2 P 114 L 36 # 45
 Dudek, Mike QLogic

Comment Type T Comment Status X

With the options to turn off the RS-FEC encoding that are included in this project (no FEC option) The additional option to turn off the error correction is not necessary. My understanding is that the performance with error correction bypassed is worse than when the RS-FEC encoding is turned off (no FEC option).

SuggestedRemedy

Remove the added text, registers etc. required for the option to bypass the error correction with RS-FEC encoding.

Proposed Response Response Status O

Cl 110 SC 110.7.1 P 146 L 14 # 46
 Dudek, Mike QLogic

Comment Type T Comment Status X

The exact losses of the Transmitter and receiver differential controlled impedance losses between TP0 and TP1 are not given in 92A.4 due to the effects of test fixtures. It would be better to refer to the whole of the annex that includes information on the test boards and how their losses are accounted for in the measurements. (as is done in the equivalent reference in clause 92).

SuggestedRemedy

Change the reference from 92A.4 to 92A.

Proposed Response Response Status O

IEEE 802.3by 25 Gb/s Ethernet 1st Task Force review comments

Cl 109 SC 109.4.6.2 P 133 L 44 # 47
 Dudek, Mike QLogic
 Comment Type T Comment Status X
 This section is about generating the PRBS in the Receive direction not checking a PRBS.
 SuggestedRemedy
 Change "ability to check" to "ability to generate"
 Proposed Response Response Status O

Cl 110 SC 110. P 141 L 48 # 50
 Dudek, Mike QLogic
 Comment Type T Comment Status X
 A BER of 1e-8 is required with the BASE-R FEC. See ran_020415_25GE_adhoc
 SuggestedRemedy
 Replace TBD with 10^-8. Here and on page 149 line 24 and Page 150 line 17,
 Proposed Response Response Status O

Cl 109 SC 109.4.6.2 P 133 L 47 # 48
 Dudek, Mike QLogic
 Comment Type T Comment Status X
 What the "PMA client" is is not very explicit.
 SuggestedRemedy
 Replace "toward the PMA client" with "toward the PCS" on lines 47 and 50. Also on page 135 line 6 and 8
 Proposed Response Response Status O

Cl 110 SC 110.8.4.2 P 150 L 11 # 51
 Dudek, Mike QLogic
 Comment Type T Comment Status X
 We should allow PRBS31 as an alternative pattern for Test 4. This will enable the use of standard test equipment, (or the internal PRBS31 generators and checkers in the PMA). Allowing testing without having a PCS connected.
 SuggestedRemedy
 For Test 4 Change to Scrambled idle or PRBS31. Add to the footnote c, "or with a PRBS31 error detector as appropriate"
 Proposed Response Response Status O

Cl 109 SC 109.4.6.2 P 134 L 2 # 49
 Dudek, Mike QLogic
 Comment Type ER Comment Status X
 The reference to MDIO for PRBS31_RX_checker ability is before this function is described, and the MDIO for this is included in 109.4.6.4
 SuggestedRemedy
 Delete PRBS31_RX_checker ability" from this list.
 Proposed Response Response Status O

Cl 110 SC 110.8.4.2.2 P 150 L 44 # 52
 Dudek, Mike QLogic
 Comment Type T Comment Status X
 110.10.7 has different parameters for the different target systems. We need to be specific.
 SuggestedRemedy
 Add to bullet a). For tests 1 and 2 the COM parameters are those for CA-L, for test 3 the COM parameters are those for CA-S, and for test 4 the COM parameters are those for CA-N (Separate comment to add parameters for CA-N). Also on page 151 line 37 insert between a) and b). "The COM parameters are as modified by table 110-8" using the COM parameters for CA-L for tests 1 and 2, the COM parameters for CA-S for test 3, and the COM parameters for CA-N for test 4.
 Proposed Response Response Status O

IEEE 802.3by 25 Gb/s Ethernet 1st Task Force review comments

Cl 110 SC 110.8.4.2.4 P 152 L 1 # 53
 Dudek, Mike QLogic
 Comment Type T Comment Status X
 The jitter of the pattern generator should be set to match the local table, not that for 100GBASE-CR4.
 SuggestedRemedy
 Change "in table 92-8" to "in table 110-5"
 Proposed Response Response Status O

Cl 110 SC 110.10.2 P 154 L 10 # 56
 Dudek, Mike QLogic
 Comment Type T Comment Status X
 Left over paragraph referring to 100GBASE-CR4. The correct equivalent paragraph is the next paragraph
 SuggestedRemedy
 Delete the paragraph containing equation 92-26.
 Proposed Response Response Status O

Cl 110 SC 110.10 P 153 L 30 # 54
 Dudek, Mike QLogic
 Comment Type TR Comment Status X
 In order to enable the lowest latency systems an additional cable type should be added that doesn't require any FEC
 SuggestedRemedy
 Add an additional cable type CA-N that can be used with no FEC. Specification for CA-N to be 13.5dB loss with a COM DER of 10e-12. Full changes to be provided in a presentation.
 Proposed Response Response Status O

Cl 110A SC 110A.7 P 225 L 42 # 57
 Dudek, Mike QLogic
 Comment Type T Comment Status X
 The Channel operating margin should reference 25Gbase-CR not 100GBASE-CR4.
 SuggestedRemedy
 Change the reference from 92.A.7 to 110.10.7
 Proposed Response Response Status O

Cl 110 SC 110.10 P 153 L 36 # 55
 Dudek, Mike QLogic
 Comment Type T Comment Status X
 It is not true that all other parameters are identically specified as the COM parameters are different.
 SuggestedRemedy
 insert between "CA-S" and "All" "and some of the input parameters for the COM calculation are different."
 Proposed Response Response Status O

Cl 110B SC 110B.1.3.6 P 227 L 28 # 58
 Dudek, Mike QLogic
 Comment Type T Comment Status X
 Section 100B.1 appears to be all intended for SFP test fixtures, but that isn't clear.
 SuggestedRemedy
 Add SFP28 at the front of all the section headings in 11B.1.3
 Proposed Response Response Status O

IEEE 802.3by 25 Gb/s Ethernet 1st Task Force review comments

Cl 111 SC 111.1 P 169 L 28 # 59
 Dudek, Mike QLogic
 Comment Type **TR** Comment Status **X**
 In order to provide lower latency options for backplanes and for compatibility with the copper cable clause the BASE-R FEC and no FEC encoding options should be added to this backplane clause.
 SuggestedRemedy
 Add the BASE-R FEC and no FEC encoding options to the backplane clause.
 Proposed Response Response Status **O**

Cl 112 SC 112.6.2 P 189 L 9 # 62
 Dudek, Mike QLogic
 Comment Type **T** Comment Status **X**
 There is one transmitter lane, but the requirements for the aggressor lanes in table 95-7 are for receive lanes.
 SuggestedRemedy
 Change "no transmitter aggressor" to "no receive aggressor".
 Proposed Response Response Status **O**

Cl 111 SC 111.10.4.1 P 177 L 50 # 60
 Dudek, Mike QLogic
 Comment Type **T** Comment Status **X**
 There is only one lane.
 SuggestedRemedy
 delete "on each lane"
 Proposed Response Response Status **O**

Cl 112 SC 112.10.3 P 193 L 25 # 63
 Dudek, Mike QLogic
 Comment Type **T** Comment Status **X**
 From the title of the document IEC 61753-021-2 is not applicable to this multimode fiber system.
 SuggestedRemedy
 Delete paragraph d).
 Proposed Response Response Status **O**

Cl 112 SC 112,5,4 P 187 L 19 # 61
 Dudek, Mike QLogic
 Comment Type **E** Comment Status **X**
 With only one lane "global" seems strange. and "For all lanes" and "for any lane" are also strange.
 SuggestedRemedy
 replace "a glogal indicator" with "an indicator" In table 112-4 delete "For any lane" and "For all lanes"
 Proposed Response Response Status **O**

Cl 112 SC 112.11.4.4 P 197 L 30 # 64
 Dudek, Mike QLogic
 Comment Type **T** Comment Status **X**
 Elsewhere (and in the value/comment) the laser safety level is called out as Class 1 not 1M.
 SuggestedRemedy
 Change the Feature to say "Hazard Level 1" not "Hazard Level 1M".
 Proposed Response Response Status **O**

IEEE 802.3by 25 Gb/s Ethernet 1st Task Force review comments

CI 004A SC 4a.4.2 P 199 L 22 # 65
 Dudek, Mike QLogic
 Comment Type T Comment Status X
 The note3 needs to reference the 25G-MII signal.
 SuggestedRemedy
 Add "or 25G-MII" so that the note reads
 NOTE 3—For 10 Gb/s and 25 Gb/s operation, the spacing between two packets, from the last bit of the FCS field of the first packet to the first bit of the Preamble of the second packet, can have a minimum value of 40 BT (bit times), as measured at the XGMII or 25G-MII receive signals at the DTE.
 Proposed Response Response Status O

CI 093A SC 93A.1 P 205 L 20 # 66
 Dudek, Mike QLogic
 Comment Type T Comment Status X
 25G-AUI (chip to chip) is missing from Table 93A-2
 SuggestedRemedy
 Add 25G-AUI C2C (Annex 109A) Table 83D-6
 Proposed Response Response Status O

CI 109B SC 109B.4.4.2 P 217 L 21 # 67
 Dudek, Mike QLogic
 Comment Type T Comment Status X
 Some of the references for the module output are incorrectly pointing to the host output sections in Annex 83E. Unfortunately this appears to be an error in 802.3bm that is also being incorporated into IEEE 802.3 2015.
 SuggestedRemedy
 Change the following references for the module output.
 TM9, TM10 and TM11 to 83E.3.2.1.
 Proposed Response Response Status O

CI 109B SC 109B.4.4.2 P 217 L 20 # 68
 Dudek, Mike QLogic
 Comment Type T Comment Status X
 There is an error in the PICS for the module output. Unfortunately this also exists in 802.3bm and the 802.3 2015 project. The value for the module output transition time should be greater than 12ps as is shown in tables 83E-3 in both 802.3bm and the 802.3 2015.
 SuggestedRemedy
 Change the value of TM8 to greater than or equal to 12ps,
 Proposed Response Response Status O

CI 110C SC 110C.1 P 233 L 20 # 69
 Dudek, Mike QLogic
 Comment Type T Comment Status X
 The reference to the systems using CA-S cables should refer to the Clause 49 FEC. The bypassing of error correction for the RS-FEC does not operate as well as no FEC so should not be described. The sentence can also be better written.
 SuggestedRemedy
 Change "The CA-S specifications enable a shorter reach of 3 m with lower loss than CA-L, and are required for compatibility with 25GBASE-CR PHYs that bypass RS-FEC error correction or that do not include the RS-FEC sublayer" to
 "Lower latency and power options are available using 25GBASE-CR PHY's that use the KR FEC or no FEC. These options require the CA-S specifications which have a shorter reach of 3 m with lower loss than CA-L."
 Proposed Response Response Status O

CI 001 SC 1.3 P 24 L 15 # 70
 Dudek, Mike QLogic
 Comment Type T Comment Status X
 Why is the footnote that describes where to find SFF documents being deleted.
 SuggestedRemedy
 Re-instate the footnote and apply it to all the SFF specifications.
 Proposed Response Response Status O

IEEE 802.3by 25 Gb/s Ethernet 1st Task Force review comments

CI 045 SC 45.2.1.95 P 42 L 23 # 71
 Dudek, Mike QLogic

Comment Type E Comment Status X

The change instruction is missing the "BASE-R"

SuggestedRemedy

Change :"
 Single lane PHY FEC" to "Single lane PHY BASE_R FEC"

Proposed Response Response Status O

CI 069 SC 69.1.2 P 50 L 16 # 72
 Dudek, Mike QLogic

Comment Type TR Comment Status X

In order to provide a lower latency backplane option the RS-FEC should be made optional using the Firecode or no FEC as alternates.

SuggestedRemedy

Change Figure 69-1a block from "RS-FEC" to "FEC" with a footnote optional/conditional. Under the diagram say FEC=REED-SOLOMON FORWARD ERROR CORRECTION or BASE-R FORWARD ERROR CORRECTION. Also in Table 69-1a Change RS-FEC to optional and insert extra column of Clause 74 FEC optional. Also in Table 105-2 for 25GBASE-KR add clause 74 as optional and change clause 108 to optional.

Proposed Response Response Status O

CI 069 SC 69.1 P 50 L 51 # 73
 Dudek, Mike QLogic

Comment Type T Comment Status X

The referencing of both chip to chip and chip to module annexes for 25G is not consistent with what is done for 40G and 100G where only the chip to chip annexes are referenced.

SuggestedRemedy

Either Delete Annex 109B or add Annexes 83B and Annex 83E to item g) and Annex 83B to item h)

Proposed Response Response Status O

CI 078 SC 78.1.4 P 72 L 26 # 74
 Dudek, Mike QLogic

Comment Type T Comment Status X

Chip to module is not included for CAUI-4 in Table 78-1. (Due I believe to the optical modules not being capable of deep sleep mode). It is inconsistent that annex 109B is included in the table.

SuggestedRemedy

Delete Annex 109B or add 83E to the CAUI-4 row.

Proposed Response Response Status O

CI 105 SC 105.4.1 P 83 L 30 # 75
 Dudek, Mike QLogic

Comment Type E Comment Status X

typo

SuggestedRemedy

replace "so" with "some"

Proposed Response Response Status O

CI 107 SC 107.4 P 104 L 37 # 76
 Brown, Matthew APM

Comment Type E Comment Status X

There is no need to explicitly call out the the references of a referenced subclause. Many or most subclauses have references.

SuggestedRemedy

Delete "and its references" in the following locations:

page 104 line 38
 page 109 line 14
 page 171 line 30
 page 185 line 27

Proposed Response Response Status O

IEEE 802.3by 25 Gb/s Ethernet 1st Task Force review comments

Cl 108 SC 108.3 P 109 L 6 # 77
 Brown, Matthew APM
 Comment Type E Comment Status X
 The word "also" is in the wrong place for its intent.
 SuggestedRemedy
 Either delete "also" or put it at the beginning of the sentence.
 Proposed Response Response Status O

Cl 108 SC 108.5.2.4 P 111 L 9 # 80
 Brown, Matthew APM
 Comment Type E Comment Status X
 It is sufficient (and common) to use "64B/66B blocks".
 SuggestedRemedy
 Change "64B/66B encoded blocks" to "64B/66B blocks".
 Proposed Response Response Status O

Cl 108 SC 108.5.2.2 P 109 L 45 # 78
 Brown, Matthew APM
 Comment Type E Comment Status X
 "periodical" is not the correct word
 SuggestedRemedy
 Change "periodical" to "periodic".
 Proposed Response Response Status O

Cl 108 SC 108.5.3.2 P 114 L 18 # 81
 Brown, Matthew APM
 Comment Type T Comment Status X
 It is not clear what the following note is saying:
 "NOTE—The PHY may rely on the error correction capability of the 25GBASE-R RS-FEC sublayer to achieve its performance objectives. It is recommended that acceptable performance of the underlying link is verified before error correction is bypassed."
 SuggestedRemedy
 Please clarify.
 Proposed Response Response Status O

Cl 108 SC 108.5.1 P 110 L 14 # 79
 Brown, Matthew APM
 Comment Type E Comment Status X
 In figure 108-2...
 Use of CW which is not defined. Use "codeword" instead to be consistent with rest of clause.
 SuggestedRemedy
 In figure 108-2...
 Change all instances of "CW" with "codeword".
 Proposed Response Response Status O

Cl 108 SC 108.5.3.6 P 115 L 40 # 82
 Brown, Matthew APM
 Comment Type T Comment Status X
 Regarding list item c, the inclusion of the PCS transmit encoding process was not included in the FEC/PCS baseline specification. However, this process or an equivalent process must be specified.
 SuggestedRemedy
 Retain item c as it is written or specify an alternate encoding in detail.
 Proposed Response Response Status O

IEEE 802.3by 25 Gb/s Ethernet 1st Task Force review comments

Cl 108 SC 108.5.3.6 P 115 L 48 # 83
Brown, Matthew APM

Comment Type T Comment Status X

The extra encoding instructions are not clearly tied to the process in the previous list.

SuggestedRemedy

Change:
"If rx_coded<1:0> is either 00 or 11, rx_coded_out<1:0> shall be set to rx_coded<1:0> and idle characters shall not be inserted at the next block after rx_coded_out."

To:
"If rx_coded<1:0> is either 00 or 11, the process in list item c shall set rx_coded_out<1:0> to rx_coded<1:0> and the process in list item b shall not insert idle characters at the next block after rx_coded_out."

Alternately, add these exceptions to list items b and c.

Proposed Response Response Status O

Cl 108 SC 108.5.4.2 P 117 L 47 # 84
Brown, Matthew APM

Comment Type T Comment Status X

The test_cwm is set to false in two locations in the state diagram. Instead, just refer to the state diagram.

SuggestedRemedy

Change:
"when the FIND_1ST state is entered"
To:
"according to the FEC synchronization state diagram in Figure 108-5."

Similarly, on same page, line 50
Change:
"when the TEST_CW state is entered"

To:
"according to the codeword monitor state diagram in Figure 108-6"

Proposed Response Response Status O

Cl 108 SC 108.5.4.4 P 118 L 13 # 85
Brown, Matthew APM

Comment Type E Comment Status X

redundant word

SuggestedRemedy

Change:
"codeword offset"
To:
"offset"

Proposed Response Response Status O

Cl 108 SC 108.6 P 120 L 44 # 86
Brown, Matthew APM

Comment Type E Comment Status X

Incorrect use of commas and run on sentence.

SuggestedRemedy

Replace:
"If MDIO is implemented, it shall map MDIO control bits to RS-FEC control variables as shown in Table 108-1, and MDIO status bits to RS-FEC status variables as shown in Table 108-2, and if a separated PMA (see 45.2.1) is connected to the FEC service interface it shall map additional MDIO status bits to additional RS-FEC status variables as shown in Table 108-3."

With:
"If MDIO is implemented, it shall map MDIO control bits to RS-FEC control variables as shown in Table 108-1 and MDIO status bits to RS-FEC status variables as shown in Table 108-2. If a separated PMA (see 45.2.1) is connected to the FEC service interface, it shall map additional MDIO status bits to additional RS-FEC status variables as shown in Table 108-3."

Proposed Response Response Status O

IEEE 802.3by 25 Gb/s Ethernet 1st Task Force review comments

Cl 109 SC 109.6.4.1 P 139 L 30 # 87
 Brown, Matthew APM
 Comment Type E Comment Status X
 Incorrect Heading Name
 SuggestedRemedy
 Change:
 "109.6.45.1 PMA"
 To:
 "109.6.45.1 PMA Functions"
 Proposed Response Response Status O

Cl 110 SC 110.8.4.2 P 150 L 6 # 90
 Brown, Matthew APM
 Comment Type E Comment Status X
 For each of the test parameter columns, there should be a brief description of each in the heading row.
 SuggestedRemedy
 In test 1 heading add "RS-FEC min. loss"
 In test 2 heading add "RS-FEC max. loss"
 In test 3 heading add "BASE-R FEC max. loss"
 In test 4 heading add "no FEC max. loss"
 Proposed Response Response Status O

Cl 110 SC 110.1 P 141 L 53 # 88
 Brown, Matthew APM
 Comment Type E Comment Status X
 It is not necessary to point to specific subclauses for the cable assembly if you do not do the same for the PMD transmitter and receiver.
 SuggestedRemedy
 Replace:
 "cable assembly meeting the requirements of 110.10"
 With:
 "compliant cable assembly"
 Proposed Response Response Status O

Cl 110 SC 110.8.4.2 P 150 L 7 # 91
 Brown, Matthew APM
 Comment Type E Comment Status X
 There is no need to call out the subclauses as they are a part of 110.10.7.2.
 SuggestedRemedy
 Delete "and its subclauses".
 Proposed Response Response Status O

Cl 110 SC 110.8.4.1 P 149 L 35 # 89
 Brown, Matthew APM
 Comment Type T Comment Status X
 The BASE-R FEC mode should be tested with a minimum cable insertion loss test similar to test 1 for the RS-FEC mode. Assuming a no-FEC mode is supported a similar test will be required for that mode.
 SuggestedRemedy
 Add a new test for the BASE-R FEC mode with the same channel characteristics as test 1 but with test pattern and receiver targets the same as for test 3.
 Add a new test for the no-FEC mode with the same channel characteristics as test 1 but with test pattern and receiver targets the same as for test 4.
 Since each of these modes are unique and the table includes a long of descriptive information, create a parameter table for each mode with two tests (three tables total).
 Proposed Response Response Status O

Cl 105 SC 105.1 P 81 L 40 # 92
 Brown, Matthew APM
 Comment Type T Comment Status X
 In Table 105-2, specify "M" or "O" for TBD values for 25GBASE-CR.
 SuggestedRemedy
 Set these values according once mandatory and optional modes are specified for 25GBASE-CR.
 Proposed Response Response Status O

IEEE 802.3by 25 Gb/s Ethernet 1st Task Force review comments

Cl 106 SC 106.1.2 P 94 L 27 # 93
 Brown, Matthew APM
 Comment Type E Comment Status X
 MAC has been used previously in the clause.
 SuggestedRemedy
 Replace "media access controller" with "MAC".
 Proposed Response Response Status O

Cl 106 SC 106.1.4 P 94 L 37 # 94
 Brown, Matthew APM
 Comment Type E Comment Status X
 The definitions of bit time and pause_quanta are being references.
 SuggestedRemedy
 Change "specified" to "defined" twice.
 Proposed Response Response Status O

Cl 106 SC 106.1.7.1 P 95 L 30 # 95
 Brown, Matthew APM
 Comment Type E Comment Status X
 XGMII is not mapped, the signals are.
 SuggestedRemedy
 Change "in the same was as XGMII is mapped"
 To "in the same way as for XGMII"
 Change in the following locations:
 page 95, lines 30, 35, 51
 Proposed Response Response Status O

Cl 106 SC 106.1.7.3 P 95 L 39 # 96
 Brown, Matthew APM
 Comment Type E Comment Status X
 Include the name of the primitive in the paragraph to be consistent with other similar subclauses.
 SuggestedRemedy
 Change "this primitive"
 To "the PLS_CARRIER.indication primitive"
 Similarly, on page 95, line 46
 Change "this primitive"
 To "the PLS_SIGNAL.indication primitive"
 Proposed Response Response Status O

Cl 107 SC 107.1.2 P 99 L 22 # 97
 Brown, Matthew APM
 Comment Type T Comment Status X
 Include scrambled idles test pattern generation and checker in PCS.
 The scrambled idles test pattern generation is required for PMD transmitter testing for 25GBASE-CR and 25GBASE-KR PMDs.
 A generator and checker is required for testing of an entire PHY with a 25G-AUI instantiation.
 SuggestedRemedy
 Remove editor's note.
 Proposed Response Response Status O

IEEE 802.3by 25 Gb/s Ethernet 1st Task Force review comments

CI 107 SC 107.1.3 P 100 L 31 # 98
Brown, Matthew APM

Comment Type E Comment Status X

Need consistent notes for FEC and AN amongst all of the layer diagrams.

SuggestedRemedy

Use one not for both FEC and AN, with the same text as in Figure 105-1.
"CONDITIONAL BASED ON PHY TYPE"

Also, in Figure 105-1, use a single note since both notes have the same text.

Proposed Response Response Status O

CI 107 SC 107.1.4 P 100 L 53 # 99
Brown, Matthew APM

Comment Type E Comment Status X

The use of Gtransfers was due to the interface being a multi-bit interface.

SuggestedRemedy

Change "Gtransfers/s" to "Gb/s".

Proposed Response Response Status O

CI 107 SC 107.1.4.1 P 101 L 7 # 100
Brown, Matthew APM

Comment Type E Comment Status X

PCS Interface should be PCS service interface

SuggestedRemedy

Change "PCS Interface" to "PCS service interface".

Proposed Response Response Status O

CI 107 SC 107.2 P 101 L 17 # 101
Brown, Matthew APM

Comment Type E Comment Status X

The heading "107.2 Physical Coding Sublayer (PCS)" is not required since this entire clause is exactly that. Also, there is only one subclause under 107.2.

SuggestedRemedy

Remove the heading 107.2 and promote 107.2.1 and its subclauses.

Proposed Response Response Status O

CI 107 SC 107.2.1 P 101 L # 102
Brown, Matthew APM

Comment Type T Comment Status X

The functionality in Clause 49 and 82.2.11 are more than definitions.
Also, the first reference to PCS is specifically the 25GBASE-R PCS.

SuggestedRemedy

Change "The PCS supports" to "The 25GBASE-R PCS supports".
Change "defined" to "specified" in the following locations
page 101 line 22
page 101 line 23
page 103 line 52
page 104 line 43

Proposed Response Response Status O

CI 110 SC 110.10.7.1.1 P 155 L 41 # 103
Brown, Matthew APM

Comment Type T Comment Status X

Should be specific about what is being calculated.

SuggestedRemedy

Change:
"The channel signal path from TP0 to TP5"
To:
"The S-parameters of the channel signal path from TP0 to TP5"

Proposed Response Response Status O

IEEE 802.3by 25 Gb/s Ethernet 1st Task Force review comments

CI 110 SC 110.10.7.2 P 156 L 46 # 104
 Brown, Matthew APM
 Comment Type T Comment Status X
 Subclauses should include 110.10.7.2.4.
 SuggestedRemedy
 Change:
 "110.10.7.2.3"
 To:
 "110.10.7.2.4"
 Proposed Response Response Status O

CI 110 SC 110.2 P 142 L 47 # 107
 Brown, Matthew APM
 Comment Type E Comment Status X
 The acronym PMD has been introduced and used multiple times prior to this subclause.
 SuggestedRemedy
 Change heading from:
 "Physical Medium Dependent (PMD) service interface"
 To:
 "PMD service interface"
 Proposed Response Response Status O

CI 110 SC 110.11 P 157 L 34 # 105
 Brown, Matthew APM
 Comment Type E Comment Status X
 Subclause 110.7 is the PMD functional characteristics. The PMD is specified in multiple subclauses. Since there is just one 25GBASE-CR PMD and it is this clause it is not necessary to call out the clause number(s) here. If it is necessary use the form "(x.x.x)" rather than "as per x.x.x". And there is no need to repoint to these subclauses in the next sentence.
 SuggestedRemedy
 Change ", as per 110.7" to "(110.7)" on line 33
 Change ",as per 110.10" to "(110.10)" on line 34
 Delete "of 110.8" and "of 110.10" on line 37.
 Proposed Response Response Status O

CI 110 SC 110.11.1 P 158 L 35 # 108
 Brown, Matthew APM
 Comment Type T Comment Status X
 It appears that the table only includes the data signals.
 SuggestedRemedy
 Change:
 "The contact assignments"
 To:
 "The transmit and receive data signal contact assignments"
 Proposed Response Response Status O

CI 110 SC 110.8 P 148 L 40 # 106
 Brown, Matthew APM
 Comment Type E Comment Status X
 110 includes specifications for the 25GBASE-CR PMD, MDI, and Channel. Subclause titles should be specific about this.
 SuggestedRemedy
 Change heading from:
 "25GBASE-CR electrical characteristics"
 To:
 "PMD electrical characteristics"
 Proposed Response Response Status O

CI 110B SC 110B.1.3.6 P 229 L 4 # 109
 Brown, Matthew APM
 Comment Type E Comment Status X
 Eqs. 110B-1 and 110B-2 are identical to 92-44 and 92-45.
 SuggestedRemedy
 Delete eqs. 110B-1 and 110B-2 and refer to eqs. 92-44 and 92-45, instead.
 Proposed Response Response Status O

IEEE 802.3by 25 Gb/s Ethernet 1st Task Force review comments

Cl **109B** SC **109B.4.4.4** P **217** L **40** # **110**
 Maki, Jeffery Juniper Networks

Comment Type **T** Comment Status **X**

"As 83E.1.1 with settings associated with Recommended_CTLE_value" is not compatible with mandatory use of Adaptive receiver. 25G-AUI chip to module needs to use autonomous Adaptive receiver.

SuggestedRemedy

Should read "As 83E.1.1 with autonomous adaptive CTLE."

Proposed Response Response Status **O**

Cl **105** SC **105.1.3** P **81** L **40** # **111**
 Wertheim, Oded Mellanox Technologie

Comment Type **E** Comment Status **X**

Table 105-2 indicates that 25G-MII (clause 106) is Mandatory for 25GBASE-CR, 25GBASE-KR, 25GBASE-SR. 25G-MII should be optional.

SuggestedRemedy

Change the table to indicate that 25G-MII is Optional for 25GBASE-CR, 25GBASE-KR, 25GBASE-SR.

Proposed Response Response Status **O**

Cl **108** SC **108.5.2.4** P **111** L **9** # **112**
 Wertheim, Oded Mellanox Technologie

Comment Type **ER** Comment Status **X**

20480 257-bit transcoded blocks are equivalent to 81920 64B/66B encoded blocks. (instead of 81960).

SuggestedRemedy

The distance between the beginning of successive codeword markers is therefore 20480 257-bit transcoded blocks, equivalent to 81920 64B/66B encoded blocks.

Proposed Response Response Status **O**

Cl **108** SC **108.4** P **109** L **13** # **113**
 Wertheim, Oded Mellanox Technologie

Comment Type **TR** Comment Status **X**

A 24576 bit time (983.04 ns) maximum delay where the latency target is 250ns creates an unnecessary burden on the buffers management. In addition the delay is inconsistent with table 105-3. Propose to change to 614.4ns (2.5x the Clause 74 maximum delay)

SuggestedRemedy

Change the maximum delay to 15360 bit time (614.4 ns). Update table 105.3 accordingly.

Proposed Response Response Status **O**

Cl **105** SC **105.5** P **90** L **47** # **114**
 Cober, Don CoMIRA Solutions Inc

Comment Type **ER** Comment Status **X**

The delay for 25GBASE-R RS-FEC in Sublayer Delay Constraints Table 105-3 does not match delay in 108.4.

SuggestedRemedy

Change 5th row to:

25GBASE-R RS-FEC | 24576 | 48 | 983.04 | See 108.4.

or appropriate to match Clause 108.4

Proposed Response Response Status **O**

IEEE 802.3by 25 Gb/s Ethernet 1st Task Force review comments

Cl 108 SC 108.4 P 109 L 12 # 115
 Cober, Don CoMIRA Solutions Inc

Comment Type T Comment Status X

Maximum delay in UI of equivalent FECs should scale based on codeword length.
 Maximum delay in ns of equivalent FECs should scale based on codeword length and inversely based on rate.

In Clause 74 the delay in UI is shown to scale based on codeword length:

10G = 2112 bits of CW , delay = 6144 UI
 40G = 4 x 2112 bits of CW , delay = 4 x 6144 = 24576 UI
 100G = 20 x 2112 bits of CW , delay = 20 x 6144 = 122880 UI

Since the Clause 108 FEC is using the same codeword length and structure of Clause 91, the delay in UI should be the same : 40960. Since the data rate is 1/4 of Clause 91 we would expect the max delay to be 4x~400ns =~1600ns.

A target delay of 250ns is very aggressive for 25G. In 100G the target was 100ns. The delay of the FEC layer can be broken into two parts, the CW accumulation and the decoding:

1. The codeword accumulation time is fixed for a given codeword size / datarate. In 100G this value is 5280/100G = 51.2ns. In 25G this is 5280/25G = 204.8ns.
2. The decoder time can vary depending on the hardware implementation (There is a tradeoff of area vs latency). In 100G the target is 100-51.2=48.8ns. A 25G target of 250ns would imply a decoder time of 250-204.8=45.2ns. To hit this target an implementation would need to use a 25G decoder of the same area (or greater) as a 100G decoder.

SuggestedRemedy

1. Change line 12 to:
 shall be no more than 40960 bit times (80 pause_quanta or 1638.4 ns)....
2. Update Table 105-3 to match.

Proposed Response Response Status O

Cl 108 SC 108.5.4.2 P 117 L 23 # 116
 Cober, Don CoMIRA Solutions Inc

Comment Type T Comment Status X

cwm_valid state variable is checking 48 nibbles (4 AMs) to find the edge of the codeword, while the original amp_valid for Clause 91.5.4.2.1 only checks for 12 (Only AM0 is sought for alignment).

The extra checking should not be required for 25G RSFEC if it is not needed for 100G RSFEC.

SuggestedRemedy

Change to:

cwm_valid
 Boolean variable that is set to true if the received 257-bit block is a valid codeword marker. Bits [0:23] and [32:55] of the candidate block are compared to the known 48 bits of the AM0 codeword marker on a nibble-wise basis (12 comparisons). If no more than 3 nibbles in the candidate block fail to match the corresponding known nibbles in the codeword marker, the candidate block is considered a valid codeword marker.

Proposed Response Response Status O

Cl 106 SC 1 P 93 L 6 # 117
 Nicholl, Gary Cisco Systems

Comment Type E Comment Status X

It is probably worth mentioning that Clause 106 is based on Clause 46. Suggest using a statement that is similar to the one included in section that is included in section 107.1.2 on page 99.

SuggestedRemedy

Suggest including a statement along the lines of " The 25Gigabit Reconciliation Sublayer (RS) is identical to the 10Gigabit Reconciliation Sublayer specified in Clause 49.

Proposed Response Response Status O

IEEE 802.3by 25 Gb/s Ethernet 1st Task Force review comments

Cl 107 SC 2 P 101 L 17 # 118
 Nicholl, Gary Cisco Systems

Comment Type E Comment Status X

This clause is essentially referencing Clause 49. Most of Clause 49 is simply referenced, so I am not sure Figure 107-2 and Figure 107-3 are special and copied directly into Clause , compared to all of the other Figures in Clause 49 that are not copied across.

SuggestedRemedy

I suggest not copying Figure 107-2 and Figure 107-3 , and simply referencing Clause 49, to be consistent with the rest of the detailed information and Figures in Clause 49 which are not copied.

Proposed Response Response Status O

Cl 105 SC 4.3.2.2 P 87 L 36 # 119
 Nicholl, Gary Cisco Systems

Comment Type E Comment Status X

I think the word 'trasmits' is missing in the follwoing sentence " The sublayer continuously a bit strea"

SuggestedRemedy

Replace with "The sublayer continuously transmits a bit stream"

Proposed Response Response Status O

Cl 107 SC 107.3 P 104 L 50 # 120
 Lusted, Kent Intel

Comment Type E Comment Status X

This paragraph is one sentence and it hard for a reader to determine what is mandated by the "shall" statements.

"If the 25GBASE-R PCS is part of a PHY configured for EEE fast wake operation the PCS shall encode and decode LPI as required, however it shall not perform the actions described in the transmit and receive state diagrams defined in Figure 49-12 and Figure 49-13 but behave as if in the TX_ACTIVE and RX_ACTIVE states depicted in those diagrams."

I think that the intent is 2-fold:

1. a PHY configured for EEE FW shall encode and decode LPI
2. a PHY configured for EEE FW shall behave as if in the TX_ACTIVE and RX_ACTIVE states when in the FW mode.

SuggestedRemedy

I don't have a good example. sorry.

Proposed Response Response Status O

Cl 105 SC 105.1.1 P 79 L 14 # 121
 Lusted, Kent Intel

Comment Type E Comment Status X

pointer to definition of frame loss ratio (see 1.4.223) is not correct.

P802.3bx draft 2.0 has frame loss ratio as 1.4.222. (see P8023_D2p0_SECTION1.pdf, pg 74, line 13)

SuggestedRemedy

Update to 1.4.222 if necessary.

Proposed Response Response Status O

IEEE 802.3by 25 Gb/s Ethernet 1st Task Force review comments

Cl 105 SC 105.4.1 P 83 L 30 # 122
 Lusted, Kent Intel
 Comment Type E Comment Status X
 typo. the interface includes some or all...
 SuggestedRemedy
 change "then the inter-sublayer service interface includes so or all..." to "change "then the inter-sublayer service interface includes some or all..."
 Proposed Response Response Status O

Cl 109 SC 109.2 P 130 L 23 # 125
 Ran, Adee Intel
 Comment Type E Comment Status X
 PMA service interface, so primitives should be PMA:*.
 Also in line 39.
 SuggestedRemedy
 Change PMD to PMA, 4 times.
 Proposed Response Response Status O

Cl 107 SC Figure 107-1 P 100 L 17 # 123
 Lusted, Kent Intel
 Comment Type E Comment Status X
 the 1 in FEC1 should be a superscript.
 same with the 2 in AN2
 SuggestedRemedy
 Consider changing the 1 in AN1 and 2 in AN2 to be superscript.
 Proposed Response Response Status O

Cl 109 SC 109.2 P 130 L 41 # 126
 Ran, Adee Intel
 Comment Type T Comment Status X
 "The PMA:IS_SIGNAL.indication primitive is generated through a set of Signal Indication Logic (SIL) that reports signal health based on receipt of the inst:IS_SIGNAL.indication from the sublayer below, data being received from the sublayer below, and bits being sent to the PMA client"
 This statement is unclear, and it seems that it actually means "implementation dependent SIL".

Cl 105 SC Figure 105-2 P 85 L 16 # 124
 Lusted, Kent Intel
 Comment Type T Comment Status X
 The FEC block shown on the inter-sublayer service interface can be optional or omitted depending on the phy type.
 It would also be useful to change "FEC" in the block to be "FEC or RS-FEC" as in Figure 105-3.
 SuggestedRemedy
 Update Figure 105-2 with appropriate note, such as "NOTE 1—OPTIONAL OR OMITTED DEPENDING ON PHY TYPE", and mark FEC block appropriately.
 change "FEC" in the block to be "FEC or RS-FEC"
 Proposed Response Response Status O

Also, the requirement to relay the IS_SIGNAL.indication from the sublayer below should be normative when it has the value FAIL.
 SuggestedRemedy
 Change this paragraph to read:
 The PMA:IS_SIGNAL.indication primitive is generated based on receipt of the inst:IS_SIGNAL.indication from the sublayer below and PMA internal signal indication methods at the discretion of the implementor. When the SIGNAL_OK parameter of inst:IS_SIGNAL.indication from the sublayer below has the value FAIL, or the PMA internally indicates no signal, the SIGNAL_OK parameter of the PMA:IS_SIGNAL.indication primitive shall have the value FAIL. Otherwise, SIGNAL_OK shall have the value OK.
 Proposed Response Response Status O

IEEE 802.3by 25 Gb/s Ethernet 1st Task Force review comments

Cl 108 SC 108.2 P 115 L 6 # 127
 Ran, Adee Intel

Comment Type T Comment Status X

The current text in subclause 108.2 makes the RS-FEC output undefined when SIGNAL_OK is FAIL. This is fine if the PCS is the client of the RS-FEC and FEC:IS_SIGNAL.indication is available to it. However, if 25G-AUI separates the RS-FEC and the PCS, then the SIGNAL_OK might not be available to the PCS.

We need to guarantee that the PCS identifies this condition, so that upper layers can be informed and AN restarted when the link is interrupted. This could be achieved with pervasive management, but a solution that does not involve management is preferable.

In order to guarantee that "multiple blocks are marked as bad" and cause hi_ber that will restart AN (as suggested in 108.5.3.3), it is required that the RS-FEC output be well-defined with blocks marked as bad even after codeword marker lock is lost (restart_lock is set to true and SIGNAL_OK becomes FAIL).

This can be achieved by continuing to send 64b/66b blocks with corrupted headers when SIGNAL_OK is FAIL (FEC_align_status is false and codewords are uncorrectable). The Reed-Solomon decoder (108.5.3.2) includes this behavior already - the only requirement is to continue passing its output to the service interface.

SuggestedRemedy

Delete the sentence "When SIGNAL_OK is FAIL, the rx_bit parameter of the FEC:IS_UNITDATA.indication primitive is undefined."

Proposed Response Response Status O

Cl 108 SC 108.5.2.4 P 111 L 19 # 128
 Ran, Adee Intel

Comment Type T Comment Status X

Values of RSVD3, RSVD7 and Pad are TBD.

SuggestedRemedy

Change RSVD3 to hexadecimal FF and RSVD7 to hexadecimal 00 everywhere.

Change Pad to 0.

Delete editor's note.

Proposed Response Response Status O

Cl 108 SC 108.5.4 P 117 L 3 # 129
 Ran, Adee Intel

Comment Type T Comment Status X

EEE signaling over the RS-FEC sublayer is not addressed

SuggestedRemedy

A detailed proposal should be provided.

Proposed Response Response Status O

Cl 110 SC 110.10 P 153 L 13 # 130
 Ran, Adee Intel

Comment Type T Comment Status X

SFP28 and QSFP28 were not part of the adopted nomenclature. SFP28 appears in the normative reference list, but QSFP does not.

SuggestedRemedy

Adopt the terms SFP28 and QSFP28 for the two MDI connector types.

Add a reference to SFF-8665 (QSFP28) in 1.3.

Remove editor's note.

Proposed Response Response Status O

Cl 069 SC 69.1.2 P 50 L 14 # 131
 Dawe, Piers Mellanox

Comment Type E Comment Status X

Looks unfinished.

SuggestedRemedy

In Figure 69-1, make the stack wider so 25GBASE-R PCS fits on one line, like Figure 105-1.

Proposed Response Response Status O

IEEE 802.3by 25 Gb/s Ethernet 1st Task Force review comments

Cl 078 SC 78.1.4 P 72 L 21 # 132
 Dawe, Piers Mellanox
 Comment Type E Comment Status X
 Entries not in the usual order (slow to fast, short to long or ...).
 SuggestedRemedy
 Put all the new entries before XLAUI/CAUI-10.
 Move 25G-AUI to above 25GBASE-KR.
 Proposed Response Response Status O

Cl 112 SC 112.5.10 P 188 L 30 # 135
 Dawe, Piers Mellanox
 Comment Type E Comment Status X
 If the PMD has detected a local fault on any receive lane
 SuggestedRemedy
 If the PMD has detected a local fault on the receiver
 Proposed Response Response Status O

Cl 109 SC 109.4.6.2 P 133 L # 133
 Dawe, Piers Mellanox
 Comment Type E Comment Status X
 Receive PRBS31 Test Pattern Generation - rogue capitals?
 SuggestedRemedy
 Receive PRBS31 test pattern generation (like 109.4.6.1 Transmit PRBS31 test pattern generation above).
 Proposed Response Response Status O

Cl 093A SC 93A.1 P 205 L 18 # 136
 Dawe, Piers Mellanox
 Comment Type E Comment Status X
 Now that this list is growing, we should put the entries in the conventional order: slow to fast, low power to high power (which is usually short to long). Also, if there is an entry for 25GBASE-CR there should be one for 100GBASE-CR4.
 "CAUI-4" is ambiguous.
 There are really three columns here.

SuggestedRemedy
 3 columns:
 25GBASE-KR (Clause 111) Table 93-8
 25GBASE-CR (Clause 110) Table 110-8
 Chip-to-chip CAUI-4 (Annex 83D) Table 83D-6
 100GBASE-KR4 (Clause 93) Table93-8
 100GBASE-KP4 (Clause 94) Table94-17
 100GBASE-CR4 (Clause 92) Table 93-8
 Proposed Response Response Status O

Cl 112 SC 112.5.9 P 188 L 23 # 134
 Dawe, Piers Mellanox
 Comment Type E Comment Status X
 If the PMD has detected a local fault on the transmit lane
 SuggestedRemedy
 If the PMD has detected a local fault on the transmitter
 Proposed Response Response Status O

IEEE 802.3by 25 Gb/s Ethernet 1st Task Force review comments

Cl 105 SC 105.4 P 83 L 7 # 137
Dawe, Piers Mellanox

Comment Type ER Comment Status X

There are nearly 7 pages of service interface specification method and notation, which should be the same as 40 and 100G.

If there are more than the natural differences because 25GBASE-R is serial, they should be explicitly identified anyway, rather than leaving the reader to wade through all this. I hope there aren't, and this is an editorial comment.

SuggestedRemedy

Remove everything in 105.4 except the figures and some text introducing them.

Say that the service interface specification for 25GBASE-R Physical Layers is the same as for 40GBASE-R, 100GBASE-R, and 100GBASE-P Physical Layers, as in 80.3, except there is one lane in each direction (n = 1). Therefore the primitives shown there as IS_UNITDATA_i.request and IS_UNITDATA_i.indication are called IS_UNITDATA.request and IS_UNITDATA.indication for 25GBASE-R.

If you are feeling very conscientious, mention 25GBASE-R and Clause 108 in 80.3/80.3.1.

Proposed Response Response Status O

Cl 109A SC 109A P 207 L 6 # 138
Dawe, Piers Mellanox

Comment Type ER Comment Status X

In English, adjectives come before nouns.

SuggestedRemedy

Change 25G-AUI C2C and 25G-AUI C2M to C2C 25G-AUI and C2M 25G-AUI throughout.

Or create new acronyms such as 25G-AUI-C and 25G-AUI-M.

Proposed Response Response Status O

Cl 111 SC 111.9 P 175 L 17 # 139
Dawe, Piers Mellanox

Comment Type T Comment Status X

Surely the environmental specifications should be just the same as for 100GBASE-KR4?

SuggestedRemedy

Remove the duplicate text.

Insert:

The 25GBASE-KR4 environmental specifications are as defined in 93.10 for 100GBASE-KR4.

Change PICS subclause to 111.9, twice.

Proposed Response Response Status O

Cl 112 SC 112.5.4 P 187 L 19 # 140
Dawe, Piers Mellanox

Comment Type T Comment Status X

There's only one signal detect function here, unlike the multi-lane PMDs.

SuggestedRemedy

Delete "global" from "SIGNAL_DETECT shall be a global indicator of the presence of the optical signal."

Merge 112.5.5 into 112.5.4 - it's the same function.

Proposed Response Response Status O

Cl 112 SC 112.8.2 P 190 L 39 # 141
Dawe, Piers Mellanox

Comment Type T Comment Status X

The operating range section is the same as 95.7.

SuggestedRemedy

Remove the duplicate text and table. Insert:

The operating range and fiber types for the 25GBASE-SR PMD are as specified in 95.7 for 100GBASE-SR4.

Proposed Response Response Status O

IEEE 802.3by 25 Gb/s Ethernet 1st Task Force review comments

Cl 112 SC 112.10.3 P 193 L 24 # 142
 Dawe, Piers Mellanox

Comment Type T Comment Status X
 25GBASE-SR uses multimode fibre. Does IEC 61753-021-2, Fibre optic passive components performance standard, Part 021-2: Fibre optic connectors terminated on single-mode fibre for Category C-Controlled environment, performance Class S apply?

SuggestedRemedy
 Delete.

Proposed Response Response Status O

Cl 112 SC 112.10.3 P 193 L 22 # 143
 Dawe, Piers Mellanox

Comment Type T Comment Status X
 Are these references OK for both SFP+ and QSFP formats?
 95.11.3.2 has performance specifications IEC 61753-1 and IEC 61753-022-2. 52.14.4 has performance specifications IEC 61753-1-1 and IEC 61753-022-2.
 Is there a difference between IEC 61753-1 and IEC 61753-1-1?

SuggestedRemedy
 Consider if IEC 61753-1-1 should be IEC 61753-1 here or IEC 61753-1 be IEC 61753-1-1 in 95.11.3.2.

Proposed Response Response Status O

Cl 112 SC 112.6 P 188 L 32 # 144
 Dawe, Piers Mellanox

Comment Type TR Comment Status X
 A 25GBASE-SR transceiver in SFP+ format might be Hazard Level 1, but four of them in QSFP would be the same Hazard Level as 100GBASE-SR4, which is 1M in Clause 95. So I think we have to allow either.

SuggestedRemedy
 Do we want to tie the Hazard Level to the form factor?
 If not, just say Hazard Level 1 or Hazard Level 1M.

Proposed Response Response Status O

Cl 109B SC 109B.1.1 P 214 L 22 # 145
 Dawe, Piers Mellanox

Comment Type TR Comment Status X
 This bit error ratio spec goes with non-FEC PMDs that can't be connected to 25G-AUI. It adds a pointless burden of test cost and power - this is most obvious for a 25GBASE-SR module for which the PMD type is known.
 Also, any consideration of error correlation should take the FEC into account.
 The remedy below is intended to put no burden on the host and allow dual-use hosts or modules that are tested to CAUI-4 only.

SuggestedRemedy
 Change
 The bit error ratio (BER) shall be less than 10^{-15} with any errors sufficiently uncorrelated to ensure an acceptably high mean time to false packet acceptance (MTTFPA) assuming 64B/66B coding.
 to
 The bit error ratio (BER) shall be less than 10^{-6} with any errors sufficiently uncorrelated to ensure an acceptably high mean time to false packet acceptance (MTTFPA) assuming 64B/66B coding and the RS-FEC of Clause 108.
 In 109B.3.1, add exceptions:
 EW15 and EH15 do not apply.
 Limits for EW6 and EH6 A and B are 0.46 UI and 95, 80 mV.
 In 109B.3.2, add exceptions:
 EW15 and EH15 do not apply.
 Limits for EW6 and EH6 are 0.57 UI and 228 mV.
 VEC6 is defined as $20 \cdot \log_{10}(AV/EH6)$. Limit 4.5 dB.
 In 109B.3.3, add exceptions:
 Host implementer may comply to either the host stressed input test of 83E.3.3.2 (BER $\leq 1e-15$) or to a test to BER $\leq 1e-6$ with the EW6, EH6 defined for the module output in 109B.3.2 with a VEC6 in the range of 3.5 dB to 4.5 dB with a target value of 4 dB.
 In 109B.3.4, add exceptions:
 Module implementer may comply to either the module stressed input test of 83E.3.4.1 (BER $\leq 1e-15$) or to a test to BER $\leq 1e-6$ with the EW6, EH6 defined for the host output in 109B.3.1.

Proposed Response Response Status O

IEEE 802.3by 25 Gb/s Ethernet 1st Task Force review comments

Cl 110 SC 110.8.4.2.3 P 150 L 11 # 146
 Mellitz, Richard Intel Corporation
 Comment Type **TR** Comment Status **X**
 test 3 and test 4 fitted insertion loss coefficients are not aligned with posted cable measurements
 SuggestedRemedy
 See mellitz_by_xxx for recommended values.
 Proposed Response Response Status **O**

Cl 110C SC 110C.1 P L # 147
 Mellitz, Richard Intel Corporation
 Comment Type **TR** Comment Status **X**
 A no FEC link will like not work for a 3 meter cable.
 SuggestedRemedy
 Add another MDI called CA-N.
 Change
 25GBASE-CR has two specified MDI connectors, single-lane (SFP28, specified in 110.11.1) and multi-lane (QSFP28, specified in 92.12). This creates two host interface types and three cable assembly types with different combinations of the connectors at each end. These host and cable assembly types are referred to as form factors, distinguishing both the host receptacle (MDI) and the cable assembly plug. 25GBASE-CR cable assemblies have two sets of electrical specifications, denoted CA-L and CA-S, as specified in 110.10. CA-L specifications are based on a single lane of 100GBASE-CR4 cable assembly (see 92.10), enabling a 5 m reach, and are compatible with 25GBASE-CR PHYs that include the RS-FEC sublayer (Clause 108) with error correction enabled. The CA-S specifications enable a shorter reach of 3 m with lower loss than CA-L, and are required for compatibility with 25GBASE-CR PHYs that bypass RS-FEC error correction or that do not include the RS-FEC sublayer.
 To
 25GBASE-CR has three specified MDI connectors, single-lane (SFP28, specified in 110.11.1) and multi-lane (QSFP28, specified in 92.12). This creates two host interface types and three cable assembly types with different combinations of the connectors at each end. These host and cable assembly types are referred to as form factors, distinguishing both the host receptacle (MDI) and the cable assembly plug. 25GBASE-CR cable assemblies have two sets of electrical specifications, denoted CA-L, CA-S and CA-N, as specified in 110.10. CA-L specifications are based on a single lane of 100GBASE-CR4 cable assembly (see 92.10), enabling a 5 m reach, and are compatible with 25GBASE-CR PHYs that include the RS-FEC sublayer (Clause 108) with error correction enabled. The CA-S specifications enable a shorter reach of 3 m with lower loss than CA-L for interfaced which use a Clause 74 FEC. . The CA-S specifications enable even a shorter reach of 2 m with lower loss than CA-C for interfaced which use a no FEC operation.
 Proposed Response Response Status **O**

IEEE 802.3by 25 Gb/s Ethernet 1st Task Force review comments

Cl 112 *SC* 112.9 *P* 191 *L* 36 # 148

Dawe, Piers Mellanox

Comment Type **T** *Comment Status* **X**

Fiber optic cabling model is the same as for 100GBASE-SR4.

SuggestedRemedy

Delete present contents, refer to 95.10 Fiber optic cabling model and state that Cabling Skew and Cabling Skew Variation don't apply.

Proposed Response *Response Status* **O**