

Comments Received

IEEE P802.3ca D2.1 25/50G-EPON Task Force 1st Working Group recirculation ballot comments

Cl FM SC FM P1 L27 # 585

Anslow, Pete Ciena

Comment Type E Comment Status X

This list should contain all of the amendments assumed to be in front of the P802.3ca draft in the queue as determined by the IEEE 802.3 Chair.

SuggestedRemedy

Change to: "as amended by IEEE Std 802.3cb-2018, IEEE Std 802.3bt-2018, IEEE Std 802.3cd-2018, IEEE Std 802.3cn-20xx, IEEE Std 802.3cg-20xx, IEEE Std 802.3cq-20xx, IEEE Std 802.3cm-20xx, and IEEE Std 802.3ch-20xx."

Proposed Response Response Status O

Cl FM SC FM P7 L3 # 586

Anslow, Pete Ciena

Comment Type E Comment Status X

The first paragraph of "Participants" is not in line with the latest boilerplate.

SuggestedRemedy

Change to: "The following individuals were officers and members of the IEEE 802.3 Working Group at the beginning of the IEEE P802.3ca Working Group ballot."

Proposed Response Response Status O

Cl FM SC FM P7 L20 # 587

Anslow, Pete Ciena

Comment Type E Comment Status X

The list of WG ballot members should not include the officers of the Working Group or the Task Force who are already listed. Also, the column widths are not as per the latest 802.3 FrameMaker template.

SuggestedRemedy

Remove the 8 officers names from the WG ballot list of names. Change the column widths to be in accordance with the latest 802.3 FrameMaker template (so that Kochuparambil, Elizabeth does not line wrap)

Proposed Response Response Status O

Cl FM SC FM P11 L53 # 588

Anslow, Pete Ciena

Comment Type E Comment Status X

The text of the summary for P802.3cg does not match the latest version in P802.3cg D3.2

SuggestedRemedy

Change "balanced pair copper cable" to: "balanced pair of conductors"

Proposed Response Response Status O

Cl FM SC FM P12 L1 # 589

Anslow, Pete Ciena

Comment Type E Comment Status X

IEEE Std 802.3ca is not going to be approved in 2019. Also, it is not likely to be Amendment 5. Amendment numbers should only be added to drafts when the assumed order has been announced by the 802.3 Chair.

SuggestedRemedy

On line 1 change "201x" to "20xx"
On line 3 delete "Amendment 5-"

Proposed Response Response Status O

Cl 1 SC 1.3 P24 L5 # 590

Anslow, Pete Ciena

Comment Type TR Comment Status X

This draft adds a reference to ITU-T G.652, 2016 in addition to the existing reference to ITU-T G.652, 2009. While all of the references to G.652 in this draft have been changed to dated references to G.652-2016, this would leave the 27 existing references to G.652 in IEEE Std 802.3-2018 ambiguous as to which version is being referenced.

SuggestedRemedy

Either:
Change back to the D2.0 text which changes G.652-2009 to G.652-2016
or:
Bring the 27 existing undated references to G.652 in to the draft and make them all dated references.

Proposed Response Response Status O

Comments Received

IEEE P802.3ca D2.1 25/50G-EPON Task Force 1st Working Group recirculation ballot comments

Cl 1 SC 1.4.90c P24 L34 # 591
 Anslow, Pete Ciena
 Comment Type E Comment Status X
 1.4.90c should be 1.4.90b as per the editing instruction.
 SuggestedRemedy
 Re-number 1.4.90c to 1.4.90b
 Proposed Response Response Status O

Cl 1 SC 1.5 P26 L42 # 594
 Anslow, Pete Ciena
 Comment Type E Comment Status X
 The expansion of LDPC should be "low-density parity check" rather than "low-density parity code"
 SuggestedRemedy
 Change "parity code" to "parity check"
 Proposed Response Response Status O

Cl 1 SC 1.4.334a P26 L13 # 592
 Anslow, Pete Ciena
 Comment Type E Comment Status X
 The sorting order for definitions in 1.4 is defined at:
http://www.ieee802.org/3/WG_tools/editorial/requirements/words.html#sort
 This means that "Multi-Channel Reconciliation Layer (MCRS)" comes before "MultiGBASE-T". Also, "MultiGBASE-T" has been re-numbered to 1.4.333 due to the deletion of 1.4.294 by IEEE Std 802.3bt-2018.
 SuggestedRemedy
 Change the editing instruction to:
 "Insert the following new definition after 1.4.332 "modulation error ratio (MER)" (re-numbered from 1.4.333 due to the deletion of 1.4.294 by IEEE Std 802.3bt-2018) as follows:"
 Re-number the new definition to 1.4.332a
 Proposed Response Response Status O

Cl 30 SC 30.5.1.1.2 P31 L46 # 501
 Hajduczenia, Marek Charter Communications
 Comment Type TR Comment Status X
 A comment against D2.0 requested changes to MAU type description. The changes did introduce an issue, though. For example, 25/10GBASE-PQG-D3 description is correct (1x25G continuous transmission / 1x10G burst mode reception, i.e., OLT MAU with continuous downstream and burst mode upstream); however, descriptions for all U type MAUs are wrong (for example, 25/10GBASE-PQG-U2, reads now 1x25G continuous transmission / 1x10G burst mode reception).
 SuggestedRemedy
 Change all U type MAU descriptions in 30.5.1.1.2 to indicate they are "burst-mode transmission" and "continuous reception"
 Proposed Response Response Status O

Cl 1 SC 1.4.334a P26 L15 # 593
 Anslow, Pete Ciena
 Comment Type E Comment Status X
 "Multi-Channel Reconciliation Layer (MCRS)" should be: "Multi-Channel Reconciliation Sublayer (MCRS)" as per the expansion of the abbreviation in 1.4
 SuggestedRemedy
 Change "Multi-Channel Reconciliation Layer (MCRS)" to: "Multi-Channel Reconciliation Sublayer (MCRS)"
 Proposed Response Response Status O

Cl 30 SC 30.5.1.1.2 P31 L54 # 502
 Hajduczenia, Marek Charter Communications
 Comment Type E Comment Status X
 Missing space in "1x25G continuous transmission /1x10G burst"
 SuggestedRemedy
 Should be "1x25G continuous transmission / 1x10G burst"
 Proposed Response Response Status O

Comments Received

IEEE P802.3ca D2.1 25/50G-EPON Task Force 1st Working Group recirculation ballot comments

Cl 45 SC 45.2.1.23a.1 P35 L28 # 569

Kramer, Glen Broadcom

Comment Type T Comment Status X

Conflicting requirements:
C142 PMA clause says that "The ONU shall implement automatic detection of receive path differential encoding, and switch in the decoder as appropriate."

on the other hand, PMA control register bit 1.29.15 is R/W and it enables/disables the differential encoding in both the OLT and ONU

SuggestedRemedy

Change "R/W" to
"R/W in OLT
RO in ONU"

Proposed Response Response Status O

Cl 45 SC 45.2.3.6 P45 L15 # 553

Kramer, Glen Broadcom

Comment Type T Comment Status X

Clause 45 uses terminology incorrect terminology. There is no 25/25GBASE-PQ PCS type.

SuggestedRemedy

Replace 7 occurrences of 25/25GBASE-PQ with 25GBASE-PQ

Proposed Response Response Status O

Cl 45 SC 45.2.3.45a P49 L54 # 596

Anslow, Pete Ciena

Comment Type E Comment Status X

Bottom ruling missing for Table 217a at the foot of page 49

SuggestedRemedy

Uncheck "Draw Bottom Ruling on Last Sheet Only"

Proposed Response Response Status O

Cl 45 SC 45.5.3.3 P53 L5 # 597

Anslow, Pete Ciena

Comment Type E Comment Status X

This draft is assumed to be applied after P802.3cg and P802.3ch. The P802.3ch draft adds items up to "MM231" in the D2.1 version

SuggestedRemedy

Change "MM152" to be "MM232"

Proposed Response Response Status O

Cl 56 SC 56.1.2 P55 L11 # 504

Hajduczenia, Marek Charter Communications

Comment Type T Comment Status X

A comment against D2.0 added footnotes to 25GMII instances. Footnote a) implies the use of 25GMII and XGMII halves to achieve assymmetric data rates. Yet 25GMII is defined as capable of 25G and 10G operation, hence the reference to XGMII is not needed and may be considered confusing.

To further add to confusion, we have also heavily used the term "xMII" to imply the 25GMII or XGMII when the actual clock rate across the MII does not matter for the purpose of description. There are in total 85 instances where xMII is used in the draft (drawings and text alike).

To avoid discussion on actual physical implementation of 25GMII and XGMII, it might be best to use a generic term we already define (xMII) where referring to a generic MII between RS and PCS and not distinguish the speed unless specifically needed.

SuggestedRemedy

Suggest to change "25GMII" with "xMII" in Figures 141-1, 142-1, 144-1, Figure 56-5a, and Figure 143-17

Proposed Response Response Status O

Cl 67 SC 67.1 P64 L16 # 557

Kramer, Glen Broadcom

Comment Type E Comment Status X

In table 67-1, link types 25/25PQ and 25/10PQ are missing hyphen before the "PQ"

SuggestedRemedy

Add hyphen in 4 places

Proposed Response Response Status O

Comments Received

IEEE P802.3ca D2.1 25/50G-EPON Task Force 1st Working Group recirculation ballot comments

Cl 141 SC 141.1.3 P65 L34 # 562

Kramer, Glen Broadcom

Comment Type E Comment Status X

"Nx25G-EPON PHY Link Types supporting 50 Gb/s use wavelength division multiplexing on two wavelengths; two wavelengths are listed for these links in Table 141-1 through Table 141-5."

This sentence is confuising, as it seems like to unrelated sentences joined into one. The original text came as comment #356 against D2.0 and it had the two senetences linked properly.

SuggestedRemedy

Link the two sentences as it was in the original comment:

"Nx25G-EPON PHY Link Types supporting 50 Gb/s use wavelength division multiplexing on two wavelengths *and hense* two wavelengths are listed for these links in Table 141-1 through Table 141-5."

Proposed Response Response Status O

Cl 141 SC 141.2.6 P69 L12 # 561

Kramer, Glen Broadcom

Comment Type T Comment Status X

Table 144-6 has several issues:

- 1) Some rows refer to singular PMD, some refere to plural PMDs.
- 2) "PMDs use a PON P2MP protocol" is wrong. PMDs do not use any protocols. They convert serial optical stream to electrical and vise versa.
- 3) the only table with a caption "Explanation". Most other tables use caption "Description"
- 4) "PMD power budget class" should be called "PMD power class"
- 5) Descriptions for most rows properly point to the relevant PMD class, except the description for the coexistence parameter. This description just repeats the already given definition.

SuggestedRemedy

Modify the table 141-6 as shown in kramer_3ca_4_0919.pdf. Make cross-references live.

Proposed Response Response Status O

Cl 141 SC 141.3.1.1 P71 L51 # 565

Kramer, Glen Broadcom

Comment Type T Comment Status X

Rerference to 142.x.x.x

SuggestedRemedy

Use142.4.1. make it live.

Proposed Response Response Status O

Cl 141 SC 141.3.1.1 P71 L51 # 598

Anslow, Pete Ciena

Comment Type ER Comment Status X

"see 142.x.x.x" renders this draft unready for progression to SA ballot - hence a required comment

SuggestedRemedy

Change "see 142.x.x.x" to a suitable cross-reference

Proposed Response Response Status O

Cl 141 SC 141.3.1.1 P71 L52 # 599

Anslow, Pete Ciena

Comment Type T Comment Status X

"shall be as illustrated in Table 141-10" is conflicting language.

"shall" is appropriate for a normative requirement.

"illustrated" is appropriate for something informative.

SuggestedRemedy

Change "shall be as illustrated in Table 141-10" to: "shall be as given in Table 141-10"

Proposed Response Response Status O

Comments Received

IEEE P802.3ca D2.1 25/50G-EPON Task Force 1st Working Group recirculation ballot comments

Cl 141 SC 141.3.1.1 P71 L52 # 503
 Hajduczenia, Marek Charter Communications
 Comment Type ER Comment Status X
 Cross reference is missing (marked in red)
 SuggestedRemedy
 Not sure where the piinter should be do, but x.x.x.x will not work for sure :)
 Proposed Response Response Status O

Cl 141 SC 141.5.1 P76 L19 # 506
 Hajduczenia, Marek Charter Communications
 Comment Type ER Comment Status X
 Editor's note with no text at this time.
 SuggestedRemedy
 Proposed Response Response Status O

Cl 141 SC 141.3.1.3 P72 L41 # 600
 Anslow, Pete Ciena
 Comment Type E Comment Status X
 In "PMD_UNITDATA[i].request(tx_bit) (where i = 0 or 1)" i is a variable and should be italic
 SuggestedRemedy
 Change "I" to be in italic font here (2 places) and anywhere else in the draft that this occurs
 Proposed Response Response Status O

Cl 141 SC 141.5.2 P78 L11 # 512
 Lee, Han Hyub ETRI
 Comment Type E Comment Status X
 To be consistent with other tables, the first parameter should be Signaling rate (range)
 SuggestedRemedy
 Change the order of Channel wavelength ranges and Signaling rate
 Proposed Response Response Status O

Cl 141 SC 141.5.1 P76 L19 # 601
 Anslow, Pete Ciena
 Comment Type TR Comment Status X
 The editor's note in 141.5.1, the reference to non-existent 143.4.4, and the editor's note in 143.4.1.2 render this draft unready for progression to SA ballot - hence a required comment
 SuggestedRemedy
 Include a new eye mask definition and remove editor's note in 141.5.1.
 Populate 143.4.4 with suitable "details" in 143.4.4 and remove editor's note in 143.4.1.2
 Proposed Response Response Status O

Cl 141 SC 141.5.2 P78 L11 # 513
 Lee, Han Hyub ETRI
 Comment Type ER Comment Status X
 Missing Unit of channel wavelengths
 SuggestedRemedy
 Insert 'nm' as Unit
 Proposed Response Response Status O

Cl 141 SC 141.6.1 P82 L12 # 514
 Lee, Han Hyub ETRI
 Comment Type ER Comment Status X
 Missing Unit of channel wavelengths
 SuggestedRemedy
 Insert 'nm' as Unit
 Proposed Response Response Status O

Comments Received

IEEE P802.3ca D2.1 25/50G-EPON Task Force 1st Working Group recirculation ballot comments

Cl 141 SC 141.6.1 P82 L18 # 515
 Lee, Han Hyub ETRI
 Comment Type ER Comment Status X
 Missing Unit of Average launch power, each channel (max)
 SuggestedRemedy
 Insert 'dBm' as Unit
 Proposed Response Response Status O

Cl 141 SC 141.6.1 P83 L11 # 516
 Lee, Han Hyub ETRI
 Comment Type E Comment Status X
 To be consistent with other tables, the first parameter should be Signaling rate (range)
 SuggestedRemedy
 Change the order of Channel wavelength ranges and Signaling rate
 Proposed Response Response Status O

Cl 141 SC 141.7.13.2 P89 L26 # 517
 Lee, Han Hyub ETRI
 Comment Type T Comment Status X
 TP4 should be change to TP4 [i]
 SuggestedRemedy
 Change TP4 to TP4 [i]
 Proposed Response Response Status O

Cl 141 SC 141.10.4.1 P98 L24 # 602
 Anslow, Pete Ciena
 Comment Type T Comment Status X
 Comment #101 against D2.0 clarified the rules for the PICS "Support" column:
 for items with status of:
 "M" change the Support entry to "Yes []"
 "O" change the Support entry to "Yes [] No []"
 "Something:M" change the Support entry to "Yes [] N/A []"
 "Something:O" change the Support entry to "Yes [] No [] N/A []"
 "O.Number" change the Support entry to "Yes [] No []"
 "O/Number" change the Support entry to "Yes [] No []"
 SuggestedRemedy
 For Items FN7, FN8, and FN9 change the entry to "Yes [] No []"
 In 141.10.4.42 item OM10 change the entry to "Yes [] No []"
 Proposed Response Response Status O

Cl 142 SC 142.1.1.2 P111 L40 # 507
 Hajduczenia, Marek Charter Communications
 Comment Type E Comment Status X
 "... the following conventions are used in this clause" - well, it is not just in Clause 142,
 really.
 SuggestedRemedy
 Change to "the following conventions are used:"
 Proposed Response Response Status O

Cl 142 SC 142.1.1.6 P115 L28 # 508
 Hajduczenia, Marek Charter Communications
 Comment Type E Comment Status X
 "...State diagrams used in this clause make extensive use of first-in, first-out..." - well, not
 just in this clause
 SuggestedRemedy
 Change to "State diagrams make extensive use of first-in, first-out"
 Proposed Response Response Status O

Comments Received

IEEE P802.3ca D2.1 25/50G-EPON Task Force 1st Working Group recirculation ballot comments

Cl 142 SC 142.2.2 P119 L33 # 500
 Hajduczenia, Marek Charter Communications
 Comment Type E Comment Status X
 I do not believe INPUT_FIFO and TX_FIFO exist (are defined) anymore.
 SuggestedRemedy
 Change INPUT_FIFO to InputFifo
 Change TX_FIFO to TxFifo
 Proposed Response Response Status O

Cl 142 SC 142.2.4.1 P120 L16 # 577
 Wienckowski, Natalie General Motors
 Comment Type E Comment Status X
 In text, where this improves clarity, follow the IEEE Editorial Style Manual: Use spaces instead of commas between numbers in tens or hundreds of thousands (e.g., 62 000, 100 000, but 4000). The groups should be separated by a space, and not a comma, period, or dash.
 SuggestedRemedy
 Change: = 3072 x 17664
 To: = 3 072 x 17 664
 Proposed Response Response Status O

Cl 142 SC 142.2.4.2 P123 L8 # 578
 Wienckowski, Natalie General Motors
 Comment Type E Comment Status X
 In text, where this improves clarity, follow the IEEE Editorial Style Manual: Use spaces instead of commas between numbers in tens or hundreds of thousands (e.g., 62 000, 100 000, but 4000). The groups should be separated by a space, and not a comma, period, or dash.
 SuggestedRemedy
 Change: 14592
 To: 14 592
 Also on P123 L12
 Proposed Response Response Status O

Cl 142 SC 142.2.4.2 P123 L10 # 579
 Wienckowski, Natalie General Motors
 Comment Type E Comment Status X
 In text, where this improves clarity, follow the IEEE Editorial Style Manual: Use spaces instead of commas between numbers in tens or hundreds of thousands (e.g., 62 000, 100 000, but 4000). The groups should be separated by a space, and not a comma, period, or dash.
 SuggestedRemedy
 Change: 17664
 To: 17 664
 Proposed Response Response Status O

Cl 142 SC 142.2.4.2 P123 L11 # 580
 Wienckowski, Natalie General Motors
 Comment Type E Comment Status X
 In text, where this improves clarity, follow the IEEE Editorial Style Manual: Use spaces instead of commas between numbers in tens or hundreds of thousands (e.g., 62 000, 100 000, but 4000). The groups should be separated by a space, and not a comma, period, or dash.
 SuggestedRemedy
 Change: 14392
 To: 14 392
 Proposed Response Response Status O

Cl 142 SC 142.2.4.2 P123 L17 # 581
 Wienckowski, Natalie General Motors
 Comment Type E Comment Status X
 In text, where this improves clarity, follow the IEEE Editorial Style Manual: Use spaces instead of commas between numbers in tens or hundreds of thousands (e.g., 62 000, 100 000, but 4000). The groups should be separated by a space, and not a comma, period, or dash.
 SuggestedRemedy
 Change: 16962
 To: 16 962
 Proposed Response Response Status O

Comments Received

IEEE P802.3ca D2.1 25/50G-EPON Task Force 1st Working Group recirculation ballot comments

Cl 142 SC 142.2.4.3 P123 L49 # 550

Laubach, Mark Broadcom

Comment Type T Comment Status X

Change to improve clarity based on feedback from previous comment resolution against D2.0.

SuggestedRemedy

Insert new paragraph after sub-clause title and before paragraph beginning with "For the purposes here":

The Interleaver and De-interleaver are realized by using Omega Networks and Reverse-Omega Networks. An Omega network is a multistage interconnection network that uses multiple stages of switches. At each stage, the switches can be controlled independently to "pass-through" or "cross". The outputs from each stage are connected to the inputs of the next stage using an interconnection system. The details of interconnection and switch programming are shown in Figure 142-9.

Proposed Response Response Status O

Cl 142 SC 142.2.4.3 P123 L50 # 551

Laubach, Mark Broadcom

Comment Type T Comment Status X

Change to improve clarity based on feedback from previous comment resolution against D2.0.

SuggestedRemedy

Replace paragraph beginning with "For the purposes here" with the following paragraph:

For the purposes here: "De-interleaver" refers to the mapping from transmitted sequence to encoding/decoding sequence (including user and parity). This is implemented using "Reverse-Omega (R->L)" (i.e., data input from the right side and output from the left). "Interleaver" refers to the mapping from encoding/decoding sequence to transmitted sequence. This is implemented as "Omega (L->R)" (i.e., data input from the left side and output from the right). Note that the Interleaver and De-interleaver area reverse mapping (permutation) of each other. That is, the Omega and Reverse-Omega Networks are just the reverse of the data flow of each other.

Proposed Response Response Status O

Cl 142 SC 142.2.4.3 P127 L1 # 548

Laubach, Mark Broadcom

Comment Type T Comment Status X

Change to improve clarity based on feedback from previous comment resolution against D2.0.

SuggestedRemedy

Change "57 independent user interleavers" to "57 independent user omega networks"

Proposed Response Response Status O

Cl 142 SC 142.2.4.3 P128 L48 # 549

Laubach, Mark Broadcom

Comment Type T Comment Status X

Change to improve clarity based on feedback from previous comment resolution against D2.0.

SuggestedRemedy

Change "10 independent parity Interleavers" to "10 independent parity omega networks"

Proposed Response Response Status O

Cl 142 SC 142.2.5.3 P133 L24 # 560

Kramer, Glen Broadcom

Comment Type T Comment Status X

In D2.1, we have renamed FecDecode to PassToFecDecoder (see comment #358) to more accurately reflect the behavior of the function. We should do the same with its counterpart function FecEncode. These functions do not perform any action of encoding or decoding (which take relatively long time in LDPC). These frctions only pass the data from one functional block to another and return immediately.

SuggestedRemedy

Rename FecEncode to PassToFecEncoder in 142.2.5.3 and in SD 142-10, Also move the lines that set TxInput<256:0> and TxInput<257> to be next to each other. The exact changes are shown in kramer_3ca_3_0919.pdf.

Proposed Response Response Status O

Cl 142 SC 142.2.5.3 P133 L 32 # 555
 Kramer, Glen Broadcom
 Comment Type T Comment Status X
 Definition of function PassToPMA(v) mentions PMA_UNITDATA[i].request(v), which is in a different clause. A reference would be very helpful here.
 SuggestedRemedy
 Add "(see 142.4.1.1)" after "PMA_UNITDATA[i].request(v)"
 Proposed Response Response Status O

Cl 142 SC 142.2.5.3 P133 L 35 # 563
 Kramer, Glen Broadcom
 Comment Type TR Comment Status X
 Definition of ResetScrambler() function is wrong. We don't rest to IEI_EQ anymore. Also, the definition said that function erstes both scrambler and descrambler. This is not correct. It only resets one, depending on whether it is called in the ONU or the OLT.
 SuggestedRemedy
 1) Use the following definition of ResetScrambler() function in 142.2.5.3:
 ResetScrambler()
 Description: This function resets the scrambler to the value of 0x3-(FF)₇, i.e., each of the bits S0 through S57 of the scrambler shift register is set to 1 (see Figure 49–8).
 2) Replace the definition of ResetScrambler() function in 142.3.5.3 with a new function ResetDescrambler
 ResetDescrambler()
 Description: This function resets the descrambler to the value of 0x3-(FF)₇, i.e., each of the bits S0 through S57 of the descrambler shift register is set to 1 (see Figure 49–10).
 3) In SD 142-18, replace ResetScrambler() with ResetDescrambler().
 4) In 142.2.2, replace the sentence "In the ONU, at the beginning of each burst, the scrambler is initialized with the value of 0x3-(FF)7, i.e., each of the bits S0 through S57 is set to 1 (see Figure 49–8)." with "In the ONU, at the beginning of each burst, the scrambler is reset to a known initialization value (see the definition of ResetScrambler() function in 142.2.5.3)."
 5) In 142.3.3, replace the sentence "In the OLT, at the beginning of each burst, the descrambler is initialized with the value of 0x3-(FF)7, i.e., each of the bits S0 through S57 is set to 1 (see Figure 49–8)." with "In the OLT, at the beginning of each burst, the descrambler is reset to a known initialization value (see the definition of ResetDescrambler() function in 142.3.5.3)."
 Proposed Response Response Status O

Cl 142 SC 142.3.5.1 P139 L16 # 582

Wienckowski, Natalie General Motors

Comment Type ER Comment Status X

In text, where this improves clarity, follow the IEEE Editorial Style Manual: Use spaces instead of commas between numbers in tens or hundreds of thousands (e.g., 62 000, 100 000, but 4000). The groups should be separated by a space, and not a comma, period, or dash.

SuggestedRemedy

Change: 16,962
To: 16 962

Proposed Response Response Status

Cl 142 SC 142.3.5.4 P144 L1 # 558

Kramer, Glen Broadcom

Comment Type TR Comment Status X

Comment #485 against D2.0 was correct. The state GET_NEXT_BLOCK contains a blocking function that takes 257 bit times to execute. While this function is executing, no exit conditions from this block are tested. This causes the SignalFail and MatchFound conditions to be tested simultaneously. So, we need to handle the case when both conditions evaluate to true.

SuggestedRemedy

change the State diagram 142-15 as shown in kramer_3ca_2_0919.pdf.

Proposed Response Response Status

Cl 142 SC 142.4 P144 L47 # 564

Kramer, Glen Broadcom

Comment Type T Comment Status X

The text under 142.4 is out of place. This section should be an introduction to the entire PMA. Instead it focuses only of the differential encoding, which is a small part of PMA.

The following text is confusing and serves no purpose:
"(output bits represent changes to succeeding input values rather than in respect to a given reference)"

SuggestedRemedy

Use the following text:

The PMA adopts the serial PMD service interface (PMD_UNITDATA, see 141.3.3 and 141.34) to the 257-bit wide interface of the PCS (PMA_UNITDATA, see 142.4.1). Where Nx25G-EPON operates over multiple channels, the PMA sublayer includes multiple identical instances of the transmit data path and/or the receive data path.

In the downstream direction (from the OLT to the ONUs), the PMA includes a differential encoding option (see 142.4.2 and 142.4.3). This encoding technique facilitates the use of lower bandwidth receivers at the ONUs.

Proposed Response Response Status

Cl 142 SC 142.4.1.1.1 P146 L52 # 566

Kramer, Glen Broadcom

Comment Type E Comment Status X

In "PCS Transmit State Diagram", the "state diagram" should be lower case

SuggestedRemedy

Change to lower case

Proposed Response Response Status

Cl 142 SC 142.4.1.2.1 P146 L45 # 603

Anslow, Pete Ciena

Comment Type E Comment Status X

"Figure 142-15" should be a cross-reference

SuggestedRemedy

Change "Figure 142-15" to be a cross-reference

Proposed Response Response Status

Comments Received

IEEE P802.3ca D2.1 25/50G-EPON Task Force 1st Working Group recirculation ballot comments

Cl 142 SC 142.4.2 P148 L1 # 546
 Powell, William Nokia
 Comment Type T Comment Status X
 A D2.0 commenter expressed concern over this section:
 - Not sure if we're dealing with serial bits or 257b vectors
 - Not happy with Fig. 142-19 Figure output going to the PMA (already in the PMA)
 SuggestedRemedy
 Implement the proposed Fig. 142-19 and 142-20 changes shown in RED in
 powell_3ca_1_0919.pdf
 Proposed Response Response Status O

Cl 142A SC 142A.2 P266 L22 # 534
 Lynskey, Eric Broadcom
 Comment Type T Comment Status X
 Table 142A-6 shows the bits Post Interleaver.
 SuggestedRemedy
 Change Pre to Post.
 Proposed Response Response Status O

Cl 143 SC 143.3.1.2.3 P165 L36 # 509
 Hajduczenia, Marek Charter Communications
 Comment Type E Comment Status X
 Inconsistent primitive formatting. We had rules on variable formatting, etc. but right now it seems that primitives are formatted inconsistently. In some locations, the whole primitive is italicised, in others it is not.
 SuggestedRemedy
 For consistency, it seems a better approach would be to italicize names of primitives as a whole.
 Proposed Response Response Status O

Cl 143 SC 143.3.3.3 P170 L32 # 510
 Hajduczenia, Marek Charter Communications
 Comment Type E Comment Status X
 Compound adjective: application specific
 SuggestedRemedy
 Change to "application-specific"
 Proposed Response Response Status O

Cl 143 SC 143.3.3.4 P170 L36 # 537
 Lynskey, Eric Broadcom
 Comment Type T Comment Status X
 Add Encryption Enable and Encryption Key variables in the correct alphabetical order.
 SuggestedRemedy
 E
 Type: integer
 Description: Reserved for encryption.
 K
 Type: integer
 Description: Reserved for encryption.
 Proposed Response Response Status O

Cl 143 SC 143.3.3.4 P171 L41 # 547
 Powell, William Nokia
 Comment Type E Comment Status X
 rRow Variable:
 Current Last Sentence:
 The value of this variable is synchronized to wRow and is equal wRow - 1.
 Missing preposition "to"
 SuggestedRemedy
 Change wording to:
 The value of this variable is synchronized to wRow and is equal to wRow - 1.
 -or-
 The value of this variable is synchronized to wRow and equals wRow - 1.
 Proposed Response Response Status O

Comments Received

IEEE P802.3ca D2.1 25/50G-EPON Task Force 1st Working Group recirculation ballot comments

Cl 143 SC 143.3.3.5 P172 L20 # 568
 Kramer, Glen Broadcom
 Comment Type TR Comment Status X
 Conventions in Table 142-1 are not applied consistently to code fragments throughout the draft.
 SuggestedRemedy
 Apply conventions to:
 1) EnvContHeader() function, page 172
 2) EnvStartHeader() function, page 172
 3) GetMacBlock() function, page 173
 4) IsHeader() function, page 179
 5) IsMisaligned() function, page 179
 6) OutputToMac() function, page 179
 7) ProcessTimestamp() function, page 198
 8) RegAllowed variable, page 227
 9) GetResponseCode() function, page 249
 10) UpdateChState() function, page 250
 Proposed Response Response Status O

Cl 143 SC 143.3.3.5 P172 L25 # 535
 Lynskey, Eric Broadcom
 Comment Type T Comment Status X
 Earlier in the draft, it is stated that bit 17 is set to 0 by the transmitter. That should be shown here.
 SuggestedRemedy
 In both EnvContHeader and EnvStartHeader, add:
 hdr<17> = 0; // Reserved
 Proposed Response Response Status O

Cl 143 SC 143.3.3.5 P172 L27 # 536
 Lynskey, Eric Broadcom
 Comment Type T Comment Status X
 The E and K bits are previously defined in 143.3.2, but there is no way to set either of these bits in the ESH or ECH.
 SuggestedRemedy
 In both EnvContHeader and EnvStartHeader, add:
 hdr<46> = E; // Encryption enable
 hdr<47> = K; // Encryption Key
 Proposed Response Response Status O

Cl 143 SC 143.3.3.6.1 P175 L23 # 556
 Kramer, Glen Broadcom
 Comment Type T Comment Status X
 MCRS Input Process has a transition labelled "LinkId[wCo] != 0x00-00". We have defined a names constant for 0x00-00. It is called ESC_LLID.
 SuggestedRemedy
 1) Replace the SD 143-12 with the one shown in kramer_3ca_1_0919.pdf
 2) Add the following definition to 143.3.3.3:
 ESC_LLID
 See Table 144-1
 Proposed Response Response Status O

Cl 143 SC 143.3.4.4 P179 L42 # 511
 Hajduczenia, Marek Charter Communications
 Comment Type E Comment Status X
 Comment #366 fixed one location in the draft; one more instance is missing
 SuggestedRemedy
 Change "octet_index = 0; octet_index < 8," to "octet_index = 0; octet_index < 8;"
 Proposed Response Response Status O

Comments Received

IEEE P802.3ca D2.1 25/50G-EPON Task Force 1st Working Group recirculation ballot comments

Cl 143 SC 143.3.4.4 P180 L7 # 567

Kramer, Glen Broadcom

Comment Type T Comment Status X

We provided a very precise definition for GetMacOctet function, giving the exact details of how a data octet is constructed from multiple PLS_DATA.requests. But we only have very high-level, imprecise definition for the SetMacOctet function. No details are given on how 8 bit values are passed to MAC 1 bit at a time.

SuggestedRemedy

Replace the definition of SetMacOctet with the definition provided in kramer_3ca_5_0919.pdf. Observe the italics and make the links live.

Proposed Response Response Status O

Cl 143 SC 143.3.4.5.2 P182 L17 # 538

Lynskey, Eric Broadcom

Comment Type T Comment Status X

Bit ordering in the PROCESS_HEADER state of Figure 143-16 should be flipped.

SuggestedRemedy

Change to OutEQ<63:48> and OutEQ<39:18>.

Proposed Response Response Status O

Cl 143 SC 143.3.4.5.2 P182 L22 # 559

Kramer, Glen Broadcom

Comment Type TR Comment Status X

State diagram 143-16 misses a label in a transition from INSERT_PREAMBLE to CHECK_ENV_SIZE

SuggestedRemedy

Add label UCT

Proposed Response Response Status O

Cl 143 SC 143.4.1.2 P186 L8 # 505

Hajduczenia, Marek Charter Communications

Comment Type ER Comment Status X

Editor's note with no text at this time.

SuggestedRemedy

Proposed Response Response Status O

Cl 143 SC 143.5.4.2 P189 L17 # 539

Lynskey, Eric Broadcom

Comment Type T Comment Status X

Missing PICS. There are four shall statements in 143.4.1.1, but only three PICS entries.

SuggestedRemedy

EPON4 - Channel bonding - 143.4.1.1 - Device supports channel bonding - 50G10G:M or 50G25G:M or 50G50G:M - Yes [] N/A []

Proposed Response Response Status O

Cl 144 SC 144.3.1.1 P202 L31 # 605

Anslow, Pete Ciena

Comment Type E Comment Status X

The IEEE style manual has: "Only one occurrence of any level of an ordered list may be presented in any subclause to avoid confusing cross-references [e.g., it is OK to have an a) level list followed by a 1) level list , etc., but there should not be more than one a) level list in the same clause or subclause]."

SuggestedRemedy

Change the second numbered list (starting at line 31) to a lettered list.

Proposed Response Response Status O

Comments Received

IEEE P802.3ca D2.1 25/50G-EPON Task Force 1st Working Group recirculation ballot comments

Cl 144 SC 144.3.1.1 P202 L 33 # 604
 Anslow, Pete Ciena
 Comment Type E Comment Status X
 IEEE uses an en-dash as a minus sign
 SuggestedRemedy
 Change the minus signs to en-dashes (Ctrl-q Shft-p) (5 instances)
 Proposed Response Response Status O

Cl 144 SC 144.3.6.1 P209 L 12 # 571
 Kramer, Glen Broadcom
 Comment Type E Comment Status X
 Where a subset of bits is taken to represent a single field or a single numericvalue, we should use the notation "M:N" instead of "N to M". This will make it consistent with C45 and vector notation used throughout the draft.
 SuggestedRemedy
 Apply the following changes:
 1) Table 144-2: change "2 to 7" to "7:2"
 2) Table 144-4: change "3 to 4" to "4:3"
 3) Table 144-4: change "7 to 15" to "15:7"
 4) Table 144-7: change "3 to 4" to "4:3"
 5) Table 144-7: change "7 to 13" to "13:7"
 6) Table 144-8: change "0 to 1" to "1:0"
 7) Table 144-8: change "3 to 4" to "4:3"
 8) Table 144-8: change "5 to 6" to "6:5"
 9) Table 144-8: change "8 to 14" to "14:8"
 10) Table 144-11: change "0 to 3" to "3:0"
 11) Table 144-11: change "4 to 6" to "6:4"
 12) Table 144-12: change "0 to 3" to "3:0"
 13) Table 144-12: change "4 to 7" to "7:4"
 Proposed Response Response Status O

Cl 144 SC 144.3.6.1 P209 L 39 # 573
 Kramer, Glen Broadcom
 Comment Type TR Comment Status X
 MPCPDUs are not allowed to be fragmented, as this breaks the timestamping reference.
 A fragmented MPCPDU would be transmitted in two or more PLID envelopes. Every time an ESH is received, a new MPCP time is latched, overwriting the previous time. A timestamp in fragmented MPCPDU may reference the time of the first ESH, but this timestamp is parsed out of an MPCPDU and checked after the entire MPCPDU is received, which means the MPCP time will already be overwritten by the later ESH.
 SuggestedRemedy
 The draft shall specify that MPCPDU shall not be fragmented. Add the following statement at the end of definition of "Fragmentation" flag (new paragraph):
 "If the value of <i>LLID</i> field represents a PLID, the <i>Fragmentation</i> flag shall be equal zero."
 Add PICS.
 Proposed Response Response Status O

Cl 144 SC 144.3.6.1 P210 L 31 # 533
 Lynskey, Eric Broadcom
 Comment Type T Comment Status X
 Figure 144-12 shows extra EnvAlloc[7].
 SuggestedRemedy
 Remove EnvAlloc[7].
 Proposed Response Response Status O

Cl 144 SC 144.3.6.1 P210 L 31 # 570
 Kramer, Glen Broadcom
 Comment Type TR Comment Status X
 GATE and REPORT MPCPDU figures are showing 8 EnvAlloc/LlidStatus elements instead of 7.
 SuggestedRemedy
 Remove EnvAlloc[7] from figure 144-12
 Remove LlidStatus[7] element from figure 144-13
 Proposed Response Response Status O

Comments Received

IEEE P802.3ca D2.1 25/50G-EPON Task Force 1st Working Group recirculation ballot comments

Cl 144 SC 144.3.6.2 P211 L35 # 531
 Lynskey, Eric Broadcom
 Comment Type T Comment Status X
 Figure 144-13 shows incorrect LlidStatus[0] length.
 SuggestedRemedy
 Change to 5 octets.
 Proposed Response Response Status O

Cl 144 SC 144.3.6.2 P211 L47 # 532
 Lynskey, Eric Broadcom
 Comment Type T Comment Status X
 Figure 144-13 shows extra LlidStatus[7].
 SuggestedRemedy
 Remove LlidStatus[7].
 Proposed Response Response Status O

Cl 144 SC 144.3.6.3 P213 L39 # 530
 Lynskey, Eric Broadcom
 Comment Type T Comment Status X
 Figure 144-14 shows the incorrect pad length.
 SuggestedRemedy
 Change to 33 octets.
 Proposed Response Response Status O

Cl 144 SC 144.3.7 P222 L32 # 572
 Kramer, Glen Broadcom
 Comment Type T Comment Status X
 The last paragraph in 144.3.7 is very confusing and does not reflect the behavior specified in state diagrams.
 When an ONU wants to deregister, it deregisters unconditionally. Sending REGISTER_REQ/NACK to the OLT is just a courtesy call.
 SuggestedRemedy
 Replace the last paragraph in 144.3.7 with the text provided in kramer_3ca_6_0919.pdf. Observe italics.
 Proposed Response Response Status O

Cl 144 SC 144.3.7.7 P230 L27 # 554
 Kramer, Glen Broadcom
 Comment Type TR Comment Status X
 State diagram 144-21 uses not-existent flag value "Deregister"
 SuggestedRemedy
 Replace "Deregister" with "NACK"
 Proposed Response Response Status O

Cl 144 SC 144.3.8 P232 L3 # 575
 Kramer, Glen Broadcom
 Comment Type E Comment Status X
 A couple of missing commas in sub-clause 144.3.8
 SuggestedRemedy
 Insert the following commas:
 1) After "As noted in 144.1.1.1", line 3
 2) Before "which" in "state diagram (see 144.3.8.11) which results", line 25
 Proposed Response Response Status O

Comments Received

IEEE P802.3ca D2.1 25/50G-EPON Task Force 1st Working Group recirculation ballot comments

Cl 144 SC 144.3.8 P 232 L 28 # 574

Kramer, Glen Broadcom

Comment Type E Comment Status X

Sentence "In the OLT transmission is continuous,..." either needs a comma after the OLT, or better, should be re-phrased.

Missing comma after "In the case of the OLT"

The text includes a reference to the OLT Envelope Commitment process, but is missing a reference to the Envelope Activation process

SuggestedRemedy

Change the paragraph starting with "Grants are not explicitly used by the OLT..." with

"Since the OLT transmits continuously, grants are not explicitly used by the OLT in the downstream direction. However, the OLT does use the envelope descriptors, OLT Envelope Commitment process (see 144.3.8.9), and Envelope Activation process (see 144.3.8.11) in a manner similar to how these processes are used in the ONUs. In the case of the OLT, the transition from Inter-Envelope Idle to data transmission begins with the issuing of an envelope descriptor by the OLT MPMC Client (MPCP). The envelope descriptor is processed by the OLT Envelope Commitment state diagram and Envelope Activation state diagram as described for the ONU."

Proposed Response Response Status O

Cl 144 SC 144.3.8.1 P 232 L 42 # 583

Wienckowski, Natalie General Motors

Comment Type ER Comment Status X

In text, where this improves clarity, follow the IEEE Editorial Style Manual: Use spaces instead of commas between numbers in tens or hundreds of thousands (e.g., 62 000, 100 000, but 4000). The groups should be separated by a space, and not a comma, period, or dash.

SuggestedRemedy

Change: 6,400
To: 6 400 or 6400 as 4 digit numbers don't have to have the space unless they are in a column with larger numbers.

Proposed Response Response Status O

Cl 144 SC 144.3.8.1 P 232 L 49 # 584

Wienckowski, Natalie General Motors

Comment Type ER Comment Status X

In text, where this improves clarity, follow the IEEE Editorial Style Manual: Use spaces instead of commas between numbers in tens or hundreds of thousands (e.g., 62 000, 100 000, but 4000). The groups should be separated by a space, and not a comma, period, or dash.

SuggestedRemedy

Change: 19,531,250
To: 19 531 250

Proposed Response Response Status O

Cl 144 SC 144.4.3.1 P 245 L 17 # 552

Remein, Duane independent

Comment Type TR Comment Status X

Persistently disabling all downstream or all upstream channels to an ONU results in that ONU being unusable. The user should be warned of this.
This comment is submitted as an alternative solution to unsatisfied comment # 249 and # 253

SuggestedRemedy

Add a note to Table 144-11 to read as follows:
NOTE - Persistently disabling all downstream or all upstream channels of an ONU results in that ONU being unusable requiring replacement or repair.

Proposed Response Response Status O

Cl A SC A P 27 L 1 # 595

Anslow, Pete Ciena

Comment Type ER Comment Status X

Amendments to IEEE 802.3-2018 place all of the annexes at the end after all of the clauses (as was the case in D2.0 for Annex 31A)

SuggestedRemedy

Move Annex A and Annex 31A between Clause 144 and Annex 142A

Proposed Response Response Status O