Clause		Page Line	Commenter Dieter	Comment	Suggested change	Proposed resolution
	1	14	20 Schicketanz Dieter	Different definitions in ISO and TIA	Change Category to Class	REJECT - definition reflects usage in the
	1	14	28 Schicketanz	Different definitions in ISO and TIA	Change Category to Class	document
	98	Gene ral	Dieter Schicketanz Dieter	it says often up to 30 m, is that a length limitation? If the channel values are met it could be more. Should it not be at least 30m?	Discuss	REJECT REJECT - link segment is defined under
	98.7	168	1 Schicketanz	Where is the definition of IEEE link States that 40GBASE-T is designed to operate over Class I cabling – but we have not made this decision in 802.3bq. We have only adopted IL and RL requirements specified by Class I cabling.	Discuss	definitions
	98.7	168	3 Alan Flatman	(COMMENT AF01)	Replace "ISO/IEC 11801 Class I" with "TBD"	
	98.7	168	12 Alan Flatman	Editor's note is premature.	Delete editors note	
	98.8	176	36 Wayne Larsen	Explain why MDI-X is needed, both here and in 10GBASE-T	Discuss	
	98.8	176	Alan Flatman	802.3bq has not chosen an MDI connector as yet.	This entire subclause should be marked "TBD"	ACCEPT - Note undecided items as TBD
98.5.4.3		161	Dieter 13 Schicketanz	Common Mode Noise Rejection - there is no limit as the cabling is shielded now measurement set up may have to be redefined	Discuss	REJECT - need specific proposals
98.5.4.5.1		162	Dieter 26 Schicketanz	Short reach test channel - category is wrong	Discuss	REJECT - text is not in the spec - only there as editors note marked needed to delete or replace w/appropriate channel
			Brett	Bit 16 description is incorrect, 'U16 10GBASE-T ability (1=support of	Change to 'U16 10GBASE-T ability (1 = support of 10GBASE-T and	
98.6.1.2		164 Table 98-	15 McClellan	40GBASE-T and 0 = no support)'	0= no support)', and define bit in Next Page for 40GBASE-T	Accept
98.7.1		168	17 Alan Flatman	See comment AF01	Replace "ISO/IEC 11801 Class I" with "TBD"	
98.7.1		168	23 Alan Flatman	See comment AF01	Replace "ISO/IEC 11801 Class I" with "TBD"	
98.7.1		168	24 Alan Flatman	Editor's note is premature.	Delete editor's note	
				Set frequency range of all link segment parameters to 1 MHz ≤ f ≤	Set frequency range of all link segment parameters to 1 MHz \leq f \leq	
98.7.2		168	28 Chris Diminico		2000 MHz	
98.7.2		168	30 Alan Flatman	See comment AF01	Replace "Class I" with "TBD cabling"	
		150		The insertion loss of each duplex channel using Equation (98–11) to Equation (98–14) unnecessarily complex. Equation can be simplified by regression. Link segment insertion need not implicitly represent	Replace equations 98-11 to 98-14 with regression equation, per	
98.7.2.1		169	1 Chris Diminico Dieter	cable and connector insertion losses.	diminico_3bq_01_0914.pdf slide 5	
98.7.2.2		170	22 Schicketanz	What is this? Could be deleted is explained better in 98.7.1	Discuss a. Use the title of 98.7.2.4.3 as the title of 98.7.2.4.2. b. Change the variable in equation 98-17 to PSNEXT. c. Fill in the right side of equation 98-17 with whatever we agree	Discuss
				\ensuremath{MDNEXT} and \ensuremath{PSNEXT} are same thing, redundant and only \ensuremath{PSNEXT} is		
98.7.2.4.2		171	17 Wayne Larsen	used	d. Delete section 98.7.2.4.3.	

ConsolidatedComments_byClause.xlsx Page 1 of 3

98.7.2.4.4	172	•	Fill in Equation 98-21 right hand side	See proposal	
98.7.2.4.4	172	35 Alan Flatman	Equation 98-22 wrong & references 100m cable ACR-F: '100 meter reference?' Also formula 98-22, IEC draft specifies	correct	
98.7.2.4.4	172	Dieter 36 Schicketanz	50m, published TR11801-9901 also 50m, TIA draft 30m, should be left TBD for the moment	Replace 100m with TBD	Discuss
98.7.2.4.4	172	40 Wayne Larsen		Remove length scaling from connector contribution, or If we leave it in, we should compare it with the equation for length scaling of ACRF in Annex D of the latest TIA draft. This equation breaks down the contributions of connectors and cables, and length scales only the cables, which would be correct. 6a. Use the title of 98.7.2.4. as the title of 98.7.2.4.5 b. Change the variable in equation 98-23 to PSACRF. c. Fill in the right side of equation 98-23 with whatever we agree	
98.7.2.4.5	172	47 Wayne Larsen	MDACRF and PSACRF are same thing, redundant and only PSACRF is	on. d. Delete section 98.7.2.4.6	
96.7.2.4.3	172	47 Wayne Larsen	useu	u. Delete section 98.7.2.4.0	
98.7.2.5	173	•	Delay is inconsistent with 30m cable	Change delay to 176 nsec	ACCEPT
98.7.2.6	173	Dieter 33 Schicketanz	Link delay skew, $50/570 = ^9\%$ does not match 4% resistance unbalance.	Discussion needed which one is more important	Discuss
98.7.2.6	173	33 Wayne Larsen	Delay skew is inconsistent with 30m cable	Change delay skew tolerance to 3ns (from 10ns. This is the same for both TIA and ISO, and in both class 1 and class 2	ACCEPT
		•	·		
98.7.3.2.1	174	45 Chris Diminico Dieter	Remove coupling length correction from PSAACRF	Remove coupling length correction from PSAACRF	REJECT - specific updates not identified
98.7.4	175	50 Schicketanz	Needs update to 40G	Update to 40G	nor apparent
98.8.1	175	Dieter 40 Schicketanz	MDI connectors should be called 'connections'	Change title to MDI connections, Fig 98-41 is a connector, OK	REJECT - IEEE nomenclature is consistent with other clauses
96.6.1	1/5	40 Schicketanz	MDI connectors should be called connections	change from "IEC 60603-7-4 (unscreened) or IEC 60603-7-5	with other clauses
98.8.1	176	· ·	Connector references are inconsistent with bandwidth and channel	(screened)" to "IEC 60603-7-82".	DELECT LEEF
98.8.1	176	Dieter 53 Schicketanz	Figure is called 'connector - should be called a plug	Change caption nomenclature from 'connector' to 'plug'	REJECT - IEEE nomenclature is consistent with other clauses
		5			ACCEPT IN PRINCIPLE - Add editors note -
98.8.2	177	Dieter 30 Schicketanz	All electrical values are still Cat6a	Update to 40G values	MDI electrical characteristics to be specified
				·	
98.8.2	177	37 Wayne Larsen	Reference to 500MHz should be 2000MHz	Change 500 MHz to 2000 MHz move the dB to the left column, and add MHz as the units in the	ACCEPT
98.8.2.1	177	50 Wayne Larsen	Equation 98-33, (editorial)	right column. This also applies to equation 98-34 on line 10 on page 178. equation 98-33, add a new row to specify a plateau of 3 dB from	
98.8.2.1	177	54 Wayne Larsen	Equation 98-33 Specification to 500MHz should go to 2000MHz	500 to 2000	
98.8.2.2	178	12 Wayne Larsen	Equation 98-34, specifications to 500Mhz should go to 2000MHz	Extend frequency range to 2000MHz	

ConsolidatedComments_byClause.xlsx Page 2 of 3

			states that this requirement applies when the transmitter is		
			transmitting, but the test method details state that only the part of		
			the voltage that is due to the injected common mode counts and the		
98.8.2.2	178	16 Wayne Larsen	transmitter is to be disabled during the test.	Discuss	
98.8.2.2	178	41 Wayne Larsen	specifications to 500Mhz should go to 2000MHz	Extend frequency range to 2000MHz	
			Figure 98-42 describes Ediff and points to a location, and the		
			requirement specifies this relative to Ecm which is shown in the		
			figure, but there is no clarity as to what point in the MDI to connect		
			to for detection of Ediff, or what kind of interconnection network.		
			The test on page 178 lines 48-54 describes doing this with a network		
			analyzer and measuring Scd11, which would imply the NA becomes		
			the common mode source (should really then be Sdc11), in which		
			case the common-mode coupling circuit would not be needed, but		
			again there is no clarity as to where and how to connect it. The		
			common mode impedances are not consistent. It is specified 75		
	.=0		ohms in this case, 50 Ohms in figure 98-42, and the circuit of figure		
98.8.2.2	179	1 Wayne Larsen	98-43 implies 24.95 Ohms.	Discuss and reconcile	
			The resistors in figure 98-43 should be matched to each other within		
98.8.2.2	179	25 Wayne Larsen	0.1 %, otherwise an error will arise in the calibration.	Add note to this effect	
		Dieter	General wording OK but use reference to nearly finished bonding TR		
98.9.2	180	7 Schicketanz	from ISO (ISO/IEC 30129)	Consider reference to ISO/IEC 30129	Discuss
		51.		D. I	ACCEPT IN PRINCIPLE - Add ISO/IEC
	100	Dieter	Installation and maintenance practices - delete wording, just	Delete wording, reference ISO/IEC 14763-2, delete language on	reference. Reference to bonding is in
98.9.3	180	28 Schicketanz	reference ISO/IEC 14763-2, bonding here is wrong.	bonding	editors note, not text
Equation 98-15	170	37 Wayne Larsen	Combine last 2 rows of RL equation	Combine last 2 rows of RL equation	
Table 98-17	168	37 Alan Flatman	See comment AF01	Replace table content with "TBD"	
			The cabling entry should be ISO Class 1 / ISO Class 2 / TIA Category 8.		
			Category 8.1 is an ISO designation of components. There is no such		
Table 98-17	168	38 Wayne Larsen	channel designation. The TIA is strictly Category 8 with no dots.	Repace entries as described	
. 3510 30 17	-00	33 Wayne Larsen	and the first strictly edecating with no dots.	nepade entities as described	

ConsolidatedComments_byClause.xlsx Page 3 of 3