

IEEE P802.3dm D0.c Asymmetrical Electrical Automotive Ethernet 3rd Task Force review comments

CI 45 SC 45.2.1.6 P 33 L 46 # 1  
 Lo, William Axonne Inc.  
 Comment Type T Comment Status X  
 The field changed to 8 bits. But there is no corresponding change to the description.  
 SuggestedRemedy  
 45.2.1.6.3 Editors discretion to make changes needed to refer to 8 bits (7:0).  
 Proposed Response Response Status O

CI 45 SC 45.2.1.16 P 36 L 17 # 2  
 Lo, William Axonne Inc.  
 Comment Type T Comment Status X  
 The ability bits are done inconsistently between AT1/AV1 and T1/V1. Either there should be 1 bit for both AT1/AV1 or separate bits for T1 and V1. Everything points to register 1.77 anyway so we should make this consistent.  
 SuggestedRemedy  
 Pick either of the options. I'm ok with either one but prefer option 1 to preserve bits for the future.  
 Option1:  
 Consolidate AT1/AV1 into bit 11 and make bit 12 reserved. Consolidate 45.2.1.16.aaaa and aaab into 1 section  
 Option 2:  
 Expand T1/V1 in bit 10 into T1 for bit 10, V1 for bit 11, Move AT1 and AV1 up 1 bit. Split 45.2.1.6.aaac into 2 separate sections, and adjust text in aaaa and aaab to reflect bit movement.  
 Proposed Response Response Status O

CI 201 SC 201.1.1 P 69 L 1 # 3  
 Lo, William Axonne Inc.  
 Comment Type E Comment Status X  
 Style change  
 SuggestedRemedy  
 Change line 1, 6, 10:  
 "When talking about"  
 To:  
 "For"  
 Proposed Response Response Status O

CI 201 SC 201.1.3 P 60 L 7 # 198  
 Razavi, Alireza Infineon  
 Comment Type E Comment Status X  
 Missing space and capitalization issues: "NOTE-Annex K" and "leader"and"; LEADER and FOLLOWER should be capitalized.  
 SuggestedRemedy  
 Change to "NOTE—Annex K ... LEADER and FOLLOWER ..." and correct spacing and quotation formatting.  
 Proposed Response Response Status O

CI 201 SC 201.1.3 P 61 L 50 # 268  
 Wienckowski, Natalie IVN Solutions LLC  
 Comment Type T Comment Status X  
 The notes on Figure 201-3 and 201-4 don't make sense.  
 SuggestedRemedy  
 Change the note on Figure 201-3 to: The recovered\_clock arc is shown to indicate delivery of the received clock signal by the LS\_RX PMA RECEIVE to the HS\_TX PMA TRANSMIT for loop timing when PHY\_S is in FOLLOWER mode.  
 Change the note on Figure 201-4 to: The recovered\_clock arc is shown to indicate delivery of the received clock signal by the HS\_RX PMA RECEIVE to the LS\_TX PMA TRANSMIT for loop timing when PHY\_D is in FOLLOWER mode.  
 Proposed Response Response Status O

IEEE P802.3dm D0.c Asymmetrical Electrical Automotive Ethernet 3rd Task Force review comments

CI 201 SC 201.1.3 P 62 L 50 # 151  
 Pandey, Sujan Velinktech  
 Comment Type T Comment Status X  
 NOTE—The recovered\_clock arc,FOLLOWER only, is shown to indicate delivery of the received clock signal by the HS\_TX PMA TRANSMIT for loop timing.  
 SuggestedRemedy  
 NOTE—The recovered\_clock arc,FOLLOWER only, is shown to indicate delivery of the received clock signal by the LS\_TX PMA TRANSMIT for loop timing.  
 Proposed Response Response Status O

CI 201 SC 201.1.3 P 62 L 50 # 200  
 Razavi, Alireza Infineon  
 Comment Type E Comment Status X  
 Missing space in "arc,FOLLOWER"; also HS\_TX is used instead of LS\_TX in the PHY\_D context.  
 SuggestedRemedy  
 Change to "NOTE—The recovered\_clock arc is shown to indicate delivery of the received clock signal by the LS\_RX PMA RECEIVE for loop timing." for figure 201.3,and chnage to "NOTE—The recovered\_clock arc is shown to indicate delivery of the received clock signal by the HS\_RX PMA RECEIVE for loop timing." for figure 201.3  
 Proposed Response Response Status O

CI 201 SC 201.1.3.4 P 64 L 20 # 152  
 Pandey, Sujan Velinktech  
 Comment Type T Comment Status X  
 The wording "time and control link failure, and act as the data source for the PHY control state diagram" is not clear  
 SuggestedRemedy  
 no suggestion  
 Proposed Response Response Status O

CI 201 SC 201.1.4 P 64 L 26 # 201  
 Razavi, Alireza Infineon  
 Comment Type E Comment Status X  
 Passive voice: "HS\_PATH signaling is performed by the HS\_TX PCS generating ...".  
 SuggestedRemedy  
 Grant editorial latitude to convert passive constructions to active. For example, change this instance to "HS\_TX PCS generates ...".  
 Proposed Response Response Status O

CI 201 SC 201.1.4 P 64 L 31 # 153  
 Pandey, Sujan Velinktech  
 Comment Type T Comment Status X  
 PAM2 symbols in the 2.5 Gb/s and  
 SuggestedRemedy  
 PAM2 symbols on the MDI port in the 2.5 Gb/s and  
 Proposed Response Response Status O

CI 201 SC 201.1.4 P 64 L 45 # 154  
 Pandey, Sujan Velinktech  
 Comment Type T Comment Status X  
 in definition it is called "normal data mode" but later in text everywhere sometime it is used as normal mode or data mode. Please make it consistent  
 SuggestedRemedy  
 normal data mode or normal mode or data mode  
 Proposed Response Response Status O

IEEE P802.3dm D0.c Asymmetrical Electrical Automotive Ethernet 3rd Task Force review comments

Cl 201 SC 201.1.5 P 65 L 2 # 155  
 Pandey, Sujan Velinktech  
 Comment Type E Comment Status X  
 to DME symbols in the transmit path  
 SuggestedRemedy  
 to DME symbols on the MDI port in the transmit path  
 Proposed Response Response Status O

Cl 201 SC 201.1.5 P 65 L 15 # 156  
 Pandey, Sujan Velinktech  
 Comment Type E Comment Status X  
 normal mode  
 SuggestedRemedy  
 normal data mode or normal mode or data mode  
 Proposed Response Response Status O

Cl 201 SC 201.2.1 P 61 L 8 # 199  
 Razavi, Alireza Infineon  
 Comment Type E Comment Status X  
 Inconsistent naming: "PMA\_LINK" in text vs "PMA\_Link" in figures.  
 SuggestedRemedy  
 Normalize the naming to a single format, recommended "PMA\_LINK", throughout the text and figures.  
 Proposed Response Response Status O

Cl 201 SC 201.2.1.2.2 P 66 L 59 # 202  
 Razavi, Alireza Infineon  
 Comment Type E Comment Status X  
 Broken reference: "Figure 201–32 Figure 149–33"  
 SuggestedRemedy  
 delete figure 149-33  
 Proposed Response Response Status O

Cl 201 SC 201.2.2.1.1 P 70 L 10 # 189  
 Muma, Scott Microchip  
 Comment Type T Comment Status X  
 Various changes on SEND\_Z are required to clarify that it is only used in the case no TDD bursts are being sent and continuous transmission of Z symbols is required. Also changing the symbol from 0 to Z is useful and showing that during TDD bursts a fixed number of Z's will be transmitted in the TDD interval depending on the N\_r and N\_p in use.  
 SuggestedRemedy  
 See attached 8023d0pc-202\_202.3.5\_sendz\_changes.doc and P8023dm\_D0pc\_bit\_order\_figure\_markup.pdf  
 Proposed Response Response Status O

Cl 201 SC 201.3 P 74 L 11 # 203  
 Razavi, Alireza Infineon  
 Comment Type E Comment Status X  
 The clause opener "The PCS functions for HS\_PATH are as specified for MultiGBASE-T1 PHYs in 149.3 with the exception that ..." again over-relies on remote text.  
 SuggestedRemedy  
 Remove this sentence; Clause 201.3 shall fully describe HS\_PATH behavior locally.  
 Proposed Response Response Status O

Cl 201 SC 201.3.2 P 61 L 25 # 233  
 Razavi, Alireza Infineon  
 Comment Type T Comment Status X  
 Undefined variable: 'rx\_boundary' and 'tx\_boundary' are shown as signals in Figures 201–5, 201–6 (PCS-PMA interface diagrams) and used in state diagram code, but neither is defined in the variable tables of 201.5.2.6.2, 201.5.2.7.1, or 201.5.2.8.1, nor in the PMA service interface description of 201.2.2.  
 SuggestedRemedy  
 Add definitions for 'rx\_boundary' and 'tx\_boundary' in 201.2.2 or the appropriate state diagram variable table, specifying their type, source, and role in frame boundary alignment.  
 Proposed Response Response Status O

IEEE P802.3dm D0.c Asymmetrical Electrical Automotive Ethernet 3rd Task Force review comments

Cl 201 SC 201.3.2 P 61 L 40 # 234

Razavi, Alireza Infineon  
 Comment Type T Comment Status X

Undefined signal: 'recovered\_clock' appears in Figures 201–3 and 201–4 (PHY\_S and PHY\_D functional block diagrams) as a signal arc between PMA Receive and PMA Transmit, but is not defined as a primitive or variable anywhere in 201.2 or 201.5.

*SuggestedRemedy*

Add 'recovered\_clock' to the PMA service interface description in 201.5.2.9 (Clock Recovery), or add a NOTE in 201.5.2.2 (PMA Transmit) explaining its source and usage. The two existing NOTES in the figures reference it without a normative anchor.

Proposed Response Response Status O

Cl 201 SC 201.3.2 P 75 L 2 # 204

Razavi, Alireza Infineon  
 Comment Type E Comment Status X

Mixed-signal naming inconsistency in Figures 201–7 and 201–8: TXc/TXC.

*SuggestedRemedy*

Normalize all such labels to TXC/RXC across the affected figures.

Proposed Response Response Status O

Cl 201 SC 201.3.2 P 75 L 35 # 231

Razavi, Alireza Infineon  
 Comment Type E Comment Status X

Figures 201–8 has formatting issue on HS\_RX box, LS\_TXI.

*SuggestedRemedy*

Align arrows for loc\_rcvr\_status, link\_status, tx\_symb, tx\_mode, and pcs\_data\_mode so they terminate at the bottom of the PCS\_RECEIVE and HS\_LX PCS\_TRANSMIT blocks

Proposed Response Response Status O

Cl 201 SC 201.3.2 P 75 L 35 # 157

Pandey, Sujun Velinktech  
 Comment Type E Comment Status X

correct the arrows in the figures

*SuggestedRemedy*

Proposed Response Response Status O

Cl 201 SC 201.3.2 P 75 L 36 # 190

Jonsson, Ragnar Infineon  
 Comment Type E Comment Status X

Arrow start and finish is not aligned with the box boundary

*SuggestedRemedy*

Align arrows with the box boundary

Proposed Response Response Status O

Cl 201 SC 201.3.2.2 P 76 L 32 # 129

Maguire, Valerie Copperopolis; affl w/ CME Consulting, Microchip, and  
 Comment Type T Comment Status X

PCS Transmit is more accurately a function, not a process. PCS Receive is more accurately a function, not a process.

*SuggestedRemedy*

Replace, "PCS Transmit process" with "PCS Transmit function" in 11 locations in the document. Replace, "PCS Receive process" with "PCS Receive function" in 11 locations in the document.

Proposed Response Response Status O

IEEE P802.3dm D0.c Asymmetrical Electrical Automotive Ethernet 3rd Task Force review comments

CI 201 SC 201.3.2.2 P 101 L 50 # 211  
 Razavi, Alireza Infineon  
 Comment Type E Comment Status X  
 Field naming drifts between "OAM field" and "OAM\_field" in the PCS framing descriptions.  
 SuggestedRemedy  
 Use tx\_oam\_field consistently where the transmit OAM field signal is meant.  
 Proposed Response Response Status O

CI 201 SC 201.3.2.2.1 P 78 L 28 # 12  
 Zimmerman, George CME Consulting/ADI,APL Gp, Cisco, Infineon, OnSe  
 Comment Type T Comment Status X  
 the text says ENCODE and DECODE work according to the rules in 201.3.2.2.2, but there are no rules there (this was an error in earlier text, discovered in dg). Since the ENCODE and DECODE functions produce & interpret the 64B/65B blocks, the rules for blocks are indicated. These are in 201.3.2.2.4 (Block structure),  
 SuggestedRemedy  
 Change 201.3.2.2.2 to 201.3.2.2.4  
 Proposed Response Response Status O

CI 201 SC 201.3.2.2.5 P 79 L 15 # 13  
 Zimmerman, George CME Consulting/ADI,APL Gp, Cisco, Infineon, OnSe  
 Comment Type T Comment Status X  
 There is no "transcoder". The blocks shown are simply the encoded 65B blocks concatenated. Where the text said transcoder (in 201.3.2.2.12 and 201.4.2.2.12) it clearly meant RS-FEC encoder.  
 SuggestedRemedy  
 Delete "Output of transcoder" from Figures 201-11 and 201-12, and change "to the transcoder" to "to the RS-FEC encoder" in 201.3.2.2.12 (P83 L3) and 201.4.2.2.12 (P101 L8).  
 Proposed Response Response Status O

CI 201 SC 201.3.2.2.13 P 83 L 8 # 14  
 Zimmerman, George CME Consulting/ADI,APL Gp, Cisco, Infineon, OnSe  
 Comment Type T Comment Status X  
 We jump directly from tx\_coded, a 64B/65B block to "The resulting RS-FEC frame..." only 2 sections later does the RS-FEC encoding get described. This is because we skipped the definition of tx\_group50x65B which had been in 201.1.3.1. (an awkward place).  
 SuggestedRemedy  
 Insert the following new first paragraph for 201.3.2.2.13: "To form the RS-FEC frame, 50 65B blocks are grouped as follows:  
 $tx\_group50x65B,65 * i + j = tx\_coded\_i <j>$   
 where  $i = 0$  to 49,  $j = 0$  to 64, and  $tx\_coded\_i <64:0>$  is the  $i$ th 65B/65B block and  $tx\_coded\_0 <64:0>$  is the first block transmitted."  
 (note "\_" is subscript, and "\*" is the multiplication symbol)  
 Proposed Response Response Status O

CI 201 SC 201.3.2.2.18 P 83 L 38 # 193  
 Zhu, Liang Infineon  
 Comment Type ER Comment Status X  
 "Dn , which are represented in Figure 201-7 as Dn [0]" -- equation linking error  
 SuggestedRemedy  
 link to Figure 201-10  
 Proposed Response Response Status O

CI 201 SC 201.3.2.3 P 84 L 39 # 158  
 Pandey, Sujan Velinktech  
 Comment Type T Comment Status X  
 and signals the reliable  
 SuggestedRemedy  
 and indicates the reliable  
 Proposed Response Response Status O

IEEE P802.3dm D0.c Asymmetrical Electrical Automotive Ethernet 3rd Task Force review comments

CI 201 SC 201.3.2.3 P 85 L 7 # 205  
 Razavi, Alireza Infineon  
 Comment Type E Comment Status X  
 Subheadings 201.3.2.3.1 and 201.3.2.3.2 both read "Frame and block synchronization".  
 SuggestedRemedy  
 Differentiate the subclause headings if they cover different functions, or confirm and document that the duplication is intentional.  
 Proposed Response Response Status O

CI 201 SC 201.3.2.3.1 P 85 L 7 # 4  
 Lo, William Axonne Inc.  
 Comment Type T Comment Status X  
 This section lines 7 to 16 was intended to be replaced with 201.3.2.3.2.  
 SuggestedRemedy  
 Delete 201.3.2.3.1 in its entirety.  
 Proposed Response Response Status O

CI 201 SC 201.3.2.3 P 98 L 22 # 210  
 Razavi, Alireza Infineon  
 Comment Type E Comment Status X  
 State-variable naming drifts between "block lock" and "block\_lock". Sentence reads "It obtains block lock ...".  
 SuggestedRemedy  
 Change the wording to "the PHY PCS locks the FEC frame ..." and use consistent state-variable naming.  
 Proposed Response Response Status O

CI 201 SC 201.3.2.3.1 P 85 L 9 # 159  
 Pandey, Sujun Velinktech  
 Comment Type T Comment Status X  
 in the data mode  
 SuggestedRemedy  
 normal data mode or normal mode or data mode  
 Proposed Response Response Status O

CI 201 SC 201.3.2.3.1 P 85 L 7 # 194  
 Zhu, Liang Infineon  
 Comment Type ER Comment Status X  
 201.3.2.3.1 and 201.3.2.3.2 have a lot of duplication  
 SuggestedRemedy  
 merge  
 Proposed Response Response Status O

CI 201 SC 201.3.2.3.1 P 85 L 12 # 160  
 Pandey, Sujun Velinktech  
 Comment Type T Comment Status X  
 in the data mode  
 SuggestedRemedy  
 normal data mode or normal mode or data mode  
 Proposed Response Response Status O

CI 201 SC 201.3.2.3.2 P 85 L 20 # 161  
 Pandey, Sujun Velinktech  
 Comment Type T Comment Status X  
 in the data mode  
 SuggestedRemedy  
 normal data mode or normal mode or data mode  
 Proposed Response Response Status O

IEEE P802.3dm D0.c Asymmetrical Electrical Automotive Ethernet 3rd Task Force review comments

CI 201 SC 201.3.2.3.2 P 85 L 25 # 162  
 Pandey, Sujan Velinktech  
 Comment Type T Comment Status X  
 in the data mode  
 SuggestedRemedy  
 normal data mode or normal mode or data mode  
 Proposed Response Response Status O

CI 201 SC 201.3.4 P 85 L 32 # 207  
 Razavi, Alireza Infineon  
 Comment Type E Comment Status X  
 For readability, import Section 149.4.3 and Equations (149–5) and (149–6) into Clause 201.  
 Text of 149.3.4 should also be moved, as it contains key information.  
 SuggestedRemedy  
 see comment  
 Proposed Response Response Status O

CI 201 SC 201.3.2.3.3 P 85 L 32 # 206  
 Razavi, Alireza Infineon  
 Comment Type E Comment Status X  
 The text says “The descrambling process is as specified in 149.3.2.3.2, except Equation (149–5) shall be applied regardless of whether PHY\_S is LEADER or FOLLOWER.” The exception ties strongly to Equation (149–5), making the reference too narrow.  
 SuggestedRemedy  
 Bring the relevant descrambling text and equation content from 149 into Clause 201 so the full rule is stated locally.  
 Proposed Response Response Status O

CI 201 SC 201.3.5 P 86 L 2 # 163  
 Pandey, Sujan Velinktech  
 Comment Type E Comment Status X  
 shown in Figure 201-16  
 SuggestedRemedy  
 shown in Figure 201-15  
 Proposed Response Response Status O

CI 201 SC 201.3.2.3.4 P 85 L 37 # 266  
 Wienckowski, Natalie IVN Solutions LLC  
 Comment Type T Comment Status X  
 Refers to 149, but needs to be brought in to refer to 201 specific requirements and Figures.  
 SuggestedRemedy  
 Copy 149.3.2.3.3 into 201.3.2.3.4, and change the reference to be to 201.3.2.2.13.  
 Proposed Response Response Status O

CI 201 SC 201.3.5 P 86 L 5 # 164  
 Pandey, Sujan Velinktech  
 Comment Type E Comment Status X  
 shown in Figure 201-15  
 SuggestedRemedy  
 shown in Figure 201-16  
 Proposed Response Response Status O

CI 201 SC 201.3.5 P 86 L 39 # 208  
 Razavi, Alireza Infineon  
 Comment Type E Comment Status X  
 “InfoField” should be “Infocfield” to align with the rest of the text.  
 SuggestedRemedy  
 see comment  
 Proposed Response Response Status O

IEEE P802.3dm D0.c Asymmetrical Electrical Automotive Ethernet 3rd Task Force review comments

CI 201 SC 201.3.6.1 P 87 L 2 # 15  
 Zimmerman, George CME Consulting/ADI,APL Gp, Cisco, Infineon, OnSe  
 Comment Type E Comment Status X  
 201.3.6.1 is unnecessary, since this has been previously stated for the entire clause (in 201.1.7)  
 SuggestedRemedy  
 Delete 201.3.6.1  
 Proposed Response Response Status O

CI 201 SC 201.4.2.2 P 96 L 41 # 264  
 Wienckowski, Natalie IVN Solutions LLC  
 Comment Type T Comment Status X  
 Reference to 149-16 replaced by 201-18, which has no dashed rectangles.  
 SuggestedRemedy  
 Delete sentence: Dashed rectangles in Figure 149-16 are not part of the low speed PCS.  
 Proposed Response Response Status O

CI 201 SC 201.3.8 P 94 L 41 # 209  
 Razavi, Alireza Infineon  
 Comment Type E Comment Status X  
 The OAM field is tied to two different defining subclauses: 201.3.8 points to 201.3.2.2.13, while 201.3.8.1 points to 201.3.2.2.14.  
 SuggestedRemedy  
 Clarify that the OAM frame data is carried in the 10-bit OAM field described in 201.3.2.2.13 for HS\_PATH.  
 Proposed Response Response Status O

CI 201 SC 201.4.2.2 P 97 L 26 # 239  
 Wang, Frank Realtek Semiconductor Corp.  
 Comment Type E Comment Status X  
 typo: no space after comma  
 SuggestedRemedy  
 change "(50,46, 6)" to "(50,46,6)"  
 Proposed Response Response Status O

CI 201 SC 201.4 P 96 L 10 # 263  
 Wienckowski, Natalie IVN Solutions LLC  
 Comment Type T Comment Status X  
 Change references to 149 to those in 201.3 as content was brought in from 149.  
 SuggestedRemedy  
 P96L33: Change 149.3.2.1 to 201.3.2.1  
 P96L37&P101L7: Change Figure 149-16 to Figure 201-18.  
 P104L10&P104L25: Change Figure 149-18 to Figure 201-19.  
 P104L12: Change 149.3.7.2.2 to 201.3.6.2.2.  
 Proposed Response Response Status O

CI 201 SC 201.4.2.2 P 98 L 38 # 235  
 Razavi, Alireza Infineon  
 Comment Type E Comment Status X  
 Notation inconsistency: 'RS-FEC(50,46) ( in figures) ' and 'RS-FEC(50,46,6)' (120 occurrences).  
 SuggestedRemedy  
 please use RS-FEC(50,46,6)  
 Proposed Response Response Status O

CI 201 SC 201.4.2.2.1 P 98 L 4 # 16  
 Zimmerman, George CME Consulting/ADI,APL Gp, Cisco, Infineon, OnSe  
 Comment Type E Comment Status X  
 RS\_FEC should be RS-FEC  
 SuggestedRemedy  
 See comment.  
 Proposed Response Response Status O

IEEE P802.3dm D0.c Asymmetrical Electrical Automotive Ethernet 3rd Task Force review comments

CI 201 SC 201.4.2.2.2 P 98 L 39 # 240  
 Wang, Frank Realtek Semiconductor Corp.  
 Comment Type E Comment Status X  
 typo: insert a space before "decoder"  
 SuggestedRemedy  
 change "RS-FEC(50,46)decoder" to "RS-FEC(50,46) decoder"  
 Proposed Response Response Status O

CI 201 SC 201.4.2.2.14 P 101 L 51 # 212  
 Razavi, Alireza Infineon  
 Comment Type E Comment Status X  
 RS-message assignment text uses vendor-specific\_field<5:0> (double "l" in "field").  
 SuggestedRemedy  
 see comment  
 Proposed Response Response Status O

CI 201 SC 201.4.2.2.14 P 102 L 43 # 241  
 Wang, Frank Realtek Semiconductor Corp.  
 Comment Type E Comment Status X  
 typo: no space after comma  
 SuggestedRemedy  
 change "RS-FEC(50, 46)" to "RS-FEC(50,46)"  
 Proposed Response Response Status O

CI 201 SC 201.4.2.2.16 P 103 L 14 # 5  
 Lo, William Axonne Inc.  
 Comment Type T Comment Status X  
 Copy and paste error  
 SuggestedRemedy  
 sections 201.4.2.2.16 to 201.4.2.2.22 should be deleted in its entirety  
 Proposed Response Response Status O

CI 201 SC 201.4.2.2.18 P 103 L 22 # 213  
 Razavi, Alireza Infineon  
 Comment Type E Comment Status X  
 High-speed-path wording is used inside a low-speed-path subsection (e.g., "All incoming PAM2 path HS\_RX ..."). Low-speed-path scrambling text points to 201.3.4, which appears to be a carried-over high-speed reference rather than a local 201.4 reference.  
 SuggestedRemedy  
 Review and update the text and references to use the correct LS\_PATH wording and the correct local Clause 201.4 subclause references.  
 Proposed Response Response Status O

CI 201 SC 201.4.2.3 P 96 L 41 # 265  
 Wienckowski, Natalie IVN Solutions LLC  
 Comment Type T Comment Status X  
 Reference to 149-18 replaced by 201-19, which has no dashed rectangles.  
 SuggestedRemedy  
 Delete sentence: Dashed rectangles in Figure 149-18 are not part of the low speed PCS.  
 Proposed Response Response Status O

CI 201 SC 201.4.2.3 P 104 L 30 # 165  
 Pandey, Sujan Velinktech  
 Comment Type E Comment Status X  
 signals  
 SuggestedRemedy  
 indicates  
 Proposed Response Response Status O

IEEE P802.3dm D0.c Asymmetrical Electrical Automotive Ethernet 3rd Task Force review comments

CI 201 SC 201.4.2.3.2 P 105 L 6 # 6  
 Lo, William Axonne Inc.  
 Comment Type T Comment Status X  
 Inconsistent referencing.  
 201.4.2.2.15 points to 201.4.4  
 This section should do so as well.  
 SuggestedRemedy  
 Delete the existing text and replace with:The descrambling process is as specified in  
 149.3.2.3.2, except gM(x) shall be applied as defined in 201.4.4.  
 Proposed Response Response Status O

CI 201 SC 201.4.5 P 105 L 54 # 7  
 Lo, William Axonne Inc.  
 Comment Type T Comment Status X  
 There is no 64 to 65 bit conversion for the training frame  
 SuggestedRemedy  
 Change 64B/65B to 65-bit  
 Proposed Response Response Status O

CI 201 SC 201.4.6 P 106 L 45 # 8  
 Lo, William Axonne Inc.  
 Comment Type T Comment Status X  
 We went through all the trouble to put in 201.3.6 so we should point to that.  
 SuggestedRemedy  
 Detailed functions and state diagrams are as specified in 201.3.6  
 Proposed Response Response Status O

CI 201 SC 201.4.7 P 106 L 48 # 9  
 Lo, William Axonne Inc.  
 Comment Type T Comment Status X  
 This section is identical to 201.3.7 so we should point to that.  
 SuggestedRemedy  
 Delete all contents in 201.4.7 including subclauses and replace with:  
 See 201.3.7.  
 Proposed Response Response Status O

CI 201 SC 201.4.8 P 107 L 31 # 195  
 Zhu, Liang Infineon  
 Comment Type ER Comment Status X  
 "The MultiG+100MBASE-T1/V1 PCS level operations administration, and ..." -- HS type in  
 LS chapter  
 SuggestedRemedy  
 change to 100M+MultiGBASE-T1/V1...  
 Proposed Response Response Status O

CI 201 SC 201.5.2.2 P 109 L 27 # 10  
 Lo, William Axonne Inc.  
 Comment Type E Comment Status X  
 Grammar.  
 SuggestedRemedy  
 Line 17 "A PHY\_D" and "A PHY\_S" should be "PHY\_D" and "PHY\_S"  
 Proposed Response Response Status O

IEEE P802.3dm D0.c Asymmetrical Electrical Automotive Ethernet 3rd Task Force review comments

CI 201 SC 201.5.2.4 P 111 L 1 # 166  
 Pandey, Sujan Velinktech  
 Comment Type E Comment Status X  
 The infofield is also denoted IF  
 SuggestedRemedy  
 The infofield is also denoted as IF  
 Proposed Response Response Status O

CI 201 SC 201.5.2.4.4 P 112 L 20 # 214  
 Razavi, Alireza Infineon  
 Comment Type E Comment Status X  
 "message field" capitalization is inconsistent.  
 SuggestedRemedy  
 Use "Message Field" consistently throughout the text.e capitalize "Message Field" in titles of tables 201-5 and 201-6.  
 Proposed Response Response Status O

CI 201 SC 201.5.2.4.6 P 113 L 27 # 127  
 van Dyck, Peter Infineon  
 Comment Type T Comment Status X  
 Since the time to send a complete set of infofields is speed dependent, see 201.5.2.4, the length of the countdown must also be speed dependent for HS\_PATH.  
 SuggestedRemedy  
 Replace:  
 "DataSwPFC24 shall be a minimum of 4081 and a maximum of 4785 from the current PFC24 value."  
 With:  
 "For 10Gb/s and 5Gb/s, DataSwPFC24 shall be a minimum of 4081 and a maximum of 4785 from the current PFC24 value. For 2.5Gb/s, DataSwPFC24 shall be a minimum of 2033 and a maximum of 2385 from the current PFC24 value."  
 Proposed Response Response Status O

CI 201 SC 201.5.2.5.4 P 112 L 50 # 217  
 Razavi, Alireza Infineon  
 Comment Type E Comment Status X  
 OAMen is expanded differently in HS\_PATH and LS\_PATH text.  
 SuggestedRemedy  
 Change "OAMen indicates MultiGBASE-T1 OAM capability enable, respectively. The PHY shall indicate the support of optional capabilities by setting the corresponding capability bits." - change to read: "OAMen indicates that the MultiGBASE-T1 OAM capability is enabled." (the second shall isn't needed, and grammar is fixed). In 201.5.2.5.4 (P116 L1) change "OAMen indicates 100M+MultiGBASE-T1/V1 OAM capability enable. The PHY shall indicate the support of this OAM capability by setting the OAMen capability bit to 1." to "OAMen indicates that the MultiGBASE-T1 OAM capability is enabled." (there is only one OAM capability, since both link partners need to exchange it - and the second shall isn't needed again.)  
 Proposed Response Response Status O

CI 201 SC 201.5.2.6.1 P 116 L 24 # 215  
 Razavi, Alireza Infineon  
 Comment Type E Comment Status X  
 Labels "startup sequence" and "PHY Control function, HS\_PATH, LS\_PATH" are redundant.  
 SuggestedRemedy  
 see comment  
 Proposed Response Response Status O

CI 201 SC 201.5.2.6.1 P 116 L 27 # 216  
 Razavi, Alireza Infineon  
 Comment Type E Comment Status X  
 Startup Sequence text uses mr\_autoneg\_en, while PHY Control / Link Synchronization uses mr\_autoneg\_enable.  
 SuggestedRemedy  
 Use mr\_autoneg\_enable consistently throughout.  
 Proposed Response Response Status O

IEEE P802.3dm D0.c Asymmetrical Electrical Automotive Ethernet 3rd Task Force review comments

Cl 201 SC 201.5.2.6.1 P 117 L 6 # 236  
 Razavi, Alireza Infineon  
 Comment Type E Comment Status X  
 replace 'en\_slave\_tx = 1' with en\_follower\_tx = 1'.  
 SuggestedRemedy  
 see comment  
 Proposed Response Response Status O

Cl 201 SC 201.5.2.6.4 P 120 L 33 # 218  
 Razavi, Alireza Infineon  
 Comment Type E Comment Status X  
 The condition loc\_rcvr\_status = OK should apply to both PHY\_D and PHY\_S for TX\_SWITCH state  
 SuggestedRemedy  
 see comment  
 Proposed Response Response Status O

Cl 201 SC 201.5.2.8.1 P 124 L 1 # 191  
 Jonsson, Ragnar Infineon  
 Comment Type T Comment Status X  
 Incorrect condition for TRUE state  
 SuggestedRemedy  
 Change "No SEND\_S pulses" to "Less than three SENBD\_S pulses".  
 Proposed Response Response Status O

Cl 201 SC 201.5.2.8.1 P 124 L 4 # 192  
 Jonsson, Ragnar Infineon  
 Comment Type T Comment Status X  
 Incorrect condition for FALSE state  
 SuggestedRemedy  
 Change "At least one SEND\_S pulse" to At least three SEND\_S pulses".  
 Proposed Response Response Status O

Cl 201 SC 201.5.2.10 P 127 L 8 # 219  
 Razavi, Alireza Infineon  
 Comment Type E Comment Status X  
 Text should be brought in from Clause 149, and subclauses 201.5.2.11 and 201.5.2.10 should be merged. It would be helpful to add a sentence describing the difference between MDI for T1 and V1.  
 SuggestedRemedy  
 see comment  
 Proposed Response Response Status O

Cl 201 SC 201.6.2.2 P 131 L 43 # 267  
 Wienckowski, Natalie IVN Solutions LLC  
 Comment Type E Comment Status X  
 No specific changes have been requested.  
 SuggestedRemedy  
 Delete Editor's Note  
 Proposed Response Response Status O

Cl 201 SC 201.6.2.3.2 P 133 L 24 # 196  
 Wei, Fan Infineon  
 Comment Type T Comment Status X  
 Should separate PAM4 and PAM2 mode EOJ test method, for PAM4, follow 94.3.12.6.2 with JP03B pattern, while for PAM2, pattern changed to 1010 patter, should follow a PAM2 standard, i.e. 130.7.1.9  
 SuggestedRemedy  
 To measure peak-to-peak even-odd jitter (EOJpk-pk), for PAM4 mode, follow the steps as specified in 94.3.12.6.2; for PAM2 mode, follow the steps as specified in 130.7.1.9  
 Proposed Response Response Status O

IEEE P802.3dm D0.c Asymmetrical Electrical Automotive Ethernet 3rd Task Force review comments

CI 201 SC 201.6.2.5 P 135 L 37 # 11  
 Lo, William Axonne Inc.  
 Comment Type T Comment Status X  
 10GBASE-T1 PSD in 149.5.2.4 is -1dBm to 2 dBm.and 149.5.2.5 peak is less than 1.3V  
 201.6.2.4 for 10G also lists PSD of -1dBm to 2 dBm.but 201.6.2.5 list the max peak as  
 1.7V which is inconsistent.  
 SuggestedRemedy  
 Change 1.7 to 1.3  
 Change 0.85 to 0.65  
 Proposed Response Response Status O

CI 201 SC 201.6.3.1 P 136 L 8 # 220  
 Razavi, Alireza Infineon  
 Comment Type E Comment Status X  
 The test is called "BER monitoring" in Table 201-13.  
 SuggestedRemedy  
 Adjust the segment title to match " frame error ratio requirement" and state explicitly that  
 Test Mode 7 can be used.  
 Proposed Response Response Status O

CI 201 SC 201.6.3.1 P 136 L 11 # 197  
 Wei, Fan Infineon  
 Comment Type T Comment Status X  
 Low speed RX spec refers to high speed spec, which is 1e-12, for 100M signal, to qualify  
 1e-12, the test time will be too long, low speed should follow 100BT1 spec, which is 1e-10  
 SuggestedRemedy  
 Proposed Response Response Status O

CI 201 SC 201.6.3.1 P 143 L 1 # 228  
 Razavi, Alireza Infineon  
 Comment Type E Comment Status X  
 section 201.6.4 , and 201.7.4 should be removed  
 SuggestedRemedy  
 see comment  
 Proposed Response Response Status O

CI 201 SC 201.6.3.2 P 136 L 22 # 114  
 Zimmerman, George CME Consulting/ADI,APL Gp, Cisco, Infineon, OnSe  
 Comment Type T Comment Status X  
 The broadband stationary noise test is missing a "shall" (both 201 & 202)  
 SuggestedRemedy  
 change "the frame loss ratio is less than" to "the frame loss ratio shall be less than" at P136  
 L22, and P228 L9 (202.5.3.2)  
 Proposed Response Response Status O

CI 201 SC 201.6.3.2 P 137 L 19 # 221  
 Razavi, Alireza Infineon  
 Comment Type E Comment Status X  
 An Editor's Note remains in the clause text.  
 SuggestedRemedy  
 Delete the editor's note at the end of 201.6.3.2  
 Proposed Response Response Status O

IEEE P802.3dm D0.c Asymmetrical Electrical Automotive Ethernet 3rd Task Force review comments

CI 201 SC 201.7.1 P 138 L 11 # 222  
 Razavi, Alireza Infineon  
 Comment Type T Comment Status X  
 the standard text already makes clear that if one direction requires a precoder, the transmitter shall provide it. The section should not define a test for each "shall" statement.  
 SuggestedRemedy  
 Remove Test Mode 3 and the precoder test.  
 Proposed Response Response Status O

CI 201 SC 201.7.2 P 138 L 42 # 223  
 Razavi, Alireza Infineon  
 Comment Type E Comment Status X  
 For readability, ordering test descriptions by test mode would be helpful.  
 SuggestedRemedy  
 see comment  
 Proposed Response Response Status O

CI 201 SC 201.7.2.3 P 139 L 47 # 224  
 Razavi, Alireza Infineon  
 Comment Type E Comment Status X  
 Timing jitter test text appears in 201.6.2.3 and 201.7.2.3 but needs clarification and a clear distinction between the two tests. If they are equivalent, one should reference the other to reduce ambiguity.  
 SuggestedRemedy  
 Proposed Response Response Status O

CI 201 SC 201.7.2.4 P 140 L 27 # 225  
 Razavi, Alireza Infineon  
 Comment Type E Comment Status X  
 It would improve clarity if the draft explicitly stated that MDI deterministic jitter is not defined for low data rate.  
 SuggestedRemedy  
 Add subsections for transmit MDI random jitter and transmit MDI deterministic jitter, and state that MDI deterministic jitter for low data rate is not defined. Use the same structural approach for the high data-rate direction.  
 Proposed Response Response Status O

CI 201 SC 201.7.2.6 P 142 L 27 # 227  
 Razavi, Alireza Infineon  
 Comment Type E Comment Status X  
 The test mode for peak output is not explicitly mentioned.  
 SuggestedRemedy  
 State explicitly that Test Mode 5 can be used for the peak output test. Apply the same clarification for the low data-rate direction.  
 Proposed Response Response Status O

CI 201 SC 201.7.2.7 P 142 L 40 # 226  
 Razavi, Alireza Infineon  
 Comment Type E Comment Status X  
 The test mode for clock frequency is not explicitly mentioned.  
 SuggestedRemedy  
 State explicitly that Test Mode 2 can be used for the clock frequency test. Apply the same clarification for the low data-rate direction.  
 Proposed Response Response Status O

IEEE P802.3dm D0.c Asymmetrical Electrical Automotive Ethernet 3rd Task Force review comments

Cl 201 SC 201.9.1.2 P 145 L 10 # 232  
 Razavi, Alireza Infineon  
 Comment Type T Comment Status X  
 to be consistent with other setting, return loss for 2.5G may cover up to 2G not 4G  
 SuggestedRemedy  
 define Fmax similar to equation 201-14.  
 Proposed Response Response Status O

Cl 201 SC 201.14 P 152 L 50 # 123  
 Turner, Max Ethernovia  
 Comment Type E Comment Status X  
 it is from D to S PHY, i.e. 2 PHYs  
 SuggestedRemedy  
 add a plural s to PHY  
 Proposed Response Response Status O

Cl 201 SC 201.10.1.5 P 146 L 48 # 229  
 Razavi, Alireza Infineon  
 Comment Type T Comment Status X  
 Screen attenuation lower-frequency limit is 30 MHz in Clause 149.  
 SuggestedRemedy  
 Use 30 MHz as the lower bound and update Figure 201–51 accordingly.  
 Proposed Response Response Status O

Cl 201 SC 201.14 P 153 L 17 # 121  
 Turner, Max Ethernovia  
 Comment Type E Comment Status X  
 the link to Annex 201A is wrong (A is missing) and the hyperlink does not work  
 SuggestedRemedy  
 change to Annex 201A and add hyperlink  
 Proposed Response Response Status O

Cl 201 SC 201.10.2.1. P 148 L 18 # 230  
 Razavi, Alireza Infineon  
 Comment Type E Comment Status X  
 Please add the word “loss” after PSANEXT on the vertical-axis label.  
 SuggestedRemedy  
 Proposed Response Response Status O

Cl 201A SC 201A P 149 L 26 # 125  
 Turner, Max Ethernovia  
 Comment Type T Comment Status X  
 For interleaving, this definition is useless, as the X(n) may completely change order on the MDI  
 SuggestedRemedy  
 The only useful reference point is the beginning of the first superframe of an interleaving block, but it seems we lack good naming for this.  
 Commenter to provide a presentation, as this text field will not suffice.  
 Proposed Response Response Status O

Cl 201 SC 201.14 P 152 L 45 # 122  
 Turner, Max Ethernovia  
 Comment Type E Comment Status X  
 it is from S to D PHY, i.e. 2 PHYs  
 SuggestedRemedy  
 add a plural s to PHY  
 Proposed Response Response Status O

IEEE P802.3dm D0.c Asymmetrical Electrical Automotive Ethernet 3rd Task Force review comments

CI 201A SC 201A P 149 L 29 # 126  
 Turner, Max Ethernetovia  
 Comment Type T Comment Status X  
 For interleaving, this definition is useless, as the X(n) may completely change order on the MDI  
 SuggestedRemedy  
 The only useful reference point is the beginning of the first superframe of an interleaving block, but it seems we lack good naming for this.  
 Commenter to provide a presentation, as this text field will not suffice.  
 Proposed Response Response Status O

CI 201A SC 201A P 249 L 21 # 124  
 Turner, Max Ethernetovia  
 Comment Type E Comment Status X  
<https://www.merriam-webster.com/dictionary/insure> - seems not the most fitting term  
 SuggestedRemedy  
 replace insure by ensure  
 Proposed Response Response Status O

CI 202 SC 202.1 P 157 L 8 # 150  
 Gorshe, Steve Microchip Technology  
 Comment Type E Comment Status X  
 Proposed editorial clean up in multiple places  
 SuggestedRemedy  
 See proposed editorial changes in attached file 8023d0pc-202-gorshe.docx  
 Proposed Response Response Status O

CI 202 SC 202.1.1 P 157 L 14 # 140  
 Maguire, Valerie Copperopolis; affl w/ CME Consulting, Microchip, and  
 Comment Type E Comment Status X  
 Content has been added to address all Editor's Notes in clause 202.  
 SuggestedRemedy  
 Delete all Editor's Notes in clause 202. Grant Editor's license to work with TDD champion to determine appropriate insertion text as needed for grammatical and technical correctness.  
 Proposed Response Response Status O

CI 202 SC 202.1.3 P 159 L 2 # 128  
 Maguire, Valerie Copperopolis; affl w/ CME Consulting, Microchip, and  
 Comment Type E Comment Status X  
 Ensure that all figures, tables, and equations have a text call-out.  
 SuggestedRemedy  
 Insert, " The MultiGBASE-A functional block diagram is shown in Figure 202-1."  
 Proposed Response Response Status O

CI 202 SC 202.1.3 P 159 L 6 # 167  
 Chini, Ahmad Broadcom  
 Comment Type E Comment Status X  
 The text use training mode while the diagram shows training\_phase.  
 SuggestedRemedy  
 Replace training Phase with training\_mode  
 Proposed Response Response Status O

IEEE P802.3dm D0.c Asymmetrical Electrical Automotive Ethernet 3rd Task Force review comments

CI 202 SC 202.1.3 P 159 L 18 # 173  
 Chini, Ahmad Broadcom  
 Comment Type E Comment Status X  
 Arrow going out from Link Monitor is going nowhere  
 SuggestedRemedy  
 Remove the arrow going out from Link Monitor Block  
 Proposed Response Response Status O

CI 202 SC 202.1.3.1 P 160 L 18 # 243  
 Wang, Frank Realtek Semiconductor Corp.  
 Comment Type T Comment Status X  
 According to [https://www.ieee802.org/3/dm/public/0126/muma\\_3dm\\_01\\_0126.pdf](https://www.ieee802.org/3/dm/public/0126/muma_3dm_01_0126.pdf), some numbers are not updated yet.  
 SuggestedRemedy  
 change "L × 1040 bits" to "L × 1024 bits"  
 Proposed Response Response Status O

CI 202 SC 202.1.3 P 159 L 19 # 242  
 Wang, Frank Realtek Semiconductor Corp.  
 Comment Type E Comment Status X  
 It could be an accident when the editor tried to solve comment #213 for D0pb (remove the connection between "LINK MONITOR" and "Technology Dependent Interface (optional)"). An arrow going out from "Link Monitor" is now going nowhere.  
 SuggestedRemedy  
 The output of "LINK MONITOR" should be connected to "PCS TRANSMIT", "PCS OAM", and "PCS RECEIVE".  
 Proposed Response Response Status O

CI 202 SC 202.1.4 P 161 L 39 # 18  
 Zimmerman, George CME Consulting/ADI,APL Gp, Cisco, Infineon, OnSe  
 Comment Type T Comment Status X  
 The text says LS\_PATH PCS generates continuous code-group sequences that the PMA transmits. Is this correct? I thought the TDD bursts were separated by the PCS, with the PMA not transmitting in between.  
 SuggestedRemedy  
 change "generating continuous code-group sequences" to "generating bursts of code-group sequences"  
 Proposed Response Response Status O

CI 202 SC 202.1.3 P 159 L 29 # 17  
 Zimmerman, George CME Consulting/ADI,APL Gp, Cisco, Infineon, OnSe  
 Comment Type T Comment Status X  
 detect\_lp\_burst is never used by the PCS. It's action is all within the PMA PHY Control, so it shouldn't be a primitive or presented at the PMA Service Interface.  
 SuggestedRemedy  
 Delete line from PMA RECEIVE to PCS\_RECEIVE in Figure 202-1, put arrowhead into PHY CONTROL for this signal.  
 Delete PMA\_DET\_LP\_BURST.indication primitive (202.2.1 P163 L37, and 202.2.1.10 and subclauses P169 L28 to L36)  
 Delete line going to the PMA SERVICE INTERFACE in Figure 202-22 (P206 L16)  
 Proposed Response Response Status O

CI 202 SC 202.1.4 P 162 L 3 # 19  
 Zimmerman, George CME Consulting/ADI,APL Gp, Cisco, Infineon, OnSe  
 Comment Type T Comment Status X  
 The text says that the PCS generates a continuous stream of PAM2 symbols that are transmitted via the PMA. This is in conflict with the definition of the primitive PMA\_UNITDATA.request at 202.1.3.1.1 which says that the value is PAM2 or PAM4, or zeroes (e.g. during training or QUIET period)  
 SuggestedRemedy  
 Change "continuous stream" to "bursts".  
 Proposed Response Response Status O

IEEE P802.3dm D0.c Asymmetrical Electrical Automotive Ethernet 3rd Task Force review comments

CI 202 SC 202.1.4 P 162 L 9 # 149  
 Gorshe, Steve Microchip Technology  
 Comment Type T Comment Status X  
 Proposed technical changes in multiple places for completeness and to address recent discussions  
 SuggestedRemedy  
 See proposed technical changes in attached file 8023d0pc-202-gorshe.docx  
 Proposed Response Response Status O

CI 202 SC 202.1.5 P 162 L 8 # 20  
 Zimmerman, George CME Consulting/ADI,APL Gp, Cisco, Infineon, OnSe  
 Comment Type T Comment Status X  
 The text says HS\_PATH PCS generates continuous code-group sequences that the PMA transmits. Is this correct? I thought the TDD bursts were separated by the PCS, with the PMA not transmitting in between.  
 SuggestedRemedy  
 change "generating continuous code-group sequences" to "generating bursts of code-group sequences"  
 Proposed Response Response Status O

CI 202 SC 202.1.5 P 162 L 26 # 21  
 Zimmerman, George CME Consulting/ADI,APL Gp, Cisco, Infineon, OnSe  
 Comment Type T Comment Status X  
 The text says that the PCS generates a continuous stream of PAM2 or PAM4 symbols that are transmitted via the PMA. This is in conflict with the definition of the primitive PMA\_UNITDATA.request at 202.1.3.1.1 which says that the value is PAM2 or PAM4, or zeroes (e.g. during training or QUIET period)  
 SuggestedRemedy  
 Change "continuous stream" to "bursts".  
 Proposed Response Response Status O

CI 202 SC 202.2.1.1.1 P 165 L 8 # 22  
 Zimmerman, George CME Consulting/ADI,APL Gp, Cisco, Infineon, OnSe  
 Comment Type T Comment Status X  
 SEND\_N is defined as representing the XGMII data stream. According to the PHY control state diagram, it represents the TDD bursting of the XGMII data stream, including Z (0, or QUIET) symbols. Other parts of the text (see other comments) suggest that SEND\_Z is sent during TDD quiet periods.  
 SuggestedRemedy  
 Change "representing an XGMII data stream in the data mode." to "representing the TDD bursting (including QUIET periods) of an XGMII data stream in the data mode."  
 Proposed Response Response Status O

CI 202 SC 202.2.1.1.1 P 165 L 18 # 244  
 Wang, Frank Realtek Semiconductor Corp.  
 Comment Type T Comment Status X  
 To align with clause 201, using the definition of "Z".  
 SuggestedRemedy  
 change "This value is continuously asserted in case transmission of zero symbols is required." to "This value is continuously asserted in case transmission of Z symbols is required. See 202.5.2.4 for the encoding of "Z"."  
 Proposed Response Response Status O

CI 202 SC 202.2.1.3.1 P 166 L 22 # 23  
 Zimmerman, George CME Consulting/ADI,APL Gp, Cisco, Infineon, OnSe  
 Comment Type E Comment Status X  
 Suggest that nomenclature for sending quiet symbols to the transmitter be aligned with clause 201, using "Z" instead of "0" (SILENCE comment)  
 SuggestedRemedy  
 Change 0 to "Z" and change to "When Z symbols are to be transmitted..." Add appropriate definition of Z symbols at the MDI to the PMA clause.  
 Proposed Response Response Status O

IEEE P802.3dm D0.c Asymmetrical Electrical Automotive Ethernet 3rd Task Force review comments

CI 202 SC 202.2.1.3.1 P 166 L 22 # 245

Wang, Frank Realtek Semiconductor Corp.

Comment Type T Comment Status X

To align with clause 201, using the definition of "Z".

SuggestedRemedy

change lines 22~25 as follows:

Z when Z symbols are to be transmitted in the following two cases:

- 1) when PMA\_TXMODE.indication is SEND\_Z during PMA training, and
- 2) during the QUIET period in each TDD cycle.

See 202.5.2.4 for the encoding of Z symbols.

Proposed Response Response Status O

CI 202 SC 202.2.1.3.1 P 166 L 25 # 24

Zimmerman, George CME Consulting/ADI,APL Gp, Cisco, Infineon, OnSe

Comment Type T Comment Status X

The "QUIET" period, while it may show up as TA\_Quiet in Figure 202-17, is never actually defined in the state diagrams or text. Is there something missing?

SuggestedRemedy

Define state diagram for TDD burst generation and timing.

Proposed Response Response Status O

CI 202 SC 202.2.1.4.1 P 166 L 46 # 25

Zimmerman, George CME Consulting/ADI,APL Gp, Cisco, Infineon, OnSe

Comment Type T Comment Status X

There are no values given for rx\_symb.

SuggestedRemedy

Insert "The rx\_symb may take on the same values defined for tx\_symb in 202.2.1.3.1." as new last sentence of last paragraph of 202.2.1.4.1 (P166 L46)

Proposed Response Response Status O

CI 202 SC 202.2.1.8.2 P 169 L 3 # 26

Zimmerman, George CME Consulting/ADI,APL Gp, Cisco, Infineon, OnSe

Comment Type E Comment Status X

typo

SuggestedRemedy

change "requent" to "request"

Proposed Response Response Status O

CI 202 SC 202.2.1.10 P 169 L 32 # 147

Maguire, Valerie Copperopolis; affl w/ CME Consulting, Microchip, and

Comment Type E Comment Status X

Content has been added to address all TBDs in clause 202.

SuggestedRemedy

Delete all occurrences of "TBD" clause 202. Grant Editor's license to work with TDD champion to determine appropriate insertion text as needed for grammatical and technical correctness.

Proposed Response Response Status O

CI 202 SC 202.2.1.10 P 169 L 35 # 27

Zimmerman, George CME Consulting/ADI,APL Gp, Cisco, Infineon, OnSe

Comment Type T Comment Status X

The parameter detect\_lp\_burst is shown going from PMA Receive to PHY Control and PCS in the diagrams, but does not appear anywhere in the PCS text. It only shows up being used one place in the PHY control state diagram, and its generation is not specified in the PMA Receive text or state diagram.

SuggestedRemedy

delete "PCS Receive function" (at line 36 and line 46) and remove conneciton of this parameter to the PCS Receive function in Figures 202-1 and 202-3. (or add use of this to the PCS...),

Add definition of how detect\_lp\_burst is set to the PMA\_Receive section.

Proposed Response Response Status O

IEEE P802.3dm D0.c Asymmetrical Electrical Automotive Ethernet 3rd Task Force review comments

CI 202 SC 202.3.2 P 170 L 15 # 28  
 Zimmerman, George CME Consulting/ADI,APL Gp, Cisco, Infineon, OnSe  
 Comment Type E Comment Status X  
 If I understand TDD operation correctly, the PCS transmit and receive functions, like the PMA transmit and receive are NOT simultaneous.  
 SuggestedRemedy  
 Delete "simulataneous and"  
 Proposed Response Response Status O

CI 202 SC 202.3.2.1 P 171 L 14 # 29  
 Zimmerman, George CME Consulting/ADI,APL Gp, Cisco, Infineon, OnSe  
 Comment Type E Comment Status X  
 the MultiGBASE-T1 PCS reset bit is 3.2322.15 - no need for the TBD  
 SuggestedRemedy  
 Delete (TBD)  
 Proposed Response Response Status O

CI 202 SC 202.3.2.2 P 171 L 33 # 30  
 Zimmerman, George CME Consulting/ADI,APL Gp, Cisco, Infineon, OnSe  
 Comment Type T Comment Status X  
 Figure 202-4 is not the PCS transmit function block diagram - it is only a subset. Where are the interfaces (XGMII)? Where is the RS-FEC encoder? Where do Dn[0]and Dn[1] come from (they are combined and used in the scrambler as shown here, but where do they come from? - they are probably the c\_i out of the RS-FEC encoder, but this is neither said nor shown.)  
 More importantly, the diagram shows "TDD control" muxing the data bits from teh scrambler and the silent (0, or "Z") symbols. This, as the most important functional feature needs explanation including an obvious change in bit rate through this diagram.  
 SuggestedRemedy  
 Redraw Figure 202-4 showing service interfaces to the PCS, XGMII and PMA service interface and all blocks in the data path. Moreover, show buffering or speed shifts for the PCS rate, which must be necessary for the TDD control to function. I am willing to help, but the specification is not sufficiently complete for me to offer a correct alternative at this time.  
 Proposed Response Response Status O

CI 202 SC 202.3.2.2 P 171 L 43 # 31  
 Zimmerman, George CME Consulting/ADI,APL Gp, Cisco, Infineon, OnSe  
 Comment Type T Comment Status X  
 What does the dashed line around 'selectable precoder' block in Figures 202-4 and 202-6 mean? There is an editor's note saying to check figures. I think this should be removed, since it has been removed from the text.  
 SuggestedRemedy  
 Delete selectable precoder block and dashed line around it in figure 202-4 and figure 202-6.  
 Proposed Response Response Status O

CI 202 SC 202.3.2.2 P 171 L 43 # 246  
 Wang, Frank Realtek Semiconductor Corp.  
 Comment Type E Comment Status X  
 There is no selectable precoder in clause 202 now.  
 SuggestedRemedy  
 For Figure 202-4, remove the "selectable precoder" block and connect the output of "Gray mapping" block to the input of "PAM4 mapper" block.  
 The same modification should be applied to Figure 202-6, too.  
 Proposed Response Response Status O

CI 202 SC 202.3.2.2 P 171 L 48 # 247  
 Wang, Frank Realtek Semiconductor Corp.  
 Comment Type T Comment Status X  
 To align with clause 201, using the definition of "Z".  
 SuggestedRemedy  
 For Figure 202-4, change '0' to 'Z'  
 Proposed Response Response Status O

IEEE P802.3dm D0.c Asymmetrical Electrical Automotive Ethernet 3rd Task Force review comments

CI 202 SC 202.3.2.2 P 171 L 51 # 32  
 Zimmerman, George CME Consulting/ADI,APL Gp, Cisco, Infineon, OnSe  
 Comment Type T Comment Status X  
 "0" is a bit, "Z" is silent. See prior comment on 202.2.1.3.1 (marked "SILENCE comment")  
 SuggestedRemedy  
 Change "0" to "Z" if prior comment on 202.2.1.3.1 is accepted for nomenclature of silent.  
 This also occurs at P172 L32. (202.3.2.2 description of SEND\_Z)  
 Proposed Response Response Status O

CI 202 SC 202.3.2.2 P 172 L 17 # 248  
 Wang, Frank Realtek Semiconductor Corp.  
 Comment Type T Comment Status X  
 According to [https://www.ieee802.org/3/dm/public/0126/muma\\_3dm\\_01\\_0126.pdf](https://www.ieee802.org/3/dm/public/0126/muma_3dm_01_0126.pdf), some numbers are not updated yet.  
 SuggestedRemedy  
 change "L x 64 parity bits" to "L x 48 parity bits"  
 Proposed Response Response Status O

CI 202 SC 202.3.2.2 P 172 L 7 # 33  
 Zimmerman, George CME Consulting/ADI,APL Gp, Cisco, Infineon, OnSe  
 Comment Type T Comment Status X  
 The way I understand it, the PCS controls the PMA sublayers alternation between transmit and receive, This paragraph suggests that the PMA and PCS are fully independent, with the PCS just passing data continuously to the PMA. That obscures the TDD functionality which is in the PCS.  
 SuggestedRemedy  
 Insert, new final sentence (after "format."): " The PCS passes and receives bursts of data over the PMA service interface, interspersed with quiet periods (Z symbols) to effect an alternation between PMA transmit and PMA receive in a TDD cycle."  
 Proposed Response Response Status O

CI 202 SC 202.3.2.2 P 172 L 19 # 35  
 Zimmerman, George CME Consulting/ADI,APL Gp, Cisco, Infineon, OnSe  
 Comment Type E Comment Status X  
 The text here is repetitive for 2.5G/5G and 10G, which could be improved for clarity, since the number of bits scrambled (as a function of L) is identical in both cases.  
 SuggestedRemedy  
 Change P172 L18 through 22 ("L =1 for 2.5 Gb/s..." through "...PAM4 symbol.") to read: "For 2.5 Gb/s, L=1, for 5 Gb/s, L=2, and for 10 Gb/s, L=4. The resulting L x 1024 x 25 bits are then scrambled. For 2.5 Gb/s and 5 Gb/s, these bits are then mapped, one at a time into a PAM2 symbol. For 10 Gb/s, they are mapped two at a time into a PAM4 symbol.:  
 Proposed Response Response Status O

CI 202 SC 202.3.2.2 P 172 L 11 # 34  
 Zimmerman, George CME Consulting/ADI,APL Gp, Cisco, Infineon, OnSe  
 Comment Type E Comment Status X  
 "forms the input to the RS\_FEC(130,124) which adds..." missing word - "encoder" and RS\_FEC should be RS-FEC  
 SuggestedRemedy  
 change "RS\_FEC(130,124) which " to "RS-FEC(130,124) encoder which "  
 Proposed Response Response Status O

CI 202 SC 202.3.2.2 P 172 L 25 # 36  
 Zimmerman, George CME Consulting/ADI,APL Gp, Cisco, Infineon, OnSe  
 Comment Type T Comment Status X  
 The text here describes a continuous flow of PAM2 or PAM4 symbols from the PCS to the PMA. That is only true during the TDD burst.  
 SuggestedRemedy  
 Change the start of the sentence at L25 to read "In each symbol period of a TDD burst, when communicating..."  
 Add new 2nd sentence (after "request primitive.") : "Between TDD bursts, the PCS Transmit transfers Z symbols to the PMA via the PMA\_UNITDATA.request primitive."  
 Proposed Response Response Status O

IEEE P802.3dm D0.c Asymmetrical Electrical Automotive Ethernet 3rd Task Force review comments

Cl 202 SC 202.3.2.2 P 172 L 32 # 249  
 Wang, Frank Realtek Semiconductor Corp.  
 Comment Type T Comment Status X  
 To align with clause 201, using the definition of "Z".  
 SuggestedRemedy  
 change "pass a vector of zeros" to "pass a vector of Z symbols"  
 Proposed Response Response Status O

Cl 202 SC 202.3.2.2 P 172 L 32 # 37  
 Zimmerman, George CME Consulting/ADI,APL Gp, Cisco, Infineon, OnSe  
 Comment Type T Comment Status X  
 The modes SEND\_Z, SEND\_TA, and SEND\_TS are only used during training. (according to PHY control, SEND\_N is used in data mode). The text should say this, as it is giving introductory information of how the PCS transmit works.  
 SuggestedRemedy  
 Insert "During training, PMA\_TXMODE.indication has values SEND\_Z, SEND\_TS, and SEND\_TA, before transitioning to SEND\_N for data mode." after "PHY Control function."  
 Proposed Response Response Status O

Cl 202 SC 202.3.2.2.1 P 173 L 14 # 38  
 Zimmerman, George CME Consulting/ADI,APL Gp, Cisco, Infineon, OnSe  
 Comment Type T Comment Status X  
 the text says ENCODE and DECODE work according to the rules in 202.3.2.2.2, but there are no rules there (this was an error in earlier text, discovered in dg). Since the ENCODE and DECODE functions produce & interpret the 64B/65B blocks, the rules for blocks are indicated. These are in 202.3.2.2.4 (Block structure),  
 SuggestedRemedy  
 Change 202.3.2.2.2 to 202.3.2.2.4  
 Proposed Response Response Status O

Cl 202 SC 202.3.2.2.2 P 174 L 30 # 39  
 Zimmerman, George CME Consulting/ADI,APL Gp, Cisco, Infineon, OnSe  
 Comment Type T Comment Status X  
 After the PAM symbols are created on both Figure 202-5 and 202-6, the figure indicates that this is the PMA service interface. The figure needs to show the insertion of the quiet (Z) symbols prior to the PMA service interface to form a TDD burst.  
 SuggestedRemedy  
 Add step of inserting the quiet symbols (a mux with the RS-FEC frame and a "Z" on the other input) and then show as the last line the output of the mux as a TDD burst with the correct number of PAM symbols and quiet symbols. Do this for both Figures 202-5 and 202-6  
 Proposed Response Response Status O

Cl 202 SC 202.3.2.2.2 P 174 L 30 # 184  
 Muma, Scott Microchip  
 Comment Type T Comment Status X  
 The intent of this figure has expanded beyond bit ordering to also show the payload transmitted in a burst. It may help to also show the refresh header and quiet symbols transmitted to illustrate the complete TDD cycle.  
 SuggestedRemedy  
 See attached PDF P8023dm\_D0pc\_bit\_order\_figure\_markup.pdf Figure 202-5  
 Proposed Response Response Status O

Cl 202 SC 202.3.2.2.2 P 175 L 24 # 40  
 Zimmerman, George CME Consulting/ADI,APL Gp, Cisco, Infineon, OnSe  
 Comment Type T Comment Status X  
 Since the TDD is a multirate PHY, show a demux at the place where the 2.5/5 Gb/s path diverges from the 10 Gb/s path with the control being the speed selection.  
 SuggestedRemedy  
 See comment.  
 Proposed Response Response Status O

IEEE P802.3dm D0.c Asymmetrical Electrical Automotive Ethernet 3rd Task Force review comments

CI 202 SC 202.3.2.2.2 P 175 L 30 # 185  
 Muma, Scott Microchip  
 Comment Type T Comment Status X  
 The intent of this figure has expanded beyond bit ordering to also show the payload transmitted in a burst. It may help to also show the refresh header and quiet symbols transmitted to illustrate the complete TDD cycle.  
 SuggestedRemedy  
 See attached PDF P8023dm\_D0pc\_bit\_order\_figure\_markup.pdf Figure 202-6  
 Proposed Response Response Status O

CI 202 SC 202.3.2.2.6 P 178 L 46 # 41  
 Zimmerman, George CME Consulting/ADI,APL Gp, Cisco, Infineon, OnSe  
 Comment Type T Comment Status X  
 Remote fault is used by the link fault state diagram, Figure 46-11 in response to receiving a local fault. Do not delete....  
 SuggestedRemedy  
 Delete editor's note at 202.3.2.2.6  
 Proposed Response Response Status O

CI 202 SC 202.3.2.2.12 P 180 L 3 # 43  
 Zimmerman, George CME Consulting/ADI,APL Gp, Cisco, Infineon, OnSe  
 Comment Type T Comment Status X  
 There is no "transcoder". The blocks shown are simply the encoded 65B blocks concatenated. Where the text said transcoder it clearly means RS-FEC encoder.  
 SuggestedRemedy  
 Change "to the transcoder" to "to the RS-FEC encoder" in 202.3.2.2.12 (P180 L3).  
 Proposed Response Response Status O

CI 202 SC 202.3.2.2.12 P 180 L 3 # 42  
 Zimmerman, George CME Consulting/ADI,APL Gp, Cisco, Infineon, OnSe  
 Comment Type E Comment Status X  
 Tx\_coded is a variable name and should not be capitalized...  
 SuggestedRemedy  
 change "Tx\_coded<0> contains" to "The bit tx\_coded<0> contains"  
 Proposed Response Response Status O

CI 202 SC 202.3.2.2.13 P 180 L 7 # 44  
 Zimmerman, George CME Consulting/ADI,APL Gp, Cisco, Infineon, OnSe  
 Comment Type E Comment Status X  
 We jump directly from tx\_coded, a 64B/65B block to "The resulting RS-FEC frame..." - the definition of tx\_group and aggregation are a long ways away back in 202.1.3.1.  
 SuggestedRemedy  
 Insert new first sentence in 202.3.2.2.13: "Fifteen of 65B blocks (tx\_coded) are grouped together to form tx\_group15x65B as described in 202.1.3.1."  
 Replace the first sentence of the first paragraph of 202.3.2.2.13 with "For LS\_TX transmission, tx\_group15x65B, followed by the 17-bit OAM/Reserved field, and 48 parity bits are grouped to form an RS-FEC frame of 1040 bits."  
 Replace the first sentence of the second paragraph of 202.3.2.2.13 with "For HS\_TX transmission, tx\_group15x65B, followed by the 1-bit OAM/Reserved field, and 48 parity bits are grouped to form an RS-FEC frame of 1024 bits."  
 Proposed Response Response Status O

IEEE P802.3dm D0.c Asymmetrical Electrical Automotive Ethernet 3rd Task Force review comments

CI 202 SC 202.3.2.2.14 P 180 L 26 # 45  
 Zimmerman, George CME Consulting/ADI,APL Gp, Cisco, Infineon, OnSe  
 Comment Type E Comment Status X  
 The text says <x speed> "mode supports L = " - Are other values of L allowed? It seems that a requirement is needed here as to which value of L is used.  
**SuggestedRemedy**  
 Change "supports" to "shall use" for all four speeds (lines 26 to 32). Alternatively, replace lines 24 to 32 with: "The value of L used depends on the speed mode, and shall comply with Table 202-x." (and add table 202-x with 2 columns:  
 Speed mode | Interleave depth (L)  
 100 Mb/s | 1  
 2.5 Gb/s | 1  
 5 Gb/s | 2  
 10 Gb/s | 4  
 Proposed Response Response Status O

CI 202 SC 202.3.2.2.15 P 180 L 47 # 130  
 Maguire, Valerie Copperopolis; affl w/ CME Consulting, Microchip, and  
 Comment Type E Comment Status X  
 Shown be "an" before an "H".  
**SuggestedRemedy**  
 Replace, "...operates as a HS\_RX."  
 with "...operates as an HS\_RX."  
 Proposed Response Response Status O

CI 202 SC 202.3.2.2.16 P 181 L 27 # 46  
 Zimmerman, George CME Consulting/ADI,APL Gp, Cisco, Infineon, OnSe  
 Comment Type E Comment Status X  
 The text spells out the RS-FEC message symbols separately for the LS PATH and the HS PATH; however, it uses a variable "k" in each definition, and then defines the values of k. Using the value in the descriptions and nomenclature will improve clarity.  
**SuggestedRemedy**  
 Replace "k" on line 27 with 124, and replace (130-k) on line 27 with 6.  
 Replace "k" on line 30 with 122, and "(128-k) on line 31 with 6.  
 Replace "RS-FEC(n,k)" at line 33 through the end of the paragraph ("HS\_PATH" at line 34) with:  
 "RS-FEC(130,124) for the LS\_PATH and RS-FEC(128, 122) for the HS\_PATH."  
 Proposed Response Response Status O

CI 202 SC 202.3.2.2.16 P 181 L 28 # 47  
 Zimmerman, George CME Consulting/ADI,APL Gp, Cisco, Infineon, OnSe  
 Comment Type E Comment Status X  
 RS FEC message should be RS-FEC message  
**SuggestedRemedy**  
 See comment  
 Proposed Response Response Status O

CI 202 SC 202.3.2.2.17 P 183 L 42 # 48  
 Zimmerman, George CME Consulting/ADI,APL Gp, Cisco, Infineon, OnSe  
 Comment Type T Comment Status X  
 All of a sudden the text jumps to description of a refresh header. It needs some introduction first if it goes here (and the whole TDD frame structure probably needs to go up front before the scrambler) but perhaps the section can be rewritten without refresh frame.  
**SuggestedRemedy**  
 Change "PAM2 encoding is used for the refresh header (see 202.3.5) at all symbol rates. Consequently, the scrambled header data stream, Cn, is shown in Equation (202-4)." to "Different scramblers are used for the refresh header and for the data stream.  
 The scrambled PAM2 header data stream, Cn shall be as in Equation (202-4). "  
 Proposed Response Response Status O

IEEE P802.3dm D0.c Asymmetrical Electrical Automotive Ethernet 3rd Task Force review comments

CI 202 SC 202.3.2.2.17 P 184 L 14 # 49  
 Zimmerman, George CME Consulting/ADI,APL Gp, Cisco, Infineon, OnSe  
 Comment Type E Comment Status X  
 The paragraph beginning at line 15 should be part of the previous paragraph, since it also only applies to 10 Gb/s transmission.  
 SuggestedRemedy  
 see comment.  
 Proposed Response Response Status O

CI 202 SC 202.3.2.3 P 185 L 40 # 52  
 Zimmerman, George CME Consulting/ADI,APL Gp, Cisco, Infineon, OnSe  
 Comment Type E Comment Status X  
 "descrambling is performed according to rules." - what does this mean? Having unreferenced or undefined rules is meaningless. This appears to be specified in the clause, so deleting the phrase is fine.  
 SuggestedRemedy  
 delete "according to rules."  
 Proposed Response Response Status O

CI 202 SC 202.3.2.2.19 P 185 L 1 # 50  
 Zimmerman, George CME Consulting/ADI,APL Gp, Cisco, Infineon, OnSe  
 Comment Type E Comment Status X  
 Now that there is no precoder, you might as well do the gray-coding and encoding as one step. 202.3.2.2.19 is unnecessary.  
 Also, the output that goes to the TDD control is called Tn according to Figure 202-4. This makes Gn, and Mn both unnecessary notation.  
 SuggestedRemedy  
 Delete 202.3.2.2.19 (P185 L1 through 22)  
 Change references to G(n) on P184 L31 and L39 to T(n).  
 Change 0, 1, 2, 3 on P184 L32-37 and L41-45 to -1, -1/3, +1/3, and +1 respectively.  
 In Figure 202-4, Change "Gray mapping" to "Gray mapping PAM4 encoder", delete PAM4 mapper, and delete label of Gn.  
 Proposed Response Response Status O

CI 202 SC 202.3.2.3 P 185 L 46 # 53  
 Zimmerman, George CME Consulting/ADI,APL Gp, Cisco, Infineon, OnSe  
 Comment Type T Comment Status X  
 "In each burst,"... no burst structure has been defined yet. It appears this is referring to the number of bits in a L-interleaved superframe (which may be the same as a burst, but at that's actually something that has been defined already).  
 SuggestedRemedy  
 Delete "In each burst, " Or have a discussion of the burst structure with regards to bits, superframe length, and OAM bits before this...  
 Proposed Response Response Status O

CI 202 SC 202.3.2.3 P 185 L 35 # 51  
 Zimmerman, George CME Consulting/ADI,APL Gp, Cisco, Infineon, OnSe  
 Comment Type T Comment Status X  
 What does "including compliance with the associated state variable as specified in 202.3.7.2.2" mean? You can't comply with a variable... Conforming with the state diagram (Figure 202-21) is enough.  
 SuggestedRemedy  
 Delete "including compliance with the associated state variable as specified in 202.3.7.2.2."  
 Proposed Response Response Status O

CI 202 SC 202.3.2.3 P 185 L 49 # 54  
 Zimmerman, George CME Consulting/ADI,APL Gp, Cisco, Infineon, OnSe  
 Comment Type E Comment Status X  
 "This process" has no precedent. I assume it is referring to the PCS Receive function, not a process...  
 SuggestedRemedy  
 Replace "This process" with "The PCS Receive function"  
 Proposed Response Response Status O

IEEE P802.3dm D0.c Asymmetrical Electrical Automotive Ethernet 3rd Task Force review comments

CI 202 SC 202.3.2.3 P 185 L 53 # 55

Zimmerman, George CME Consulting/ADI,APL Gp, Cisco, Infineon, OnSe

Comment Type T Comment Status X

The text describes adapting between PMA and XGMII rates, but they are NEVER synchronized, and, as I understand it, the PCS doesn't just adjust by inserting/deleting idles & sequence ordered sets, but also deletes the inter-burst gaps, nowhere does it describe recombining bursts. This seems an appropriate place.

SuggestedRemedy

Change at P184 L51 "Where the XGMII and PMA sublayer data rates are not synchronized, the receive process inserts idles..." to "Because the received data stream is divided into TDD bursts, with silence interspersed, the PCS receive function recombines separated bursts before passing to the XGMII. Where the XGMII and the PMA sublayer transmit clocks are not frequency synchronized, the PCS receive process also inserts idles..."

Proposed Response Response Status O

CI 202 SC 202.3.2.3 P 186 L 7 # 250

Wang, Frank Realtek Semiconductor Corp.

Comment Type E Comment Status X

wording

SuggestedRemedy

remove "(TBD)"

Proposed Response Response Status O

CI 202 SC 202.3.2.3 P 186 L 14 # 56

Zimmerman, George CME Consulting/ADI,APL Gp, Cisco, Infineon, OnSe

Comment Type E Comment Status X

The paragraph break between the monitoring of loc\_rcvr\_status and what loc\_rcvr\_status does isn't necessary and reduces clarity

SuggestedRemedy

Delete paragraph break at P186 L14

Proposed Response Response Status O

CI 202 SC 202.3.2.3 P 187 L 1 # 57

Zimmerman, George CME Consulting/ADI,APL Gp, Cisco, Infineon, OnSe

Comment Type E Comment Status X

In Figure 202-10 and 202-11 show where the TDD bursts are delineated, refresh headers are stripped and bursts are combined. These are necessary for completeness.

SuggestedRemedy

See comment

Proposed Response Response Status O

CI 202 SC 202.3.2.3.1 P 189 L 3 # 58

Zimmerman, George CME Consulting/ADI,APL Gp, Cisco, Infineon, OnSe

Comment Type T Comment Status X

The RECEIVE PCS doesn't form PAM2 streams. See prior comment where the values of rx\_symb, passed by PMA\_UNITDATA.indication are not defined. Generally, the PMA would receive PAM2 and pass the values to the PCS, and generally these would be the same format as the PMA\_UNITDATA.request (tx\_symb)... It seems the purpose of this paragraph is to say that requests are concatenated. It also doesn't concatenate requests - it concatenates the rx\_symb values conveyed by the indications. Finally, the Figure referenced for 10Gb/s is incorrect (Fig 202-10 is the LS\_RX figure...)

SuggestedRemedy

Replace first paragraph of 202.3.2.3.1 with:

"When operating in 100 Mb/s, 2.5 Gb/s, or 5 Gb/s data mode, the receiving PCS shall concatenate rx\_symb values conveyed by the PMA\_UNITDATA.indication in order from rx\_PAM2\_0 to rx\_PAM2\_1023 (see Figure 202-10 for LS\_RX or Figure 202-11 for HS\_RX). When operating in 10 Gb/s data mode, the receiving PCS shall concatenate rx\_symb values conveyed by the PMA\_UNITDATA.indication in order from rx\_PAM4\_0 to rx\_PAM4\_511 (see Figure 202-11)."

Proposed Response Response Status O

IEEE P802.3dm D0.c Asymmetrical Electrical Automotive Ethernet 3rd Task Force review comments

CI 202 SC 202.3.2.3.2 P 189 L 17 # 59  
 Zimmerman, George CME Consulting/ADI,APL Gp, Cisco, Infineon, OnSe  
 Comment Type T Comment Status X  
 Equation (202-6) and Equation (202-5) are not the scrambler polynomials. They are also not active cross references.  
 SuggestedRemedy  
 Make "Equation (202-6)" an active cross-reference to Equation (202-10) and "Equation (202-5)" an active cross-reference to Equation (202-9)  
 Proposed Response Response Status O

CI 202 SC 202.3.3 P 189 L 39 # 60  
 Zimmerman, George CME Consulting/ADI,APL Gp, Cisco, Infineon, OnSe  
 Comment Type T Comment Status X  
 Figures 202-5 and 202-6 are the bit ordering, they don't show TDD bursts...Not clear whether there is a missing figure, but I can't find one showing TDD bursts that might be meant to be indicated. Perhaps the word "TDD bursts" is incorrect.  
 The same issue exists in teh receiver description on line 43  
 SuggestedRemedy  
 delete "TDD bursts" (in 2 locations) or add new figures showing what is meant.  
 Proposed Response Response Status O

CI 202 SC 202.3.3 P 189 L 45 # 61  
 Zimmerman, George CME Consulting/ADI,APL Gp, Cisco, Infineon, OnSe  
 Comment Type T Comment Status X  
 I don't think the output of the RS-FEC decoder should also be zero, because it representes SCRAMBLED zeros. It can't be zero and have the received descrambled values be zero unless the descrambler is off.  
 SuggestedRemedy  
 Change "The output of the RS-FEC decoder should also be zero." to "The output of the RS-FEC decoder should represent scrambled zeros."  
 Proposed Response Response Status O

CI 202 SC 202.3.3 P 189 L 46 # 62  
 Zimmerman, George CME Consulting/ADI,APL Gp, Cisco, Infineon, OnSe  
 Comment Type E Comment Status X  
 The sentence that "However, there is a possibility that the RS-FEC decoder corrected some errors." isn't relevant. It is unclear what this is supposed to mean.  
 SuggestedRemedy  
 Delete "However, there is a possibility that the RS-FEC decoder corrected some errors."  
 Proposed Response Response Status O

CI 202 SC 202.3.3 P 189 L 47 # 63  
 Zimmerman, George CME Consulting/ADI,APL Gp, Cisco, Infineon, OnSe  
 Comment Type E Comment Status X  
 The test mode is in fact Test Mode 7, the TBD is unnecessary.  
 SuggestedRemedy  
 Delete (TBD) at P189 L46  
 Proposed Response Response Status O

CI 202 SC 202.3.3 P 189 L 47 # 251  
 Wang, Frank Realtek Semiconductor Corp.  
 Comment Type E Comment Status X  
 wording  
 SuggestedRemedy  
 remove "(TBD)"  
 Proposed Response Response Status O

IEEE P802.3dm D0.c Asymmetrical Electrical Automotive Ethernet 3rd Task Force review comments

CI 202 SC 202.3.4 P 189 L 50 # 65  
 Zimmerman, George CME Consulting/ADI,APL Gp, Cisco, Infineon, OnSe  
 Comment Type E Comment Status X  
 The scrambler polynomials should be defined with the scrambler, in 202.3.2.2.17. That section already defines when 202.3.4.1 is used and when 202.3.4.2 is used. These sections should be moved up to right after 202.3.2.2.17.  
 SuggestedRemedy  
 Delete 202.3.4  
 Move 202.3.4.1 and 202.3.4.2 after 202.3.2.2.17  
 Proposed Response Response Status O

CI 202 SC 202.3.4 P 189 L 50 # 64  
 Zimmerman, George CME Consulting/ADI,APL Gp, Cisco, Infineon, OnSe  
 Comment Type E Comment Status X  
 The TDD bursts have not been described, and are unnecessary in the description.  
 SuggestedRemedy  
 Replace the first sentence with "Different scrambler polynomials are used for the refresh header and the burst payload."  
 Proposed Response Response Status O

CI 202 SC 202.3.4 P 189 L 51 # 66  
 Zimmerman, George CME Consulting/ADI,APL Gp, Cisco, Infineon, OnSe  
 Comment Type T Comment Status X  
 The term "refresh\_hdr" looks like a variable. It is not. It is otherwise called the "refresh header". This is the first instance, but it appears in a number of places.  
 SuggestedRemedy  
 Replace "refresh\_hdr" with "refresh header" globally. (P189 L51 & 53, Figure 202-14, P191 L28, P192 L3, P193 L14 (Eq 202-13), P193 L29 (twice), P193 L30, Figure 202-16 (P195 L46), Figure 202-17 (P196 L14 & 25), Figure 202-18 (P197 L14 & 21) )  
 AND delete "(refresh\_hdr)" at P191 L24.  
 Proposed Response Response Status O

CI 202 SC 202.3.4.1 P 190 L 3 # 67  
 Zimmerman, George CME Consulting/ADI,APL Gp, Cisco, Infineon, OnSe  
 Comment Type T Comment Status X  
 Duplicate shall. The requirement for the refresh header scrambling is already stated in 202.3.2.2.17  
 SuggestedRemedy  
 change "shall be scrambled" to "is scrambled".  
 Proposed Response Response Status O

CI 202 SC 202.3.5 P 191 L 19 # 68  
 Zimmerman, George CME Consulting/ADI,APL Gp, Cisco, Infineon, OnSe  
 Comment Type E Comment Status X  
 It seems that 202.3.5 defines the PMA TDD framing structure for both training and data mode, because it defines the SEND\_N structure too. (TDD\_BURST comment)  
 SuggestedRemedy  
 Change title of 202.3.5 to TDD Burst Structure  
 Replace first paragraph in 202.3.5 to read: "The PCS generates signals to be transmitted by the PMA in the form of TDD bursts. TDD burst structure depends on the value of tx\_mode and the data rate of transmission. Each TDD burst is comprised of two parts, a refresh header and a payload section. During training, in addition to indicating silence with SEND\_Z, the PCS transmits TDD bursts in two different formats for tx\_modes SEND\_TS and SEND\_TA, before finally switching to SEND\_N. SEND\_TS uses a symmetric frame format and shall be transmitted at a 3 GBd rate, regardless of the speed selected. SEND\_TA and SEND\_N use an asymmetric frame format, and transmit at either 3 GBd or 6 GBd depending on the transmitter speed selected. Quiet times between transmissions are introduced between TDD bursts by the PCS, when the PCS inserts Z symbols between TDD bursts. The duration of quiet time length depends on the state of tx\_mode."  
 Proposed Response Response Status O

IEEE P802.3dm D0.c Asymmetrical Electrical Automotive Ethernet 3rd Task Force review comments

CI 202 SC 202.3.5 P 191 L 20 # 174  
 Chini, Ahmad Broadcom  
 Comment Type T Comment Status X  
 Nr and Np is specified for normal modes as well as training mode in 202.3.5.1, however the normal mode frame is not descibed  
 SuggestedRemedy  
 1- Change the title of 202.3.5 to PMA training and Normal frame  
 2- Add a new plot similar to Figure 202-14 but without info field and rename it to Normal mode frame.  
 3- Rewrite to include normal mode, see Chini-3dm\_01b\_0326.pdf  
 Proposed Response Response Status O

CI 202 SC 202.3.5 P 191 L 21 # 186  
 Muma, Scott Microchip  
 Comment Type T Comment Status X  
 This subclause begins with several sections describing training burst/operation, but then also goes into describing data bursts. Much of what is happening is actually leveraging or directly using PCS functions, as shown in Figure 202-4. So some parts of this description need to be moved to the PCS description and more clearly explain the SEND\_N data burst generation.  
 SuggestedRemedy  
 See attached 8023d0pc-202\_202.3.5\_sendz\_changes.doc  
 Proposed Response Response Status O

CI 202 SC 202.3.5 P 191 L 23 # 131  
 Maguire, Valerie Copperopolis; aff'l w/ CME Consulting, Microchip, and  
 Comment Type E Comment Status X  
 Ensure that all figures, tables, and equations have a text call-out.  
 SuggestedRemedy  
 Replace, "...by a training payload."  
 with "...by a training payload as shown in Figure 202-14."  
 Proposed Response Response Status O

CI 202 SC 202.3.5 P 191 L 25 # 69  
 Zimmerman, George CME Consulting/ADI,APL Gp, Cisco, Infineon, OnSe  
 Comment Type E Comment Status X  
 Missing articles.  
 SuggestedRemedy  
 Change "Refresh header" to "The refresh header".  
 Change "Training payload" to "The training payload"  
 Proposed Response Response Status O

CI 202 SC 202.3.5 P 191 L 43 # 70  
 Zimmerman, George CME Consulting/ADI,APL Gp, Cisco, Infineon, OnSe  
 Comment Type E Comment Status X  
 It seems that Figure 202-14 is repeated as part of Figure 202-16. Additionally, with a little augmentation, Figure 202-14 could define all the right parameters of the training frame.  
 SuggestedRemedy  
 Consider deletingthe expansion in figure 202-16, and augmenting Figure 202-14 to show the location (Ninf symbol) of the InfoField. Spell out InfoField.  
 Proposed Response Response Status O

CI 202 SC 202.3.5.1 P 192 L 1 # 176  
 Chini, Ahmad Broadcom  
 Comment Type T Comment Status X  
 The title does not include Normal mode  
 SuggestedRemedy  
 Rewrite title of the cluse as follows  
 Refresh header, training and normal payload length  
 Proposed Response Response Status O

IEEE P802.3dm D0.c Asymmetrical Electrical Automotive Ethernet 3rd Task Force review comments

---

CI 202 SC 202.3.5.1 P 192 L 3 # 175  
Chini, Ahmad Broadcom  
Comment Type T Comment Status X  
Tables have normal mode numbers but text does not refer to training  
SuggestedRemedy  
Rewrite as follows  
  
The lengths for refresh\_hdr along with training and Normal mode payload are described in Table 202-5, Table 202-6, and Table 202-7.  
Proposed Response Response Status O

---

CI 202 SC 202.3.5.1 P 192 L 7 # 252  
Wang, Frank Realtek Semiconductor Corp.  
Comment Type T Comment Status X  
According to [https://www.ieee802.org/3/dm/public/0126/muma\\_3dm\\_01\\_0126.pdf](https://www.ieee802.org/3/dm/public/0126/muma_3dm_01_0126.pdf), the values of Training\_payload N\_p(symb) for SEND\_TA and SEND\_N in Tables 202-5, 202-6, and 202-7 need to be updated.  
SuggestedRemedy  
For Table 202-5, change the two "1024" to "1040".  
For Table 202-6, change the two "26 000" to "25 600".  
For Table 202-7, change the two "52 000" to "51 200".  
Proposed Response Response Status O

---

CI 202 SC 202.3.5.1 P 192 L 6 # 71  
Zimmerman, George CME Consulting/ADI,APL Gp, Cisco, Infineon, OnSe  
Comment Type E Comment Status X  
Adding the number of quiet symbols to the tables would be very useful. Reconciling this to the times, exposed errors in the documentation of timing.  
SuggestedRemedy  
Add "Quiet symbols" column to Tables 202-5, 202-6 and 202-7. and change titles to "N\_r, N\_p, and N\_q values for..."  
I believe that for 100 Mb/s N\_q is 960 for SEND\_TS and 27136 for SEND\_TA & SEND\_N;  
for 2.5 Gb/s it is 960 for SEND\_TS, 528 for SEND\_TA & SEND\_N;  
for 5Gbs & 10 Gb/s it is 960 for SEND\_TS and 1056 for SEND\_TA & SEND\_N  
Add Note below Table 202-7: NOTE - SEND\_TS is sent at 3 GBd whereas SEND\_TA and SEND\_N are at 6 GBd. N\_r, N\_p, and N\_q are at the baud indicated for the appropriate tx\_mode.  
Proposed Response Response Status O

IEEE P802.3dm D0.c Asymmetrical Electrical Automotive Ethernet 3rd Task Force review comments

CI 202 SC 202.3.5.2 P 193 L 1 # 72

Zimmerman, George CME Consulting/ADI,APL Gp, Cisco, Infineon, OnSe

Comment Type E Comment Status X

The nomenclature here is unnecessarily complex. The variables aren't introduced before the tables, the names "refresh\_header" and "training\_payload" are only used in the tables. N\_b isn't necessary - it is just N\_p. N\_b is only used in this subclause. Trn is also unnecessary, as it is the same as S\_tn. The values of N\_r and N\_p are key to the frame structure and need to be clear. N\_p isn't just the training payload length, it appears to be the length of the payload field regardless of whether it is in training - since the tables define it for SEND\_N, which is also the format in data mode...

It also defines the parameters of the training frame without any requirement.

SuggestedRemedy

Change the first sentence of 202.3.5.1 (P192 L1) to "The lengths for the refresh header, N\_r, and the payload field are described in Table 202-5, Table 202-6, and Table 202-7.

Replace the 1st paragraph of 202.3.5.2 wit:

"For TDD bursts, the refresh header shall be composed of eight bytes of zeros, followed by four bytes of 0xF0. The refresh header is scrambled by the PRBS11 scrambler in 202.3.4.1. The PRBS11 scrambler stops at the last bit of the refresh header and resumes at the first bit of the next refresh header.

The TDD burst is completed by N\_p payload symbols following the refresh header. The payload symbols are scrambled by the PRBS33 scrambler defined in 202.3.4.2. Except when txmode is SEND\_N transmitting at 10 Gb/s, the payload symbols are PAM2, defined by Equation 202-5. When transmitting at 10 Gb/s and tx\_mode is SEND\_N, the payload symbols are the output of the Gray-mapped PAM-4 encoder, specified in 202.2.2.18." (note to editor, this assumes a previous comment was accepted combining 202.2.2.18 & 19, if it is not then this should be 202.3.2.2.19)

<new paragraph>

"The contents of the training frame are specified in equation 202-12 and equation 202-13." Delete Equation 202-11, and 202-14, and replace N\_b with N\_p in Equations 202-12 and 202,13.

Delete the last sentence in 202.3.5.2 (Trn[0] is the same...) at Lines 24 & 25.

Consider combining sections 202.3.5.1 and 202.3.5.2

Delete 202.3.5.2.1 as it is now unnecessary.

Replace Trn[0] with S\_tn at Figure 202-4 (P171 L33), in Equation 202-5, and in 202.3.5.3 at P193 L36. (these are the only other occurrences of it - note, the 202.3.5.3 might be deleted by another comment)

Add: "NOTE - See 202.3.5.1 for definition of S\_tn ." after Equation 202-5 (P184 L6)

Proposed Response Response Status O

CI 202 SC 202.3.5.2 P 193 L 3 # 138

Maguire, Valerie Copperopolis; affl w/ CME Consulting, Microchip, and

Comment Type E Comment Status X

Ensure that all figures, tables, and equations have a text call-out.

SuggestedRemedy

Replace "...in the training payload."

with "...in the training payload as shown in Equation (202-11)."

Proposed Response Response Status O

CI 202 SC 202.3.5.2 P 193 L 4 # 253

Wang, Frank Realtek Semiconductor Corp.

Comment Type E Comment Status X

wording: minus sign

SuggestedRemedy

change "N\_r - 1" to "N\_r - 1"

Proposed Response Response Status O

CI 202 SC 202.3.5.2 P 193 L 4 # 139

Maguire, Valerie Copperopolis; affl w/ CME Consulting, Microchip, and

Comment Type E Comment Status X

Ensure that all figures, tables, and equations have a text call-out.

SuggestedRemedy

Replace "...in the training payload."

with "...in the training payload as shown in Equation (202-12)."

Proposed Response Response Status O

IEEE P802.3dm D0.c Asymmetrical Electrical Automotive Ethernet 3rd Task Force review comments

CI 202 SC 202.3.5.2.1 P 193 L 31 # 73  
 Zimmerman, George CME Consulting/ADI,APL Gp, Cisco, Infineon, OnSe  
 Comment Type E Comment Status X  
 "defined in (see 202.3.4.1)." should be "defined in 202.3.4.1."  
 SuggestedRemedy  
 see comment.  
 Proposed Response Response Status O

CI 202 SC 202.3.5.3 P 193 L 33 # 74  
 Zimmerman, George CME Consulting/ADI,APL Gp, Cisco, Infineon, OnSe  
 Comment Type E Comment Status X  
 202.3.5.3 is unnecessary in its entirety (P193 L33 through P194 L14), as these requirements are all elsewhere - either in the PCS scrambler (202.3.4.1) or in 202.3.5.2, and in the mapper sections.  
 SuggestedRemedy  
 Delete 202.3.5.3 in its entirety, including the editor's note.  
 Proposed Response Response Status O

CI 202 SC 202.3.5.3 P 193 L 49 # 141  
 Maguire, Valerie Copperopolis; affl w/ CME Consulting, Microchip, and  
 Comment Type E Comment Status X  
 Equation (202–15) and Equation (202–16) are missing call-outs. Technical changes to this text are anticipated, so it's not possible to propose the exact call-out at this time.  
 SuggestedRemedy  
 Grant Editorial license for Editor to add call-outs to Equation (202–15) and Equation (202–16) in clause 2.3.5.3 .  
 Proposed Response Response Status O

CI 202 SC 202.3.5.4 P 194 L 16 # 75  
 Zimmerman, George CME Consulting/ADI,APL Gp, Cisco, Infineon, OnSe  
 Comment Type T Comment Status X  
 This section describes the generation of TDD bursts, and insertion of the quiet symbols. It should be renamed and rewritten so as not to hide that.  
 SuggestedRemedy  
 Retitle 202.3.5.4 PAM Mapping and generation of TDD bursts  
 With text:  
 "Except for when transmitting payload symbols for 10 Gb/s when tx\_mode is SEND\_N, the symbols are encoded by the PAM2 mapper defined in 202.3.2.2.20.  
 When transmitting 10 Gb/s payload symbols and tx\_mode is SEND\_N, the symbols are encoded by the Gray-coded PAM4 encoder defined in 202.3.2.2.18 and 202.3.2.2.19.  
 Quiet symbols, Z, are then introduced between each TDD burst frame to form the sequence On, as defined in Equation 202-17.  
 The values of On are then conveyed to the PMA for transmission via the parameter tx\_symb of the PMA\_UNITDATA.request primitive.  
 Retain equation 202-17.  
 After equation 202-17 insert: "Where N\_tdd is the number of symbols equivalent to the nominal 9.6 us TDD cycle time."  
 Proposed Response Response Status O

CI 202 SC 202.3.5.4 P 194 L 24 # 142  
 Maguire, Valerie Copperopolis; affl w/ CME Consulting, Microchip, and  
 Comment Type E Comment Status X  
 Ensure that all figures, tables, and equations have a text call-out.  
 SuggestedRemedy  
 Replace "...based on symbol time index n."  
 with "...based on symbol time index n as shown in Equation (202–17)."  
 Proposed Response Response Status O

IEEE P802.3dm D0.c Asymmetrical Electrical Automotive Ethernet 3rd Task Force review comments

CI 202 SC 202.3.6 P 195 L 1 # 76  
 Zimmerman, George CME Consulting/ADI,APL Gp, Cisco, Infineon, OnSe  
 Comment Type E Comment Status X  
 If we define the TDD frames in 202.3.5, it is not clear what value 202.3.6 adds, other than Table 202-8 and perhaps some informative figures. If the figures are necessary, they should be in 202.3.5  
 SuggestedRemedy  
 Move text and figures from P195 L2 through P197 L30 to 202.3.5, after Table 202-7. Alternatively, move only P195 L2 through P195 L34 (including first paragraph, Figure 202-15, and table 202-8) to 202.3.5, after Table 202-7, and delete the remaining content of 202.3.6.  
 Proposed Response Response Status O

CI 202 SC 202.3.6 P 195 L 9 # 77  
 Zimmerman, George CME Consulting/ADI,APL Gp, Cisco, Infineon, OnSe  
 Comment Type T Comment Status X  
 tdd\_cycle\_time and gap\_time are not used or defined anywhere else  
 SuggestedRemedy  
 Please define it. - suggest add all times shown in the figure (e.g., tdd\_cycle\_time, and gap\_time) to Table 202-8. (alternately, replace labels in the figure with defined values)  
 Proposed Response Response Status O

CI 202 SC 202.3.6 P 195 L 9 # 254  
 Wang, Frank Realtek Semiconductor Corp.  
 Comment Type E Comment Status X  
 wording  
 SuggestedRemedy  
 change "tdd\_cycle\_time" to "TDD\_cycle\_time"  
 Proposed Response Response Status O

CI 202 SC 202.3.6 P 195 L 25 # 78  
 Zimmerman, George CME Consulting/ADI,APL Gp, Cisco, Infineon, OnSe  
 Comment Type E Comment Status X  
 Adding the gap time to the table would make it far more useful. Checking these times revealed an error in Table 202-8.  
 SuggestedRemedy  
 Change title of Table 202-8 to "TDD cycle timing"  
 In Table 202-8:  
 Add column to table for gap\_time with appropriate values (I think 320ns for SEND\_TS, and 176 for SEND\_TA and SEND\_N)  
 Change LS\_TX\_time for SEND\_TA & SEND\_N to 554.67 ns , and HS\_TX\_time to 8693.33 ns  
 Proposed Response Response Status O

CI 202 SC 202.3.6 P 195 L 25 # 255  
 Wang, Frank Realtek Semiconductor Corp.  
 Comment Type T Comment Status X  
 According to [https://www.ieee802.org/3/dm/public/0126/muma\\_3dm\\_01\\_0126.pdf](https://www.ieee802.org/3/dm/public/0126/muma_3dm_01_0126.pdf), the values of LS\_TX\_time and HS\_TX\_time in Table 202-8 need to be updated.  
 SuggestedRemedy  
 change "560" to "554.67" and change "8826.67" to "8693.33"  
 Proposed Response Response Status O

CI 202 SC 202.3.6 P 195 L 25 # 256  
 Wang, Frank Realtek Semiconductor Corp.  
 Comment Type E Comment Status X  
 Add an additional column, "Tdd cycle\_time", to better understanding the timing in each TDD cycle.  
 SuggestedRemedy  
 Add 4th column "TDD\_cycle\_time (ns)" and a "9600" is assigned to SEND\_TS, SEND\_TA, and SEND\_N.  
 Proposed Response Response Status O

IEEE P802.3dm D0.c Asymmetrical Electrical Automotive Ethernet 3rd Task Force review comments

CI 202 SC 202.3.6 P 195 L 32 # 188  
 Muma, Scott Microchip  
 Comment Type T Comment Status X  
 The times in SEND\_TA/SEND\_N are not updated in Table 202-8  
 SuggestedRemedy  
 Change 560 to 554.67  
 Change 8826.67 to 8693.33  
 Proposed Response Response Status O

CI 202 SC 202.3.7.1 P 197 L 34 # 81  
 Zimmerman, George CME Consulting/ADI,APL Gp, Cisco, Infineon, OnSe  
 Comment Type E Comment Status X  
 202.3.7.1 is unnecessary, since this has been previously stated for the entire clause (in 202.1.7)  
 SuggestedRemedy  
 Delete 202.3.7.1  
 Proposed Response Response Status O

CI 202 SC 202.3.6 P 195 L 37 # 79  
 Zimmerman, George CME Consulting/ADI,APL Gp, Cisco, Infineon, OnSe  
 Comment Type T Comment Status X  
 TS\_Quiet doesn't show up anywhere else it needs definition. Is this the TDD\_on\_s timer value?  
 SuggestedRemedy  
 Please replace with QUIET or appropriate term and define its duration.  
 Proposed Response Response Status O

CI 202 SC 202.3.7.2.2 P 198 L 24 # 169  
 Chini, Ahmad Broadcom  
 Comment Type E Comment Status X  
 training\_mode is used but not specified as a variable  
 SuggestedRemedy  
 Add training\_mode to the list of variables  
 Proposed Response Response Status O

CI 202 SC 202.3.6 P 196 L 7 # 80  
 Zimmerman, George CME Consulting/ADI,APL Gp, Cisco, Infineon, OnSe  
 Comment Type T Comment Status X  
 TA\_Quiet doesn't show up anywhere else it needs definition. How does this differ from TS\_Quiet or QUIET? Is this the 9040 ns LEADER TDD\_qt\_timer? Or is it the 773.33 ns FOLLOWER value? If it differs, specify that.  
 SuggestedRemedy  
 Please replace with QUIET or appropriate term in Figures 202-17 and 202-18 and define its duration.  
 Proposed Response Response Status O

CI 202 SC 202.3.7.2.2 P 199 L 1 # 170  
 Chini, Ahmad Broadcom  
 Comment Type E Comment Status X  
 rx\_data\_active specifies but not used  
 SuggestedRemedy  
 remove rx\_data\_active  
 Proposed Response Response Status O

CI 202 SC 202.3.7.2.2 P 199 L 12 # 168  
 Chini, Ahmad Broadcom  
 Comment Type E Comment Status X  
 tdd\_detect is not used.  
 SuggestedRemedy  
 remove tdd\_detect  
 Proposed Response Response Status O

IEEE P802.3dm D0.c Asymmetrical Electrical Automotive Ethernet 3rd Task Force review comments

CI 202 SC 202.3.7.2.2 P 199 L 18 # 82  
 Zimmerman, George CME Consulting/ADI,APL Gp, Cisco, Infineon, OnSe  
 Comment Type T Comment Status X  
 The variables tx\_data\_active, tx\_qt\_active, and tdd\_detect are unused in the state diagrams.  
 All the timers are unused in the state diagrams.  
 SuggestedRemedy  
 delete definitions for tdd\_detect, tx\_data\_active, and tx\_qt\_active.  
 Delete 202.3.7.2.3 and all timers  
 Proposed Response Response Status O

CI 202 SC 202.3.7.2.2 P 199 L 19 # 171  
 Chini, Ahmad Broadcom  
 Comment Type E Comment Status X  
 tx\_data\_active specified but not used  
 SuggestedRemedy  
 remove tx\_data\_active  
 Proposed Response Response Status O

CI 202 SC 202.3.7.2.2 P 199 L 29 # 172  
 Chini, Ahmad Broadcom  
 Comment Type E Comment Status X  
 tx\_qt\_active specified but not used  
 SuggestedRemedy  
 remove tx\_qt\_active  
 Proposed Response Response Status O

CI 202 SC 202.3.8.2 P 205 L 26 # 83  
 Zimmerman, George CME Consulting/ADI,APL Gp, Cisco, Infineon, OnSe  
 Comment Type E Comment Status X  
 The bits of the MultiGBASE-T1 PCS registers which reference clause 149 and are used by  
 clauses 201 and 202 need to have the references added.  
 SuggestedRemedy  
 Add 45.2.3.87.1, 45.2.3.87.2, 45.2.3.87.3, 47.2.3.87.6  
 Add references to 201.4.7.1 and 202.3.7.2.2 where it says "defined in 149.8.1.", for  
 definitions of pcs\_status, block\_lock, and hi\_rfer. to 45.2.3.87.1, .2, and .3.  
 Add reference to 201.3.7.2, 201.4.7.2, and 202.3.8.2 where it says "as defined by  
 RFER\_count in 149.3.8.2" to 47.2.3.87.6.  
 Delete editor's note at 202.3.8.2  
 Delete TBDs in definitions of pcs\_status, block\_lock, and hi\_rfer in 202.3.8.1 (P205 L10-20)  
 Proposed Response Response Status O

CI 202 SC 202.4.2 P 206 L 47 # 132  
 Maguire, Valerie Copperopolis; affl w/ CME Consulting, Microchip, and  
 Comment Type E Comment Status X  
 Use more common reference structure.  
 SuggestedRemedy  
 Replace, "The PMA reference diagram, Figure 202-22, shows..."  
 with "The PMA reference diagram (see Figure 202-22) shows..."  
 Proposed Response Response Status O

CI 202 SC 202.4.2.2 P 207 L 21 # 85  
 Zimmerman, George CME Consulting/ADI,APL Gp, Cisco, Infineon, OnSe  
 Comment Type T Comment Status X  
 The TDD cycles are generated by the PCS. The PMA doesn't have a requirement to repeat  
 the cycles - it does what the PCS tells it to.  
 SuggestedRemedy  
 Delete "The PMA shall repeat such TDD cycles with the predefined timing parameters  
 specified in 202.3.6."  
 Proposed Response Response Status O

IEEE P802.3dm D0.c Asymmetrical Electrical Automotive Ethernet 3rd Task Force review comments

CI 202 SC 202.4.2.3 P 207 L 42 # 86  
 Zimmerman, George CME Consulting/ADI,APL Gp, Cisco, Infineon, OnSe  
 Comment Type T Comment Status X  
 The PMA Receive function must be able to receive PAM2 in all cases and PAM4 in 10Gb/s mode. Not "PAM2 or PAM4 signals"  
 SuggestedRemedy  
 Change "for PAM2 or PAM4 signals on the balanced pair or the single ended coaxial cable." to "for PAM2 signals and for PAM4 signals when receiving 10 Gb/s on the balanced pair or the single ended coaxial cable."  
 Proposed Response Response Status O

CI 202 SC 202.4.2.3 P 208 L 1 # 84  
 Zimmerman, George CME Consulting/ADI,APL Gp, Cisco, Infineon, OnSe  
 Comment Type T Comment Status X  
 The description of loc\_rcvr\_status is unclear and may be contradictory. First it says it is "expected to" become NOT\_OK when the link\_partner's tx\_mode changes to SEND\_Z from any other value, then it says that the failing to receive the "consecutive TDD bursts" could trigger deassertion (which should say "NOT\_OK"), then it REQUIRES that SEND\_Z during the QUIET period NOT trigger de-assertion. I looked at Figure 202-26, but only see SEND\_Z transmitted during training. During data mode tx\_mode is SEND\_N....  
 SuggestedRemedy  
 Suggest: Change "The SEND\_Z signal during the TDD QUIET period alone shall not trigger the DUT to de-assert its loc\_rcvr\_status." to "The reception of Z symbols during the TDD QUIET period alone, if followed by a TDD burst shall not trigger setting loc\_rcvr\_status to NOT\_OK."  
 Proposed Response Response Status O

CI 202 SC 202.4.2.3 P 208 L 3 # 257  
 Wang, Frank Realtek Semiconductor Corp.  
 Comment Type T Comment Status X  
 To align with clause 201, using the definition of "Z".  
 SuggestedRemedy  
 change:  
 "The SEND\_Z signal during the TDD QUIET period alone shall not trigger the DUT to de-assert its loc\_rcvr\_status."  
 to:  
 "The received Z symbols during the TDD QUIET period alone shall not trigger setting loc\_rcvr\_status to become NOT\_OK."  
 Proposed Response Response Status O

CI 202 SC 202.4.2.4.2 P 209 L 20 # 87  
 Zimmerman, George CME Consulting/ADI,APL Gp, Cisco, Infineon, OnSe  
 Comment Type E Comment Status X  
 Octet 3<T:0> appears to be a typo - should be <7:0>  
 SuggestedRemedy  
 See comment.  
 Proposed Response Response Status O

CI 202 SC 202.4.2.4.5 P 210 L 24 # 148  
 Maguire, Valerie Copperopolis; affl w/ CME Consulting, Microchip, and  
 Comment Type E Comment Status X  
 Missing "." at the end of the sentence.  
 SuggestedRemedy  
 Replace "misconfiguration"  
 with "misconfiguration."  
 Proposed Response Response Status O

IEEE P802.3dm D0.c Asymmetrical Electrical Automotive Ethernet 3rd Task Force review comments

CI 202 SC 202.4.2.4.5 P 210 L 26 # 136  
 Maguire, Valerie Copperopolis; affl w/ CME Consulting, Microchip, and  
 Comment Type E Comment Status X  
 Use more typical reference language and more the reference closer to the descriptive text.  
 SuggestedRemedy  
 Replace "... contains the PHY capability bits."  
 with "... contains the PHY capability bits as shown in Table 202–10."  
 Delete, "See Table 202–10 for the details." on P210, L27.  
 Proposed Response Response Status O

CI 202 SC 202.4.2.4.5 P 211 L 1 # 88  
 Zimmerman, George CME Consulting/ADI,APL Gp, Cisco, Infineon, OnSe  
 Comment Type T Comment Status X  
 I thought the precoder was deleted.  
 SuggestedRemedy  
 Delete sentence at P211 L1-2: " PrecodeSel indicates... 202.3.2.2.19)."  
 Replace PrecodeSel with Reserved in Table 202-10  
 At P211 L47, change "the negotiated speed, and the PrecodeSel" to ", and the negotiated speed"  
 Delete "PrecoderSel," at P213 L35 (202.4.2.4.11)  
 Proposed Response Response Status O

CI 202 SC 202.4.2.4.6 P 211 L 12 # 137  
 Maguire, Valerie Copperopolis; affl w/ CME Consulting, Microchip, and  
 Comment Type E Comment Status X  
 Use more typical reference language.  
 SuggestedRemedy  
 Replace "...Oct8<7> = delay\_count\_valid. See Table 202–11 for the details."  
 with "...Oct8<7> = delay\_count\_valid as shown in Table 202–11."  
 Proposed Response Response Status O

CI 202 SC 202.4.2.4.11 P 213 L 29 # 90  
 Zimmerman, George CME Consulting/ADI,APL Gp, Cisco, Infineon, OnSe  
 Comment Type T Comment Status X  
 "When entering the TRAINING0 state" - does this mean that the alignment is already there upon entry? If so, "Prior to entering" would make sense. If not (which I think is the meaning), then when does alignment need to take place by? If it is the latter, separation of TRAINING0 into an alignment state and a state maintaining the alignment is recommended, with the requirements language removed.  
 SuggestedRemedy  
 Either : Change "When entering... on the transmit MDI" to "Upon entry to the TRAINING0 state, the first symbol to of the FOLLOWER's transmit PMA training frame at the transmit MDI shall be aligned so that it is "  
 OR: Consider when the alignment must occur by, and separate the TRAINING0 state into multiple states - one where alignment occurs and one where the alignment is maintained. This also necessitates removal of the 2 "shalls" on P213 L29 and L32.  
 Proposed Response Response Status O

CI 202 SC 202.4.2.4.11 P 213 L 30 # 89  
 Zimmerman, George CME Consulting/ADI,APL Gp, Cisco, Infineon, OnSe  
 Comment Type T Comment Status X  
 The timing requirement for the FOLLOWER's transmit frame is infinitely precise - no tolerance. Suggest some tolerance is appropriate (either +/- or express as a matter of baud intervals). The situation also applies to the  
 SuggestedRemedy  
 Suggest +/- 1/2 baud interval. (TFTD - this is probably wrong)  
 Proposed Response Response Status O

IEEE P802.3dm D0.c Asymmetrical Electrical Automotive Ethernet 3rd Task Force review comments

CI 202 SC 202.4.2.4.11 P 213 L 33 # 91

Zimmerman, George CME Consulting/ADI,APL Gp, Cisco, Infineon, OnSe

Comment Type T Comment Status X

Suggest that the requirement for the FOLLOWER Infocfield burst coun to match the LEADER's from the preceding frame isn't what you want - it can be met by simply echoing the count. I think this isn't a 'shall' but rather a recommendation that the counts should equal each other. Also, the name of the field is PHY burst count, not Infocfield burst count.

SuggestedRemedy

Change "shall match" to "should match" at P213 L33  
 Change "FOLLOWER Infocfield burst count" to "PHY burst count communicated by the FOLLOWER"  
 Change "LEADER Infocfield burst count from" to "PHY burst count communicated by the leader during"

Proposed Response Response Status O

CI 202 SC 202.4.2.4.11 P 213 L 36 # 92

Zimmerman, George CME Consulting/ADI,APL Gp, Cisco, Infineon, OnSe

Comment Type E Comment Status X

I think you mean exchanged "using" infocfields (you're not swapping these for infocfields)

SuggestedRemedy

see comment.

Proposed Response Response Status O

CI 202 SC 202.4.2.4.11 P 213 L 36 # 94

Zimmerman, George CME Consulting/ADI,APL Gp, Cisco, Infineon, OnSe

Comment Type T Comment Status X

the exit from TRAINING0 is "negotiation\_done" which means the speed must be negotiated before exit. Therefore, "will be" should be "is", as it isn't a future action, it happens in the TRAINING0 state, which is what the paragraph is about. This might be clearer with some discussion of moving on after the negotiation as well.

SuggestedRemedy

change "will be" to "is"  
 Suggest that a final sentence, something like "Upon successful completion of the negotiation, training moves on to the COUNTDOWN."

Proposed Response Response Status O

CI 202 SC 202.4.2.4.11 P 213 L 38 # 93

Zimmerman, George CME Consulting/ADI,APL Gp, Cisco, Infineon, OnSe

Comment Type T Comment Status X

The paragraph is already talking about being IN the TRAINING0 state, but this last sentence talks about 'until it enters the TRAINING0 state', and refers to 'this alignment' which doesn't have a precedent (what is "this alignment" here?) seems to be out of place, possibly left over and referring to the requirement on line 32.

SuggestedRemedy

Delete "The FOLLOWER shall continue to maintain this alignment until it enters the TRAINING0 state."

Proposed Response Response Status O

CI 202 SC 202.4.2.4.11 P 213 L 43 # 178

Chini, Ahmad Broadcom

Comment Type T Comment Status X

The delay requirement is for both training and normal mode, but normal mode is not mentioned anywhere else.

SuggestedRemedy

Include normal mode as in below

When entering the TRAINING1 state or normal mode, the FOLLOWER shall use the LEADER transmitted delay\_count to align its transmit PMA frame to be 176 ns - delay\_count × 5.33 ns (+-5.3ns), after the last PMA training or normal mode payload symbol from the LEADER appears on the FOLLOWER input MDI.

Proposed Response Response Status O

CI 202 SC 202.4.2.4.11 P 213 L 44 # 95

Zimmerman, George CME Consulting/ADI,APL Gp, Cisco, Infineon, OnSe

Comment Type T Comment Status X

shall align its transmit PMA training frame... again, precise timing (see earlier comment about alignment in TRAINING0). It looks like the accuracy here should be related to the granular resolution of delay\_count, which is 5.333 ns per tha above. There is a mismatch in the precision of the 5.33ns here and the 5.333 stated in the definition of delay\_count...

SuggestedRemedy

Change "5.33 ns" to insert, "5.333 ns, +/- 0.5 delay count units," at P213 L44

Proposed Response Response Status O

IEEE P802.3dm D0.c Asymmetrical Electrical Automotive Ethernet 3rd Task Force review comments

CI 202 SC 202.4.2.4.11 P 213 L 47 # 96

Zimmerman, George CME Consulting/ADI,APL Gp, Cisco, Infineon, OnSe

Comment Type T Comment Status X

The link\_fail\_inhibit timer is started within the TRAINING0 state. This may never happen. The conventions of 21.5 are adopted. These say that the actions in the state are executed instantaneously - and then the state waits for the exit conditions. Therefore, when training0 is entered, it checks once, and only once for training\_active and detect\_lp\_burst, and starts the link fail inhibit timer, setting training\_active to 1. training\_active should be 0 on the first pass through. so it becomes a matter of whether detect\_lp\_burst is true on entry - For the FOLLOWER, since loc\_rcvr\_status needs to be OK, this is probably fine, but the text is still not right since teh follower could get more than one burst before loc\_rcvr\_status = OK. For the LEADER, this is a problem, because it goes straight to TRAINING0 and detect\_lp\_burst will be FALSE (because the follower is SILENT, and the leader doesn't start transmitting until it enters TRAINING0). The statement to start the link\_fail\_inhibit timer never happens (and training\_active never gets set to 1). When the follower transitions, negotiation may complete, you come out of TRAINING0 without the link\_fail\_inhibit timer started and without the LEADER's training\_active being set to 1.

NOTE - the suggestion fixes the link\_fail\_inhibit\_timer & training\_active problem, and aligns the descriptive text, but might not be the desired behavior - this may require more work on the state diagram to get the desired behavior....

SuggestedRemedy

Suggest TRAINING0 be changed in Figure 202-26 to delete "IF (training\_active = 0 \* detect\_lp\_burst) THEN" and "END" (and adjust indent on currently nested statements) Delete first two sentences of the 5th paragraph (The LEADER link\_fail\_inhibit\_timer... training frame to the LEADER.)

Proposed Response Response Status O

CI 202 SC 202.4.2.4.11 P 213 L 54 # 97

Zimmerman, George CME Consulting/ADI,APL Gp, Cisco, Infineon, OnSe

Comment Type E Comment Status X

The description of the startup sequence seems to stop halfway through. It's odd and not helpful. It would be nice to complete.

SuggestedRemedy

Suggest, adding new text after last paragraph of 202.4.2.4.11:  
 "The COUNTDOWN0 state synchronizes the link partners' transition from symmetric training TDD bursts (SEND\_TS) to asymmetric training TDD bursts (SEND\_TA) in the TRAINING1 state. The TRAINING1 state then waits until both local and remote receivers settle and signal that their status is OK, before transitioning to a subsequent countdown, COUNTDOWN1. Following the completion of COUNTDOWN1, the PCS is tested, and, if the link is reliable, as indicated by block lock and the RS-FEC error rate, PHY Control transitions to PCS\_DATA and begins transferring data."

Proposed Response Response Status O

CI 202 SC 202.4.3.1 P 214 L 28 # 112

Zimmerman, George CME Consulting/ADI,APL Gp, Cisco, Infineon, OnSe

Comment Type T Comment Status X

There is no mention of what signals are transmitted during 2.5Gb/s or 5 Gb/s transmission. "all other symbols" isn't really sufficient specification.

SuggestedRemedy

Insert the following new second sentence in the first paragraph of 202.4.3.1:  
 "For 100 Mb/s, 2.5 Gb/s or 5 Gb/s, all transmit symbols are PAM2."

Proposed Response Response Status O

CI 202 SC 202.4.4.1 P 215 L 6 # 100

Zimmerman, George CME Consulting/ADI,APL Gp, Cisco, Infineon, OnSe

Comment Type T Comment Status X

Definition of config should just reference the parameter passed by the primitive. There is no reason to reference passing to the PCS here either.

SuggestedRemedy

Change definition of config to : "See 202.2.1.2."

Proposed Response Response Status O

IEEE P802.3dm D0.c Asymmetrical Electrical Automotive Ethernet 3rd Task Force review comments

CI 202 SC 202.4.4.1 P 215 L 11 # 101

Zimmerman, George CME Consulting/ADI,APL Gp, Cisco, Infineon, OnSe

Comment Type T Comment Status X

A better description is needed for link\_control than just how it is set. Also descriptions are needed for the values. Consider using a different name too - link\_control is used for the variable going to the TDI throughout 802.3, and this one doesn't do that - it is more like sync\_link\_control in the automotive clauses.

SuggestedRemedy

Suggest change name of link\_control to link\_enable  
 Change Description to : "This link\_enable variable is set by management or default to enable or disable the PHY. It is set to disable the link upon power on reset or release from power down (See 202.4.2.5). Transition to ENABLE initiates PHY Control and the Link Monitor state diagrams. Values:  
 DISABLE Disable the transmitter and await initiation of training.  
 ENABLE Enable operation of the PHY.

Proposed Response Response Status O

CI 202 SC 202.4.4.1 P 215 L 16 # 102

Zimmerman, George CME Consulting/ADI,APL Gp, Cisco, Infineon, OnSe

Comment Type T Comment Status X

The values of link\_status need definition.

SuggestedRemedy

Change "Values: OK or FAIL" to "Values:  
 FAIL No valid link established.  
 OK The Link Monitor function indicates that a valid MultiGBASE-A link is established.  
 Reliable reception of signals transmitted from the remote PHY is possible."

Proposed Response Response Status O

CI 202 SC 202.4.4.1 P 215 L 18 # 99

Zimmerman, George CME Consulting/ADI,APL Gp, Cisco, Infineon, OnSe

Comment Type T Comment Status X

You shouldn't put the state diagram actions in the variable definitions. Put the reset of loc\_countdown\_done in the state diagram. However, it isn't clear this is the right variable. The text says (202.3.2.4.7) "The LEADER will exit a COUNTDOWN state after sending the last burst (BC24=PhaseSwBC24-1), and receiving the last burst from the FOLLOWER. The FOLLOWER will exit a COUNTDOWN state after receiving the last burst (BC24=PhaseSwBC24-1) from the LEADER and finishing sending the last burst of its own."

The same can be said of rem\_countdown\_done at P216 L1

SuggestedRemedy

Change definition of loc\_countdown\_done to:  
 This variable is only used by the LEADER. It indicates that the LEADER has finished sending the last LEADER countdown Infofield and received the responding (last) Infofield from the FOLLOWER at the current TRAINING stage.  
 Values:  
 TRUE: The LEADER has sent it's last burst (BC24=PhaseSwBC24-1), and received the last burst from the FOLLOWER as indicated by the received InfoField since the latest entry to a TRAINING state.  
 FALSE: The LEADER has not sent it's last burst (BC24=PhaseSwBC24-1), or has not received the last burst from the FOLLOWER as indicated by the received InfoField since the latest entry to a TRAINING state.

Change definition of rem\_countdown\_done to:  
 This variable is only used by the FOLLOWER. It indicates that the FOLLOWER has finished receiving the last Infofield from the LEADER at the current TRAINING stage, and has sent at least one Infofield.  
 Values:  
 TRUE: The FOLLOWER has received the last burst (BC24=PhaseSwBC24-1) sent by the leader, and has sent at least one InfoField since the latest entry to a TRAINING state.  
 FALSE: The FOLLOWER has not received the last burst (BC24=PhaseSwBC24-1) sent by the leader, or has not sent at least one InfoField since the latest entry to a TRAINING state.

Insert "loc\_countdown\_done <= FALSE" in states TRAINING0 and TRAINING1.

Proposed Response Response Status O

IEEE P802.3dm D0.c Asymmetrical Electrical Automotive Ethernet 3rd Task Force review comments

CI 202 SC 202.4.4.1 P 215 L 26 # 103  
 Zimmerman, George CME Consulting/ADI,APL Gp, Cisco, Infineon, OnSe  
 Comment Type T Comment Status X  
 what is "correct" or "incorrect" operation?. The remaining description is already covered. I believe what is meant is similar to other phys where the operation is implementation dependent, which is defined in 202.4.2.3. Fortunately, the variable is already defined in 202.2.1.7.  
 SuggestedRemedy  
 Change description of loc\_rcvr\_status to read:  
 See 202.2.1.7.  
 Proposed Response Response Status O

CI 202 SC 202.4.4.1 P 215 L 34 # 258  
 Wang, Frank Realtek Semiconductor Corp.  
 Comment Type E Comment Status X  
 wording  
 SuggestedRemedy  
 change "loc\_rcvr\_status=1" to "loc\_rcvr\_status = OK"  
 Proposed Response Response Status O

CI 202 SC 202.4.4.1 P 215 L 34 # 104  
 Zimmerman, George CME Consulting/ADI,APL Gp, Cisco, Infineon, OnSe  
 Comment Type E Comment Status X  
 Duplicate shall. There is already a requirement to exchange capabilities.  
 SuggestedRemedy  
 delete "shall" (the LEADER and FOLLOWER exchange capabilities...)  
 Proposed Response Response Status O

CI 202 SC 202.4.4.1 P 215 L 40 # 105  
 Zimmerman, George CME Consulting/ADI,APL Gp, Cisco, Infineon, OnSe  
 Comment Type T Comment Status X  
 There are no values given for pcs\_data\_mode. It appears to be a Boolean (TRUE/FALSE).  
 SuggestedRemedy  
 Change description to begin, "A Boolean variable generated by..."  
 Proposed Response Response Status O

CI 202 SC 202.4.4.1 P 215 L 50 # 261  
 Wang, Frank Realtek Semiconductor Corp.  
 Comment Type E Comment Status X  
 remove the text highlight  
 SuggestedRemedy  
 remove the the text highlight for "7:6"  
 Proposed Response Response Status O

CI 202 SC 202.4.4.1 P 216 L 9 # 106  
 Zimmerman, George CME Consulting/ADI,APL Gp, Cisco, Infineon, OnSe  
 Comment Type E Comment Status X  
 what is "correct" or "incorrect" operation?. The remaining description is already covered. Like loc\_rcvr\_status, the variable is already defined in the primitives section, see 202.2.1.8.  
 SuggestedRemedy  
 The status of the link partner's receiver indicated in the loc\_rcvr\_status received in the InfoField from the remote PHY. See 202.2.1.8.1.  
 Proposed Response Response Status O

IEEE P802.3dm D0.c Asymmetrical Electrical Automotive Ethernet 3rd Task Force review comments

CI 202 SC 202.4.4.1 P 216 L 16 # 107

Zimmerman, George CME Consulting/ADI,APL Gp, Cisco, Infineon, OnSe

Comment Type T Comment Status X

tdd\_watchdog\_status is not set anywhere. There is no defined function as a TDD monitor. This variable appears to be used only in the link monitor, and it might be eliminated if the link monitor were expanded to include the referenced TDD monitor (or might be deleted altogether) This functionality appears to involve a timeout counter of 96 usec, and some criterion for detection of reliable operation of TDD bursts...

SuggestedRemedy

Either: Delete tdd\_watchdog\_status and the definition (P216 L16-24, and its use on exit from LINK\_UP in Figure 202-28 (Link Monitor SD))  
OR: provide the referenced TDD monitor functionality, preferably by augmenting the link monitor state diagram.

Proposed Response Response Status O

CI 202 SC 202.4.4.1 P 216 L 18 # 237

Lee, Ching-Yen Realtek Semiconductor Corp.

Comment Type T Comment Status X

The description of tdd\_watchdog\_status needs to be modified.

SuggestedRemedy

change "Variable indicating the status of the TDD monitor." to "Variable indicating whether a reliable TDD burst is detected."

Proposed Response Response Status O

CI 202 SC 202.4.4.1 P 216 L 25 # 108

Zimmerman, George CME Consulting/ADI,APL Gp, Cisco, Infineon, OnSe

Comment Type E Comment Status X

tx\_mode is defined identically in 202.2.1.1. It isn't a good idea to duplicate text, as they may get out of sync.

SuggestedRemedy

Replace definition of tx\_mode with "See 202.2.1.1"

Proposed Response Response Status O

CI 202 SC 202.4.4.1 P 216 L 35 # 259

Wang, Frank Realtek Semiconductor Corp.

Comment Type T Comment Status X

To align with clause 201, using the definition of "Z".

SuggestedRemedy

change "zero symbols" to "Z symbols"

Proposed Response Response Status O

CI 202 SC 202.4.4.2 P 216 L 40 # 109

Zimmerman, George CME Consulting/ADI,APL Gp, Cisco, Infineon, OnSe

Comment Type T Comment Status X

the link\_fail\_inhibit timer is started when the state diagram says it is. The variable text contradicts the diagram. But as noted earlier there is a problem with the diagram. If fixed as described in the comment, the timer starts when PHY control enters TRAINING0. For the LEADER this is when the first symmetric burst starts to be generated by the PCS, for the follower, this is when the loc\_rcvr\_status is OK AND minwait\_timer is done.

SuggestedRemedy

Delete P216 L45-48 ("LEADER: This timer.... to the LEADER.")

Proposed Response Response Status O

CI 202 SC 202.4.5 P 217 L 3 # 238

Lee, Ching-Yen Realtek Semiconductor Corp.

Comment Type T Comment Status X

The PHY Control state diagram needs to be updated.

SuggestedRemedy

An updated figure will be provided.  
Add the following two variable to 202.4.4.1:  
detect\_ip\_burst  
A Boolean variable that is set TRUE when the TDD burst has been detected. Set to FALSE when the PMA detected the burst has ended (PMA could use timer timeout to terminate this detection signal).

training\_active  
A Boolean variable that is set TRUE when the link\_fail\_inhibit\_timer is started. Set to FALSE after entering the DISABLE\_TRANSMITTER state and PCS\_DATA state.

Proposed Response Response Status O

IEEE P802.3dm D0.c Asymmetrical Electrical Automotive Ethernet 3rd Task Force review comments

CI 202 SC 202.4.5 P 217 L 16 # 110

Zimmerman, George CME Consulting/ADI,APL Gp, Cisco, Infineon, OnSe

Comment Type T Comment Status X

training\_active is not defined. This appears to be boolean. It appears to be an indication that this is the first pass through TRAINING0 and has not made it to PCS\_DATA

SuggestedRemedy

Add definition for training\_active to 202.4.4.1

training\_active

A Boolean variable indicating that PHY Control has passed through the TRAINING0 state at least once since the exiting DISABLE\_TRANSMITTER and has not yet reached PCS\_DATA.

Change training\_active <= 0 in DISABLE\_TRANSMITTER and PCS\_DATA to training\_active <= FALSE

Change training\_active <= 1 in TRAINING0 to training\_active <= TRUE

Proposed Response Response Status O

CI 202 SC 202.4.5 P 217 L 22 # 111

Zimmerman, George CME Consulting/ADI,APL Gp, Cisco, Infineon, OnSe

Comment Type T Comment Status X

training\_phase is not defined. This appears to be the varialbe communicated in the infofield.

SuggestedRemedy

Add definition for training\_phase to 202.4.4.1

This variable indicates whether training is currently in the symmetric mode or the assymmetric mode of training. It is transmitted to the link partner in the InfoField. See 202.4.2.4.4.

Values:

00 PHY Control is currently in either in a silent mode or a symmetric training phase.

01 PHY Control is currently in asymmetric training.

Proposed Response Response Status O

CI 202 SC 202.4.5 P 217 L 34 # 187

Muma, Scott Microchip

Comment Type T Comment Status X

Due to the way the state machine conventions work it's possible the link\_fail\_inhibit\_timer never starts. Add a re-entry to TRAINING0 when detect\_ip\_burst=TRUE to ensure the timer will be started before transitioning to COUNTDOWN0.

SuggestedRemedy

See attached PDF P8023dm\_D0pc\_bit\_order\_figure\_markup.pdf Figure 202-26 part a

Proposed Response Response Status O

CI 202 SC 202.4.5 P 218 L 17 # 98

Zimmerman, George CME Consulting/ADI,APL Gp, Cisco, Infineon, OnSe

Comment Type T Comment Status X

TRAINING1 may simply fall through since loc\_rcvr\_status and rem\_rcvr\_status will likely be true on entry. Resetting them to NOT\_OK in the state will prevent this, and they will get executed once on entry, and become OK as the local receiver settles and the remote receiver sends OK status via infofield.

SuggestedRemedy

add "loc\_rcvr\_status <= NOT\_OK" and "rem\_rcvr\_status <= NOT\_OK" to state TRAINING1.

Proposed Response Response Status O

CI 202 SC 202.5.1 P 220 L 11 # 113

Zimmerman, George CME Consulting/ADI,APL Gp, Cisco, Infineon, OnSe

Comment Type T Comment Status X

If the precoder is eliminated, then test mode 3 is eliminated too.

SuggestedRemedy

change the description of register value 3 to Test mode 3 - Reserved

Delete paragraph at P220 L20 through P220 L25 (Test mode 3)

Proposed Response Response Status O

IEEE P802.3dm D0.c Asymmetrical Electrical Automotive Ethernet 3rd Task Force review comments

CI 202 SC 202.5.1 P 220 L 24 # 177  
 Chini, Ahmad Broadcom  
 Comment Type T Comment Status X  
 Precoder is for 10Gbps link only  
 SuggestedRemedy  
 Add a sentence to indicate test mode 3 is not required if 10Gbps is not supported.  
 Proposed Response Response Status O

CI 202 SC 202.5.2.6 P 227 L 28 # 179  
 Chini, Ahmad Broadcom  
 Comment Type T Comment Status X  
 PPM is relative itself, no need to scale it by S  
 SuggestedRemedy  
 Delete  
 scaled by S  
 Proposed Response Response Status O

CI 202 SC 202.5.2.4 P 224 L 30 # 260  
 Wang, Frank Realtek Semiconductor Corp.  
 Comment Type T Comment Status X  
 To align with clause 201, using the definition of "Z".  
 SuggestedRemedy  
 add a new sentence: "When tx\_symb is "Z", the transmit signal at the MDI is nominally zero, and the transmit signal shall be less than -36dBm."  
 Proposed Response Response Status O

CI 202 SC 202.5.3.1 P 227 L 47 # 180  
 Chini, Ahmad Broadcom  
 Comment Type T Comment Status X  
 Sending decoding data to XGMII is regardless of link reset  
 SuggestedRemedy  
 Remove  
 after link reset completion  
 Proposed Response Response Status O

CI 202 SC 202.5.2.4 P 226 L 22 # 262  
 Wang, Frank Realtek Semiconductor Corp.  
 Comment Type E Comment Status X  
 wording  
 SuggestedRemedy  
 remove "(TBD)"  
 Proposed Response Response Status O

IEEE P802.3dm D0.c Asymmetrical Electrical Automotive Ethernet 3rd Task Force review comments

CI 202 SC 202.5.3.2 P 228 L 6 # 133  
 Maguire, Valerie Copperopolis; affl w/ CME Consulting, Microchip, and  
 Comment Type T Comment Status X  
 Improve clarity and improve accuracy of figures.  
 SuggestedRemedy  
 Replace, "The receive DUT is connected to the noise source through a directional coupler, as shown in Figure 202–35, with a link segment as defined in 202.7 for -T1 and shown in Figure 202–36, with a link segment as defined in 202.8 for -V1"  
 with "The -T1 receive DUT is connected to the noise source through a directional coupler with a -T1 link segment (see 202.7 ) as shown in Figure 202–35. The -V1 receive DUT is connected to the noise source through a directional coupler with a -V1 link segment (see 202.8 ) as shown in Figure 202–36."  
 Replace "Link segment" with "-T1 link segment" in Figure 202-35.  
 Replace "Link segment" with "-V1 link segment" in Figure 202-36.  
 Replace "directional coupler" with "Directional coupler" in Figure 202-36.  
 Proposed Response Response Status O

CI 202 SC 202.7.1.6 P 231 L 3 # 181  
 Chini, Ahmad Broadcom  
 Comment Type T Comment Status X  
 use a text similar to 201.  
 SuggestedRemedy  
 Replace  
 The maximum link delay of a -T1 link segment shall be 160 ns.  
 With  
 The propagation delay of a -T1 link segment shall not exceed 160 ns for all frequencies between 3 MHz and 4GHz.  
 Proposed Response Response Status O

CI 202 SC 202.7.2.1 P 231 L 18 # 143  
 Maguire, Valerie Copperopolis; affl w/ CME Consulting, Microchip, and  
 Comment Type E Comment Status X  
 Broken Equation reference.  
 SuggestedRemedy  
 Replace "Equation (202–32)"  
 with "Equation (202–25)"  
 Proposed Response Response Status O

CI 202 SC 202.7.2.1 P 231 L 29 # 144  
 Maguire, Valerie Copperopolis; affl w/ CME Consulting, Microchip, and  
 Comment Type E Comment Status X  
 Broken Equation reference.  
 SuggestedRemedy  
 Replace "Equation (202–33)"  
 with "Equation (202–26)"  
 Proposed Response Response Status O

CI 202 SC 202.7.2.1 P 232 L 1 # 134  
 Maguire, Valerie Copperopolis; affl w/ CME Consulting, Microchip, and  
 Comment Type E Comment Status X  
 Broken figure link reference.  
 SuggestedRemedy  
 Replace "Figure 202–44" with "Figure 202–39".  
 Proposed Response Response Status O

IEEE P802.3dm D0.c Asymmetrical Electrical Automotive Ethernet 3rd Task Force review comments

CI 202 SC 202.7.2.2 P 232 L 32 # 145  
 Maguire, Valerie Copperopolis; affl w/ CME Consulting, Microchip, and  
 Comment Type E Comment Status X  
 Broken Equation reference.  
 SuggestedRemedy  
 Replace "Equation (202-34)"  
 with "Equation (202-27)"  
 Proposed Response Response Status O

CI 202 SC 202.7.2.2 P 233 L 2 # 146  
 Maguire, Valerie Copperopolis; affl w/ CME Consulting, Microchip, and  
 Comment Type E Comment Status X  
 Broken Equation reference.  
 SuggestedRemedy  
 Replace "Equation (202-35)"  
 with "Equation (202-28)"  
 Proposed Response Response Status O

CI 202 SC 202.7.2.2 P 233 L 13 # 135  
 Maguire, Valerie Copperopolis; affl w/ CME Consulting, Microchip, and  
 Comment Type E Comment Status X  
 Broken figure link reference.  
 SuggestedRemedy  
 Replace "Figure 202-45" with "Figure 202-40".  
 Proposed Response Response Status O

CI 202 SC 202.8.1.6 P 236 L 42 # 182  
 Chini, Ahmad Broadcom  
 Comment Type T Comment Status X  
 use a text similar to 201.  
 SuggestedRemedy  
 Replace  
 The maximum link delay of a -V1 link segment shall be 160 ns.  
 With  
 The propagation delay of a -V1 link segment shall not exceed 160 ns for all frequencies  
 between 3 MHz and 4GHz.  
 Proposed Response Response Status O

CI 202 SC 202.11.2 P 243 L 4 # 183  
 Chini, Ahmad Broadcom  
 Comment Type E Comment Status X  
 "in a professional manner" is not a proper specification  
 SuggestedRemedy  
 Use the following instead  
 As per application requirement  
 Proposed Response Response Status O