## IEEE 802.17 Maintenance Request 0042

| MR number  | 0042       | Classification | Technical  | Date received | 3/13/2008  | Reserved for official | 802.17 use |
|--|------------|----------------|------------|---------------|------------|-----------------------|------------|
| Standard   | 802.17-200 | )4 Page        | 492 Subcl  | ause          | D.6 Figure | Table                 | -          |
| Surname  | Lemon      |                | Given Name | John          |            | _                     |            |
| Perceived Problem [ If more space is needed, please provide an additional file, preferably as plain text. ]   rprTopoImageWestProtectionStatus and rprTopoImageEastProtectionStatus are not statuses and are not bit fields. |            |                |            |               |            |                       |            |
|  |            |                |            |               |            |                       |            |
|  |            |                |            |               |            |                       |            |

[ If more space is needed, please provide an additional file, preferably as plain text. ] **Proposed Remedy** 

Change rprTopoImageWestProtectionStatus and rprTopoImageEastProtectionStatus to rprTopoImageWestProtectionState and rprTopoImageEastProtectionState. Change them from bit fields to integers.

## Rationale For Remedy

[ If more space is needed, please provide an additional file, preferably as plain text. ] These provide the current protection state. Only one state can be active at a time.

Remedy's Effect On Existing Equipment

[ If more space is needed, provide an additional file, preferably as plain text. ]

None.

When you have completed this form, please mail it to STDS-802-17-MR @ listserv.ieee.org.