

IEEE 802.17 Maintenance Request 0052

MR number 0052 Classification Technical Date received 3/15/2005 **Reserved for official 802.17 use**

Standard 802.17-2004 Page 525 Subclause D.6 Figure _____ Table _____

Surname Lemon Given Name John

Perceived Problem [If more space is needed, please provide an additional file, preferably as plain text.]

rprSpanStatsInOamEchoFrames and rprSpanStatsOutOamEchoFrames each mistakenly combined two counters from the standard.

Proposed Remedy [If more space is needed, please provide an additional file, preferably as plain text.]

Divide rprSpanStatsInOamEchoFrames into rprSpanStatsInOamEchoReqFrames and rprSpanStatsInOamEchoRspFrames. Divide rprSpanStatsOutOamEchoFrames into rprSpanStatsOutOamEchoReqFrames and rprSpanStatsOutOamEchoRspFrames.

Rationale For Remedy [If more space is needed, please provide an additional file, preferably as plain text.]

The standard purposely counted the two types of echo frames separately, and the MIB was supposed to follow the standard.

Remedy's Effect On Existing Equipment [If more space is needed, provide an additional file, preferably as plain text.]

None.

When you have completed this form, please mail it to STDS-802-17-MR @ listserv.ieee.org.