

IEEE 802.17 Maintenance Request 0060

MR number 0060 Classification Technical Date received 4/5/2005 **Reserved for official 802.17 use**

Standard 802.17-2004 Page 164 Subclause 7.7.1.6.4 Figure _____ Table 7.29

Surname James Given Name David

Perceived Problem [If more space is needed, please provide an additional file, preferably as plain text.]

This code appears to send a bidirectional flooded frame on both ringlets.
This will not work on a center-wrapped station.
Instead, they should be sent through the same datapath, but with distinct frame.ri identifiers.

Proposed Remedy [If more space is needed, please provide an additional file, preferably as plain text.]

- 1) Provide text that clarifies how bidirectional frames are processed on a center-wrapped station, so the intent is clear.
- 2) Revise state machines to track the text of (1).

Rationale For Remedy [If more space is needed, please provide an additional file, preferably as plain text.]

Remedy's Effect On Existing Equipment [If more space is needed, provide an additional file, preferably as plain text.]

When you have completed this form, please mail it to STDS-802-17-MR @ listserv.ieee.org.