IEEE 802.17 Maintenance Request 0077

MR number	0077	Classification	Technical	Date received	7/25/2005	Reserved for o	fficial 802.17 use
Standard	802.17-20	04 Page	355 Subc	ause 11.6.8.4	Figure	Table	11.18
Surname	li		Given Name	jian			
Perceived Problem [If more space is needed, please provide an additional file, preferably as plain text.]							
If there's a fiber loopback, ReceiveTpFrame state can not clear notify this error, just detect a large scope error - miscable.							
IIIISCADI	G.						
Proposed Remedy [If more space is needed, please provide an additional file, preferably as plain text.] 1. insert a row between row4 and row5, the content in new row is following:							
condition " frame.ri!=ri && frame.ttl==MAX_STATION && frame.sa==myMacAddress"							
action "loopbackDefect[ri] = TRUE" state "START"							
2. add content as following at the action of row5:							
loopbac	kDefect[ri] =	FALSE					
Rationale For Remedy [If more space is needed, please provide an additional file, preferably as plain text.]							
Clearly and definitely islate the fiber loopback that is a very normal problem. If we add this remedy, we can easyly notify this problem, rather than a widely common problem - "miscabling".							
	,		, ,		5		
Remedy's Effect On Existing Equipment [If more space is needed, provide an additional file, preferably as plain text.] very simply.							