

## IEEE 802.17 Maintenance Request 0127

MR number 0127 Classification Technical Date received 9/15/2006 **Reserved for official 802.17 use**

Standard 802.17-2004 Page 355 Subclause 11.6.8.4 Figure \_\_\_\_\_ Table 11.18

Surname Juźwiak Given Name Piotr

**Perceived Problem** [ If more space is needed, please provide an additional file, preferably as plain text. ]

Inconsistent notation "frame.seq" in ReceiveTpFrame machine specification.

**Proposed Remedy** [ If more space is needed, please provide an additional file, preferably as plain text. ]

Condition in row 8 of table 11.18 should be changed from:

"topoEntry[ri][hops].sequenceNumber == frame.seq"

to:

"topoEntry[ri][hops].sequenceNumber == frame.seqnum"

**Rationale For Remedy** [ If more space is needed, please provide an additional file, preferably as plain text. ]

Definition of TP frame field prefs (11.3.1.4) calls these bits "seqnum" not a "seq" .

**Remedy's Effect On Existing Equipment** [ If more space is needed, provide an additional file, preferably as plain text. ]

Rather no impact – error must have been found during implementation process.

**When you have completed this form, please mail it to STDS-802-17-MR @ listserv.ieee.org.**