

IEEE 802.17 Maintenance Request 0130

MR number 0130 Classification Technical Date received 10/4/2006 **Reserved for official 802.17 use**

Standard 802.17-2004 Page 478 Subclause D.6 Figure _____ Table _____

Surname Ram Given Name Rafi

Perceived Problem [If more space is needed, please provide an additional file, preferably as plain text.]

The following description in the rprfIdleThreshold MIB item is incorrect - "When the PTQ depth exceeds this value, the incoming link is considered adversely rate mismatched".

Proposed Remedy [If more space is needed, please provide an additional file, preferably as plain text.]

The sentence should be corrected to "When the free space in the PTQ becomes less than or equal to this value, the incoming link is considered adversely rate mismatched"

Rationale For Remedy [If more space is needed, please provide an additional file, preferably as plain text.]

The original description contradicts the example in the MIB description and the text in subclauses 7.5.3 and 7.5.3.2, and the implementation described in table 7.7.

Remedy's Effect On Existing Equipment [If more space is needed, provide an additional file, preferably as plain text.]

None.

When you have completed this form, please mail it to STDS-802-17-MR @ listserv.ieee.org.