

IEEE P802.3REVam Draft 0.99 comments

Cl 00 SC CR P L # 19
Peter Bradshaw Intersil Inc.

Comment Type E Comment Status A

All my other comments relate to Maintenance requests; if, as I suspect, these are not incorporated in the current review document, the following should be ignored.

SuggestedRemedy

Response Response Status C

ACCEPT.

Maintenance requests are not incorporated in the current review document.

Cl 00 SC CR P L # 3
Pat Thaler

Comment Type E Comment Status A

The current pdf of 802.3 only has bookmarks for 1st and 2nd level headings which matches what they have chosen to do in the table of contents. Many of the level 2 subclauses are 10-20 pages in length so the bookmarks don't get you very close. This is inconvenient and wastes time.

Is there some way we can convince them to put in bookmarks to at least level 3?

It isn't like an extra level gets in the way of readers who don't need it since you choose whether to expand

SuggestedRemedy

Response Response Status C

ACCEPT IN PRINCIPLE.

Will work with IEEE-SA editorial staff to see if bookmarks to at least level 3 can be included in pdf files.

Cl 01 SC 1.5 CR P 37 L 24 # 4
John Jetzt Avaya Inc.

Comment Type E Comment Status A

Extra text

SuggestedRemedy

Delete "MuxMultiplier"

Response Response Status C

ACCEPT IN PRINCIPLE.

The definition Mux Multiplexer will be restored to its corrcet position.

Cl 14 SC 14.10.4.5.11 CR P 353 L 33 # 5
John Jetzt Avaya Inc.

Comment Type E Comment Status A

Missing sentence

SuggestedRemedy

Add second sentence "Function provided by MAUs that do not encompass the PI of a PD within their MDI." (similar to sentence in 1b.)

Response Response Status C

ACCEPT.

Cl 14 SC 14.4.1 CR 1 P 337 L 13 # 1
Pat Thaler

Comment Type T Comment Status A

802.3aj changed the text of the note on 14.4.1 to update the reference to a wiring standard. In the Clause 14 draft for am, the note is deleted rather than updated.

SuggestedRemedy

Response Response Status C

ACCEPT.

Cl 30 SC 30.1 CR P 277 L 6 # 6
John Jetzt Avaya Inc.

Comment Type E Comment Status A

Missing word

SuggestedRemedy

Should be "...repeater, MAUs, and Midspan"

Response Response Status C

ACCEPT.

Cl 30 SC 30.1.4 CR P 280 L 6 # 7
John Jetzt Avaya Inc.

Comment Type E Comment Status A

wrong numbers

SuggestedRemedy

should be "30.3 through 30.10"

Response Response Status C

ACCEPT.

IEEE P802.3REVam Draft 0.99 comments

CI 30 SC 30.2.3 CR P 286 L 29 # 8
 John Jetzt Avaya Inc.
 Comment Type E Comment Status A
 missing "s"
 SuggestedRemedy
 should be "relationship diagrams"
 Response Response Status C
 ACCEPT.

CI 30 SC 30.3.1.1.1 CR P 300 L 32 # 12
 John Jetzt Avaya Inc.
 Comment Type E Comment Status A
 Table 30-4, wrong item
 SuggestedRemedy
 "aWISID" should be "aPSEID"
 Response Response Status C
 ACCEPT.

CI 30 SC 30.2.4 CR P 287 L 31 # 9
 John Jetzt Avaya Inc.
 Comment Type E Comment Status A
 wrong numbers in Figure 30-3
 SuggestedRemedy
 the two oPSE boxes should have "30.9.1"
 Response Response Status C
 ACCEPT.

CI 30 SC 30.3.1.1.1 CR P 300 L 33 # 13
 John Jetzt Avaya Inc.
 Comment Type E Comment Status A
 Table 30-4, wrong item
 SuggestedRemedy
 "aSectionStatus" should be "aPSEAdminState"
 Response Response Status C
 ACCEPT.

CI 30 SC 30.2.4 CR P 288 L 16 # 10
 John Jetzt Avaya Inc.
 Comment Type E Comment Status A
 wrong number in Figure 30-4
 SuggestedRemedy
 the oPSE box should have "30.9.1"
 Response Response Status C
 ACCEPT.

CI 30 SC 30.3.1.1.1 CR P 300 L 34 # 14
 John Jetzt Avaya Inc.
 Comment Type E Comment Status A
 Table 30-4, wrong item
 SuggestedRemedy
 "aSectionSESThreshold" should be "aPSEPowerPairsControlAbility"
 Response Response Status C
 ACCEPT.

CI 30 SC 30.3.1.1.1 CR P 300 L 31 # 11
 John Jetzt Avaya Inc.
 Comment Type E Comment Status A
 Table 30-4, wrong number
 SuggestedRemedy
 "PSE Managed Object Class" should be 30.9.1;
 Response Response Status C
 ACCEPT.

CI 30 SC 30.3.1.1.1 CR P 300 L 35 # 15
 John Jetzt Avaya Inc.
 Comment Type E Comment Status A
 Table 30-4, wrong item
 SuggestedRemedy
 "aSectionSES" should be "aPSEPowerPairs"
 Response Response Status C
 ACCEPT.

IEEE P802.3REVam Draft 0.99 comments

CI 30 SC 30.3.1.1.1 CR P 300 L 36 # 16
 John Jetzt Avaya Inc.
 Comment Type E Comment Status A
 Table 30-4, wrong item
 SuggestedRemedy
 "aLineSESThreshold" should be "aPSEPowerDetectionStatus"
 Response Response Status C
 ACCEPT.

CI 30 SC 30.3.1.1.1 CR P 300 L 38 # 17
 John Jetzt Avaya Inc.
 Comment Type E Comment Status A
 Table 30-4, wrong item
 SuggestedRemedy
 "aSectionESSs" should be "aPSEInvalidSignatureCounter"
 Response Response Status C
 ACCEPT.

CI 33 SC 33.2.10.1.1 CR 1 P 492 L 11 # 2
 Gerard Nadeau
 Comment Type T Comment Status R
 Typo -> "TPMDO"
 SuggestedRemedy
 Change to "TMPDO"
 Response Response Status C
 REJECT.

This is not a consolidation error but rather an error in IEEE Std 802.3af. Please submit this at Working Group ballot of IEEE P802.3REVam.

CI 44 SC 44.3 CR P 4 L 50 # 18
 Peter Bradshaw Intersil Inc.
 Comment Type E Comment Status R
 Second paragraph, last sentence '...convert fiber delay values...' should be '...convert fiber or electrical cable delay values...'
 SuggestedRemedy
 Fix as per 802.3ak-2004, page 5 (19 of 56), last line.
 Response Response Status C
 REJECT.

This is not a consolidation error but rather an error in IEEE Std 802.3af. Please submit this at Working Group ballot of IEEE P802.3REVam.