

IEEE P802.3az D2.4 Energy Efficient Ethernet comments

Cl 55 SC 55.4.6.5 P217 L34 # 1

Anslow, Peter Ciena

Comment Type E Comment Status D

Comment 9 against D 2.3 was not fully implemented

SuggestedRemedy

In the editing instruction "Insert a new subclause 55.4.6.5, containing Figure 55-27b, after subclause 55.3.6.4, , as shown below"
"subclause 55.3.6.4, , as" should be "subclause 55.4.6.4, as"

Proposed Response Response Status Z

PROPOSED REJECT.

This comment was WITHDRAWN by the commenter.

Cl 78 SC 78.4.2.1 P254 L53 # 2

Abbott, John Corning Incorporated

Comment Type E Comment Status R

In the sentence "Should there be a discrepancy between a state diagram" There should not be any discrepancies between diagram and text. Can you give an example of a discrepancy?

SuggestedRemedy

Change "Should there be a discrepancy..." to "Should there appear to be a discrepancy ..."

Response Response Status C

REJECT.

This comment is on unchanged text and therefore is out of scope. This phrase is used throughout 802.3 in subclauses that specify state diagram conventions.