

Comment #20 (Clause 33.4.9.2, Page 162, Line 30)

Proposed updated remedy

Delete 33.4.9.2 and the editor note.

The content of 33.4.9.2 is covered in “Configurations with the Midspan PSE in the cabling channel shall not alter the transmission requirements of the “permanent link.” A Midspan PSE shall not provide DC continuity between the two sides of the segment for the pairs that inject power.”