

IEEE 802.17 Maintenance Request 0007

MR number 0007 Classification Technical Date received 1/25/2005 **Reserved for official 802.17 use**

Standard 802.17-2004 Page 270 Subclause 10.4.8.4 Figure _____ Table 10.13

Surname Bruckman Given Name Leon

Perceived Problem [If more space is needed, please provide an additional file, preferably as plain text.]

According to row 5 in table 10.13, if frame.ri != Other (myRi) the receivedTtl is not set, but in Table 10.10 row 13 the value of receivedTtl is used to set frame.ttl. Actually, in the case of frame.ri != Other (myRi) the value of receivedTtl is not set at all.

Proposed Remedy [If more space is needed, please provide an additional file, preferably as plain text.]

In table 10.13 row 5 add the action: receivedTtl = frame.ttl

Rationale For Remedy [If more space is needed, please provide an additional file, preferably as plain text.]

Minimum change.

Remedy's Effect On Existing Equipment [If more space is needed, provide an additional file, preferably as plain text.]

Since this is an obvious error, implementors should have seen this problem and no effect is expected

When you have completed this form, please mail it to STDS-802-17-MR @ listserv.ieee.org.