

## IEEE 802.17 Maintenance Request 0037

MR number 0037 Classification Technical Date received 3/13/2005 **Reserved for official 802.17 use**

Standard 802.17-2004 Page 341 Subclause 11.6.5.6 Figure \_\_\_\_\_ Table 11.15

Surname Lemon Given Name John

**Perceived Problem** [ If more space is needed, please provide an additional file, preferably as plain text. ]

This allows an FS to be replaced by an MS.

**Proposed Remedy** [ If more space is needed, please provide an additional file, preferably as plain text. ]

Add the following row after Row 4:  
Condition: adminReqProtection[ri] == MS && myTopoInfo.spanProtState[ri] >= MS  
Action: spanProtAdmin = IDLE;  
        adminReqProtection = NULL;  
Next State: MAIN

**Rationale For Remedy** [ If more space is needed, please provide an additional file, preferably as plain text. ]

If you start with FS on the east side of a station and then command MS on the east side of the same station, the standard will currently allow the FS to be replaced by MS.

**Remedy's Effect On Existing Equipment** [ If more space is needed, provide an additional file, preferably as plain text. ]

None.

**When you have completed this form, please mail it to STDS-802-17-MR @ listserv.ieee.org.**