

# IEEE 802.17 Maintenance Request 0061

MR number 0061 Classification Technical Date received 4/5/2005 **Reserved for official 802.17 use**

Standard 802.17-2004 Page 164 Subclause 7.7.1.6.4 Figure \_\_\_\_\_ Table \_\_\_\_\_

Surname James Given Name David

**Perceived Problem** [ If more space is needed, please provide an additional file, preferably as plain text. ]

I believe the Transmit states will send all topo frames to the single connected datapath on a center wrapped ring. This should not be forced to be the case. Also, its unclear how fairness frames go across the wrapped center-wrapped station.

**Proposed Remedy** [ If more space is needed, please provide an additional file, preferably as plain text. ]

- 1) Provide text that clarifies how control frames are processed, so the intent is clear.
- 2) Revise state machines to track the text of (1).

**Rationale For Remedy** [ If more space is needed, please provide an additional file, preferably as plain text. ]

**Remedy's Effect On Existing Equipment** [ If more space is needed, provide an additional file, preferably as plain text. ]

**When you have completed this form, please mail it to STDS-802-17-MR @ listserv.ieee.org.**