

## IEEE 802.17 Maintenance Request 0064

MR number 0064 Classification Technical Date received 4/5/2005 **Reserved for official 802.17 use**

Standard 802.17-2004 Page 503 Subclause D.6 Figure \_\_\_\_\_ Table \_\_\_\_\_

Surname James Given Name David

**Perceived Problem** [ If more space is needed, please provide an additional file, preferably as plain text. ]

The rprOamTimeout has no meaning within the current definition, but appears to be from the history of when we assumed the MAC would support some sort of auto-retry and timeouts. Furthermore, there is no cross-reference to an RPR variable, which reinforced the aforementioned thoughts.

**Proposed Remedy** [ If more space is needed, please provide an additional file, preferably as plain text. ]

Delete rprOamTimeout material at the top of page 503 to further down on page 503 as well as other rprOamTimeout related material.

**Rationale For Remedy** [ If more space is needed, please provide an additional file, preferably as plain text. ]

**Remedy's Effect On Existing Equipment** [ If more space is needed, provide an additional file, preferably as plain text. ]

**When you have completed this form, please mail it to STDS-802-17-MR @ listserv.ieee.org.**