

IEEE 802.17 Maintenance Request 0066

MR number 0066 Classification Technical Date received 4/5/2005 **Reserved for official 802.17 use**

Standard 802.17-2004 Page 503 Subclause D.6 Figure _____ Table _____

Surname James Given Name David

Perceived Problem [If more space is needed, please provide an additional file, preferably as plain text.]

The rprOamResponseCount has no meaning within the current definition, but appears to be from the history of when we assumed the MAC would support some sort of auto-retry and timeouts. Furthermore, there is no cross-reference to an RPR variable, which reinforced the aforementioned thoughts.

Proposed Remedy [If more space is needed, please provide an additional file, preferably as plain text.]

Delete rprOamResponseCount material at the middle of page 503 to further down on page 503 as well as other rprOamResponseCount related material.

Rationale For Remedy [If more space is needed, please provide an additional file, preferably as plain text.]

Remedy's Effect On Existing Equipment [If more space is needed, provide an additional file, preferably as plain text.]

When you have completed this form, please mail it to STDS-802-17-MR @ listserv.ieee.org.