

# IEEE 802.17 Maintenance Request 0131

MR number 0131 Classification Technical Date received 4/25/2007 **Reserved for official 802.17 use**

Standard 802.17-2004 Page 295 Subclause 11.2.3 Figure \_\_\_\_\_ Table \_\_\_\_\_

Surname Holness Given Name Marc

**Perceived Problem** [ If more space is needed, please provide an additional file, preferably as plain text. ]

txSlowTimeout variable specified a default of 100msec. However, in clause D.6, the rprIfProtectionSlowTimer MIB specifies a default of 1 sec. The value conflict each other.

**Proposed Remedy** [ If more space is needed, please provide an additional file, preferably as plain text. ]

Change the txSlowTimeout variable default (defined in 11.2.3) to 1 second.

**Rationale For Remedy** [ If more space is needed, please provide an additional file, preferably as plain text. ]

There is no need to run at 100msec when there is no fault on the system.

**Remedy's Effect On Existing Equipment** [ If more space is needed, provide an additional file, preferably as plain text. ]

**When you have completed this form, please mail it to STDS-802-17-MR @ listserv.ieee.org.**