Cl 44 SC 44 Ρ MyBallot # 95 GROW, ROBERT M Individual Comment Type ER Comment Status X Reconcile base text. SuggestedRemedy While I tried to do a detailed base text review of earlier clauses, someone else doing it would be good. I didn't get a chance to do it again on clause 44 and 45 and it needs to be done. Proposed Response Response Status 0 C/ 00 SC 0 P = 0MyBallot # 15 BOOTH, MR BRAD J Individual Comment Type E Comment Status D P. Dawe - Editorials: capitals, column widths, font sizes, odd marks in figures, front matter. 802.3-2005 vs 802.3REVAam, singular/plural... SuggestedRemedy per file sent to editor Proposed Response Response Status W PROPOSED ACCEPT IN PRINCIPLE. Some of the changes will be made. Others will be deferred to the IEEE editorial staff. P = 0C/ 00 SC 0 MvBallot# COORDINATION, EDITORIAL Comment Type GR Comment Status D At the time of submission to the IEEE-SASB, or just prior to publication, you will need to supply email address for each member of the Working Group that worked on this standard. This will ensure that all members of the Working Group receive a complimentary

Response Status W

PDF of the published standard.

SuggestedRemedy

Proposed Response

PROPOSED ACCEPT.

P 1 C/ 00 SC 0 MyBallot # 70 L 6 GROW, ROBERT M Individual Comment Type E Comment Status D Based on MEC comments on another project, this is "Draft amendment to" SugaestedRemedy Change "of" to "to" Proposed Response Response Status W PROPOSED ACCEPT. P 2 CI 00 SC_0 MyBallot # 71 L 39 GROW, ROBERT M Individual Comment Status D Comment Type Some of the front matter introduction has been changed inconsistently. For example 802.3-2005 has "Section One" rather than "Section one". "Section One" is also used in the body of 2005 (one footnote). SuggestedRemedy Reconcile front matter in consultation with WG Chair and Editors. Incorporate valid comments submitted on other projects against this same front matter information. This

Reconcile front matter in consultation with WG Chair and Editors. Incorporate valid comments submitted on other projects against this same front matter information. This includes a rewrite of section descriptions for accuracy (e.g., not all 10 Mb/s specifications are in Section One), listing of anticipated published standards per MEC comments, and making consistent for all amendments per MEC comments.

Proposed Response Response Status W

PROPOSED ACCEPT IN PRINCIPLE.

This will be attempted but can never be fully accomplished till the last draft as other projects could continue to change the front matter.

C/ 01 SC 1.3 P 12 L 15 MyBallot # 72 GROW, ROBERT M Individual

Comment Type TR Comment Status X

The reference and Editor's note may not pass RevCom criteria and are confusing. While the Editor's Note may be appropriate for the reference on line 11, it isn't for the reference on 15.

SuggestedRemedy

If 2.1 is an approved draft awaiting publication then: "Edition 2.1 of ISO/IEC 11801 is an approved draft awaiting publication. When published this draft will superceed the 11801:2002 reference included in IEEE Std 802.3-2005, and the existing reference year can be changed to the current year of 11801 publication. If not published, the referenced draft should be included as a separate reference because it contains unique material required for this amendment. If 2.1 is not an approved draft, it is inappropriate to blindly give license to the publication editor to update when the final content is not known, and the reference should be to the latest draft known to have the relevant material for this amendment.

Proposed Response Response Status O

C/ 01 SC 1.4 P 12 L 36 MyBallot # 73 GROW, ROBERT M Individual

Comment Type ER Comment Status D

It is not wise to ignore MEC comments whether required or not. There was a pre-ballot MEC comment on 1.5 and it is appropriate to be consistent here.

SuggestedRemedy

List these items in alphanumeric order.

Proposed Response Response Status W

PROPOSED ACCEPT IN PRINCIPLE.

Change to order below: 1.4.xxx 10GBASE-T: . . .

1.4.xxx 64B/65B transmission code: . . .

1.4.xxx DSQ128: . . .

1.4.xxx Hybrid: A circuit . . .

1.4.xxx LDPC(1723,2048) frame: . . .

1.4.xxx Tomlinson-Harashima precoder (THP): . . .

C/ 01 SC 1.5 GROW, ROBERT M

P 13 Individual MyBallot # 74

Comment Type ER Comment Status D

Implement the pre-ballot MEC comment

SugaestedRemedy

List these items in alphanumeric order.

Proposed Response Response Status W

PROPOSED ACCEPT.

Put into the order shown below: Cat 6 Category 6 balanced cabling

AN Auto-Negotiation

DSQ double square

FIR finite impulse response

LD local device

LDPC low density parity check

LP link partner NP next page

SFDR spurious free dynamic range

THP Tomlinson-Harashima precoder

XNP extended next page

Cl 28 SC 28.2 P 14

L 33

MyBallot # 75

GROW, ROBERT M Individual

Comment Type ER Comment Status X

Reconcile base text.

SuggestedRemedy

Is Figures 28-14 to 28-17 in base text. These should probably be hot links "Figure 28-14 to Figure 28-18". An Editor's Note to explain if numbers are 2005 or autoadjusted would be appropriate.

Proposed Response

Response Status O

Cl 28 SC 28.2.1.1.2

Reconcile base text.

ER

(Figure 28-6) is existing text, remove underscore.

P 15 L 2 MyBallot # 76

CI 28 SC 28.2.1.2.2

G

P 15

L **42** MyBallot # 51

GROW, ROBERT M

SuggestedRemedy

Proposed Response

Comment Type

Individual

Comment Status X

Response Status 0

LAW, DAVID J

Individual

Comment Type

Comment Status X

*** Comment submitted with the file 1142200024-XNP_changes.FM attached ***

Subclause 28.2.1.2.2 'Technology Ability Field' specifies that bit D12 of the Base page encoding is Technology Ability field bit A7. As described in subclause 28.2.1.2.2 the meaning of the Technology Ability field bits are dependent on the value of the Selector field - the meaning of A7 when the Selector field value is IEEE 802.3 is defined in Annex 28B - in IEEE P802.3an bit A7 is defined as the Extended Next page (XNP) bit.

It is therefore not correct to state in the new subclause 28.2.1.2.3 'Extended Next Page' found in IEEE P802.3an that Extended Next page (XNP) is encoded in D12 of the base Link Code word or in subclause 28.2.3.4 that the XNP is a mandatory control bit (Page 16. line 19). This is only true when the Selector Field value is 'IEEE 802.3 as defined in Annex 28A'. When the Selector Field value is any other value defined in Annex 28A it is up to that particular standard to define the meaning of the Technology Ability field bits - they could choose to define A7 as XNP bit - but as the specification stands it would be guite legitimate, perverse, but legitimate, for them to define the XNP bit as any of the other Technology Ability field bits. It is also permissible to decide not to support Extended Next page and define A7 for their Selector Field value to mean something else.

This now means that we have now included a facility. Extended Next Page, in Clause 28 that is dependent on the Selector field value. I thought that was something we didn't do and that the functions in Clause 28 were available to all Auto-Negotiation uses. I think this is a pity as I believe that IEEE 1394c intend to use Auto-Negotiation Next Page Message code #5 and the ability to use Extended Next Pages would have made things more efficient for them. INCITS T11.2, who I understand are also about to ask for a Selector field (see item 8.1.4 of 'Draft minutes from FC-BaseT interim meeting on 1/19/06'), may also want to take advantage of Extended Next Page.

Now for them to be able to use Extended Next Page they will have to define a Ability bit in their standards, hopefully A7, to represent Extended Next page (XNP) bit. I agree that this is not a great effort and we can make sure we tell them to do this but it is all a bit confusing and an added complication.

SuggestedRemedy

[Option 1 - which I would recommend]. Redefine the Technology Ability Field to be seven bits long A[6:0] freeing up bit D12 of the Base Page encoding. I note that Table 55û10 '10GBASE-T Base and Next Pages bit assignments' already does this. To complete this, change the text in subclause 28.2.1.2.3 to state that the XNP bit is not supported for the Selector Field encoding 'IEEE Std 802.5' and 'IEEE Std 802.9' where bit D12 instead forms a eight Technology Ability Field - this will grandfather in existing implementations. Subclauses 28.2.4.1.3, Figures 28-2, 28-3 and 28B-1 changed to reflect the smaller Technology Ability Field. I have attached a FrameMaker file with the appropriate changes.

Register 7.16 and register 7.19 also need changed with XNP moved to 7.16.11 & 7.19.11 (see also my other comment related to these registers.

TYPE: TR/technical required ER/editorial required GR/general required T/technical E/editorial G/general COMMENT STATUS: D/dispatched A/accepted R/rejected RESPONSE STATUS: O/open W/written C/closed U/unsatisfied Z/withdrawn SORT ORDER: Page, Line

Li 42

Page 3 of 22 2/25/2006 10:38:22 AM This seems the best approach as all future uses of Auto-Negotiation will be able to use Extended Next page without having to define the XNP in there version of the Technology Ability field. It also seems reasonable to redefine what was a reserved bit, thought admittedly it was defined as a reserved Ability bit. We should however contact IEEE 1394 to make sure they are aware of this change, their draft is about to undergo sponsor ballot.

[Option 2] Subclause 28.2.1.2.3 'Extended Next Page' should be moved to be a subclause of 28.2.1.2.2 'Technology Ability Field'. Text should be added to make it clear that this bit is guaranteed to be encoded in bit D12 when the selector encoding is IEEE 802.3. For other values of the selector field the Extended Next Page bit may not exist, and when it does exist the bit position it is in will be defined by that standard.

Proposed Response Response Status O Cl 28 P 15 L **42** MyBallot # 55 SC 28.2.1.2.2

LAW, DAVID J Individual

Comment Type TR Comment Status X

Subclause 28.2.1.2.2 'Technology Ability Field' specifies that bit D12 of the Base page encoding is Technology Ability field bit A7. As described in subclause 28.2.1.2.2 the meaning of the Technology Ability field bits are dependent on the value of the Selector field - the meaning of A7 when the Selector field value is IEEE 802.3 is defined in Annex 28B - in IEEE P802.3an bit A7 is defined as the Extended Next page (XNP) bit.

It is therefore not correct to state in the new subclause 28.2.1.2.3 'Extended Next Page' found in IEEE P802.3an that Extended Next page (XNP) is encoded in D12 of the base Link Code word or in subclause 28.2.3.4 that the XNP is a mandatory control bit (Page 16. line 19). This is only true when the Selector Field value is 'IEEE 802.3 as defined in Annex 28A'. When the Selector Field value is any other value defined in Annex 28A it is up to that particular standard to define the meaning of the Technology Ability field bits - they could choose to define A7 as XNP bit - but as the specification stands it would be guite legitimate, perverse, but legitimate, for them to define the XNP bit as any of the other Technology Ability field bits. It is also permissible to decide not to support Extended Next page and define A7 for their Selector Field value to mean something else.

This now means that we have now included a facility. Extended Next Page, in Clause 28 that is dependent on the Selector field value. I thought that was something we didn't do and that the functions in Clause 28 were available to all Auto-Negotiation uses. I think this is a pity as I believe that IEEE 1394c intend to use Auto-Negotiation Next Page Message code #5 and the ability to use Extended Next Pages would have made things more efficient for them. INCITS T11.2, who I understand are also about to ask for a Selector field (see item 8.1.4 of 'Draft minutes from FC-BaseT interim meeting on 1/19/06'), may also want to take advantage of Extended Next Page.

Now for them to be able to use Extended Next Page they will have to define a Ability bit in their standards, hopefully A7, to represent Extended Next page (XNP) bit. I agree that this is not a great effort and we can make sure we tell them to do this but it is all a bit confusing and an added complication.

SuggestedRemedy

[Option 1 - which I would recommend]. Redefine the Technology Ability Field to be seven bits long A[6:0] freeing up bit D12 of the Base Page encoding. I note that Table 55û10 '10GBASE-T Base and Next Pages bit assignments' as well as regsiters 7.16 and 7.19 already do this.

To complete this, change the text in subclause 28.2.1.2.3 to state that the XNP bit is not supported for the Selector Field encoding 'IEEE Std 802.5' and 'IEEE Std 802.9' where bit D12 instead forms a eight Technology Ability Field - this will grandfather in existing implementations. Subclauses 28.2.4.1.3, Figures 28-2, 28-3 and 28B-1 changed to reflect the smaller Technology Ability Field. I have attached a FrameMaker file with the appropriate changes.

^{***} Comment submitted with the file 1142700024-XNP changes.FM attached ***

This seems the best approach as all future uses of Auto-Negotiation will be able to use Extended Next page without having to define the XNP in there version of the Technology Ability field. It also seems reasonable to redefine what was a reserved bit, thought admittedly it was defined as a reserved Ability bit. We should however contact IEEE 1394 to make sure they are aware of this change, their draft is about to undergo sponsor ballot.

[Option 2] Subclause 28.2.1.2.3 'Extended Next Page' should be moved to be a subclause of 28.2.1.2.2 'Technology Ability Field'. Text should be added to make it clear that this bit is guaranteed to be encoded in bit D12 when the selector encoding is IEEE 802.3. For other values of the selector field the Extended Next Page bit may not exist, and when it does exist the bit position it is in will be defined by that standard.

Proposed Response

Response Status 0

CI 28 SC 28.2.1.2.2 P 15

MyBallot # 56 L 42

LAW. DAVID J

Individual

Comment Type Comment Status R

Please ignore the 'General' category I placed against this subclause, it should have been 'Technical' but Myballot will not let category be changed after a comment is submitted. I have therefore submitted the comment again as a 'Technical require'.

SuggestedRemedy

See comment.

Response

Response Status C

REJECT.

This comment was entered incorrectly by the commentor and he has submitted his comment again and it shows up with a different number.

CI 28 SC 28.2.3.4 P 16

MvBallot # 16

BOOTH, MR BRAD J

Individual

Comment Type T Comment Status X

P. Dawe - Here and elsewhere, some "will be"s that maybe should be is, shall be, should be or as appropriate

SuggestedRemedy

Scrub the document for bad "will"s

Proposed Response

Response Status 0

Cl 28 SC 28.2.3.4.2

P 16 Individual L 50 MyBallot # 80

GROW, ROBERT M Comment Type E

Comment Status X

Inconsistent subclause number.

SugaestedRemedy

Change instruction to 28.2.3.4.2

Proposed Response

Response Status O

SC 28.2.3.4.12

P 17

L 59

MyBallot # 79

GROW, ROBERT M

Cl 28

Individual

Comment Type Comment Status X

Is this to mean Insert subclause 28.2.3.4.12 after existing 28.2.3.4.10 (renumbered to 28.2.3.4.11), and renumber subsequent subclauses.

SugaestedRemedy

Fix editing instruction per comment

Proposed Response

Response Status O

SC 28.2.4.1.8 CI 28

P 18 Individual MyBallot # 81

GROW, ROBERT M

Comment Status X Comment Type E

Reconcile base text.

SuggestedRemedy

Line 38, third column heading should be underscoreLine 46, 53, 55, 2005 is "Link

Partner"Line 59, 2005 is "Able"Page 19, Line 10, 2005 is "Able"

Proposed Response

Response Status O

TYPE: TR/technical required ER/editorial required GR/general required T/technical E/editorial G/general COMMENT STATUS: D/dispatched A/accepted R/rejected RESPONSE STATUS: O/open W/written C/closed U/unsatisfied Z/withdrawn SORT ORDER: Page, Line

18 Li 38

Page 5 of 22 2/25/2006 10:38:22 AM Cl 28 SC 28.2.4.1.8 P 19 L 12 MyBallot # 60
LAW, DAVID J Individual

Comment Type T Comment Status X

*** Comment submitted with the file 1143200024-table_28-8.fm attached ***

The State Diagram variable column defines the Next Page transmit as mr_np_tx[page_size:1] which seems to tie the size of these registers to a variable that is 'set during the entry to the NEXT PAGE WAIT state' (see page 20, line 54). Also when page_size does take the value 48 there is a mismatch between mr_np_tx and the MII register which is only 16 bits.

SuggestedRemedy

Suggest that a separate line be provided for mr_np_tx[16:1] and mr_np_tx[48:17]. These do have fixed mapping to the MII and MDIO register, also can add text to make it clear that the MII register set does not support extended next Page Operation.

See attached FrameMaker file.

Proposed Response Status O

Comment Type **E** Comment Status **X**Should probably be written for hot links.

SuggestedRemedy

Figure x to Figure y

Proposed Response Status O

Cl 28 SC 28.3.1 P 20 L 53 MyBallot # 64

LAW, DAVID J Individual

Comment Type T Comment Status X

I cannot find where page_size is set to any value, there is a comment in it's definition in the variables subclause that it will be set to the value 48 on entry to the NEXT PAGE WAIT state. There is however no statement if and when it will ve returned to the value of 16 which I assume may happen if the link is moved from one port to another that does not support extended Next pages.

SuggestedRemedy

I assume what is intended here is that page_size is set by the variable definition and will not be explicitly set in the state machine. Assuming this is correct:

- [1] Add page size to list of variables in note in lower right of Figure 28-18
- [2] Add the text 'NOTEùThis variable is set by this variable definition; it is not set explicitly in the state diagrams.' under the page_size variable
- [3] Is the text that page_size is set to 48 on entry to NEXT PAGE WAIT correct, I suspect simply the value is updated prior to entry to NEXT PAGE WAIT and it could be to 48 or to 16.
- [4] Doesn't the value of page_size also depend on the value of XNP received, even in the device supports extended next page and it is enabled it still should not transmit extended Next Pages if the XNP bit received is zero. If this is correct update the description of page size to include the condition of the last received XNP.

Proposed Response Status O

TYPE: TR/technical required ER/editorial required GR/general required T/technical E/editorial G/general COMMENT STATUS: D/dispatched A/accepted R/rejected RESPONSE STATUS: O/open W/written C/closed U/unsatisfied Z/withdrawn SORT ORDER: Page, Line

Pa **20** Li **53** Page 6 of 22 2/25/2006 10:38:23 AM

Cl 28 SC 28.3.1 P 20 Cl 28 SC 28.3.2 P 22 L 53 MyBallot # 65 L 7 MyBallot # 84 LAW, DAVID J Individual GROW, ROBERT M Individual Comment Type Comment Status X Comment Type E Comment Status X I cannot find where page size is set to any value, there is a comment in it's definition in the Reconcile base text. variables subclause that it will be set to the value 48 on entry to the NEXT PAGE WAIT SuggestedRemedy state. There is however no statement if and when it will ve returned to the value of 16 which Space should be underscore to get it 2005 editorial error corrected. For clarity Strike I assume may happen if the link is moved from one port to another that does not support through "5ms" and underscore "5 ms". extended Next pages. Proposed Response Response Status O SuggestedRemedy I assume what is intended here is that page size is set by the variable definition and will not be explicitly set in the state machine. Assuming this is correct: P 22 Cl 28 SC 28.3.2 L **19** MyBallot # 85 [1] Add page size to list of variables in note in lower right of Figure 28-18 GROW, ROBERT M Individual [2] Add the text 'NOTEùThis variable is set by this variable definition: it is not set explicitly in the state diagrams.' under the page_size variable Comment Type E Comment Status X [3] Is the text that page_size is set to 48 on entry to NEXT PAGE WAIT correct, I suspect Reconcile base text. simply the value is updated prior to entry to NEXT PAGE WAIT and it could be to 48 or to SuggestedRemedy [4] Doesn't the value of page_size also depend on the value of XNP received, even in the Ending "." isn't new text. Remove underscore device supports extended next page and it is enabled it still should not transmit extended Proposed Response Response Status O Next Pages if the XNP bit received is zero. If this is correct update the description of page_size to include the condition of the last received XNP. Proposed Response Response Status O P 23 CI 28 SC 28.3.3 L 39 MyBallot # 86 GROW, ROBERT M Individual CI 28 SC 28.3.2 P 21 MyBallot # 83 L 48 Comment Status X Comment Type E GROW, ROBERT M Individual Reconcile base text. Comment Type E Comment Status X SuggestedRemedy Reconcile base text. Needs the ending "." included in 2005. SuggestedRemedy Proposed Response Response Status O Ending "." isn't new text. Remove underscore Proposed Response Response Status O Cl 28 SC 28.5 P 25 MyBallot # 89 GROW, ROBERT M Individual Comment Type ER Comment Status X Reconcile base text. SuggestedRemedy

Is "link" in 2005.

Proposed Response

TYPE: TR/technical required ER/editorial required GR/general required T/technical E/editorial G/general COMMENT STATUS: D/dispatched A/accepted R/rejected RESPONSE STATUS: O/open W/written C/closed U/unsatisfied Z/withdrawn SORT ORDER: Page, Line

Pa **25** Li **4**

Response Status 0

Page 7 of 22 2/25/2006 10:38:23 AM

Cl 28 SC 28.5.1 P 25 C/ 30 SC 30.5.1.1.17 P 28 MyBallot # 94 L 14 MyBallot # 90 L 7 GROW, ROBERT M Individual GROW, ROBERT M Individual Comment Type ER Comment Status X Comment Type E Comment Status D Reconcile base text. Grammar SuggestedRemedy SuggestedRemedy Is "protocol" in 2005 delete "a" Proposed Response Proposed Response Response Status O Response Status W PROPOSED ACCEPT IN PRINCIPLE. Cl 28 SC 28.5.4.3 P 26 L 7 MyBallot # 91 Page number entered is incorrect. I assume it applies to page 29. GROW, ROBERT M Individual See response to comment #63 on same item. Comment Status X Comment Type ER C/ 30 SC 30.3.2.1.2 P 28 L 48 MyBallot # 93 Reconcile base text. GROW, ROBERT M Individual SuggestedRemedy Comment Type E Comment Status X The subclause number of item 3 in 2005 is 28.2.1.1.1. Either correct base text or mark Incorrect marking changes as appropriate. Proposed Response Response Status O SuggestedRemedy As an insert, it doesn't need to be underscore. Also line 57, page 28 line 6, page 30 line 29 Proposed Response Response Status O SC 28.5.4.8 P 26 MyBallot # 92 CI 28 L 38 GROW, ROBERT M Individual Comment Type E Comment Status X C/ 30 SC 30.5.1.1.2 P 29 L **7** MyBallot # 63 Reconcile base text. LAW, DAVID J Individual SuggestedRemedy Comment Type Comment Status D Change marking would be clearer if entire value string were struck out and new entire value Typo. string were underscored (tough to see a strike through of a dash). Change Page 27 line 3 SuggestedRemedy consistently. 'Insert a new management attributes ..' should read 'Insert the following new management Proposed Response Response Status O attributes ..' Proposed Response Response Status W PROPOSED ACCEPT.

TYPE: TR/technical required ER/editorial required GR/general required T/technical E/editorial G/general COMMENT STATUS: D/dispatched A/accepted R/rejected RESPONSE STATUS: O/open W/written C/closed U/unsatisfied Z/withdrawn SORT ORDER: Page, Line

Pa **29** Li **7** Page 8 of 22 2/25/2006 10:38:23 AM

Comment Type T Comment Status D

This is a pile-on to comment 113 by Tom Lindsay on D3.0. Surveying additional module vendors and EDC vendors since the last meeting has revealed a growing concern that the TWDP limit should be raised to allow more manufacturing margin and that this would not be a problem for EDC chips on the market given the current margin in the link budget.

SuggestedRemedy

Increase the TWDP limit to 5.0 dB.

Proposed Response Status W

PROPOSED REJECT.

This is a comment on clause 68 which is out of the scope of the 802.3an project

Comment Type G Comment Status D

This is a pile-on to comment 113 by Tom Linday on D3.0. Surveying additional module vendors and EDC vendors since the last meeting has revealed a growing concern that the TWDP limit should be raised to allow more manufacturing margin and that this would not be a problem for EDC chips on the market.

SuggestedRemedy

Increase the TWDP limit to 5.0 dB.

Proposed Response Status W

PROPOSED REJECT.

This comment is on clause 68, which is out of the scope of the 802.3an project.

 CI 05
 SC 5
 P 33
 L 31
 MyBallot # 6

 SWENSON, NORMAN L
 Individual

Comment Type T Comment Status R

This is a pile-on to comment 113 by Tom Lindsay on D3.0. Surveying additional module vendors and EDC vendors since the last meeting has revealed a growing concern that the TWDP limit should be raised to allow more manufacturing margin and that this would not be a problem for EDC chips on the market given the current margin in the link budget.

SuggestedRemedy

Increase the TWDP limit to 5.0 dB.

Response Status C

REJECT.

This comment appears to be on 802.3aq and it is out of the scope of the 802.3an project

CI 45 SC 45.2.7.1 P 35 L 30 MyBallot # 14 MARRIS. ARTHUR Individual

Comment Type T Comment Status X

The following text has been added to 802.3ap at the end of subclause 45.2.7.1 (backplane Ethernet) to address multispeed (1000BaseT and 100BASE-TX) operation.

"A device that supports multiple port types may implement both Clause 22 control register operation and Clause 45 control register operation. Some control functions have been duplicated in both definitions. The register bits to control these functions are simply echoed in both locations, any reads or writes to these bits behave identically whether made through the Clause 22 location or the Clause 45 location."

This text is either out-of-date or properly belongs in 802.3an.

SuggestedRemedy

Consider adding the above text to 802.3an.

Proposed Response Response Status O

Cl 45 SC 45.2.1.1.3 P 37 Cl 45 SC 45.2.1.6 P 38 L 35 MyBallot # 12 L 43 MyBallot # 17 MARRIS, ARTHUR Individual BOOTH, MR BRAD J Individual Comment Type T Comment Status X Comment Type T Comment Status X Bits 5 through 2 may be used to select EFM copper PHYs or 1000BASE-KX which would P. Dawe - No PMD for 10BASE-T and 100BASE-T. be included in '10, 100 or 1000 Mb/s' SugaestedRemedy SuggestedRemedy Remove non-existent PMDs. Also in PICS 10T. Delete the recently added text 'For devices not operating at 10, 100 or 1000 Mb/s,' Proposed Response Response Status O Proposed Response Response Status O Cl 45 SC 45.2.1.10 P 40 MyBallot # 8 L 27 P 37 C/ 45 SC 45.2.1.1.3 MyBallot # 13 L 40 MARRIS, ARTHUR Individual MARRIS. ARTHUR Individual Comment Type E Comment Status X Comment Type T Comment Status X Delete 10G from title of Table 45-11 Insert additional paragraph at end of 45.2.1.1.3 for clarity. SuggestedRemedy When set to 0000, bits 5:2 select the use of a 10G PMA/PMD. More specific selection is Delete 10G from title of Table 45-11 performed using the PMA/PMD control 2 register (Register 1.7) (see 45.2.1.6). Proposed Response Response Status O SuggestedRemedy as above C/ 45 SC 45.2.1.10.1 P 41 L 5 MyBallot # 18 Proposed Response Response Status O BOOTH, MR BRAD J Individual Comment Type E Comment Status X Cl 45 SC 45.2.1.4 P 37 L 46 MvBallot # 7 P. Dawe - The descriptions of ability bits are not consistent in 45. In the text, we have MARRIS. ARTHUR Individual 'PMA/PMD is able to operate as 10GBASE-LRM' but 'PMA/PMD is able to support a 10GBASE-CX4 PMA/PMD type'. "Support' is not precise (that's why we sometimes use it in Comment Status X Comment Type E objectives!). Nor accurate: 'The floor supports the table, the computer supports Linux, the The table number for speed ability is 45-6 not 45-5 as stated in the document modem supports PPP. PCS is able to support PRBS31 pattern testing...' This should be harmonized across .3ap. .3ag (I have made a comment), and in the next revision. SuggestedRemedy SuggestedRemedy Chenge 45-5 to 45-6 Change to 'operate as 10GBASE-T.' (6 times. I think) Proposed Response Response Status O Proposed Response Response Status O

Comment Type T Comment Status X

Insert subclauses for KR and KX4 ability bit definitions.

SuggestedRemedy

45.2.1.10.5 10GBASE-KR ability (1.11.4)

When read as a one, bit 1.11.4 indicates that the PMA/PMD is able to support a 10GBASE-KR PMA/PMD type. When read as a zero, bit 1.11.4 indicates that the PMA/PMD is not able to support a 10GBASE-KR PMA/PMD type.

45.2.1.10.6 10GBASE-KX4 ability (1.11.3)

When read as a one, bit 1.11.3 indicates that the PMA/PMD is able to support a 10GBASE-KX4 PMA/PMD type. When read as a zero, bit 1.11.3 indicates that the PMA/PMD is not able to support a 10GBASE-KX4 PMA/PMD type.

Proposed Response Response Status **0**

Comment Type T Comment Status X

Need to add a note saying that these registers do not apply to Clause 37 auto-negotiation.

SuggestedRemedy

Insert.

Note: These registers are not used for Clause 37 1000BASE-X autonegotiation. Clause 37 defines the registers used for Clause 37 1000BASE-X autonegotiation.

Proposed Response Status O

CI 45 SC 45.2.7.2 P 54 L 30 MyBallot # 11 Individual

with the control to t

Comment Type **E** Comment Status **X**In table 45-119 the two lower order reserved bit should be labelled 1:0

SuggestedRemedy

Change 2:0 to 1:0

Proposed Response Status O

Cl 45 SC 45.2.7.2 P 54 L 30 MyBallot # 31

MARRIS, ARTHUR Individual

Comment Type T Comment Status X

In Table 45-119 there is no bit definition for 'Link Partner Auto-Negotiation Able' as defined by bit 6.0 in Table 28-5. There is a corresponding state machine variable mr_lp_autoneg_able (Register bit 6.0). There is a definition of Auto-Negotiation able device in 28.2.2.1. So 802.3an should support a mirror of this bit in Clause 45 for backwards compatibility. This variable is in 802.3an-D3.0 Table 28-8 but there is no mapping of this bit to Cl.45 MDIO register.

SuggestedRemedy

Add following bit to Table 45-119 AN status register:

7.1.0 Link Partner Auto-Negotiation Ability 1 = LP is able to perform Auto-Negotiation 0 = LP is not able to perform Auto-Negotiation

Add subclause

Link Partner Auto-Negotiation Ability (7.1.0)

The Link Partner Auto-Negotiation Ability bit shall be set to one to indicate that the Link Partner is able to participate in the auto-negotiation function. This bit bit shall be reset to zero if the Link Partner is not auto-negotiation able.

Proposed Response Status O

CI 45 SC 45.2.7.6 P 56 L 24 MyBallot # 54

LAW. DAVID J Individual

Comment Status X

, ttt, D/ttlD 0

The register definition for 7.16 and 7.19 treat the Technology Ability field as a 7 bit field and the Extended next page bit as being a separate bit. As I have pointed out in another comment this definition is not supported by the text in subclause 28.2.1.2.2 'Technology Ability Field' which specifies this field as 8 bits wide. Only when the Selector field value is IEEE 802.3, as defined in Annex 28B, is bit A7 the Extended Next page (XNP) bit.

SuggestedRemedy

Comment Type T

Personally I would suggest that this definition is correct, that my other comment be accepted, and the Clause 28 text changed to aligned with this register. If however this is not accepted this register should be changed to provide a 8 bit Technology Ability field and the Extended Next page (XNP) bit removed.

Proposed Response Status O

TYPE: TR/technical required ER/editorial required GR/general required T/technical E/editorial G/general COMMENT STATUS: D/dispatched A/accepted R/rejected RESPONSE STATUS: O/open W/written C/closed U/unsatisfied Z/withdrawn SORT ORDER: Page, Line

Pa **56** Li **24** Page 11 of 22 2/25/2006 10:38:23 AM

Cl 45 SC 45.2.7.8 P 57 L 50 MyBallot # 61 LAW. DAVID J Individual

Comment Type Comment Status X

Maybe this is intended but since it is stated that these registers contain 'the next page link codeword to be transmitted when extended next page is enabled and that, as far as I can see, there is no Clause 45 alternative register to use when extended next page is not enabled this Clause 45 Auto-Negotiation interface cannot be used to communicate with a, for example, legacy 1000BASE-T device.

Don't guite understand the need for this restriction, the state machine would seem to happily ignore the additional bits in registers 7.23 and 7.24 if extended Next Page exchange is not occurring. Similarly is all that is required on the receive side is to ignore registers 7.26 and 7.27.

SuggestedRemedy

See comment, if this is an inteded restriction do nothing.

Proposed Response Response Status O

C/ 45 SC 45.2.7.8 P 58 L 20 MyBallot # 57

LAW, DAVID J Individual

Comment Type TR Comment Status X

The implication in the Name column that register bits 7:22.10:0 map to the Message Code Field: bits 7.23:15:0 map to bits U15:U0: and 7:24:15:0 map to U31:U16 is only correct for the Extended Message page Encoding (see figure 28-13 in IEEE P802.3an).

When a Extended Unformatted Page is being sent the mapping will be as follows: register 7:22.10:0 will map to U0:U10; 7.23:15:0 will map to bits U26:U11; and 7:24:15:0 mapping to U42:U27.

Note - this assumes that Table 28-8 in IEEE P802.3an is correct in that there is a fixed mapping from these registers to mr np tx.

SuggestedRemedy

Suggest that for 7:22.10:0 'Message Code Field' be changed to read 'Message/Unformatted Code Field'; that for 7.23:15:0 'Unformatted Code field (bits U15:U0)' be changed to read 'Unformatted Code field 1'; and that for 7:24:15:0 'Unformatted Code field (bits U31:U16)' be changed to read 'Unformatted Code field 2'. These new names should also be reflected in Table 28-8.

The text related to these registers may also need to be re-worded due to this.

Proposed Response Response Status O Cl 45 SC 45.2.7.9

TR

P 58

Comment Status X

MyBallot # 59

LAW, DAVID J Individual

The implication in the Name column that register bits 7:25.10:0 map to the Message Code Field: bits 7.26:15:0 map to bits U15:U0; and 7:27:15:0 map to U31:U16 is only correct for the Extended Message page Encoding (see figure 28-13 in IEEE P802.3an).

When a Extended Unformatted Page is received the mapping will be as follows: register 7:25.10:0 will map to U0:U10: 7.26:15:0 will map to bits U26:U11: and 7:27:15:0 mapping to U42:U27.

Note that this assumes a similar mapping as that between the transmit registers and the mr np tx state diagram variable. As it stands I don't think there is any definition for where the bits U32:U42 would map to in this register space.

SuggestedRemedy

Comment Type

Suggest that for 7:25.10:0 'Message Code Field' be changed to read 'Message/Unformatted Code Field'; that for 7.26:15:0 'Unformatted Code field (bits U15:U0)' be changed to read 'Unformatted Code field 1': and that for 7:27:15:0 'Unformatted Code field (bits U31:U16)' be changed to read 'Unformatted Code field 2'.

Text will need to be added to provide the mapping of bits U16:U0 for received Extended Message pages and bits U42:U0 for received Extended unformatted pages.

Proposed Response Response Status O

CI 28C SC 28C.6 P 71 MyBallot # 1 L 58 THALER, PATRICIA A Individual

Comment Type TR Comment Status X

Figure 28C-1 shows the bits being sent in a different order than the text of 28C.6 defines. This is somewhat a service to humanity change because 10GBASE-T did not introduce the text or the figure, but 10GBASE-T adds extended next pages which make it much more practical to use Message #5.

Therefore, it would be best to fix this figure as soon as possible to avoid incompatible implementations.

SugaestedRemedy

Since the text was in the original Annex 28C and the figure was added recently, the figure should be changed to match the text.

To do that, each 11-bit group will need to be flipped. An example of how the change could be made is the similar figure in 802.3ap/d2.3 Annex 73A.

Proposed Response Response Status O

TYPE: TR/technical required ER/editorial required GR/general required T/technical E/editorial G/general COMMENT STATUS: D/dispatched A/accepted R/rejected RESPONSE STATUS: O/open W/written C/closed U/unsatisfied Z/withdrawn SORT ORDER: Page, Line

Pa 71 Li 58

Page 12 of 22 2/25/2006 10:38:23 AM CI 28C SC 28C.6 P 72 L 15 MyBallot # 32

LAW, DAVID J Individual

Comment Type T Comment Status X

*** Comment submitted with the file 1139100024-figure_28C-1.fm attached ***

The bit order of Figure 28C-1 is not clear as neither LSB/MSB of D0/D15 is marked. If it were assumed that this figure was in the normal order, the transmit order, with LSB on the left and MSB on the right the figure would be interpreted incorrectly.

Instead my understanding, based on the greyed out portion to the right of each user code representing the T,Ack2,MP,Ack & NP bits, is that the figure shows the pages in the order they are transmitted, with the first transmitted page on the left, but shows the bits from each page with the first transmitted bit of each page on the right.

Regardless, this is all far too subtle and could easily be misinterpreted. This therfore should be clarified as part of the IEEE P802.3an project as the addition of Extended Next Page, with the resultant reduction in the time taken to exchange multiple Next Pages, may increase the likelihood of this message being implemented.

SuggestedRemedy

[1] Add to Figure 28C-1 annotations for: MSB/LSB on the OUI and dependant values; Next Pages Types (Message or Unformatted); D15 and D0 for the Next Pages.

[2] Add a note to Figure 28C-1 that the bit order is the opposite from normal, and in particular from Figure 28-11 and 28-12 which define the Message and Unformatted Next Pages used.

Please find an updated version of Figure 28C-1 with these changes in the FrameMaker file attached.

Proposed Response Response Status O

CI 55 SC 55 P 79 L 4 MyBallot # 19
BOOTH, MR BRAD J Individual

Comment Type E Comment Status X

P. Dawe - In time, this note will become stale and create maintenance work.

SuggestedRemedy

If you made this note an editorial note it would vanish at the next amalgamation, which I think is what we want.

Proposed Response Status O

Comment Type T Comment Status X

P. Dawe - Draft says 'the Management Function Interface is specified in Clause 45.' Not true, it's the Management Data Input/Output (MDIO) Interface that is defined in 45.

SuggestedRemedy

I don't know what to suggest because it appears from the next paragraph that your 'Management Function Interface' is the Technology Dependent Interface. If you mean an existing thing, use its existing name.

Proposed Response Status O

CI 55 SC 55.2.2 P 87 L 14 MyBallot # 21

BOOTH, MR BRAD J Individual

Comment Type T Comment Status X

P. Dawe - The thing labelled "MANAGEMENT" isn't: management is the other side if the MDIO. I commented on this diagram last time.

SuggestedRemedy

Could call this box "PCS/PMA control" or some such. Or just leave it blank: there isn't anything in there, apart from MDIO/MDC and TDI interfaces, that's specified in the standard.

Proposed Response Status O

Cl 55 SC 55.2.2 P 87 L 32 MyBallot # 22 BOOTH, MR BRAD J Individual

Comment Type T Comment Status X

P. Dawe - Per 28, PMA connects downwards (not sideways) via TDI to AN (not directly to MDI)

SuggestedRemedy

Reconcile, or correct the diagram.

Proposed Response Status O

Cl 55 SC 55.3.2.2 P 93 MyBallot # 23 L 10 BOOTH, MR BRAD J Individual Comment Type T Comment Status X

P. Dawe - Transmit data-units are sent to the PMA or service interface via the PMA UNITDATA request primitive, respectively. What choice, with respect to what?

SuggestedRemedy

Should this say "sent to the PMA service interface via the PMA UNITDATA.request primitive."?

Proposed Response Response Status O

Cl 55 SC 55.3.2.2.4 P 97 L 14 MvBallot # 24 BOOTH, MR BRAD J Individual

P. Dawe - Color. I remember this was the subject of a comment a long while back (might have been in .3ap)

Comment Status D

SuggestedRemedy

Comment Type E

Get rid of the color, use shading and hatching: but check it renders OK through pdf.

Proposed Response Response Status W

PROPOSED REJECT.

There are no colors on the page.

CI 55 SC 55.3.2.2.7 P 97 MvBallot # 25 L 54 BOOTH, MR BRAD J Individual

Comment Status X Comment Type E

P. Dawe - D3.0 # 113 refers. Ordered sets, Table 55-1 (almost), Idle, start, and more are just the same as 49.2. But not error, invalid blocks.

SuggestedRemedy

Suggest delete "10GBASE-R" from Table 49-1 (twice) then reduce 55.3.2.2.7 to "Ordered sets are as defined in 49.2.4.5." (eliminating Table 55-1). Similarly with Idle, start, and more.

Proposed Response Response Status O CI 55 SC 55.4.2.5 P 117 L 17 MyBallot # 46 UNGERBOECK, GOTTFRIED Individual

Comment Status D Comment Type ER

The entire section has gone through many changes without serious effort to improve the logical order of presenting the material. Generally, the section lacks clarity and conciseness. With more changes to be made, the time has come for a major overhaul of this section.

SuggestedRemedy

Rewrite the entire section PHY Control Function and elevate it to a higher heading level reflecting the importance of the section.

Proposed Response Response Status W

PROPOSED REJECT.

See response to comment 164 on D3.0.

The suggested remedy does not provide sufficient guidance for changes to the draft. The comment suggests no error within the draft, only a style preference.

Cl 55 SC 55.4.2.5 P 117 L 26 MyBallot # 44 UNGERBOECK, GOTTFRIED Individual

Comment Type E Comment Status X

InfoFields are decoded "at a sampling rate"?

SuggestedRemedy

Replace text by "... but is required to decode IFs frequently enough to enable correct actions in a timely manner prior to the expiration of timers and/or transition counters reaching zero values."

Proposed Response Response Status O

TYPE: TR/technical required ER/editorial required GR/general required T/technical E/editorial G/general COMMENT STATUS: D/dispatched A/accepted R/rejected RESPONSE STATUS: O/open W/written C/closed U/unsatisfied Z/withdrawn SORT ORDER: Page, Line

Pa 117 Li 26

Page 14 of 22

Cl 55 SC 55.4.2.5

L **26** N

MyBallot # 45

UNGERBOECK, GOTTFRIED

P 117 Individual

Comment Type E Comment Status X

InfoFields are decoded "at a sampling rate"?

SuggestedRemedy

Replace text by "... but is required to decode IFs frequently enough to enable correct actions in a timely manner prior to the expiration of timers and/or transition counters reaching zero values."

Proposed Response

Response Status W

This comment is identical to comment #44 submitted by the same commentor. See response to comment #44.

C/ 55 SC 55.4.2.5.6

P 119

L **22** MyBallot # 43

UNGERBOECK, GOTTFRIED

Individual

Comment Type TR Comment Status X

The bits in the message field are in one way redundant and in another way incomplete. It is not always possible to infer from a received message field the current state of the link partner.

SuggestedRemedy

Adopt the following better encoding of message bits. Two state-indicator bits indicate the state of the transmitting transceiver: 00 = PMA_Training_M or _S (forget about the 'Init_'), 01 PMA_PBO_Exch, 10 = PMA_Coeff_Exch, 11 = PMA_Fine_Adjust. One bit 'loc_rcvr_status' indicates whether or not a transceiver is ready to transition to the next state. In state PMA_Training_M, the additional bit 'en_slave_tx' is needed. In state PMA_Coeff_Exch, the additional bit 'coeff_exch_done' is required; 0 indicates IF coefficient exchange format, and 1 indicates IF transition counter format and that coefficient exchange in both directions is completed. The same bit position can be used for 'en_slave_tx' and 'coeff_exch_done'. Hence, only four message bits are needed.

Furthermore, the state-indicator bits provide a useful function during transceiver testing and determining error conditions.

Bits 'trans_to_Coeff_Exch', 'trans_to_Fine_Adjust', and 'trans_to_PCS_Test' are not needed. Initially in each state the transition counter is zero. The corresponding state transitions are announced by setting the transition counter to a non-zero value. The transition occurs when the transition counter reaches the value zero. At this time the state indicator bits assume the values for the next state.

Proposed Response

Response Status O

CI 55 SC 55.4.3.1 KOEMAN, HENRIECUS P 119

L **26** MyBallot # 34

Individual

Comment Type TR

Comment Status X

There are two comments: 1) Non-overlapping ranges are needed in the length column to match those in the received signal column. For example " $0 \le \text{length} < 35$ " or " $0 \le \text{length} < 35$ ". 2) During evaluation of PSAXtalk performance, the measured IL will always be used (instead of length). Relevant measured values should be used to estimate the power backoff.

SuggestedRemedy

Replace the "length" column information with specific range information: " $0 \le \text{length} < 35$ " or " $0 \le \text{length} < 35$ ". Also, add an informative column with the IL limits. IL @ 250 MHz (dB)(Reference), $0 \le \text{IL} < 9.9$, $9.9 \le \text{IL} < 13.4$,

13.4<|L<=16.9,16.9<|L<=20.3,20.3<|L<=23.8,23.8<|L<=27.3,27.3<|L<= 30.7,|L> 30.7

Proposed Response

Response Status W

Is this the same as comment 41 on D3.0?

Cl 55 SC 55.4.2.5.7

P 120

L **26** MyBallot # 48

ZIMMERMAN, GEORGE A

Individual

Comment Type E Comment Status X

The transmission mode to which the reported SNR margin refers needs to be specified. All that I am aware of think this SNR margin is relative to the SNR required in data mode (DSQ transmission); however, because SNR margin is reported while infofields are being transmitted in PAM-2, it could be misunderstood to be relative to the SNR required for transmission of PAM-2.

SuggestedRemedy

Add the following text, (easiest at the end of the existing paragraph): SNR Margin is relative to the SNR required for reception of LDPC-coded DSQ128 at 1e-12 BER in data mode.

Proposed Response

Response Status O

Cl 55 SC 55.4.2.5 P 121 L MyBallot # 69
TELLADO, JOSE Individual

Comment Type T Comment Status X

Startup can be simplified without loss of robustness by reducing the Master fixed PBO settings from 10dB followed by 6dB if the Slave does not respond to a single fixed PBO setting of 10dB or 8dB

SuggestedRemedy

Draft3.1 with changes will be provided

Proposed Response Status W

See comments 69 and 42

Comment Type TR Comment Status X

There is no need for the MASTER to advance in state PMA_Training_Init_M to a "second fixed" transmit power level. The "first fixed" transmit power level corresponding to a power back-off of 10 dB will always be sufficient for the SLAVE to decode In-foFields, or otherwise reliable operation in states PCS_Test and PCS_Data cannot be achieved and the link will never work. --- Notice that for reliable decoding of LDPC-encoded 128-DSQ signals a decision-point SNR of at least 24 dB is needed. Hence, with a power back-off of 10 dB a decision-point SNR of least 14 dB must be achievable, which is well sufficient for reliable decoding of InfoFields (SNR = 14 dB -> BER = 2.7e-7 for uncoded 2-PAM). The provision for advancing in state PMA_Training_Init_M to the "second fixed" transmit power level can therefore be eliminated.

SuggestedRemedy

Operations should be as follows. In state PMA_Training_Init_M the MASTER starts transmission with a power back-off of 10 dB. When it has converged its echo and NEXT cancellers, the MASTER sends en_slave_tx = 1 in its InfoFields. After detecting PMA_training frames from the SLAVE and appropriate adjustment of its receiver the MASTER will be able to decode InfoFields from the SLAVE. Otherwise, an error situa-tion exists. The MASTER then sends loc_rcvr_status = OK in its InfoFields. This indicates to the SLAVE that the MASTER is able to decode InfoFields and ready to tran-sition to the PMA_PBO_Exch state. When the MASTER receives loc_rcvr_status = OK from the SLAVE it stores this as rem_rcvr_status = OK. When loc_rcvr_status = OK and rem_rcvr_status = OK the MASTER transitions to state PMA_PBO_Exch.

The same condition is used for the transition of the SLAVE from state PMA_Training_ Init_S to state PMA_PBO_Exch. In state SILENT, loc_rcvr_status is set to NOT_OK.

Everything else in this connection should be eliminated, in particular: master_init step, maxincr_timer, slave_detect, timing_lock_OK, PBO_increase, loc_SNR_margin, state INIT_master_ init_step, the top part of the MASTER transition counter state in Figure 55-25, etc. --- It is obvious that loc_rcvr_status = OK sent by the MASTER implies that the MASTER has detected the SLAVE signal! Similarly, when loc_rcvr_status = OK is sent by the SLAVE, the SLAVE has obviously acquired timing!

Proposed Response Response Status W

See comments 69 and 42

See response to comment #69

TYPE: TR/technical required ER/editorial required GR/general required T/technical E/editorial G/general COMMENT STATUS: D/dispatched A/accepted R/rejected RESPONSE STATUS: O/open W/written C/closed U/unsatisfied Z/withdrawn SORT ORDER: Page, Line

Pa **121** Li **44** Page 16 of 22 2/25/2006 10:38:24 AM

SC 55.7.3.2.1 Cl 55 P 123 L 24 MyBallot # 33 ARY, JACOB BEN Individual

Comment Type T Comment Status X

Not clear and too complicated,

SuggestedRemedy

change to "When the computed value at a certain frequency exceeds 67 dB, the result at that frequency

is for information only.

Proposed Response Response Status O

P 124 CI 55 SC 55.4.3.1 L 124 MyBallot # 47 UNGERBOECK, GOTTFRIED Individual

Comment Type TR Comment Status X

The sign preceding the summation in equation (55-4) is wrong. ---- For TH precoding the overall channel extending from the precoder output to the output of the adaptive feedforward equalizer in the receiver is equalized towards a causal monic response c(D) = 1 + c1*D + c2*D^2 + c3*D^3 + The TH precoder pre-filters the sequence of transmit symbols a(D) by 1/c(D) and adds to each symbol an integer multiple of 2M such that the precoder output remains bounded in the interval [-M.+M), where M = 16 in the case of 10GBASE-T. Writing the precoder output as $b(D) = a(D)+k(D)*2M \hat{u} [c(D)-1]*b(D)$ corresponds to b(D) = [a(D)+k(D)*2M]/c(D), where k(D) is a sequence of integers.

SuggestedRemedy

Hence, the sign preceding the summation in equation (55-4) must be minus (-), ----Suggested further notational changes: use 'b' for the augmented symbols 'a + k*32' and 'x' for the precoder output; then in equation (55-6) replace 'a sub agmt' by 'b'.

Proposed Response Response Status O CI 55 SC 55.4.3.1 P 125

MyBallot # 62

L 8

Individual

Comment Type T Comment Status D

The PBO requested requires a 'shall' statement

SuggestedRemedy

TELLADO, JOSE

Change "The minimum power backoff levels are decribed in the power backoff schedule in Table 55-6"

"The minimum power backoff level requested shall comply with the power backoff schedule in Table 55-6"

Modify PMF19

PMF19 PMA transmit power backoff settings 55.4.3.1 M Yes []

Moreover insert new PICS in PMF

PMF20 Minimum power backoff requested 55.4.3.1 M Yes [] as per Table 55û6

Proposed Response Response Status W

PROPOSED ACCEPT.

CI 55 SC 55.4.3.1 P 125 L 9 MyBallot # 68

TELLADO, JOSE Individual

Comment Type T Comment Status D

The Slave has the additional restriction of PBO selection described in the PMA PBO Exch

SuggestedRemedy

Insert the text: "Additionally, the Slave shall select a PBO level as described in the PMA_PBO_Exch state of 55.4.2.5.14"

Proposed Response Response Status W

PROPOSED ACCEPT.

TYPE: TR/technical required ER/editorial required GR/general required T/technical E/editorial G/general COMMENT STATUS: D/dispatched A/accepted R/rejected RESPONSE STATUS: O/open W/written C/closed U/unsatisfied Z/withdrawn SORT ORDER: Page, Line

Pa 125

Page 17 of 22 2/25/2006 10:38:24 AM

SC 55.4.5.1 Cl 55 P 127 Cl 55 L 24 MyBallot # 53 TAICH, DIMITRY BOOTH, MR BRAD J Individual Comment Type Ε Comment Status X *** Comment submitted with the file 1142300024-ValidPBOSettings.doc attached *** PBO settings description is distributed over several chapters and sometime redundant (does not have single reference source). SuggestedRemedy Please add "Valid PBO Settings" table to the PBO variable description (see attached document). Please refer this table every time specific PBO settings are described. Please use this table also as a reference for the all 3 PBO related variables û PBO, PBO next and PBO tx û all on page 127. Proposed Response Response Status O Comment Type E CI 55 SC 55.4.5.1 P 128 L 49 MyBallot # 52 TAICH, DIMITRY Individual Comment Type Comment Status X transition count variable description û this paragraph describes essential start-up mechanism behavior rather then defines state-machine variables. In my opinion this text

should be moved to chapter 55.4.2.5.14, page 123, line 3. This change will makes startup description clearer, and concentrate more info in one place

SuggestedRemedy

As comment suggests

Proposed Response Response Status O

CI 55 SC 55.4.6.1 P 130 MyBallot # 66 L 31

TELLADO, JOSE Individual

Comment Type T Comment Status D

If loc_SNR_margin=OK, the Master receiver must have detected the slave

SuggestedRemedy

Eliminate the redundant slave detect=1 condition

Proposed Response Response Status W

PROPOSED ACCEPT.

SC 55.5

P 134 L 11 Individual

MyBallot # 26

Comment Type T

Comment Status D

P. Dawe - Various desirable changes identified by 802.3/Cor 1

SuggestedRemedy

Make changes to keep in step with 802.3/Cor 1

Proposed Response Response Status W

PROPOSED ACCEPT IN PRINCIPLE.

See response to comment #41

Cl 55 SC 55.5.1 P 134

L 11 MyBallot # 41

MCCLELLAN, MR BRETT A

Individual

Comment Status D

Based on changes in Draft 802.3-2005/Cor 1/D1.1 Diff I think the following changes should

- page 134 lines 11 to 22:
- line 11 change "separation" to "isolation".
- lines 15 and 22 change "Vdc" to "V dc"
- lines 15 and 21 change 5.3.2 to 5.2.2
- line 19 change "annex" to "Annex"

SuggestedRemedy

Make changes as indicated.

Proposed Response

Response Status O

TYPE: TR/technical required ER/editorial required GR/general required T/technical E/editorial G/general COMMENT STATUS: D/dispatched A/accepted R/rejected RESPONSE STATUS: O/open W/written C/closed U/unsatisfied Z/withdrawn SORT ORDER: Page, Line

Pa 134 Li 11

Page 18 of 22 2/25/2006 10:38:24 AM

CI 55 SC 55.5.3.3 P 138 L 13 MyBallot # 27

BOOTH, MR BRAD J Individual

Comment Type T Comment Status D

P. Dawe - If a signal had edges that were alternately 1 ps early and 1 ps late, the RMS itter is 1 ps. This formula gives 2 ps. Same issue as D3.0#119.

SuggestedRemedy

Please explain. Perhaps divide by 2?

Proposed Response Status W

PROPOSED REJECT.

Comment identical to comment 119 on D3.0

The given definition of RMS jitter in the draft is the correct definition of RMS jitter as is well accepted in literature so cannot be changed. In other words whatever jitter you get by application of this formula is by definition correct. Please see attached paper from Maxim detailing that RMS jitter is defined as the the square root of the expected value of the squared period jitter, as is defined in the draft. Also your example does not clearly state how you got 2ps by using the formula in the draft. Consider a waveform wherein the average period is T, and every period is T-1ps or T+1ps so that the average period is still maintained as T. Then by using the formula, we do get the rms jitter correctly to be 1ps

Cl 55 SC 55.5.4.5 P 141 L 9 MyBallot # 88

GROW. ROBERT M Individual

Comment Type TR Comment Status X

I do not accept an indication of mode of operation sufficient. With all the obfiscation in the way short reach was added to the draft, it is in many ways a different PHY type because the two reach options have very different system capabilities. With previous PHYs, the PHY type implied the cabling requrements and we have lost that ability in this draft for a link partner force a multi-PHY capable DTE to use the desired PHY type. In network operation, the cable plant and switches have traditionally been upgraded as necessary, and a switch can be configured from its end alone to assure that the link partner connecting to it is appropriate for the cable plant.

SuggestedRemedy

Add capability bits and announce them via AN. Arbitration should not allow a short reach mode link to come up unless both partners agree that short reach mode is supported. For power conservation, short reach mode should have precidence over long reach.

Proposed Response Status O

Cl 55 SC 55.6.1.2 P 141 L 20 MyBallot # 29

BOOTH, MR BRAD J Individual

Comment Type E Comment Status X

P. Dawe - Name of bit "Loop Timing" at variance with 45.2.7.10.6.

SuggestedRemedy

Harmonise name with 45.2.7.10.6. "Loop timing ability"?

Proposed Response Response Status O

Comment Type E Comment Status X

P. Dawe - Is MII really the interface you mean? I assume you want MDIO. MDIO is optional: it says so in 45.1.

SuggestedRemedy

Change "10GBASE-T makes extensive use of the management functions provided by the MII Management Interface (Clause 45)," to "10GBASE-T makes extensive use of the management functions that may be provided by the MDIO interface (Clause 45),".

Proposed Response Status O

TYPE: TR/technical required ER/editorial required GR/general required T/technical E/editorial G/general COMMENT STATUS: D/dispatched A/accepted R/rejected RESPONSE STATUS: O/open W/written C/closed U/unsatisfied Z/withdrawn SORT ORDER: Page, Line

Pa **142** Li **3** Page 19 of 22 2/25/2006 10:38:24 AM

CI 55 SC 55.6.1.2 P 143 L 43 MyBallot # 3 Individual

Comment Type GR Comment Status X

Use of a single autonegotiation bit to discriminate between Short Reach mode and Normal mode overly restricts 10GBASE-T devices by allowing advertisement of either Short Reach mode or Normal mode but not both. It seems reasonable to assume that manufacturers will eventually want to provide 10Gbsase-T chips that can operate in Normal mode for distances greater than 30 meters or in Short Reach mode for distances of 30 meters or less, with operation defined via autonegotiation. To advertise this ability we need two bitsùone for Normal mode and one for Short Reach mode, just as are provided by bits U14-15 to advertise full duplex and half duplex operation.

SuggestedRemedy

Change p143 line 36 clm 1 to U31:U22

Change p143 line 37 clm 1 to U21

Change p143 line 42 clm 1 to U20

Insert new row on p143 above line 43 (U18)

U19/ PHY short reach mode/ Defined in 45.2.1.61.2

/1=PHY can operate in short reach mode, 0=PHY cannot operate in short reach mode Change definition of bit U18 p143, line 43

U18/ PHY normal mode/

/1=PHY can operate in normal mode, 0=PHY cannot operate in normal mode

Proposed Response Status O

Comment Type TR Comment Status X

Equation (55-22) Does not contain sufficient indices. In fact, an index is needed for the wire pair of the disturbed channel, an index for the wire pair of the disturbing channel, and an index number for each disturbing channel.

SuggestedRemedy

Preferably use the same format currently used in equation (55-36).

Proposed Response Status O

Cl 55 SC 55.7.3.2.1 P 155 L 49 MyBallot # 58
MEI, RICHARD Y Individual

Comment Status X

, NOTAND I IIIIVidua

The recent ISO meeting change the definition of PSAELFEXT to PSAACR-F (Power Sum Attenuation to Alien Crosstalk Ratio - Far End). This change fixes the problem when calculation the PSAELFEXT of the victim channel surrounded by short disturbers. This definition change has no impact on 10GBASE-T operation.

SuggestedRemedy

Comment Type E

Make a global change to reflect the latest ISO terminology and definition for PSAELFEXT.

Delete line 49 to 59 on page 155 and line 1 to line 9 on page 156, since this definition deos not account for the channels with uneven length.

Use ISO terminology and definition instead.

Proposed Response Response Status **0**

Comment Type TR Comment Status X

Equation (55-28, existing) Does not contain sufficient indices. In fact, an index is needed for the wire pair of the disturbed channel, an index for the wire pair of the disturbing channel, and an index number for each disturbing channel.

SuggestedRemedy

Preferably use the same format currently used in equation (55-37). For AFEXT.

Proposed Response Status O

Cl 55 SC 55.7.3.2.1 P 155 L 52 MyBallot # 36

KOEMAN, HENRIECUS Individual

Comment Type TR Comment Status X

Equation (55-28): It is fundamentally incorrect to power sum ELFEXT results (essentially power summing SNR's: you always first power sum the noise sources, and than reference this to the signal level). When the IL values are close, this is practically not an issue. In case of alien crosstalk, there can be substantial differences in IL.

SuggestedRemedy

First compute the PS AFEXT, and then subtract the average IL of the disturbed channel wire pairs to obtain the PS AELFEXT (or the new name: PS AACR-F). Then use the same name (PS AFEXT) in the average margin computation.

Proposed Response Response Status O

CI 55 SC 55.7.3.3 P 158 L MyBallot # 30
ZHU, XING Individual

Comment Type T Comment Status X

In 55.7.3.3 Alien Crosstalk Margin Computation, Step 1 - Step 3 give a way to adjust the PSANEXT and PSAFEXT for the power backoff derived from insertion loss measurement. The purpose is to take into account the effect of power backoff to the SNR at the receiver.

However, the proposed way is not applicable to all cable laying topologies and makes the problem complex and confusing while the obtained result may be wrong. Please refer to our attached contribution, where we give an example that two victim cables with actual same PSANXET and SNR may be reported with different PSANXET and SNR due to the introduction of power backoff in the computation of PSANEXT.

SuggestedRemedy

Remove the power back-off terms from Clause 55.7.3.3.

Proposed Response Response Status O

CI 55 SC 55.7.3.3 P 158 L 34 MyBallot # 38

KOEMAN, HENRIECUS Individual

Comment Type E Comment Status X

Substantial improvements have been achieved during this last edit, but further improvements are highly desirable. Equation (55-39) is in fact the same as equation (55-23) (except that a >=" sign is used). Similar observations apply to equation (55-40) which matches equation (55-29). These unneeded equation, combined with non-matching indices introduce confusion.

SuggestedRemedy

Make reference to existing equations, rather than creating new ones. Refer to ISO/IEC liaison documents for additional information.

Proposed Response Status **O**

CI 55 SC 55.7.3.3 P 160 L 34 MyBallot # 39 Individual

Comment Type TR Comment Status X

Step 6: The process to implement the integral from discrete data is unclear, in particular if the frequency intervals are not constant (i.e., a log sweep). The same comment applies to step 11.

SuggestedRemedy

Show equations that are based on the spreadsheet that was communicated with the cabling standards committees.

Proposed Response Status O

Comment Type T Comment Status X

The number of steps can be reduced by simply stating that the overall average margin is the minimum of the 4 pair margins and the average margin over all pairs. This reduces the complexity.

SuggestedRemedy

Remove step 7 and adjust step 12 to include each of the results for each of the 4 wire pairs..

Proposed Response Status O

TYPE: TR/technical required ER/editorial required GR/general required T/technical E/editorial G/general COMMENT STATUS: D/dispatched A/accepted R/rejected RESPONSE STATUS: O/open W/written C/closed U/unsatisfied Z/withdrawn SORT ORDER: Page, Line

Pa **160** Li **51** Page 21 of 22 2/25/2006 10:38:25 AM

^{***} Comment submitted with the file 1138800024-PowerBackoff Feb06.ppt attached ***

Cl 55 SC 55.8.1 P 164 Cl 55 P 167 MyBallot # 77 SC 55.9.3 L 58 MyBallot # 49 L 18 GROW, ROBERT M COBB, TERRY R Individual Individual Comment Type ER Comment Status X Comment Type GR Comment Status X I do not believe we have properly responded to the pre-ballot MEC comment on this and Shields in cords or cables that is not properly terminated to ground will cause errors in the following figures. PHY. SuggestedRemedy See contibution from tcobb Why not reference Clause 40? SuggestedRemedy Proposed Response Response Status O Add this sentence to the end of the paragraph: Any shield in cords or cables in the link segment shall be terminated to ground when CI 55 SC 55.8.2 P 164 L 56 MyBallot # 67 connected to the MDI. TAICH. DIMITRY Individual Proposed Response Response Status O Comment Status X Comment Type We have to have clear Cross-talk specification - as measured at the MDI point. Current Cl 55 SC 55 P 177 MvBallot # 78 draft defines FEXT limits for RJ-45 connector only - excluding other potential crosstalk GROW, ROBERT M contributors - for example magnetics. This is in contrary to the rest of the MDI parameters -Individual like Return loss. Impedance balance, etc. Comment Type E Comment Status D In addition, test procedure for FEXT measurement isn't clear. For example, one can Didn't want to test the upload instructions that say no alpha characters in subclause field, wonder whether measurement should be performed using external test fixture - or by this is on Annex 55A. Should this be unnumbered or numbered as is done in 55B? analyzing signals on the transceiverÆs high-speed I/O. SugaestedRemedy SuggestedRemedy Make numbering consistent with IEEE style. (As I recall, number this heading, but check.) Use current FEXT limit line to specify worst-case combined magnetics and connector's cross-talk figures - as measured at the MDI. Proposed Response Response Status W PROPOSED ACCEPT. Please provide testing guideline (similar to Alien Cross-talk measurement setup, for example) - so it would be clear how crosstalk compliance at the MDI point can be verified. This applies to page 178 Proposed Response Response Status O Cl 55 SC 55 P 179 MyBallot # 87 GROW, ROBERT M Individual CI 55 SC 55.8.2.1 P 165 MyBallot # 50 L 20 Comment Type E Comment Status D COBB. TERRY R Individual 55B doesn't appear in bookmarks Comment Type E Comment Status D SuggestedRemedy Although the term Attenuation is correctly used in it's context, I think it is confusing with the Check style definition. title of the sub clause. Proposed Response Response Status W SuggestedRemedy

PROPOSED ACCEPT.

TYPE: TR/technical required ER/editorial required GR/general required T/technical E/editorial G/general COMMENT STATUS: D/dispatched A/accepted R/rejected RESPONSE STATUS: O/open W/written C/closed U/unsatisfied Z/withdrawn SORT ORDER: Page, Line

Change to: Return loss

PROPOSED ACCEPT IN PRINCIPLE.

Response Status W

Proposed Response

Pa **179** Li **1** Page 22 of 22 2/25/2006 10:38:25 AM