IEEE 802.3by D1.1 25 Gb/s Ethernet 3rd Task Force review comments

<i>Cl</i> <b>105</b> <i>SC</i> <b>105.5</b> Mellitz, Richard	P 89 Intel Corporation	L <b>41</b> n	# 1	C/ <b>112</b> SC <b>112.5.4</b> Fang, Jing	P <b>188</b> Marvell	L 17	# 3
Comment Type <b>T</b> table 105-3. 25G RS, M. This is not 32.678 ns	Comment Status A AC, and MAC Control is 8192	bits time of 40	Ops (note a).	Comment Type <b>TR</b> Reference to inter-sublay SuggestedRemedy	Comment Status A ver service interface primitiv	ves should be to	105.4
SuggestedRemedy Change 32.678 to 327.6	38 ns			inter-sublayer service inter-	erface primitives defined in	105.4.	
Response ACCEPT IN PRINCIPLE	Response Status C			Response ACCEPT IN PRINCIPLE	Response Status <b>C</b>		
Change 32.768 to 327.68.				Change cross-reference from 105.3 to 105.4 in two places. Page 186 Line 12 Page 188 Line 17			
C/ <b>108</b> SC <b>108.5.2.4</b> Ran, Adee	P <b>108</b> Intel	L <b>12</b>	# 2	Fage too Line Tr			
Comment Type E The editor's note about i next drafts. SuggestedRemedy Delete the editor's note.	Comment Status A implementation of comment #	7 against D1.0	) is not required for the				
Response ACCEPT.	Response Status C						
C/ 110 SC 110.7.5 Brown, Matt	P 146 Applied Micro	L <b>44</b>	# 4				
Comment Type E The lettered list begins v	Comment Status A with the letter "d" instead of "a	".					
S <i>uggestedRemedy</i> Change lettered list to b	egin with the letter "a".						
Response ACCEPT.	Response Status C						

C/ 112 SC 112.5.4