IEEE 802.3by D1.1 25 Gb/s Ethernet 3rd Task Force review comments

C/ 105 SC 105.5 P 89 L 41 # 1 Mellitz, Richard Intel Corporation Comment Type T Comment Status X table 105-3. 25G RS, MAC, and MAC Control is 8192 bits time of 40ps (note a). This is not 32.678 ns SuggestedRemedy Change 32.678 to 327.68 ns Proposed Response Response Status 0 SC 108.5.2.4 C/ 108 P 108 L 12 Ran, Adee Intel Comment Type E Comment Status X The editor's note about implementation of comment #7 against D1.0 is not required for the next drafts. SuggestedRemedy Delete the editor's note. Proposed Response Response Status 0 C/ 110 SC 110.7.5 P 146 L 44 Brown, Matt Applied Micro Comment Type E Comment Status X The lettered list begins with the letter "d" instead of "a".

SuggestedRemedy

Proposed Response

Change lettered list to begin with the letter "a".

Response Status 0

Cl 112 SC 112.5.4 P 188 L 17 # 3

Fang, Jing Marvell

Comment Type TR Comment Status X

Reference to inter-sublayer service interface primitives should be to 105.4

SuggestedRemedy

Proposed Response Response Status O

inter-sublayer service interface primitives defined in 105.4.