

8802-3/802.3 REVISION REQUEST

DATE: 5th March, 2000
NAME: David Law
COMPANY/AFFILIATION: 3Com
ADDRESS: 3Com Center
Boundary Way, Hemel Hempstead
Herts, HP2 7YU, UK
PHONE: +44 1442 438060
FAX: +44 1442 438333
E-MAIL: David_Law@3com.com

REQUESTED REVISION:
STANDARD: IEEE Std 802.3ab-1999
CLAUSE NUMBER: 40.4.2.2
CLAUSE TITLE: PMA Transmit function
PROPOSED REVISION TEXT:

The text '...shall source TX_TCLK from the recovered clock of 40.4.2.5 while meeting the jitter requirements of 40.6.1.2.5.' should read '...shall source TX_TCLK from the recovered clock of 40.4.2.6 while meeting the jitter requirements of 40.6.1.2.5.'

RATIONALE FOR REVISION:

Subclause 40.4.2.5 is the Link Monitor function and subclause 40.4.2.6 is the Clock Recovery function hence the reference to subclause 40.4.2.5 seems to be incorrect and the reference should be to subclause 40.4.2.6.

IMPACT ON EXISTING NETWORKS:

None.

Please attach supporting material, if any
Submit to:- Geoffrey O. Thompson, Chair IEEE 802.3
Nortel Networks, Inc. M/S SC5-02
4401 Great America Parkway
P. O. Box 58185
Santa Clara, CA 95052-8185 USA
Phone: +1 408 495 1339 FAX: 988 5525
E-Mail: geoff_thompson@baynetworks.com

+----- For official 802.3 use -----+
REV REQ NUMBER: 1028
DATE RECEIVED: 5th March, 2000
EDITORIAL/~~TECHNICAL~~
ACCEPTED/~~DENIED~~
BALLOT REQ'D ~~YES~~/NO
COMMENTS: Published IEEE Std 802.3-2000

For information about this Revision Request see -
http://www.ieee802.org/3/maint/requests/revision_history.html#REQ1028