

-----+  
| 8802-3/802.3 REVISION REQUEST 1116 |  
+-----+

DATE: 22nd Oct, 2003  
NAME: Geoff Thompson  
COMPANY/AFFILIATION: Nortel Networks  
E-MAIL: thompson@ieee.org

REQUESTED REVISION:  
STANDARD: IEEE Std. 802.3af-2003  
CLAUSE NUMBER: Annex 33A  
CLAUSE TITLE: PSE Detection of PDs

PROPOSED REVISION TEXT:

Figure 33A.2 (Page 86).  
Fix line through diode that is in slightly the wrong place.

RATIONALE FOR REVISION:

Fix printing error. Figure should be printed as intended.

IMPACT ON EXISTING NETWORKS:

NONE, This is all editorial.

-----+  
| Please attach supporting material, if any |  
| Submit to:- Bob Grow, Chair IEEE 802.3 |  
| E-Mail: Bob.Grow@intel.com |  
| |  
| +----- For official 802.3 use -----+ |  
| REV REQ NUMBER: 1116 |  
| DATE RECEIVED: 22nd Oct, 2003 |  
| EDITORIAL/~~TECHNICAL~~ |  
| ACCEPTED/~~DENIED~~ |  
| BALLOT REQ'D ~~YES~~/NO |  
| COMMENTS: 08-Mar-06 Ver: D2.0 Status: P |  
+-----+

| For information about this Revision Request see - |  
| [http://www.ieee802.org/3/maint/requests/revision\\_history.html#REQ1116](http://www.ieee802.org/3/maint/requests/revision_history.html#REQ1116) |  
+-----+