IEEE 802.17 Maintenance Request 0081

MR number	0081	**Classification**	Technical	**Date received**	9/25/2005	**Reserved for official 802.17 use**

Standard 802.17-2004   **Page** 56   **Subclause** 6.3.1   **Figure** _____   **Table** _____

Surname Sultan   **Given Name** Robert

Perceived Problem   [If more space is needed, please provide an additional file, preferably as plain text.]

The statement "the MAC service interface also provides the number of hops to the nearest congested station."
is not strictly correct. The MAC service interface provides the number of hops to "the congestion point" or "the head
of the congestion domain in which the local station lies".

Proposed Remedy   [If more space is needed, please provide an additional file, preferably as plain text.]

Change "For service class classC, the MAC service interface also provides the number of hops to the nearest
congested station." to "For service class classC, the MAC service interface of a station lying within a congestion
domain also provides the number of hops to the head of the congestion domain in which that station lies."

Rationale For Remedy   [If more space is needed, please provide an additional file, preferably as plain text.]

More accurate description.

Remedy's Effect On Existing Equipment   [If more space is needed, provide an additional file, preferably as plain text.]

None.

When you have completed this form, please mail it to STDS-802-17-MR   @   listserv.ieee.org.