IEEE 802.17 Maintenance Request 0114

MR number	0114	**Classification**	Technical	**Date received**	6/21/2006	**Reserved for official 802.17 use**

Standard 802.17-2004   **Page** 277   **Subclause** 10.4.10.6   **Figure** _____   **Table** 10.15

Surname Lemon   **Given Name** John

Perceived Problem   [If more space is needed, please provide an additional file, preferably as plain text.]

tailSa, tailRi, and tailIndex are not defined.

Proposed Remedy   [If more space is needed, please provide an additional file, preferably as plain text.]

Add the following to 10.4.10.4:
tailIndex
   Index into topoEntry for the current tail station.
tailRi
   Ringlet on which the tail station sent the FDD.
tailSa
   The MAC address of the tail station.

Rationale For Remedy   [If more space is needed, please provide an additional file, preferably as plain text.]

This declares these variables and defines their usage.

Remedy's Effect On Existing Equipment   [If more space is needed, provide an additional file, preferably as plain text.]

None.

When you have completed this form, please mail it to STDS-802-17-MR   @   listserv.ieee.org.