


# **ERL Measured Results for 50G-KR Device (comment #r01-89)**

**March, 2018**  
**Futoshi Terasawa, Toshiaki Sakai**  
**Socionext Inc.**


# 1. 50G-KR Device ERL measurement

## ■ Measurement Environment






VNA calibration point at RL measurement (TP0a/5a, connector)

Test fixture delay (T<sub>fx</sub>) setting point at ERL calculation (TP0, PKG ball)






# 2. 50G-KR Device Tx ERL (COM2.2.4)



**Device (Tx) ERL11 = 17.72dB  
(level = "2", worst)**

**D3.1 : 19.5dB  
ad hoc (02/21) : 16.1dB**

# 2. 50G-KR Device Rx ERL (COM2.2.4)



**Device (Rx) ERL22=22.37dB**

**D3.1 : 19.5dB**

**ad hoc (02/21) : 16.1dB**

## 4. Conclusion

### 1. "802.3cd D3.1" 50G-KR, CL 137.9.2.1 Tx ERL

- Tx ERL at TP0a > 19.5dB

# Is this TP0 or TP0a? Since the test fixture portion

# (Tfx) is subtracted in ERL calculation.

### 2. Tx ERLmin > 19.5dB is too tight, even with satisfying RL.

- This ERLmin was updated to **16.1dB** at 02/21 ad hoc.

- Measured values (TP0/TP5, Tfx excluded) :

- Tx ERL11 : 17.72dB

- Tx RL : pass

- No transmission issues with this Tx.

- Rx ERL22 : 22.37dB

- Rx RL : pass

### 3. Changing Tx ERLmin limit from **19.5dB** to **16.1dB** is appropriate, considering margin.

**Thank you**

6

# backup slides

7

# A-1 ERL test points (TP)


## Test Points

### 50GBASE-CR/100GBASE-CR2/200GBASE-CR4

#### 136.9.3.4 Transmitter effective return loss

Transmitter ERL at TP2 is recommended to be greater than 9 dB.

[updated 02/21 ad hoc] 14.5dB



#### 136.9.4.5 Receiver effective return loss

Transmitter Receiver ERL at TP2 TP3 is recommended to be greater than 9 dB.


[updated 02/21 ad hoc] 14.5dB

### 50GBASE-KR/100GBASE-KR2/200GBASE-KR4

#### 137.9.2.1 Transmitter effective return loss

Transmitter ERL at TP0a is recommended to be greater than 19.5 dB.


[updated 02/21 ad hoc] 16.1dB







#### 137.9.3.1 Receiver effective return loss

Receiver ERL at TP5a is recommended to be greater than 19.5 dB.





[updated 02/21 ad hoc] 16.1dB







# A-2-1 : Measured Tx RL (return loss)



# A-2-2 : Measured Rx RL (return loss)



# A-3 : Tx PTDR/ERL (COM 2.2.4)



**Thank you!**

SOCIONEXT™

for better quality of experience