Maintenance Task Group

- Meeting Schedule
  - Tuesday, 6PM-8PM, Room – Kennesaw – Lower Level (CC)
- Goals
  - Status update on balloting items.
  - Determine plan of action for 4 items to be categorized
- TG Delegates:
  - Interworking: Norm Finn
  - DCB: Anoop Ghanwani
  - AVB: Geoff Garner
  - Security: TBD
  - Others requested: TG Chairs, technical experts
- Comments
  - Typically maintenance TG will meet via phone prior to meeting

Maintenance Report

Detailed Totals

Summary Totals

Detailed Totals		Summary Totals	
A =	0	Ready for ballot =	2
B =	2	Balloting =	4
CB =	0	Approved =	0
CE =	0	Awaiting clarification =	0
E =	0	Errata =	0
F =	0	To be categorised =	4
I =	0	Review by Technical experts =	0
J =	1	Withdrawn =	0
P =	0	Rejected =	1
R =	4	Published =	0
S =	0		
T =	0	Total =	11
V =	4		
W =	0		
Errors =	0		
		Open =	10
Total =	11		

Code	Description	Code	Description	Code	Description
A	Approved in Ballot	F	Failed in ballot	S	Published in Errata Sheet
B	Awaiting Ballot	I	Incomplete	T	Awaiting Technical Experts
CB	Awaiting change text -Ballot	J	Rejected	V	Balloting
CE	Awaiting change text - Errata	P	Published	W	Withdrawn
E	Errata – ballot not required	R	Request Received		

Open Item Summary

Req#	Status	Standard	Clause	Submitted	Subject
0003	Balloting	802.1Q-2011	20.2.2, 20.28.2, 12.14	26-Mar-11	Inconsistent VID for Loopback Reply (LBR) frames
0005	Ready for Ballot	802.1Q-2011	D4 and LLDP-EXT-DOT1-V2-MIB.mib	17-Jun-11	Missing enable for Link Aggregation TLV
0006	Ready for Ballot	802.1AS-2011	various	23-Jun-11	Corrigendum items agreed to in AVB TG
0007	Balloting	802.1Q/D1.5	10.6	01-Aug-11	incorrect operPointToPointMAC references
0008	Balloting	802.1Q/D1.5	A.21	08-Aug-11	MVRP cut-and-paste errors
0009	Received	802.1Q & 802.1AX	D.2.7	08-Sep-11	Disambiguating LLDP over Link Aggregations
0010	Balloting	802.1Q-2011	6.11.4	13-Sep-11	Incorrect Annex reference
0011	Received	802.1Q-2011	I.5	14-Sep-11	No recommended priority to traffic class mappings for credit-based shaper in table 8-4
0012	Received	802.1Q-2011	26.8	29-Sep-11	Missing MEP/MHF icons in fig 26-2
0013	Received	802.1Q-2011	5.4.4, 5.16.3	27-Oct-11	Missing MRP address for MSRP