IEEE 802.17 Maintenance Request 0006

MR number	0006	**Classification**	Technical	**Date received**	1/25/2005	**Reserved for official 802.17 use**

Standard 802.17-2004   **Page** 139   **Subclause** 7.6.3.8.4   **Figure** _____   **Table** 7.22

Surname Bruckman   **Given Name** Leon

Perceived Problem   [If more space is needed, please provide an additional file, preferably as plain text.]

In rows 4 and 5 of table 7.22 the ps is verified for all frames, but SCFF and MCFF frames do not have this bit (no extendedControl filed in these frames)

Proposed Remedy   [If more space is needed, please provide an additional file, preferably as plain text.]

In rows 4 and 5 in the condition cell, add the condition: frame.ft != FT_FAIRNESS

Rationale For Remedy   [If more space is needed, please provide an additional file, preferably as plain text.]

Minimum change.

Remedy's Effect On Existing Equipment   [If more space is needed, provide an additional file, preferably as plain text.]

Since this is an obvious error, implementors should have seen this problem and no effect is expected