IEEE 802.17 Maintenance Request 0017

MR number	0017	**Classification**	Technical	**Date received**	3/11/2005 **Reserved for official 802.17 use**

Standard 802.17-2004   **Page** 476   **Subclause** D.6   **Figure** _____   **Table** _____

Surname Holness   **Given Name** Marc

Perceived Problem   [If more space is needed, please provide an additional file, preferably as plain text.]

Range of rprSpanProtectionHoldOffTimer object is (0..500) ms. However the state machine description provided in Section 11.2.3 states that the range should be (0..200) ms. This inconsistency needs to be resolved.

Proposed Remedy   [If more space is needed, please provide an additional file, preferably as plain text.]

Change range of rprIfKeepaliveTimeout object to (0..200).

Rationale For Remedy   [If more space is needed, please provide an additional file, preferably as plain text.]

Consistency within the specifications.

Remedy's Effect On Existing Equipment   [If more space is needed, provide an additional file, preferably as plain text.]

No impact.