IEEE 802.17 Maintenance Request 0050

MR number	0050	**Classification**	Technical	**Date received**	3/15/2005	**Reserved for official 802.17 use**

Standard 802.17-2004   **Page** 115   **Subclause** 7.5.7.4.4   **Figure** _____   **Table** 7.13

Surname Caizzone   **Given Name** Giuseppe

Perceived Problem   [If more space is needed, please provide an additional file, preferably as plain text.]

According to Table 7.13 if creditS = Min(0, creditS - 1) as shown in row 1 or creditS = Min(0, creditS + 1) as shown in row 2, the value of creditS is always equal to zero.

Proposed Remedy   [If more space is needed, please provide an additional file, preferably as plain text.]

In Table 7.13 row 1 replace Min(0,creditS-1) with Max(0,creditS-1) and in row 2 replace Min(0,creditS+1) with Max(0,creditS+1). In this way the minimum value of creditS is equal to zero

Rationale For Remedy   [If more space is needed, please provide an additional file, preferably as plain text.]

Minimum change

Remedy's Effect On Existing Equipment   [If more space is needed, provide an additional file, preferably as plain text.]

This is an obvious error and the implementors should have seen it. No particular effect is expected

When you have completed this form, please mail it to STDS-802-17-MR   @   listserv.ieee.org.