IEEE 802.17 Maintenance Request 0108

MR number	0108	Classification	Technical	Date received	6/19/2006	Reserved for official 802.17 use

Standard 802.17-2004 **Page** 311 **Subclause** 11.4.3.3 **Figure** _____ **Table** _____

Surname Lemon **Given Name** John

Perceived Problem   [If more space is needed, please provide an additional file, preferably as plain text.]

Reference is given to the wrong subclause, and no reference is given to the variable from which this obtains its value.

Proposed Remedy   [If more space is needed, please provide an additional file, preferably as plain text.]

Change
"conservative mode fairness (see 10.2.2)."
to
"conservative mode fairness, based on the value of myTopoInfo.conservativeMode defined in 11.2.5."

Rationale For Remedy   [If more space is needed, please provide an additional file, preferably as plain text.]

This corrects the reference, specifies the correct variable, and makes this subclause consistent with its neighboring subclauses.

Remedy's Effect On Existing Equipment   [If more space is needed, provide an additional file, preferably as plain text.]

None.

When you have completed this form, please mail it to STDS-802-17-MR   @   listserv.ieee.org.