IEEE 802.17 Maintenance Request 0121

MR number	0121	**Classification**	Technical	**Date received**	9/15/2006	**Reserved for official 802.17 use**

Standard 802.17-2004   **Page** 326   **Subclause** 11.6.2   **Figure** _____   **Table** _____

Surname Juźwiak   **Given Name** Piotr

Perceived Problem   [If more space is needed, please provide an additional file, preferably as plain text.]

There is no „holdoffStartTime[ri]" variable definition.

Proposed Remedy   [If more space is needed, please provide an additional file, preferably as plain text.]

Add some definition to subclause 11.6.2.2.

Rationale For Remedy   [If more space is needed, please provide an additional file, preferably as plain text.]

Remedy's Effect On Existing Equipment   [If more space is needed, provide an additional file, preferably as plain text.]

None.