IEEE 802.17 Maintenance Request 0132

MR number	0132	**Classification**	Technical	**Date received**	7/10/2008	**Reserved for official 802.17 use**

Standard 802.17-2004   **Page** 322   **Subclause** 11.5.4   **Figure** 11.27   **Table** _____

Surname Lemon   **Given Name** John

Perceived Problem   [If more space is needed, please provide an additional file, preferably as plain text.]

Figure 11.27f lists the wrong topoType.

Proposed Remedy   [If more space is needed, please provide an additional file, preferably as plain text.]

Change "topoType = CLOSED_RING" to "topoType = OPEN_RING".

Rationale For Remedy   [If more space is needed, please provide an additional file, preferably as plain text.]

The ring shown in Figure 11.27f is still broken between S8 and S9.

Remedy's Effect On Existing Equipment   [If more space is needed, provide an additional file, preferably as plain text.]

None.

When you have completed this form, please mail it to STDS-802-17-MR   @   listserv.ieee.org.