Figure 96.9---- PCS Receive State Diagram