Interface Issues

- **There are four issues regarding the interface between the optical transceiver and the PHY silicon**

  — Signal level technology (for example LVPECL)

  — AC Coupling

  — identical signal definitions (for example SD is signal detect and is low true)

  — common pin out and form factor

NORTEL NETWORKS

Karl Reinke - 01/18/98