

Seq. #	Section number	your initials	Comment type E, e, T, t	Part of NO vote	Corrected Text/Comment	Rationale	Disposition/Rebuttal
--------	----------------	---------------	-------------------------	-----------------	------------------------	-----------	----------------------

## Section 7 comments from Ballot on Draft Standard D2 (Vic Hayes, Chair, AT&amp;T WCND)

Seq. #	Section number	your initials	Comment type E, e, T, t	Part of NO vote	Corrected Text/Comment	Rationale	Disposition/Rebuttal
	7.1	BTh	t		<b>Figure 7-1 has two interfaces with the same name, PLME_SAP. Change one</b>	This is same figure as 2-11 and I had the same comment there. How can two different SAPs have the same name? Change one of them. If the last paragraph of this section is true then eliminate one of the SAPs in the picture or show it as a ghost SAP.	
	7.1	MB	e		<b>4th paragraph, second sentence.. add Acronym.... via a Service Access Point (SAP)</b>		
	7.1	TM	e		in third paragraph change The following figure .... to Figure 7-1 ...	there is no guarantee that the final document will be organized such that the illustrations fall into these locations	
	7.2	TM	e		in second paragraph change The following figure .... to Figure 7-2 ....	there is no guarantee that the final document will be organized such that the illustrations fall into these locations	
	7.2	TM	e		under XX_SET.request and XX_SET.confirm change .... that that .... to that the		
	7.3	ZJ	T	N	Delete MLME_SCAN and MLME_POWER_MGT primitives	Scanning and power management should be controlled through MIB variables, along with bit-rate and all that other stuff.	

