

IEEE 802.17 Maintenance Request 0022

MR number 0022 Classification Technical Date received 3/13/2005 **Reserved for official 802.17 use**

Standard 802.17-2004 Page 399 Subclause 12.7.3.4 Figure _____ Table _____

Surname Lemon Given Name John

Perceived Problem [If more space is needed, please provide an additional file, preferably as plain text.]

SP3 and SP4 refer to the wrong frame type.

Proposed Remedy [If more space is needed, please provide an additional file, preferably as plain text.]

In SP3, change "MA_CONTROL.request with an opcode value of OAM_ECHO_REQ" to "MA_CONTROL.request with an opcode value of OAM_FLUSH_REQ", and change "Echo flush formats" to "Flush request formats". In SP4, change "MA_CONTROL.indication with an opcode value of OAM_ECHO_IND" to "MA_CONTROL.indication with an opcode value of OAM_FLUSH_IND", and change "Echo flush formats" to "Flush request formats".

Rationale For Remedy [If more space is needed, please provide an additional file, preferably as plain text.]

It needs to be clear which opcode and frame types are meant.

Remedy's Effect On Existing Equipment [If more space is needed, provide an additional file, preferably as plain text.]

None.

When you have completed this form, please mail it to STDS-802-17-MR @ listserv.ieee.org.