

IEEE 802.17 Maintenance Request 0032

MR number 0032 Classification Technical Date received 3/13/2005 **Reserved for official 802.17 use**

Standard 802.17-2004 Page 326 Subclause 11.6.2.3 Figure _____ Table 11.12

Surname Lemon Given Name John

Perceived Problem [If more space is needed, please provide an additional file, preferably as plain text.]

holdoffTimeout and keepaliveTimeout are not shown to be using per-ringlet values.

Proposed Remedy [If more space is needed, please provide an additional file, preferably as plain text.]

Modify the statemachine table and 11.6.2.2 to correctly apply these on a per-ringlet basis.

Rationale For Remedy [If more space is needed, please provide an additional file, preferably as plain text.]

Different spans can have different characteristics and therefore can need different holdoff values and therefore also keepalive values. It is also clear from 11.2.3 that these are intended to be configured and measured on a per-ringlet basis.

Remedy's Effect On Existing Equipment [If more space is needed, provide an additional file, preferably as plain text.]

None.

When you have completed this form, please mail it to STDS-802-17-MR @ listserv.ieee.org.