

IEEE 802.17 Maintenance Request 0085

MR number 0085 Classification Technical Date received 10/3/2005 **Reserved for official 802.17 use**

Standard 802.17-2004 Page 562 Subclause D.6 Figure Table

Surname Lemon Given Name John

Perceived Problem [If more space is needed, please provide an additional file, preferably as plain text.]

The attributes of RprSpanErrorCountersCurrentEntry do not state where they get their values.

Proposed Remedy [If more space is needed, please provide an additional file, preferably as plain text.]

Change the descriptions of the attributes of RprSpanErrorCountersCurrentEntry to state which variables of the standard provide the values used for the MIB attribute values.

Rationale For Remedy [If more space is needed, please provide an additional file, preferably as plain text.]

Specifying the origin of the values disambiguates the assumed values of these MIB attributes.

Remedy's Effect On Existing Equipment [If more space is needed, provide an additional file, preferably as plain text.]

None.

When you have completed this form, please mail it to STDS-802-17-MR @ listserv.ieee.org.