

## IEEE 802.17 Maintenance Request 0092

MR number 0092 Classification Technical Date received 11/8/2005 **Reserved for official 802.17 use**

Standard 802.17-2004 Page 142 Subclause 7.6.3.9.4 Figure \_\_\_\_\_ Table 7.23

Surname Bruckman Given Name Leon

**Perceived Problem** [ If more space is needed, please provide an additional file, preferably as plain text. ]

The description of Row 7.23-4 is not consistent with the action in the table, and it is wrong (the action in the table is right) since Fairness frames do not have a "ps" bit

**Proposed Remedy** [ If more space is needed, please provide an additional file, preferably as plain text. ]

Replace the description of Row 7.23-4 with: Wrapped fairness frames don't have a ps bit, so no need to adjust it

**Rationale For Remedy** [ If more space is needed, please provide an additional file, preferably as plain text. ]

Make text consistent with table

**Remedy's Effect On Existing Equipment** [ If more space is needed, provide an additional file, preferably as plain text. ]

No impact since the table is right

**When you have completed this form, please mail it to STDS-802-17-MR @ listserv.ieee.org.**