

Cl 00 SC 0 P 0 L 0 # 14
Hajduczenia, Marek ZTE Corporation

Comment Type E Comment Status D

Pages in the PDF do not match page numbers

Suggested Remedy

Fix the page numbers to make pages in PDF match page numbers displayed by the PDF reader.

Proposed Response Response Status W

PROPOSED ACCEPT.

This happened at the boundary between the lower case roman numeral page numbers and the arabic page numbers at page 15. Will be fixed in sponsor ballot draft. The editor suggests that this comment is non-substantive.

Cl 10 SC 10.4 P 254 L 46 # 15
Hajduczenia, Marek ZTE Corporation

Comment Type TR Comment Status D

Seems that reference for some objects was not assigned correctly, for example "{dot3HCStatsEntry xx}" for dot3HCStatsTransmitLPIMicroseconds

Similar for

page 37: IldpV2Xdot3LocPowerType,
page 39: IldpV2Xdot3LocPowerSource
page 40: IldpV2Xdot3LocPowerPriority, IldpV2Xdot3LocPDRRequestedPowerValue,
IldpV2Xdot3LocPSEAllocatedPowerValue,
page 41: IldpV2Xdot3LocResponseTime, IldpV2Xdot3LocReady,
IldpV2Xdot3LocReducedOperationPowerValue
page 43: IldpV2Xdot3LocTxTwSys, IldpV2Xdot3LocTxTwSysEcho,
IldpV2Xdot3LocRxTwSys, IldpV2Xdot3LocRxTwSysEcho
page 44: IldpV2Xdot3LocFbTwSys, IldpV2Xdot3TxDllReady, IldpV2Xdot3RxDllReady,
IldpV2Xdot3LocDllEnabled
page 48: IldpV2Xdot3RemPowerType, IldpV2Xdot3RemPowerSource
page 49: IldpV2Xdot3RemPowerPriority, IldpV2Xdot3RemPDRRequestedPowerValue,
IldpV2Xdot3RemPSEAllocatedPowerValue
page 50: IldpV2Xdot3RemTxTwSys,
page 51: IldpV2Xdot3RemTxTwSysEcho, IldpV2Xdot3RemRxTwSys,
page 52: IldpV2Xdot3RemRxTwSysEcho, IldpV2Xdot3RemFbTwSys
page 148: pethPseActualPower, pethPsePowerAccuracy, pethPseCumulativeEnergy
page 184: dot3MpcpRecognizedMulticastIDs,
page 254: dot3HCStatsTransmitLPIMicroseconds, dot3HCStatsReceiveLPIMicroseconds
page 255: dot3HCStatsTransmitLPITransitions, dot3HCStatsReceiveLPITransitions,
dot3SlowProtocolFrameLimit, dot3ExtensionTable,
page 257: dot3PFCTable,
page 376: ifMauPerPCSLaneStats,
page 378: ifMauEEEESupportList and ifMauEEELDFastRetrainCount,
page 379: ifMauEEELPFastRetrainCount, ifMauTimeSyncCapabilityTX,
ifMauTimeSyncCapabilityRX, ifMauTimeSyncDelayTXmax, ifMauTimeSyncDelayTXmin
page 380: ifMauTimeSyncDelayRXmax, ifMauTimeSyncDelayRXmin,

Suggested Remedy

Fix the references for all listed objects and verify whether any additional objects are missing references.

Proposed Response Response Status W

PROPOSED REJECT.

This was deliberate, and in keeping with the long-standing IEEE 802.3 WG policy of not making OID leaf assignments until the initial sponsor ballot draft.

These assignments will be provided in the initial sponsor ballot draft, along with the branch and leaf assignments in Annex B.

The editor suggests that this comment is not substantive.