

Comment #91 D2.2

Missing INRUSH state

Proposed Remedy:

1. In page 150, line 51: Change the exit label name from MDI_POWER1 to INRUSH
2. Delete editor note in page 151 lines 5-6.
3. Add to following INRUSH state to Figure 33-33 page 151 line 7 as follows:




Figure 33-33 Cont - adding inrush state. Yair Darshan, January 2017.