


Considerations on Invalid Signature Slopes

IEEE 802.3af Task Force
July 10, 2001

John Jetzt
Don Stewart
Avaya Inc.

Problems with PSE & PD Invalid Slopes



PSE-L, PSE-U:

- Values in Source Material were never really voted (last ones were errored)
- Present Draft spec values are in error (allows no margins)

PD-L, PD-U:

- Present values are in too close to “valid”; would force tighter tolerance on PSE than required

Proposed PSE & PD Invalid Slopes

