

EIT Test Channel Return Loss

John D'Ambrosia




Tyco Electronics

February 2, 2006






Channel Data Review

- Frequency Attenuator – ITTC23
- Coupler – 90554 / 90556




Frequency Attenuator



Coupler 90554 / 90556



NewTTC23withCoupler.s4p



File is not TP1 to TP4 only and includes effects of the Rx daughtercard.

Recommendation

- In 69A.2.2
- EIT Test Channel SDD11 / 22 < -20
- For f_{min} to f_2