

31. MAC Control

Editors' Notes: To be removed prior to final publication.

Revision History:

Draft 0.1, March 2005 Initial draft for FE Task Force review.

Figure 31-2 is changed as shown below.





Figure 31 –2—MAC Control sublayer support of interlayer service interfaces

Figure 31-4 is changed as shown below.



NOTE—The opcode-specific operation is launched as a parallel process by the MAC Control sublayer, and not as a synchronous function. Progress of the generic MAC Control Receive state machine (as shown in this figure) is not implicitly impeded by the launching of the opcode-specific function.

Figure 31–4—Generic MAC Control Receive state diagram

Figure 31B-1 is changed as shown below:




Figure 31B-1—PAUSE Operation Transmit state diagram

